

WTC Visual Survey Form

Premise Address: 110 Liberty St - Closed		
Block: 52	Residential ☐ Commercial ☐	Name of Building:
Lot: 7501	Mix Use ☐ Other ☐	
# of Stories: 3	AKA's: 113-117 Liberty St Cedar St	
Building Owner/Management:		Telephone Number: ()
Name: MONC		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: <u>N/A</u>		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof _____					
Debris:	☐ No Visible /Fine Layer	☐ ½ to 1"	☒ > 1"		
Description:	Inspected from roof of 125 Cedar St				
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments Directly in front of WTC South					

Date: 1/25/2002

Inspection Team: Name: CAPA

Name: _____

Agency: DCP

Agency: _____

WTC Visual Survey Form

Premise Address: <u>110 Liberty St - Closed</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>2</u>	AKA's:	
Building Owner/Management: <u>NONC</u>		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"					
Description: <u>Inspected from top of roof of 100 Trinity St</u>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 1/26 /2002Inspection Team: Name: CARL LUTCHMORAgency: DEP

Name: _____

Agency: _____

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
110..... LIBERTY STREET..... 1 MANHATTAN 10006 BIN# 1001042
DCP GEOGRAPHICAL INFORMATION:
LIBERTY STREET 110 - 114 HEALTH AREA : 77 TAX BLK: 52...
CEDAR STREET 113 - 117 CENSUS TRACT: 2001 TAX LOT: 7501.
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : BALDWIN REALTY, AGENT BALDWIN REALTY, AGENT
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 113 CEDAR ST DOB LOCAL LAW STATUS: NO
NEW YORK NY 10006-1061
DOF BUILDING INFORMATION: TRANS LAND VALUE: 801,513
BLDG SIZE; ** UNKNOWN ** TAX EXEMPT FLAG : NO
LOT SIZE: ** UNKNOWN ** TAX EXEMPT CLASS:
BLDG CLASS : R0 CONDOMINIUMS CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 12:07:12 PM

Page: 1* Document Name: Extra

01/29/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
110..... LIBERTY STREET..... 1 MANHATTAN 10006 BIN# 1001042
DCP GEOGRAPHICAL INFORMATION:
LIBERTY STREET 110 - 114 HEALTH AREA : 77 TAX BLK: 52...
CEDAR STREET 113 - 117 CENSUS TRACT: 2001 TAX LOT: 7501.
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : BALDWIN REALTY, AGENT BALDWIN REALTY, AGENT
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 113 CEDAR ST DOB LOCAL LAW STATUS: NO
NEW YORK NY 10006-1061
DOF BUILDING INFORMATION: TRANS LAND VALUE: 801,513
BLDG SIZE; ** UNKNOWN ** TAX EXEMPT FLAG : NO
LOT SIZE: ** UNKNOWN ** TAX EXEMPT CLASS:
BLDG CLASS : R0 CONDOMINIUMS CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/29/ 2 Time: 05:09:39 PM