



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Flushing, New York
11373-5108

**Christopher O. Ward
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental
Compliance**

Building Owner/ Building Manager
114 Liberty Street
New York, NY 10006

Subject: 114 LIBERTY STREET
119 Cedar St.

Dear Sir/Madam:

May 3, 2002

(16)

CONTACT:

DENISE SWEENEY

*H 212-633-6500
x 229*

The New York City Department of Environmental Protection (DEP) in cooperation with the United States Environmental Protection Agency (USEPA) and the New York State Department of Labor (NYSDOL) has performed a series of exterior building surveys on various buildings in the vicinity of the World Trade Center (WTC). The surveys included the examination of building exteriors including building roofs, facades, setbacks, and other exterior surfaces. These surveys identified locations where debris from the collapse of the WTC was still visible. Our records indicate that visible debris accumulations were observed at the above referenced building (the "Building").

In our previous correspondence, the Department requested an assessment and appropriate clean up of visible debris accumulations. The Department has either not received information regarding your actions to address the debris accumulations or has re-inspected your building and found that visible debris was present.

The USEPA and DEP are continuing their ongoing efforts to improve air quality in lower Manhattan. In this regard, DEP is initiating a program (the "Cleaning Program") to clean the exteriors of certain buildings in the downtown Manhattan area.

Based on visual surveys and analyses of other properties in the area, we are assuming that the debris accumulations noted on the exterior of the Building may include some amount of asbestos-containing material (ACM). DEP would like to include the Building in the Cleaning Program, and clean the facades, roofs, and other exterior surfaces so as to remove such accumulations. The work would be performed by NYSDOL licensed asbestos contractors with DEP and NYSDOL certified workers. The fees and expenses of the asbestos contractor in performing the work will be paid for by the DEP.

The work will be monitored by DEP personnel. An independent third-party air monitoring firm will also be engaged to take air samples at designated points around the perimeter of the working area. The U.S. Occupational Safety and Health Administration (OSHA) will provide oversight for worker safety. The fees and expenses of DEP personnel in monitoring the work and the fees and expenses of the third-party air monitoring firm in taking and analyzing air samples will be paid for by DEP.



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: untitled

ADDRESS EXISTS WITH A.K.A.S WHICH HAVE THE SAME BIN

05/20/02 PUBLIC ACCESS PROPERTY PROFILE OVERVIEW

BISPIQ

114..... LIBERTY STREET..... 1 MANHATTAN

10006 BIN# 10010

LIBERTY STREET 110 - 114

HEALTH AREA : 77

TAX BLK: 52.

CEDAR STREET 113 - 117

CENSUS TRACT: 13

TAX LOT: 750

COMMUNITY BD: 101

CONDO : C

MULTI STRUCT: 01

VACANT :

=====

DOB SPECIAL PLACE NAME :

1 PROPERTY RECORD (

DOB BUILDING REMARKS :

FINANCE OCCUPANCY CODE : R0-CONDOMINIUMS

LANDMARK STATUS:

OTHER BINS : 1001041

COUNTS FOR THIS BIN

RECORD VERIFIED :

ACTIONS : 66 , 33

JOBS/FILINGS (PF4)

SPECIAL STATUS :

VIOLATIONS DOB : 37 , 29

OPEN

LOCAL LAW :

ECB : 0 , 0

OPEN (PF12)

SRO :

COMPLAINTS : 2 , 0

OPEN (PF11)

PF 3 = ELEVATORS ENTER KEY= ACTIONS

PF 5/6/7 = NEW ADDR/BIN/BLK-LOT

PF 8 = BOILERS (TYPE :)

PF 9/10 = BROWSE BIN/BLK-LOT

*NO ARA'S FILED

PF 15 = BROWSE 1 PROPERTY RECOR

PF 14 = LPC/HPD/LOFT USE ONLY

PF 16 = ADDTN'L PROPERTY INFO

Date: 5/20/2002 Time: 03:11:09 PM