

***** -IND. XMT JOURNAL- ***** DATE APR-01-2003 ***** TIME 09:02 *****

DATE/TIME = APR-01-2003-08:50

JOURNAL No. = 23

COMM.RESULT = OK

PAGE(S) = 007

DURATION = 00:02'21

FILE No. =

MODE = TRANSMISSION

DESTINATION = 912126374360

RECEIVED ID = / 2126374360

RESOLUTION = STD

-NYCDEP BANHM ASB/LEAD TRU-

***** -

- ***** -

718 595 3648- *****



Please Reply To:

SCIENTIFIC LABORATORIES, INC.117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

FACSIMILE TELECOPY TRANSMISSIONTo: Mary Kate Kiokeary / Penny
JLC Environmental ConsultantsFax #: (212) 420-6092 (718) 595-3744Date: Tuesday, April 01, 2003Time: 07:14:57

Comments:

From: Paul J. MuchaSCILAB Job#: 203034111Subject: AHERA Protocol 24 hour ResultsClient Project: 03-2744; NYCDEP; 114 Liberty
St., NY, NY/POST-ABATENumber of Pages: (7)

(including cover sheet)

Partial Results :This is what we have sofar, still a lot more
to go.Many elevated conb and
overloaded samples
Very difficult to analyzePaul

CONFIDENTIALITY NOTICE: Unless otherwise indicated, the information contained in this facsimile communication is confidential information intended for use of the individual named above. If the reader of this communication is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is prohibited. If you have received this communication in error, please immediately notify the sender by telephone and return the original message to the above address via the US Postal Service at our expense. Preliminary data reported here will be verified before final report is issued. Samples are disposed of in 60 days or unless otherwise instructed by the protocol or special instructions in writing. Thank you.

THE SCILAB GROUP OF LABORATORIES

Certified Analysis

Service 24 Hours A Day • 7 Days A Week

Competitive Prices

visit our web site - www.scilab.com

**SCIENTIFIC
LABORATORIES, INC.**
117 EAST 30TH STREET
NEW YORK, NY 10016
TEL: (212) 679-8600
FAX: (212) 679-9392

**SCILAB
CALIFORNIA, INC.**
24416 SOUTH MAIN ST.
CARSON, CA 90745
TEL: (310) 834-4888
FAX: (310) 834-4772

**SCILAB
BOSTON, INC.**
8 SCHOOL STREET
WEYMOUTH, MA 02189
TEL: (781) 337-9334
FAX: (781) 337-7642

**SCIENTIFIC
LABORATORIES, INC.**
13835 GENITO ROAD
MIDLOTHIAN, VA 23112
TEL: (804) 783-1200
FAX: (804) 783-1900

NEW YORK • LOS ANGELES • BOSTON • RICHMOND

SciLab Job #: 203034111

Client Name: JLC Environmental Consultants

Table I
Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)
 03-2744; NYCDEP; 114 Liberty St., NY, NY/POST-ABATE

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)	Structure Density (struc/sq. mm.) >5.0	Structure Concentration (struc/cc air) >5.0	Type of Asbestos
01	009448	FINAL: Room I (Kitchen) Adj. to Microtrap Inside W/Area 12th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
02	009449	FINAL: At the Center of the Restroom Inside the W/Area 12th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
03	009450	FINAL: At the Northern Side of Room II (Sitting Room) Inside the W/Area 12th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
04	009451	FINAL: At the Southern Side of Room II (Sitting Room) Inside W/Area 12th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
05	009452	FINAL: At the Center of the Closest Adj. to Room II Inside the W/Area 12th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
06	009453	FINAL: Room I Entrance Opposite the Elevator Inside the W/Area of 11th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
07	009454	FINAL: Room II Adj. to the Staircase inside W/Area of 11th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
08	009455	FINAL: Room III Entrance Opposite to the Staircase Inside W/Area of 11th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
09	009456	FINAL: Room IV Entrance Adj. to the Hallway Inside W/Area of 11th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
10	009457	FINAL: Room V Southern End of the Hallway Inside the W/Area of 11th Floor	3600	24	0.0004	0.0	<4.2	<0.0004	NSD
11**	009458	FINAL: 10th Floor, Living Room, Center of Room "Sample Overloaded w/Particulate-Unable To Analyze"	3600						
12**	009459	FINAL: 10th Floor, NW Bedroom "Sample Overloaded w/Particulate-Unable To Analyze"	3600						
13**	009560	FINAL: 10th Floor; NE Side of Dining Room "Sample Overloaded w/Particulate-Unable To Analyze"	3600						
14**	009461	FINAL: 10th Floor, Center of Kitchen "Sample Overloaded w/Particulate-Unable To Analyze"	3600						

* concentration represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By:

Analyzed By:

Date: 3/31/03

Paul J. Mucka

NVLAP#: 200546-0

SciLab Job #: 203034111

Client Name: JLC Environmental Consultants

Table I

Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)
03-2744; NYCDEP; 114 Liberty St.; NY, NY/POST-ABATE

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)		Structure Density (struc/sq. mm.)		Structure Concentration (struc/cc air)		Type of Asbestos
						0.5-5.0	>5.0	>5.0	Total	>5.0	Total	
15**	009462		3600									
	FINAL: 10th Floor, Center SW Bedroom					"Sample Overloaded w/Particulate-Unable To Analyze"						
16	009463		3600	.24	0.0004	13.0	4.0	17.0	70.8	0.0018	0.0076	chrysotile
17	009464		3600	.24	0.0004	34.0	4.0	38.0	158.3	0.0018	0.0169	chrysotile
18	009465		3600	.24	0.0004	28.0	3.0	31.0	129.2	0.0013	0.0138	chrysotile
19	009466		3600	.24	0.0004	15.0	3.0	18.0	75.0	0.0013	0.0080	chrysotile
20	009467		3600	.24	0.0004	15.0	1.0	16.0	66.7	0.0004	0.0071	chrysotile
21	009468		3600	.13	0.0008	47.0	3.0	50.0	384.6	0.0025	0.0411	chrysotile amphibole
22	009469		3600	.24	0.0004	37.0	4.0	41.0	170.8	0.0018	0.0183	chrysotile amphibole
23**	009470		3600									
	FINAL: 8th Floor IWA by Kitchen, West Side					"Sample Overloaded w/Particulate-Unable To Analyze"						
24	009471		3600	.24	0.0004	32.0	2.0	34.0	8.3	0.0009	0.0152	chrysotile
25	009472		3600	.12	0.0009	11.0	1.0	12.0	8.3	0.0009	0.0107	chrysotile
26	009473		3600	.24	0.0004	33.0	6.0	39.0	162.5	0.0027	0.0174	chrysotile amphibole
27**	009474		3600									
	FINAL: 7th Floor IWA by Dining Room, East Side					"Sample Overloaded w/Particulate-Unable To Analyze"						
28**	009475		3600									
	FINAL: 7th Floor IWA by Kitchen, West Side					"Sample Overloaded w/Particulate-Unable To Analyze"						

* concentration represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By:

Analyzed By:

Date: 3/31/03

Paul J. Mudra

NVLAP#: 200546-0

SciLab Job #: 203034111

Client Name: JLC Environmental Consultants

Table I

Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)

03-2744; NYCDEP; 114 Liberty St.; NY, NY/POST-ABATE

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)	Structure Density (struc/sq. mm.)	Structure Concentration (struc/cc air)	Type of Asbestos
29**	009476	3600	FINAL: 7th Floor IWA by Bedroom, Southeast						
30**	009477	3600	FINAL: 7th Floor IWA By Bedroom, Southwest						
31**	009478	3600	FINAL: 6th Floor, South Side of Living Room						
32**	009479	3600	FINAL: 6th Floor, North Side of Dining Room						
33**	009480	3600	FINAL: 6th Floor, Center of Kitchen						
34**	009481	3600	FINAL: 6th Floor, East Bedroom Just South of Kitchen						
35**	009482	3600	FINAL: 6th Floor, SW Bedroom						
36**	009483	3600	FINAL: 5th Floor, Center of Living Room						
37**	009484	3600	FINAL: 5th Floor, East Side of Dining Room						
38**	009485	3600	FINAL: 5th Floor, Center of Kitchen						
39**	009486	3600	FINAL: 5th Floor, SE Bedroom						
40**	009487	3600	FINAL: 5th Floor, SW Bedroom						
41**	009488	3600	FINAL: 4th Floor, Center of Living Room						
42**	009489	3600	FINAL: 4th Floor, Center of Dining Room						

* concentration represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By:

Analyzed By:

Date: 3/31/03



Paul J. Macha

NVLA P#: 200546-0

SciLab Job #: 203034111

Client Name: JLC Environmental Consultants

Table I

Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)

03-2744; NYCDEP; 114 Liberty St.; NY, NY/POST-ABATE

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)			Structure Density (struc/sq. mm.)		Structure Concentration (struc/cc air)	Type of Asbestos	
						0.5-5.0	>5.0	Total	>5.0	Total			
43**	009490	3600											
	FINAL: 4th Floor, Center of Kitchen												
44**	009491	3600											
	FINAL: 4th Floor, SE Bedroom												
45**	009492	3600											
	FINAL: 4th Floor, SW Bedroom												
46	009493	3600		24	0.0004	5.0	0.0	5.0	<4.2	20.8	<0.0004	0.0022	chrysotile
	FINAL: 3rd Floor IWA Bedroom #1, North Side												
47	009494	3600		24	0.0004	4.0	0.0	4.0	<4.2	16.7	<0.0004	0.0018	chrysotile amphibole
	FINAL: 3rd Floor IWA Bedroom #2, East Side												chrysotile
48	009495	3600		24	0.0004	2.0	0.0	2.0	<4.2	8.3	<0.0004	0.0009	chrysotile
	FINAL: 3rd Floor IWA by Living Room, East Side												NSD
49	009496	3600		24	0.0004	0.0	0.0	0.0	<4.2	<4.2	<0.0004	<0.0004	NSD
	FINAL: 3rd Floor IWA by Living Room, Southeast												chrysotile
50	009497	3600		24	0.0004	4.0	0.0	4.0	<4.2	16.7	<0.0004	0.0018	chrysotile
	FINAL: 3rd Floor IWA Bedroom #3, Southwest												chrysotile
51	009498	3600		24	0.0004	1.0	0.0	1.0	<4.2	4.2	<0.0004	0.0004	chrysotile
	FINAL: 3rd Floor IWA Reception Office, East Side												chrysotile
52	009499	3600		24	0.0004	1.0	0.0	1.0	<4.2	4.2	<0.0004	0.0004	chrysotile
	FINAL: 3rd Floor IWA North Side Office by Liberty Street												chrysotile
53	009500	3600		24	0.0004	2.0	0.0	2.0	<4.2	8.3	<0.0004	0.0009	chrysotile
	FINAL: 3rd Floor IWA Examination Room, South Side												chrysotile
54	009501	3600		24	0.0004	2.0	0.0	2.0	<4.2	8.3	<0.0004	0.0009	chrysotile
	FINAL: 3rd Floor IWA Mini Office Adj. to Bathroom, North Side												NSD
55	009502	3600		24	0.0004	0.0	0.0	0.0	<4.2	<4.2	<0.0004	<0.0004	NSD
	FINAL: 3rd Floor IWA Administration Office, West Side												chrysotile
56	009503	3600		24	0.0004	2.0	0.0	2.0	<4.2	8.3	<0.0004	0.0009	chrysotile
	FINAL: 2nd Floor IWA by Restaurant, North Side												chrysotile

* concentration represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By:

Analyzed By:

Date: 3/31/03

Paul J. Mucha

NVLAP#: 200546-0

SciLab Job #: 203034111

Client Name: JLC Environmental Consultants

Table I

Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)

03-2744; NYCDEP; 114 Liberty St.; NY, NY/POST-ABATE

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)		Structure Density (struc/sq. mm.)		Structure Concentration (struc/cc air)		Type of Asbestos
						0.5-5.0	>5.0	>5.0	Total	>5.0	Total	
57	009504		3600	24	0.0004	3.0	0.0	<4.2	12.5	<0.0004	0.0013	chrysotile
	FINAL: 2nd Floor IWA by Restaurant, West Side											
58**	009505		3600									
	FINAL: 2nd Floor IW by Restaurant, East Side											
59**	009506		3600									
	FINAL: 2nd Floor IWA by Restaurant, South Side											
60**	009507		3600									
	FINAL: 2nd Floor IWA by Restaurant by Cashier's Desk											
61**	009508		3600									
	FINAL: 2nd Floor IWA Weight Watchers Office Opposite Elevator, East Side											
62**	009509		3600									
	FINAL: 2nd Floor IWA Weight Watchers Office by Liberty Street, North Side											
63**	009510		3600									
	FINAL: 2nd Floor IWA Weight Watchers Rear End Office, North Side											
64**	009511		3600									
	FINAL: 2nd Floor IWA Weight Watchers Rear End Office, South Side											
65**	009512		3600									
	FINAL: 2nd Floor IWA Weight Watchers Rear End Office, West Side											

* concentration represented by the detection of 1 structure

** not analyzed

NSD: No Asbestos Structures Detected

Reviewed By:

Analyzed By:

Date: 3/31/03

Paul J. Mucha

NVLAP#: 200546-0



2030341

THE UNIVERSITY OF CHICAGO

203034111

Reason for PO: TEM

200 Park Ave South, Suite 1001 New York, New York 10003 • Tel: (212) 420-8119 • Fax: (212) 420-6092