

WTC Visual Survey Form

1001098

Premise Address: 9-11 MAIDEN LANE		
Block: 65	Residential ☒ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
Lot: 10		
# of Stories: 15	AKA's:	
Building Owner/Management:		Telephone Number:
Name:		PII
Address:		PII
On Site Contact:		Telephone Number:
Name: Edwin Pichardo		(212) 962-0734
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Facade Description: West facade at fire escape <u>West facade at fire escape</u> <u>fire escape</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" of dust ☐ > 1" of dust.					
Description: _____					
Setbacks N/A ☐					
Floor: 3 rd		Debris: ☐ No Visible/Fine Layer	☒ 1/2 to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Comments					

Date: 7/31/2002

Inspection Team: Name: Dennis Antzoulatos Agency: A020
Name: _____ Agency: _____

E N T - 000