

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 02/28/2002 03:40 PM

Submitted By

Page 1

Service # 414724

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 10 MAIDEN LA 1

10038

Cross Streets BROADWAY
LIBERTY PL

Compass Direction

Building ID 10010

Block 00064

Lot 0021

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 02/27/2002 10:22

Taken By 7240

INNISS, JAIME

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

COMPLETED

Customer Contact Req

Budget #

Problem Comments

Initial Caller

Last Name CHIBATTONI

Title

First Name, MI STEVEN

Address AREA RESIDENT

City, State/Province, ZIP/PC

Foreign

Day Phone (212)238-7514 x

Evening Phone

Call Date 02/27/2002 10:22

Reference #

Caller Comments

VACANT BUILDING HAS NOT BEEN CLEANED UP FROM WTC DEBREE / COMPL STATES DEBREE BLOWS OF BUILDING
AROUND AREA

Inspected				Resolution			
By	Date	Time		Code	Date	Time	

By *Care* Date *2/27/02* Time *5:15pm* Code *2* Date *2/27/02* Time *5:45*
Building is locked. Heavily contaminated with WTC debris

Carl

Asbestos Inspection Report**Page 1 of 1**

Premise # 10-12 Maiden Lane				Date of Inspection 07/20/2002 & 07/20/02	
Floor Roof & facade	Zip 10006	Block 19	Lot # 11	Boro Code 1	
Inspector Rammohan	Badge # A078	Squad # 1	Basis of Inspection TEM 1144MNC 2	Building Type A	Pictures yes
Contractors Name Trio Asbestos Removal Corp.			Sample # NA		
Address 14-20 129 Street			Sample # NA		
City College Point	State NY	Zip 11356	Sample # NA		
Laboratory Name Warren & Panzer			Building Owner 10-12 Maiden Lane LLC		
Address 228 East 45Th Street			Address		
City NY	State NY	Zip 10017	City	State	Zip
Contact Person At Site Marek J Trzepietowski – Project manager			Time of Inspection 8am – 8 pm		
On arrival Inspection disclosed before the project could begin we had to contact NYDP, OEM & DOT to have four vehicles towed. The Warren & Panzer representative was Gregegor Boron (7/20/02) & Cheetram Ramraj (7/21/02). The roof cleaning began first followed by the façade. A remote decontamination system was built on the 2nd floor. There were four small roofs at the lower level, which were also addressed. Later in the day a dike was built on the sidewalk and cleaning started on the façade. Work went ahead as scheduled. The site was monitored by Dennis Antzoulatos, Dennis White, and Carlstien Lutchmedial. On 7/21/02 cleaning continued with DEP requesting more cleaning in some areas. A final was performed on the roof and façade and it was found to be free of WTC debris.					

NOV # NA						Result Code 5
NOV # NA						Supervisor Initial

Boro Code 1 = Manhattan 2 = Bronx 3 = Brooklyn 4 = Queens 5 = Staten Island

Bldg. Type A > 6 Stories B < 6 Stories C - Single Family D - School

E - Hospital F - Public Owned Property

Result Codes 1= Violation Issued 2 = No Violations Issued 3 = No Access


4 = Project Not Started 5 = Project Completed

Premise Address: 16-18 Maiden Lane, Manhattan

Date of Inspection: 28th February, 2002

Inspector: Carlstien Lutchmedial

Photo shows the interior hatch that accesses the roof (6th Fl). At the seams of the hatch cover there was no visible debris.



Premise Address: Back of 10-12 Maiden Lane , Manhattan

Date of Inspection: 28th February, 2002

Inspector: Carlstien Lutchmedial

Photo shows an untouched roof and a common space of a couple buildings.




Premise Address: 6 Liberty Place, Manhattan

Date of Inspection: 28th February, 2002

Inspector: Carlstien Lutchmedial

Photo shows the ledges of the windows to be caked with debris. Also debris can be seen on the AC unit at the middle lower portion of the picture.




Premise Address: 6 Liberty Place, , Manhattan

Date of Inspection: 28th February, 2002

Inspector: Carlstien Lutchmedial

Photo shows the ledges of the windows to be caked with debris. Also debris can be seen on the AC unit at the middle portion of the picture.



Premise Address: 6 Liberty Place, 10-12 Maiden Lane, Manhattan

Date of Inspection: 28th February, 2002

Inspector: Carlstien Lutchmedial

Photo shows the ledges of the windows to be caked with debris. Also debris can be seen on the AC unit at the middle portion of the picture. The setbacks at the back of 10-12 Maiden Lane is caked "white" with debris. Including the fire escape.

