

WTC Visual Survey Form

1001016

Premise Address: <u>90 Maiden Lane</u>		
Block: <u>42</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>36</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No	Locations: _____	
ACM Clean Up ☐ Yes ☐ No	Locations: _____	
Air Monitoring ☒ Yes ☐ No	Locations: _____	
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☒ Yes ☐ No	Debris	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ ½ to 1" ☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ ½ to 1" ☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ ½ to 1" ☐ > 1"
Facade Description: _____ _____					
Roof					
Debris: ☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>ROOF CLU LETTER</u> _____ _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Comments _____ _____ _____ _____					

Date: 2/16/2002

Inspection Team: Name: Mohan

Agency: DEP

Name: _____

Agency: _____

2/19/2002

no access

✓