

Asbestos Inspection Report

Premise No. 114 Liberty Street					Inspection Date: March 29, 2003	
Floor All	Zip 10006	Borough 1 (Manhattan)	Block 52	Lot 7502	Squad # N/A	Badge # A019
Inspector Penny Theodorellys		Building Type A	Basis of Inspection TRU0273MN03			Photos Taken No
Contractor's Name ETS Construction, Inc			Sample Number			
Address City 160 Clay Street, Brooklyn			Sample Number			
State Zip Phone NY 11222 (718) 706-6300			Sample Number			
Laboratory Name JLC Environmental Consultants			Owner's Name 114 Liberty LLC			
Address City 200 Park Avenue South, New York			Address City			
State Zip Phone NY 10003 (212) 420-8119			State Zip Phone			
Contact Person			Time of Inspection from: 8:00 a.m. to 11:30 a.m.			

This inspection was the performance of a final visual inspection to confirm the absence of visible debris at the site. This was the second visual inspection since the first one had not been successful.

All work to be performed in accordance with contracts WTC-LBC and WTC-LBA. Clarifications and updates were provided to the contractors and residents by e-mail. Copies of correspondence to be incorporated with these inspection reports.

I entered the work area with the project monitors, the site supervisors, and Mr. C. Lutchmedial, Mr. A. Plumptre, Mr. D. Antzoulatos. Inspections began on the 12th and 11th floor and then proceeded to the 6th Floor. Some minimal clean-up activities were still required and were performed while DEP was present on site.

Clearance sampling to begin today.

NOV#	INFRACTION	INFRACTION	INFRACTION	INFRACTION	INFRACTION	RESULT CODE 2
NOV#	INFRACTION	INFRACTION	INFRACTION	INFRACTION	INFRACTION	SUPERVISOR

Asbestos Inspection Report

Premise No. 114 Liberty Street					Inspection Date: March 29, 2003	
Floor All	Zip 10006	Borough 1 (Manhattan)	Block 52	Lot 7502	Squad # N/A	Badge # A019
Inspector Penny Theodorellys		Building Type A	Basis of Inspection TRU0273MN03			Photos Taken No
Contractor's Name ETS Construction, Inc			Sample Number			
Address City 160 Clay Street, Brooklyn			Sample Number			
State Zip Phone NY 11222 (718) 706-6300			Sample Number			
Laboratory Name JLC Environmental Consultants			Owner's Name 114 Liberty LLC c/o Epic, LLC			
Address City 200 Park Avenue South, New York			Address 12 East 44 th Street		City New York	
State Zip Phone NY 10003 (212) 420-8119			State Zip New York 10017		Phone (212)633-6500	
Contact Person			Time of Inspection from: 4:30 p.m. to 7:30 p.m.			

All work to be performed in accordance with contracts WTC-LBC and WTC-LBA. Clarifications and updates were provided to the contractors and residents by e-mail. Copies of correspondence to be incorporated with these inspection reports.

Wipe sampling was completed. Samples were on site and being prepared for shipping. Aggressive air sampling in progress on the 10th, 11th, and 12th floors. Silica not started sampling equipment had not arrived on site.

Cleaning activities in progress in the basement and pizza store.

NOV#	INFRACTION	INFRACTION	INFRACTION	INFRACTION	INFRACTION	RESULT CODE 2
NOV#	INFRACTION	INFRACTION	INFRACTION	INFRACTION	INFRACTION	SUPERVISOR