

AMBIENT LABS, INC.
156 WEST 20TH STREET
NEW YORK, NY 10011

BULK SAMPLE LABORATORY DATA REPORT

PROJECT: L980752
CLIENT: Mr. Linda Caspe

LOCATION: 150 Franklin Street - 7th Floor

TECHNICIAN:

COLLECTED: 3/22/99
DATE RECD: 3/24/99
TIME RECD: 5:19 PM
ANALYZED: 3/26/99

BATCH ID: 1250

SIGNED FOR AMBIENT LABS INC. BY:

Todd Tate

LABORATORY ID NUMBER	FIELD ID NUMBER	SAMPLE COLOR	SAMPLE DESCRIPTION	ASBESTOS PRESENT	PERCENTAGE TOTAL ASBESTOS	SAMPLE CONSTITUENTS
059065792N	01	Brown/Black/Silver	For sample	YES	0.24 % (P)	CHRYSOCTILE: TRACE NON-FIBROUS: 35.30 % OTHER: 64.70 %
059065793N		Brown/Black/Silver	For sample	YES	2.80 % (F)	CHRYSOCTILE: 2.80 % NON-FIBROUS: 32.50 % OTHER: 64.70 %

NAD = No Asbestos Detected. Trace < 0.25 %.

(P) Analysis by Polarized Light Microscopy (PLM) NYS ELAP method 198.1 or EPA/600/R-99/116. (F) Analysis by Transmission Electron Microscopy (TEM) NYS ELAP method 198.4. Polarized Light Microscopy is not consistently reliable in detection of asbestos in floor coverings and similar non-fibered organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. No reproduction of all or any portion of this report shall occur without written approval of Ambient Labs, Inc. All results disclosed in this report relate only to the items tested.

NYS Lab ID # 101616. NYS ELAP ID # 10066. STATE OF NY ELAP ID # 2130.

AMBIENT LABS, INC.
150 WEST 25TH STREET
NEW YORK, NY 10001

BULK SAMPLE LABORATORY DATA REPORT

PROJECT: 090687
CLIENT: Linda Kaysie
LOCATION: 150 Franklin Street 7th floor
TECHNICIAN: SAMIR M. PATEL
COLLECTED: 3/17/00
DATE REC'D: 3/18/00
TIME REC'D: 11:45 AM
ANALYZED: 3/16/00
BATCH ID: 1262
SIGNED FOR AMBIENT LABS INC. BY:

LABORATORY ID NUMBER	FIELD ID NUMBER	SAMPLE COLOR	SAMPLE DESCRIPTION	ASBESTOS PRESENT	PERCENTOF TOTAL ASBESTOS	SAMPLE CONSTITUENTS
B9068756N	90687-1	Black	Southwest corner underneath sink	YES	0.24 % (P)	CHRYSOITILE : TRACE NON-FIBROUS : 33.40 % OTHER : 66.60 %
B9068758N		Black	Sample A	YES	0.24 % (T)	CHRYSOITILE : TRACE NON-FIBROUS : 33.00 % OTHER : 67.00 %
B9068757N	90687-2	Black	Southwest corner underneath sink	NAD	0.00 % (P)	NON-FIBROUS : 41.80 % OTHER : 58.20 %
B9068757N		Black	Sample B	YES	0.24 % (T)	CHRYSOITILE : TRACE NON-FIBROUS : 42.00 % OTHER : 58.00 %
B9068759N	90687-3	Black	By east wall, stairway	YES	3.00 % (P)	CHRYSOITILE : 3.00 % NON-FIBROUS : 9.60 % OTHER : 87.20 %

NAD = No Asbestos Detected. Trace < 0.25 %

(P) Analysis by Polarized Light Microscopy (PLM) NYS ELAP method 106.1 or EPA/600/R-93/116. (T) Analysis by Transmission Electron Microscopy (TEM) NYS ELAP method 106.4. Polarized Light Microscopy is not consistently reliable in detection of asbestos in floor coverings and similar non-fibrous organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. No reproduction of all or any portion of this report shall occur without written approval of Ambient Labs, Inc. All results disclosed in this report relate only to the items tested.

NYS ELAP ID # 101616. STATE OF CA ELAP ID # 2133