

FAX COVER SHEET**CHAMBERS HOUSE PARTNERS, LLC**

154 Chambers Street

New York, NY 10007

212 406-4350

Fax number 212 406-4350

e-mail: ephraimresnick@netscape.net

SEND TO	
Company name	From
NYC-DEP --Asbestos Control Program	Ephraim Resnick< P. E.
Attention	Date
R. Radhakrishnan, P. E.	2/20/02
Office location	Office location
59-17 Junction Blvd, 8 flr, Corona, NY 11373-5108	154 Chambers Street, New York, NY 10007
Fax number	Phone number
(718) 595-3744	(212) 406-4350

☐ Urgent
 ☐ Reply ASAP
 ☐ Please comment
 ☐ Please review
 ☒ For your information

Total pages, including cover:

6**COMMENTS**

We own a five story walk-up building on Chambers Street that was included in the Ground Zero fence. Here is our response to your letter of 2/12/02.

1. GENERAL: After 9/11, we hired an environmental cleaner to clean up the building both inside & outside (see enclosed bill)
2. CLEAN-UP: About a month after the clean-up, NYC-DEP inspectors came and inspected the building and agreed that it was environmentally clean. However, I did not give us any documentation. So far, we have not been reimbursed for any work, and have suffered financially, since one of the three tenants left and we are in serious financial condition
3. AIR-CONDITIONERS: We sent the window air-conditioners to a factory where they were steam-cleaned and will be in storage till next summer.
4. ON-GOING: Since we live in the building, we are very concerned with the quality of the environment. Weekly, we clean the common areas (stairway and lobby). Monthly, we check (and clean if necessary) the rain gutters, the roof, and the tiny back-yard. This yard has a drain that serves adjacent buildings and connects to Chambers St.

We would appreciate any technical assistance from DEP

CHAMBERS HOUSE PARTNERS, LLC


Ephraim Resnick, P. E.

Cleaning Naturally291 - 5th Ave. 2L
Brooklyn, NY 11215

INVOICE NO. 2866

INVOICE

01000 INVOICE 71724

TO:	RESNICK % Travelers INS.
ADDRESS:	CLAIM LPS-0607
	154 Chambers St
CITY, STATE, ZIP	New York, N.Y.

SHIP TO:
ADDRESS:
CITY, STATE, ZIP

CUSTOMER'S ORDER#	SOLD BY:	TERMS:	F.O.B.	DATE:
				Oct, 7/01

Trade Center Disaster Clean up					
Thoroughly Clean of the apt. ALL					
From above down were vacuumed, wiped					
and mopped. Closets were emptied. The					
clothe was sorted and put in plastic					
bags For the Dry cleaners and For the					
Laundry. All the Furniture including the					
Fridge was removed to clean the					
rubbish behind. All cabinets above and					
under in the kitchen were clean inside.					
also the Fridge was cleaned inside.					
Also an entire wall cover with book					
shelves. books were removed					
and wiped clean. All lamps from the					
ceiling were also washed over					

STARTING	DESCRIPTION	PRICE
	All doors, windows and their frames were thoroughly washed. All plants were wiped, all the ornaments, furniture covers were removed and put in plastic bags for the dry cleaners. Ceiling lights	
	MAN HRS WORKED 40 X 25 1000 <u>00</u>	

Cleaning Naturally291 - 5th Ave. 3L
Brooklyn, NY 11215

INVOICE NO.

2868

INVOICE

01025 7L724

TO: QUINCY Mutual POL Bo-0808
 ADDRESS: Chambers House Partners
 CITY, STATE, ZIP

SHIP TO:

ADDRESS:

CITY, STATE, ZIP

CUSTOMER'S ORDER:

SOLD BY:

TERMS:

P.O.B.

DATE:

QTY	DESCRIPTION	PRICE	AMOUNT
	Trade Center Disaster Clean up		
	The Stair way From The roof down		
	to The Street. Five Floors in total.		
	All The Surfaces were vacuumed, walls		
	were washed, Floor were mopped.		
	The exit doors were washed. Second		
	Floor The bed room was thoroughly		
	vacuumed, Floors mopped, carpet/v		
	living room was vacuumed only. Apt.		
	Fourth all Surfaces were vacuumed, and		
	Floor mopped. The Facade of the		
	building was totally Hosed down from		
	the roof to the ground. The gutters were		
	cleaned all the rubbish was pull out		
	and Hosed.		

CAM FUEL INC

88 7TH AVENUE SOUTH
NEW YORK, NY 10014

(212) 924-4306 • fax (212) 924-4551

NAME		DATE	
		10-12-01	
ADDRESS		PHONE	
154 CHAMBERS ST			
CITY	NYC		
TROUBLE REPORTED		NO. 002535	
clean up - tune up			
SERVICEMAN	ARRIVED	AM	PM
Don			
PARTS and MATERIALS		FINISHED	
VAC Boiler and chimney			
stack, resealed			
chimney base was			
packed with grey seal, 3 bags			
tuned burner, filter,			
nozzle, primed and			
started, adjusted			
TOTAL TIME	PER HOUR	COST OF PARTS	COST OF LABOR
	0	150.00	12.38
TAX		169.38	
CUSTOMER'S SIGNATURE		X	

Weisenfeld

41 River Terrace Suite 302
New York, NY 10011
TEL. 212.349.0007 FAX. 212.243.7852

CHAMBERS HOUSE PARTNERS
154 CHAMBERS STREET
NYC, NY 10007

11/05/01

INVOICE

-CLEAN & REMOVE DEBRIS FROM LOWER REAR OF BUILDING AND REAR YARD

TOTAL \$ 475.00

Address: 154 CHAMBERS ST.

Bulk Samples PLM Yes No

Number of Negative ($\leq 1\%$) Samples _____

Number of Positive ($> 1\%$) Samples _____

Air Samples Yes No

PCM

Number of Samples Collected (≤ 0.01 f/cc) _____

Number of Samples Collected (>0.01 f/cc) _____

TEM

Number of Samples Collected (≤ 70 s/mm²) _____

Number of Samples Collected (>70 s/mm²) _____

INDICATED THAT
CLEAN UP DONE