NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.

Stuyvesant High School
345 Chambers Street
New York, NY

3RD THROUGH 10TH FLOORS

Final Air Test Results (Asbestos and Lead)
Post General Cleaning Lead Wipe Sample Results
Unit Ventilator Lead Wipe Sample Results
HVAC Duct Lead Wipe Sample Results
Lead Personal (OSHA Air Monitoring Results)
Lead Area Air Monitoring Sample Results

Project #: M477-15217
LLW#: 29881

BOOK 1 OF 2

130A JERICHO TPKE., FLORAL PARK, NY 11001 • PHONE (516) 358-2955 • FAX (516) 358-1780

NYC-WTC_000106418

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.

FINAL AIR TEST RESULTS (LEAD AND ASBESTOS) 3RD THROUGH 10TH FLOORS

PROJECT #: M477-15217
LLW#: 29881

130A JERICHO TPKE., FLORAL PARK, NY 11001 • PHONE (516) 358-2955 • FAX (516) 358-1780

NYC-WTC_000106420

NYC-WTC_000106421

NYC 9/11 Public Portal Document
08/28/2002 13:09 212-290-2538 EMSL ANALYTICAL INC PAGE 02/02

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: AL. KAZANJIAN	CLIENT: NYC-SCA	SITE ADDRESS: STUYVESANT HS, NY NY	DATE SUBMITTED: 8.20-02
DATE SAMPLED: 8/20/02	CONTACT: HAMID SHAOT	WORK AREA: 10TH FLOOR	DATE LOGGED:
ROTOMETER NO: TEG-147	PROJECT NO: M477-15217-2988	PROJECT MANAGER: C. McCANN.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
10-T1		IWA ☑ OWA ☐ Room #1039 North side	9/9	03:50	06:10	140	9	1260				
10-T2		IWA ☑ OWA ☐ Room #1039 South side	9/9	03:52	06:12	140	9	1260				
10-T3		IWA ☑ OWA ☐ Corridor by room # 1033	9/9	03:54	06:14	140	9	1260				
10-T4		IWA ☑ OWA ☐ Room # 1024 North side	9/9	03:56	06:16	140	9	1260				
10-T5		IWA ☑ OWA ☐ East entrance, Corridor by room # 1017	9/9	03:58	06:18	140	9	1260				
10-T6		IWA ☑ OWA ☐ Room # 1009 N-W side	9/9	04:00	08:20	140	9	1260				
10-T7		IWA ☑ OWA ☐ Room # 1006 N-W side	9/9	04:02	06:22	140	9	1260				
10-T8		IWA ☑ OWA ☐ Room # 1007 East side	9/9	04:04	06:24	140	9	1260				
10-T9		IWA ☑ OWA ☐ East entrance Corridor by room # 1007	9/9	04:06	06:26	140	9	1260				
10-T10		IWA ☑ OWA ☐ Room # 1004 N-E side	9/9	04:08	06:28	140	9	1260				
FB-1		IWA ☐ OWA ☐ F/BLANK-1						—				
FB-2		IWA ☐ OWA ☐ F/BLANK-2						—				
SB-1		IWA ☐ OWA ☐ S/BLANK.						—				

EMSL ANALYTICAL INC RECEIVED 02 AUG 29 AM 7:25

RELINQUISHED TO TEG DROP BOX (SIGNATURE)	DATE: 8/20/02	TIME: 07:00	RECEIVED FROM TEG DROP BOX (SIGNATURE)	DATE	TIME
RELINQUISHED BY: (SIGNATURE)	DATE: 8.20.02	TIME: 07.30	RECEIVED BY: (SIGNATURE) TERESA MICHIELLI	DATE	TIME
ANALYST: (SIGNATURE)	DATE	TIME	COMMENTS: Analyze 10-T1 thru 10-T10		

CIRCLE: PCM TEM — BGRD PRE DURING POST — OSHA OTHER

LOT #: FILTER MANUFACTURER:

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001

Fax: (516) 358-1780 Phone: 516-358-2955

Project: M477-15217-29881 / NYC-SCA / STUYVESANT H.S. NY, NY / 10TH FLOOR / POST

Customer ID: TAYL50
Customer PO:
Received: 08/20/02 7:25 AM

EMSL Order: 030211480
EMSL Project ID:

Analysis Date: 8/20/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures ≥ 0.5μ < 5	# Structures ≥ 5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
10-T1 030211480-0001	1260.00	0.0625	0	None Detected			0.0049	<16.00	<0.0049	
10-T2 030211480-0002	1260.00	0.0625	0	None Detected			0.0049	<16.00	<0.0049	
10-T3 030211480-0003	1260.00	0.0625	1	None Detected			0.0049	<16.00	<0.0049	
10-T4 030211480-0004	1260.00	0.0625	0	None Detected			0.0049	<16.00	<0.0049	
10-T5 030211480-0005	1260.00	0.0625	0	None Detected			0.0049	<16.00	<0.0049	
10-T6 030211480-0006	1260.00	0.0625	1	None Detected			0.0049	<16.00	<0.0049	
10-T7 030211480-0007	1260.00	0.0625	0	None Detected			0.0049	<16.00	<0.0049	
10-T8 030211480-0008	1260.00	0.0625	0	None Detected			0.0049	<16.00	<0.0049	
10-T9 030211480-0009	1260.00	0.0625	0	None Detected			0.0049	<16.00	<0.0049	
10-T10 030211480-0010	1260.00	0.0625	0	None Detected			0.0049	<16.00	<0.0049	

Analyst(s)
Ghayath Elias (10)

José Arriaga
Laboratory Manager
or other approved signatory

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request.
Accredited for NVLAP PLM/TEM #101048-8, NY State ELAP #11505

TEMAHERA-1

NYC-WTC_000106422

NYC-WTC_000106423

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: Al. Kerakov	CLIENT: NYCSCA	SITE ADDRESS: Stuyvesant H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: 8/20/02	CONTACT: Hamid Sawot	WORK AREA: 10th Floor	DATE LOGGED:
ROTOMETER NO: TEG-L-18	PROJECT NO.: M477-15217-Z9881	PROJECT MANAGER: Curtis McClown.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
10-L1		IWA ☐ OWA ☐ Room # 1039 South side	4/4	03:53	08:14	261	4	1044				
10-L2		IWA ☐ OWA ☐ Corridor by room # 1039	4/4	03:55	08:16	261	4	1044				
10-L3		IWA ☐ OWA ☐ Room # 1010 East side	4/4	04:01	08:18	257	4	1028				
10-L4		IWA ☐ OWA ☐ Corridor by room # 1001	4/4	04:07	08:20	253	4	1012				
10-L5		IWA ☐ OWA ☐ Room # 1001 Northside	4/4	04:09	08:21	252	4	1008				
FB-1		IWA ☐ OWA ☐ F/BLANK-1										
FB-2		IWA ☐ OWA ☐ F/BLANK-2										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

21323

RELINQUISHED BY: (SIGNATURE)	DATE: 8/20/02	TIME: 1018	RECEIVED FROM TEG DROP BOX (SIGNATURE)	DATE: 8/20/02	TIME: 10:2
RELINQUISHED BY: (SIGNATURE)	DATE	TIME	RECEIVED BY: (SIGNATURE)	DATE	TIME
ANALYST: (SIGNATURE)	DATE	TIME	COMMENTS: 6HR TAT	NIOSH 7082	

CYCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER LOAD

LOT # FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-20-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 10th floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	08-20-02
DATE RECEIVED:	08-20-02
DATE ANALYZED:	08-20-02
SAMPLE MEDIA:	Air Samples
ANALYSIS REQUIRED:	Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
10-L1	21323	Room 1039 South Side	<1.4	1.4
10-L2	21323	Corridor by Room 1039	<1.4	1.4
10-L3	21323	Room 1010 East Side	<1.5	1.5
10-L4	21323	Corridor by Room 1001	<1.5	1.5
10-L5	21323	Room 1001 North Side	<1.5	1.5
FB1	21323	Field Blank	<1.5 µg	1.5 µg
FB2	21323	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106426

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: Kirk McKenzie	CLIENT: NYC SCA	SITE ADDRESS: Stuyvesant H.S.	DATE SUBMITTED: 8/20/02
DATE SAMPLED: 8/20/02	CONTACT: Hamid Saadi	WORK AREA: 9th Floor	DATE LOGGED:
ROTOMETER NO: 149 8722	PROJECT NO: M477-15217-29886	PROJECT MANAGER: Chris McGown.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
9-T1		IWA ☒ OWA ☐ Room 939, at South side	9/9	0410	0675	145	9	1305				
9-T2		IWA ☒ OWA ☐ Room 940, at NW side	9/9	0411	0636	145	9	1305				
9-T3		IWA ☒ OWA ☐ Corridor by West entrance of Room 931	9/9	0413	0639	146	9	1314				
9-T4		IWA ☒ OWA ☐ Room 936, at NE side	9/9.5	0414	0649	146	9.25	1350.5	T422-5		1350.5	
9-T5		IWA ☒ OWA ☐ Room 927, at North side	9/9	0416	0642	146	9	1314				
9-T6		IWA ☒ OWA ☐ Corridor at entrance to Staircase "W"	9/9	0417	0643	146	9	1314				
9-T7		IWA ☒ OWA ☐ Corridor, South of Escalator	9/9	0418	0644	146	9	1314				
9-T8		IWA ☒ OWA ☐ Corridor, ~~West~~ of Staircase "E"	9/9	0419	0645	146	9	1314				
9-T9		IWA ☒ OWA ☐ Room 903, at Center	9/9	0420	0647	147	9	1323				
9-T10		IWA ☒ OWA ☐ Room 913, at Center	9/8.5	0422	0649	147	8.75	1286.25				
FB-1		IWA ☐ OWA ☐ F/Blank-1										
FB-2		IWA ☐ OWA ☐ F/Blank-2										
SB-1		IWA ☐ OWA ☐ S/Blank										

	DATE	TIME		DATE	TIME
RELINQUISHED TO TEG DROP BOX (SIGNATURE)			RECEIVED FROM TEG DROP BOX (SIGNATURE)		
RELINQUISHED BY: (SIGNATURE)	8/20/02	0750	RECEIVED BY: (SIGNATURE) ATC GHEYAT	8/20/02	8am
ANALYST: (SIGNATURE) RKly	8/20/02	11:45	COMMENTS: Analyze 9-T1 thru 9-T10		

CIRCLE: PCM TEM — BGRD PRE DURING POST — OSHA OTHER

LOT # FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280 Fax: (212) 353-8306

Attn:
Taylor Evironmental Group

Received: 8/20/02 8:00:00 AM
ATC Group #: 8722
Analysis Date: 8/20/02

Fax: (516) 358-1780 Phone:

Project: NYC SCA Project #: M477-15217-29881
Stuyvesant H. S., 9th Floor

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5µ-5	# Structures 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
9-T1 8722 -1	1305.00	0.0674	0	None Detected	0	0	0.0044	<14.83	<0.0044	
9-T2 8722 -2	1305.00	0.0674	0	None Detected	0	0	0.0044	<14.83	<0.0044	
9-T3 8722 -3	1314.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
9-T4 8722 -4	1350.50	0.0674	0	None Detected	0	0	0.0042	<14.83	<0.0042	
9-T5 8722 -5	1314.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
9-T6 8722 -6	1314.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
9-T7 8722 -7	1314.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	

ROMAN PEYSAKHOV
Analyzed by

MICHAEL A. GORYCKI, Ph.D
Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101167-0, NY State ELAP #10679

NYC-WTC_000106427

NYC 9/11 Public Portal Document

Attn:

Taylor Evironmental Group

Received: 8/20/02 8:00:00 AM
ATC Group #: 8722
Analysis Date: 8/20/02

Fax: (516) 358-1780 Phone:

Project: NYC SCA Project #: M477-15217-29881
Stuyvesant H. S., 9th Floor

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5µ-5	# Structures 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
9-T8 8722 -8	1314.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
9-T9 8722 -9	1323.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
9-T10 8722 -10	1286.25	0.0674	0	None Detected	0	0	0.0044	<14.83	<0.0044	

ROMAN PEYSAKHOV
Analyzed by

MICHAEL A. GORYCKI, Ph.D.
Approved by

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

NYC-WTC_000106428

NYC-WTC_000106429

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: Kirk McKenzie	CLIENT: NYC SCA	SITE ADDRESS: STUYVESANT H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: 8/20/02	CONTACT: HAMID SAADON	WORK AREA: 9TH FLOOR	DATE LOGGED IN: 8/21/02
ROTAMETER NO: L-21	PROJECT NO.: M477-15217-29861	PROJECT MANAGER: C. McCLOWN	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
9-L1		IWA ☐ OWA ☐ CORRIDOR BETWEEN ROOMS 935 and 940	4/4	0412	0831	259	4	1036				
9-L2		IWA ☐ OWA ☐ CORRIDOR, SOUTH OF ESCALATOR ENTRANCE	4/4	0417	0833	256	4	1024				
9-L3		IWA ☐ OWA ☐ ROOM 911, AT EAST SIDE	4/4	0421	0834	253	4	1012				
9-L4		IWA ☐ OWA ☐ CORRIDOR NW OF STAIRCASE "E"	4/4	0424	0835	251	4	1004				
9-L5		IWA ☐ OWA ☐ ROOM 902, AT NE SIDE	4/4	0425	0837	252	4	1008				
FB-1		IWA ☐ OWA ☐ F/BLANK-1										
FB-2		IWA ☐ OWA ☐ F/BLANK-2										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

02021485

ENSR INTERNATIONAL RECEIVED 02 AUG 20 AM 10:36

RELINQUISHED TO/DROP BOX (SIGNATURE): Kirk McKenzie	DATE: 8-20-02	TIME: 1037	RECEIVED FROM/DROP BOX (SIGNATURE): ATC-ML	DATE: 8/20/02	TIME: 4PM
RELINQUISHED BY: (SIGNATURE)	DATE	TIME	RECEIVED BY: (SIGNATURE)	DATE: 8/21/02	TIME: 1036
ANALYST: (SIGNATURE)	DATE	TIME	COMMENTS: CHRYSO NIOSH 7082		

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER LOAD

LOT # FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-20-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 9th Floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	08-20-02
DATE RECEIVED:	08-20-02
DATE ANALYZED:	08-20-02
SAMPLE MEDIA:	Air Samples
ANALYSIS REQUIRED:	Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
9-L1	21332	Corridor Between Rooms 935 and 940	<1.3	1.3
9-L2	21332	Corridor South of Escalator Entrance	<1.3	1.3
9-L3	21332	Room 911 at East Side	<1.5	1.5
9-L4	21332	Corridor NW of Staircase E	<1.5	1.5
9-L5	21332	Room 902 at NE Side	<1.5	1.5
FB1	21332	Field Blank	<1.5 µg	1.5 µg
FB2	21332	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg
NOTE 4:
Samples prepared by ESML
NOTE 5:
LCS 9.93 PPM; LCSD 10.09 PPM; RLVS 0.32 PPM; MB <0.045 PPM

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: ML

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106432

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

TECHNICIAN: H. Plonka	CLIENT: NYC:SCA	SITE ADDRESS: Stuyvesant H.S.	DATE SUBMITTED: 8.20.02
DATE SAMPLED: 8.20.02	CONTACT: Hallid Stoot	WORK AREA: 8th Floor	DATE LOGGED:
ROTOMETER NO.: 149 8721	PROJECT NO.: M477-15217-29851	PROJECT MANAGER: C. McClown	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
8-T1		IWA ☑ OWA ☐ hallway - west side by door to rm 838	9/8	344	615	151	8.5	1283.5				
8-T2		IWA ☑ OWA ☐ hallway - outside rm 826	9/9	349	618	149	9	1341				
8-T3		IWA ☑ OWA ☐ hallway - 15ft west from escalatore	9/9	351	619	148	9	1332				
8-T4		IWA ☑ OWA ☐ hallway - 15ft west from stair E	9/9	354	620	146	9	1314				
8-T5		IWA ☑ OWA ☐ hallway - in front of rm 815	9/9	353	624	151	9	1359				
8-T6		IWA ☑ OWA ☐ hallway - outside rm 802	9/9	357	626	149	9	1341				
8-T7		IWA ☑ OWA ☐ in cl rm # 803 - by SE window	9/8	358	628	150	8.5	1275				
8-T8		IWA ☑ OWA ☐ in cl. rm # 811 by western window	9/9	359	622	143	9	1287				
8-T9		IWA ☑ OWA ☐ in cl rm # 836 - by NE window	9/9	347	617	150	9	1350				
8-T10		IWA ☑ OWA ☐ in cl rm # 834 - center of room	9/9	345	616	151	9	1359				
FB-1		IWA ☐ OWA ☐ F/BLANK - 1										
FB-2		IWA ☐ OWA ☐ F/BLANK - 2										
SB-1		IWA ☐ OWA ☐ S/BLANK										

	DATE	TIME		DATE	TIME
RELINQUISHED TO ~~LAB~~ DROP BOX (SIGNATURE): N. Plonka	8.20.02		RECEIVED FROM TEG DROP BOX (SIGNATURE):		
RELINQUISHED BY: (SIGNATURE)	8/20/02	0750	RECEIVED BY: (SIGNATURE): ATC	8/20/02	5 p.m.
ANALYST: (SIGNATURE) RRly	8/20/02	11:45	COMMENTS: ANALYZE T1 → T10 6 HR TAT		

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER

LOT #

FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280 Fax: (212) 353-8306

Attn:
Taylor Evironmental Group

Received: 8/20/02 8:00:00 AM
ATC Group #: 8721
Analysis Date: 8/20/02

Fax: (516) 358-1780 Phone:

Project: NYC SCA Project #: M477-15217-29881
Stuyvesant H. S 8th Floor

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5μ-5	# Structures 5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
S-T1 8721 -1	1283.50	0.0674	0	None Detected	0	0	0.0044	<14.83	<0.0044	
S-T2 8721 -2	1341.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
S-T3 8721 -3	1332.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
S-T4 8721 -4	1314.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
S-T5 8721 -5	1359.00	0.0674	0	None Detected	0	0	0.0042	<14.83	<0.0042	
S-T6 8721 -6	1341.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
S-T7 8721 -7	1275.00	0.0674	0	None Detected	0	0	0.0045	<14.83	<0.0045	

ROMAN PEYSAKHOV
Analyzed by

MICHAEL A. GORYCKI, Ph.D
Approved by.

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

NYC-WTC_000106433

NYC 9/11 Public Portal Document

Attn:
Taylor Evironmental Group

Received: 8/20/02 8:00:00 AM
ATC Group #: 8721
Analysis Date: 8/20/02

Fax: (516) 358-1780 Phone:
Project: NYC SCA Project #: M477-15217-29881
Stuyvesant H. S. 8th Floor

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5μ-5	# Structures 5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
S-T8 8721 -8	1287.00	0.0674	0	None Detected	0	0	0.0044	<14.83	<0.0044	
S-T9 8721 -9	1330.00	0.0674	0	None Detected	0	0	0.0043	<14.83	<0.0043	
S-T10 8721 -10	1359.00	0.0674	0	None Detected	0	0	0.0042	<14.83	<0.0042	

ROMAN PEYSAKHOV
Analyzed by:

MICHAEL A. GORYCKI, Ph.D
Approved by

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

NYC-WTC_000106434

NYC-WTC_000106435

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: N. Plonka	CLIENT: NYC-SCA.	SITE ADDRESS: STUYVESANT H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: 8/20/02	CONTACT: HAMID SAMOI	WORK AREA: 8TH FLOOR	DATE LOGGED:
ROTOMETER NO: L-21	PROJECT NO: M477-15217-29881	PROJECT MANAGER: C. McGOWN.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
8-L1		IWA ☐ OWA ☐ Western hallway - outside clrm 840	4/4	402	0823	261	4	1044				
8-L2		IWA ☐ OWA ☐ in hallway - 10ft West from escalators.	4/4	401	0825	262	4	1048				
8-L3		IWA ☐ OWA ☐ in clrm # 827 - NE part of room	4/4	403	0829	266	4	1064				
8-L4		IWA ☐ OWA ☐ in rm # 826 - center of room	4/4	405	0830	265	4	1060				
8-L5		IWA ☐ OWA ☐ in eastern hallway - outside rm # 804	4/4	406	0827	261	4	1044				
FB-1		IWA ☐ OWA ☐ F/BLANK - 1										
FB-2		IWA ☐ OWA ☐ F/BLANK - 2										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

21322

RELINQUISHED TO TEG DROP BOX (SIGNATURE): [signature]	DATE: 8-20-02	TIME: 1018	RECEIVED FROM TEG DROP BOX (SIGNATURE): [signature] NYC	DATE: 8/20/02	TIME: 10 20 hr
RELINQUISHED BY: (SIGNATURE)	DATE	TIME	RECEIVED BY: (SIGNATURE)	DATE	TIME
ANALYST: (SIGNATURE)	DATE	TIME	COMMENTS: GASTAR	NIOSH	

CIRCLE: PCM TEM — BGRD PRE DURING POST — OSHA — OTHER LOAD

LOT # FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-20-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 8th floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	08-20-02
DATE RECEIVED:	08-20-02
DATE ANALYZED:	08-20-02
SAMPLE MEDIA:	Air Samples
ANALYSIS REQUIRED:	Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
8-L1	21322	Western Hallway Outside Classroom 840	<1.4	1.4
8-L2	21322	In Hallway 15 ft West from Escalators	<1.4	1.4
8-L3	21322	In Classroom 827 NE Part of Room	<1.4	1.4
8-L4	21322	In Rm 826 Center of Room	<1.4	1.4
8-L5	21322	In Eastern Hallway Outside Rm 804	<1.4	1.4
FB1	21322	Field Blank	<1.5 µg	1.5 µg
FB2	21322	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC-WTC_000106437
PAGE 02/02
EMSL ANALYTICAL INC
212-290-2538
08/20/2002 11:51
NYC 9/11 Public Portal Document

[redacted] ENVIRONMENTAL GROUP

DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD (1)

PAGE 1 OF 1

TECHNICIAN: TERESA MICHALCZUK	CLIENT: NYCSCA	SITE ADDRESS: STUYVESANT H.S.	DATE SUBMITTED: 08.20.02
DATE SAMPLED: 08.20.02	CONTACT: HAMID SAWOT	WORK AREA: 7TH FLOOR	DATE LOGGED:
ROTOMETER ID: TEG 115	PROJECT NO.: M477-15217-29881	PROJECT MANAGER: C. McLOUGHLIN	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
7-T1		IWA ☒ INSIDE ROOM 739 OWA ☐ NORTH-WEST SIDE	9/9	04.00	06.30	150	9	1350				
7-T2		IWA ☒ CORRIDOR BY ROOM 737 OWA ☐	9/8	04.01	06.31	150	8.5	1275				
7-T3		IWA ☒ INSIDE ROOM 733 OWA ☐ NORTH-EAST SIDE	9/8.5	04.02	06.32	150	8.75	1313				
7-T4		IWA ☒ CORRIDOR BY ROOM 731 OWA ☐	9/9	04.03	06.33	150	9	1350				
7-T5		IWA ☒ INSIDE ROOM 731 OWA ☐ NORTH-EAST SIDE	9/8.5	04.04	06.34	150	8.75	1313				
7-T6		IWA ☒ CORRIDOR BY ESCALATOR OWA ☐ MIDDLE SIDE	9/9	04.05	06.35	150	9	1350				
7-T7		IWA ☒ CORRIDOR BY ROOM 717 OWA ☐	9/9	04.06	06.36	150	9	1350				
7-T8		IWA ☒ CORRIDOR EAST SIDE OWA ☐ BY ESCALATOR	9/8	04.07	06.37	150	8.5	1275				
7-T9		IWA ☒ INSIDE ROOM 709 OWA ☐ NORTH-WEST	9/9	04.08	06.38	150	9	1350				
7-T10		IWA ☒ INSIDE ROOM 703 OWA ☐ NORTH SIDE	9/8	04.09	06.39	150	8.5	1275				
FB-1		IWA ☐ OWA ☐ F/BLANK-1										
FB-2		IWA ☐ OWA ☐ F/BLANK-2										
SB-1		IWA ☐ OWA ☐ S/BLANK										

RELINQUISHED TO TEG DROP BOX (SIGNATURE): Teresa Michalczuk — DATE: 08.20.02 — TIME: 07.30

RECEIVED FROM TEG DROP BOX (SIGNATURE): TERESA MICHALCZUK — DATE: — TIME:

RELINQUISHED BY: (SIGNATURE): Teresa Michalczuk — DATE: 08.20.02 — TIME: 07.00

RECEIVED BY: (SIGNATURE): TERESA MICHALCZUK — DATE: — TIME:

ANALYST: (SIGNATURE) — DATE: — TIME:

COMMENTS: Analyze F-T1 thru F-T10

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER

LOT #

FILTER MANUFACTURER

EMSL ANALYTICAL INC RECEIVED 02 AUG 20 AM 7:24

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217-29881 / NYC SCA / STUYVESANT H.S. / 7TH FLOOR / POST

Customer ID: TAYL50
Customer PO:
Received: 08/20/02 7:24 AM
EMSL Order: 030211479
EMSL Project ID:
Analysis Date: 8/20/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures ≥0.5µ < 5	# Structures ≥ 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
7-T1 030211479-0001	1350.00	0.0625	1	None Detected			0.0046	<16.00	<0.0046	
-T2 030211479-0002	1275.00	0.0625	0	None Detected			0.0048	<16.00	<0.0048	
-T3 30211479-0003	1313.00	0.0625	0	None Detected			0.0047	<16.00	<0.0047	
7-T4 30211479-0004	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	
7-T5 030211479-0005	1313.00	0.0625	0	None Detected			0.0047	<16.00	<0.0047	
-T6 030211479-0006	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	
-T7 30211479-0007	1350.00	0.0625	0	None Detected			0.0046	<16.00	<0.0046	
7-T8 30211479-0008	1275.00	0.0625	0	None Detected			0.0048	<16.00	<0.0048	
-T9 030211479-0009	1370.00	0.0625	0	None Detected			0.0045	<16.00	<0.0045	
-T10 30211479-0010	1275.00	0.0625	0	None Detected			0.0048	<16.00	<0.0048	

Analyst(s)
Ghayath Elias (10)

José Arriaga
Laboratory Manager
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request.
Accredited for NVLAP PLM/TEM #101048-0, NY State ELAP #11508

TEMAHERA-1

NYC-WTC_000106438

NYC-WTC_000106439

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 5

TECHNICIAN: TERESA MICHALCZUK	CLIENT: NYC-SCA.	SITE ADDRESS: STUYVESANT H.S.	DATE SUBMITTED: 08.20.02
DATE SAMPLED: 08.20.02	CONTACT: HAMED SADOON	WORK AREA: 7TH FLOOR	DATE LOGGED: BATCH 21331
ROTOMETER NO: TEG L-16	PROJECT NO: M477-15217-29881	PROJECT MANAGER: C. McGOON	DATE APPROVED / SIGNATURE

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
7-L1		IWA ☐ CORRIDOR WEST SIDE OWA ☐ BY ROOM 739	4/4	04.00	0840	280	4	1120				
7-L2		IWA ☐ INSIDE ROOM 731 OWA ☐ SOUTH SIDE	4/4	04.04	0842	278	4	1112				
7-L3		IWA ☐ CORRIDOR MIDDLE SIDE OWA ☐ BY ESCALATOR	4/4	04.05	0844	279	4	1116				
7-L4		IWA ☐ CORRIDOR EAST SIDE OWA ☐ BY ROOM 707	4/4	04.08	0845	277	4	1108				
7-L5		IWA ☐ INSIDE ROOM 702 A OWA ☐	4/4	04.09	0846	277	4	1108				
FB-1		IWA ☐ OWA ☐ F/BLANK-1										
FB-2		IWA ☐ OWA ☐ F/BLANK-2										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

02 AUG 20 AM 10:35

ENVIR. MANHATTAN RECEIVED

U3C04486

RELINQUISHED TO TEG DROP BOX (SIGNATURE): X [signature]	DATE: 08.20.02	TIME: 1037	RECEIVED FROM TEG DROP BOX (SIGNATURE): ATC LAB ML	DATE: 8/20/02	TIME: 4PM
RELINQUISHED BY: (SIGNATURE) [signature]	DATE: 08.20.02	TIME:	RECEIVED BY (SIGNATURE): TERESA MICHALCZUK	DATE: [signature]	TIME: 5/24/4
ANALYST: (SIGNATURE)	DATE	TIME	COMMENTS: 6 HR-TAT	NIOSH 7082	LOT # / FILTER MANUFACTURER

CIRCLE: PCM TEM — BORO PRE DURING POST — OSHA OTHER LEAD

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-20-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
7th Floor

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE 08-20-02
DATE RECEIVED: 08-20-02
DATE ANALYZED: 08-20-02

SAMPLE MEDIA: Air Samples
ANALYSIS REQUIRED: Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
7-L1	21331	Corridor West Side by Rm 739	<1.3	1.3
7-L2	21331	Inside Rm 731 South Side	<1.3	1.3
7-L3	21331	Corridor Middle Side by Escalator	<1.3	1.3
7-L4	21331	Corridor East Side by Rm 707	<1.4	1.4
7-L5	21331	Inside Rm 702A	<1.4	1.4
FB1	21331	Field Blank	<1.5 µg	1.5 µg
FB2	21331	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg

NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.

NOTE 3:
Blank units are in µg

NOTE 4:
Samples prepared by ESML

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: ML

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR: ML

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_00010642

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE ____ OF ____

TECHNICIAN: CARLOS JOFAT	CLIENT: NYC-SCA.	SITE ADDRESS: STUYVESANT HS.	DATE SUBMITTED: 8/20/02
DATE SAMPLED: AUG. 20 2002	CONTACT: HAMID SAVONI	WORK AREA: 6TH FLOOR	DATE LOGGED:
ROTOMETER NO: T33 149 1	PROJECT NO: M477-15217-298801	PROJECT MANAGER: C. McOCOWN.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
6-T1		IWA ☑ OWA ☐ 6TH FL. Corridor O/S Rm 640	9/8	1057	1357	180	8.5	1530				
6-T2		IWA ☑ OWA ☐ Rm 629	9/8	1058	1358	180	8.5	1530				
6-T3		IWA ☑ OWA ☐ 6TH FL CORRIDOR O/S Rm 615B	9/9	1059	1359	180	9	1620				
6-T4		IWA ☑ OWA ☐ 6TH FL CORRIDOR WEST SIDE OF ESCALATOR	9/9	1100	1400	180	9	1620				
6-T5		IWA ☑ OWA ☐ 6TH FL. CORRIDOR O/S LIBRARY ENTRANCE	9/9	1101	1401	180	9	1620				
6-T6		IWA ☑ OWA ☐ 6TH FL CORRIDOR NEAR STAIR E	9/9.5	1102	1402	180	9.25	1665				
6-T7		IWA ☑ OWA ☐ 6TH FLOOR GYMNASIUM	9/7	1104	1403	179	8	1432				
6-T8		IWA ☑ OWA ☐ 6TH FLOOR DANCE STUDIO	9/9	1105	1404	179	9	1611				
6-T9		IWA ☑ OWA ☐ Rm 636	9/9	1106	1405	179	9	1611				
6-T10		IWA ☑ OWA ☐ Rm 640	9/8.5	1107	1406	179	8.75	1566.25				
FB-1		IWA ☐ OWA ☐ FIELD BLANK-1										
FB-2		IWA ☐ OWA ☐ FIELD BLANK-2										
SB-1		IWA ☐ OWA ☐ SHIPPING BLANK										

RELINQUISHED TO TEG DROP BOX (SIGNATURE): [signature]	DATE: 8/20/02	TIME: 1620	RECEIVED FROM TEG DROP BOX (SIGNATURE): [signature]	DATE: 8/20/02	TIME: 16:20
RELINQUISHED BY: (SIGNATURE)	DATE	TIME	RECEIVED BY: (SIGNATURE)	DATE	TIME
ANALYST: (SIGNATURE) [signature]	DATE: 8/20/02	TIME: 21:30	COMMENTS: 6 HR T/A ANALYZE T-1 THROUGH T-10		

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER

LOT # FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280 Fax: (212) 353-8306

Attn:

Taylor Evironmental Group

Received: 8/20/02 4:20:00 PM

ATC Group #: 8724

Analysis Date: 8/20/02

Fax: (516) 358-1780 Phone:

Project: NYC SCA Project #: M477-15217-29881

Stuyvesant H. S., 6th Floor

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5µ-5	# Structures 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
6-T1 8724 -1	1530.00	0.0562	0	None Detected	0	0	0.0045	<17.79	<0.0045	
6-T2 8724 -2	1530.00	0.0562	0	None Detected	0	0	0.0045	<17.79	<0.0045	
6-T3 8724 -3	1620.00	0.0562	0	None Detected	0	0	0.0042	<17.79	<0.0042	
6-T4 8724 -4	1620.00	0.0562	0	None Detected	0	0	0.0042	<17.79	<0.0042	
6-T5 8724 -5	1620.00	0.0562	0	None Detected	0	0	0.0042	<17.79	<0.0042	
6-T6 8724 -6	1665.00	0.0562	0	None Detected	0	0	0.0041	<17.79	<0.0041	
6-T7 8724 -7	1432.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048	

ROMAN PEYSAKHOV

Analyzed by:

MICHAEL A. GORYCKI, Ph.D

Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101167-0. NY State ELAP #10879

NYC-WTC_000106443

NYC 9/11 Public Portal Document

Attn:
Taylor Environmental Group

Received: 8/20/02 4.20:00 PM
ATC Group #: 8724
Analysis Date: 8/20/02

Fax: (516) 358-1780 Phone:
Project: NYC SCA Project #: M477-15217-29881
Stuyvesant H. S., 6th Floor

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5μ-5	# Structures 5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
6-T8 8724 -8	1611.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	
6-T9 8724 -9	1611.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	
6-T10 8724 -10	1566.25	0.0562	0	None Detected	0	0	0.0044	<17.79	<0.0044	

ROMAN PEYSAKHOV
Analyzed by:

MICHAEL A. GORYCKI, Ph.D.
Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

NYC-WTC_000106444

NYC-WTC_000106445

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: CARLOS JOFAT	CLIENT: NYC-SCA	SITE ADDRESS: STUYVESANT H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: 8-20-02	CONTACT: HAMID SADOV	WORK AREA: 6TH FLOOR	DATE LOGGED:
ROTOMETER NO.: TOG 2-16.	PROJECT NO.: M447-15217-29866	PROJECT MANAGER: C. McGOON.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
6-L1		IWA ☐ OWA ☐ 6TH FL CORRIDOR APX PM 635	4/4	10¹⁰	1508	298	4	1192				<1.3
6-L2		IWA ☐ OWA ☐ INSIDE PM 636 @ CHALK BOARD	4/4	10¹²	1509	297	4	1188				<1.3
6-L3		IWA ☐ OWA ☐ 6TH FL CORRIDOR TOP OF ESCALATOR + W. STAIR	4/4	10¹⁴	1510	296	4	1184				<1.3
6-L4		IWA ☐ OWA ☐ 6TH FL CORRIDOR @ EAST STAIR	4/4	10¹⁶	1511	295	4	1180				<1.3
6-L5		IWA ☐ OWA ☐ 6TH FL - GYMNASIUM (LARGE)	4/4	10¹⁸	1512	294	4	1176				<1.3
FB-1		IWA ☐ OWA ☐ F/BLANK - 1										<1.5
FB-2		IWA ☐ OWA ☐ F/BLANK - 2										<1.5
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

RELINQUISHED TO TEG DROP BOX: (SIGNATURE)	DATE: 8/20/02	TIME: 1705	RECEIVED FROM TEG DROP BOX: (SIGNATURE)	DATE: 8/20/02	TIME: 5:00 PM
RELINQUISHED BY: (SIGNATURE)	DATE	TIME	RECEIVED BY: (SIGNATURE) 08/20	DATE	TIME
ANALYST: (SIGNATURE)	DATE	TIME	COMMENTS: 6+R+A NIOSH 7082	LOT # / FILTER MANUFACTURER	

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER LOAD

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-21-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 6th Floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	08-20-02
DATE RECEIVED:	08-20-02
DATE ANALYZED:	08-20-02
SAMPLE MEDIA:	Air Samples
ANALYSIS REQUIRED:	Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
6-L1	21333	6th Floor Corridor Adj. Rm 635	<1.4	1.4
6-L2	21333	Inside Rm 636 @ Chaulk Board	<1.3	1.3
6-L3	21333	6th Floor Corridor Top of Escalator & W.Stair	<1.3	1.3
6-L4	21333	6th Floor Corridor @ East Stair	<1.3	1.3
6-L5	21333	6th Floor Gymnasium (Large)	<1.3	1.3
FB1	21333	Field Blank	<1.5 µg	1.5 µg
FB2	21333	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: KCU

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_00010648

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

TECHNICIAN: CARLOS JOFFAT	CLIENT: NYC-SCA.	SITE ADDRESS: STUYVESANT H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: AUG 20, 2002	CONTACT: HAMID SADAT	WORK AREA: 5TH FLOOR	DATE LOGGED:
ROTOMETER NO.: TBC 149	PROJECT NO.: M477-15217-29886	PROJECT MANAGER: C. McGLOON.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
S-T1		IWA ☒ OWA ☐ 5TH FLOOR DINING HALL / CENTER	9/9	1110	1407	177	9	1593				
S-T2		IWA ☒ OWA ☐ 5TH FLOOR DN. HALL SEATING AREA	9/8	1111	1408	177	8.5	1504.5				
S-T3		IWA ☒ OWA ☐ 5TH FLOOR KITCHEN	9/9	1112	1409	177	9	1593				
S-T4		IWA ☒ OWA ☐ RM K531 FACULTY DINING	9/9	1113	1411	178	9	1602				
S-T5		IWA ☒ OWA ☐ 5TH FL. CORRIDOR o/s RM C521	9/7	1114	1412	178	8	1424				
S-T6		IWA ☒ OWA ☐ 5TH FL. CORRIDOR NORTH SIDE E	9/8.5	1115	1413	178	8.75	1557.5				
S-T7		IWA ☒ OWA ☐ 5TH FLOOR RM 501	9/9	1116	1414	178	9	1602				
S-T8		IWA ☒ OWA ☐ 5TH FLOOR CORRIDOR NORTH SIDE G	9/9	1118	1415	177	9	1593				
S-T9		IWA ☒ OWA ☐ RM G583	9/9	1119	1416	177	9	1593				
S-T10		IWA ☒ OWA ☐ 5TH FL. CORRIDOR o/s RM G584	9/9	1120	1417	177	9	1593				
FB-1		IWA ☐ OWA ☐ F/BLANK-1										
FB-2		IWA ☐ OWA ☐ F/BLANK-2										
SB-1		IWA ☐ OWA ☐ S/BLANK										

RELINQUISHED TO TEG DROP BOX (SIGNATURE): Mary Mehra — DATE: 8/20/02 — TIME: 1620

RECEIVED FROM TEG DROP BOX (SIGNATURE): R Rly — DATE: 8/20/02 — TIME: 16:20

RELINQUISHED BY: (SIGNATURE): — DATE: — TIME:

RECEIVED BY: (SIGNATURE): GHZ — DATE: — TIME:

ANALYST (SIGNATURE): R Rly — DATE: 8/20/02 — TIME: 21:30

COMMENTS: 6 HR TAT — ANALYZE T-1 THROUGH T-10

CIRCLE: PCM TEM — BGRD PRE DURING POST — OSHA OTHER

LOT # FILTER MANUFACTURER: # 8723

WHITE: Office Copy — YELLOW: Lab Copy — PINK: Samples — ORANGE: Site Copy

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC Associates
104 East 25 Street, New York, NY 10010
Phone: (212) 353-8280 Fax: (212) 353-8306

Received: 8/20/02 4:20:00 PM

Attn: Taylor Evironmental Group

ATC Group #: 8723
Analysis Date: 8/20/02

Fax: (516) 358-1780 Phone:

Project: NYC SCA Project #: M477-15217-29881
Stuyvesant H. S., 5th Floor

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5μ-5	# Structures 5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
S-T1 8723 -1	1593.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	
S-T2 8723 -2	1504.50	0.0562	0	None Detected	0	0	0.0046	<17.79	<0.0046	
S-T3 8723 -3	1593.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	
S-T4 8723 -4	1602.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	
S-T5 8723 -5	1424.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048	
S-T6 8723 -6	1557.50	0.0562	0	None Detected	0	0	0.0044	<17.79	<0.0044	
S-T7 8723 -7	1602.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	

ROMAN PEYSAKHOV
Analyzed by

MICHAEL A. GORYCKI, Ph.D
Approved by

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

NYC-WTC_000106449

NYC 9/11 Public Portal Document

Attn:
Taylor Evironmental Group

Received: 8/20/02 4:20:00 PM
ATC Group #: 8723
Analysis Date: 8/20/02

Fax: (516) 358-1780 Phone:
Project: NYC SCA Project #: M477-15217-29881
Stuyvesant H. S., 5th Floor

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5µ-5	# Structures 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
5-T8 8723 -8	1593.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	
5-T9 8723 -9	1593.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	
5-T10 8723 -10	1593.00	0.0562	0	None Detected	0	0	0.0043	<17.79	<0.0043	

ROMAN PEYSAKHOV
Analyzed by:

MICHAEL A. GORYCKI, Ph.D
Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

NYC-WTC_000106450

NYC-WTC_000106451

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP

DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: CARLOS JOFAT	CLIENT: NYCSCA.	SITE ADDRESS: STUYVESANT H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: 8-20-02	CONTACT: DAVID SWAT	WORK AREA: 5TH FLOOR	DATE LOGGED:
ROTOMETER NO: TOG L-16.	PROJECT NO.: M477-15217-29881	PROJECT MANAGER: C. McCLOUD	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/cc
S-L1		IWA ☐ OWA ☐ KITCHEN - SERVING AREA.	4/4	1047	1513	266	4	1064			< 1.4	
S-L2		IWA ☐ OWA ☐ CAFETERIA - EATING AREA - CENTER	4/4	1050	1514	264	4	1056			< 1.4	
S-L3		IWA ☐ OWA ☐ 5TH FL CORRIDOR O/S DINING RM + W. STAIR	4/4	1052	1515	263	4	1052			< 1.4	
S-L4		IWA ☐ OWA ☐ 5TH FL CORRIDOR AT BOTTOM OF ESC.	4/4	1054	1516	262	4	1048			< 1.4	
S-L5		IWA ☐ OWA ☐ BOYS LOCKER RM @ LOCKER # 2730	4/4	1058	1517	259	4	1036			< 1.4	
FB-1		IWA ☐ OWA ☐ FIELD BLANK - 1									< 1.5	
FB-2		IWA ☐ OWA ☐ FIELD BLANK - 2									< 1.5	
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

RELINQUISHED TO TEG DROP BOX (SIGNATURE): [signature]	DATE: 8-20-02	TIME: 16:20	RECEIVED FROM TEG DROP BOX (SIGNATURE): AG 08/20 6p	DATE:	TIME:
RELINQUISHED BY: (SIGNATURE)	DATE:	TIME:	RECEIVED BY: (SIGNATURE) AT E. A. Cruz	DATE: 8/20/02	TIME: 1620
ANALYST: (SIGNATURE)	DATE:	TIME:	COMMENTS: CHRYSO NIOSH 7082		

CIRCLE: PCM TEM — BGND PRE DURING POST — OSHA OTHER LEAD

LOT # FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy ~~PINK: Samples~~ ORANGE: Site Copy

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-21-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 5th Floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	08-20-02
DATE RECEIVED:	08-20-02
DATE ANALYZED:	08-20-02
SAMPLE MEDIA:	Air Samples
ANALYSIS REQUIRED:	Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
5-L1	21334	Kitchen Serving Area	<1.4	1.4
5-L2	21334	Cafeteria Eating Area Center	<1.4	1.4
5-L3	21334	5th Floor Corridor O/S Dining Rm W.Stair	<1.4	1.4
5-L4	21334	5th Floor Corridor at Bottom of Esc.	<1.4	1.4
5-L5	21334	Boy's Locker Rm @ Locker #2730	<1.4	1.4
FB1	21334	Field Blank	<1.5 µg	1.5 µg
FB2	21334	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106454

NYC 9/11 Public Portal Document
08/20/2002 20:36 212-298-2538 EMSL ANALYTICAL INC PAGE 02/04

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: Carlos Jofat	CLIENT: NYC SCA.	SITE ADDRESS: Stuyvesant H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: Aug 20 2002	CONTACT: Hamid Saadi	WORK AREA: 4th Floor	DATE LOGGED:
ROTOMETER NO: T66149	PROJECT NO.: M477-15217-29881	PROJECT MANAGER: C. McBrown.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
4-T1		IWA ☒ OWA ☐ Rm 439	9/9	1121	1421	180	9	1620				
4-T2		IWA ☒ OWA ☐ 4th Fl. Corridor o/s Rm 432	9/9	1122	1422	180	9	1620				
4-T3		IWA ☒ OWA ☐ Rm 429	9/8	1123	1423	180	8.5	1530				
4-T4		IWA ☒ OWA ☐ 4th Fl Corridor WEST SIDE of ESCALATOR	9/7.5	1124	1424	180	8.25	1485		03021	.506	
4-T5		IWA ☒ OWA ☐ Rm 450	9/8	1125	1425	180	8.5	1530				
4-T6		IWA ☒ OWA ☐ 4th Fl. Corridor o/s Rm 432	9/9	1126	1426	180	9	1620				
4-T7		IWA ☒ OWA ☐ 4th Fl. Corridor EAST SIDE of ESCALATOR	9/7	1127	1427	180	8	1440				
4-T8		IWA ☒ OWA ☐ 4th FL Corridor NEAR LOCKER # 4-427	9/9	1128	1428	180	9	1620				
4-T9		IWA ☒ OWA ☐ 4th FL. Corridor o/s Rm 401	9/8	1129	1429	180	8.5	1530				
4-T10		IWA ☒ OWA ☐ Rm 407	9/9	1130	1430	180	9	1620				
FB-1		IWA ☐ OWA ☐ FIELD BLANK - 1										
FB-2		IWA ☐ OWA ☐ FIELD BLANK - 2										
SB-1		IWA ☐ OWA ☐ SPIKED BLANK										

EMSL ANALYTICAL INC
RECEIVED
02 AUG 20 PM 4:45

RELINQUISHED TO TEG DROP BOX (SIGNATURE):	DATE: 8/20	TIME: 1650	RECEIVED FROM TEG DROP BOX (SIGNATURE):	DATE:	TIME:
RELINQUISHED BY: (SIGNATURE)	DATE:	TIME:	RECEIVED BY: (SIGNATURE)	DATE: 8/20/02	TIME: 4:45 pm
ANALYST: (SIGNATURE)	DATE:	TIME:	COMMENTS: 6 HR T/A. Analyze T-1 through T-10		

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER

LOT # FILTER MANUFACTURER

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217-29881 / NYC SCA / Stuyvesant H.S. / 4th Floor

Customer ID: TAYL50
Customer PO:
Received: 08/20/02 4:45 PM
EMSL Order: 030211506
EMSL Project ID:
Analysis Date: 8/20/2002

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures ≥ 0.5μ < 5	# Structures ≥ 5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
4-T1 030211506-0001	1620.00	0.0500	7	None Detected			0.0048	<20.00	<0.0048	
4-T2 030211506-0002	1620.00	0.0500	0	None Detected			0.0048	<20.00	<0.0048	
4-T3 030211506-0003	1530.00	0.0625	0	None Detected			0.0040	<16.00	<0.0040	
4-T4 030211506-0004	1485.00	0.0625	0	None Detected			0.0041	<16.00	<0.0041	
4-T5 030211506-0005	1530.00	0.0625	0	None Detected			0.0040	<16.00	<0.0040	
4-T6 030211506-0006	1620.00	0.0500	0	None Detected			0.0048	<20.00	<0.0048	
4-T7 030211506-0007	1440.00	0.0625	0	None Detected			0.0043	<16.00	<0.0043	
4-T8 030211506-0008	1620.00	0.0500	0	None Detected			0.0048	<20.00	<0.0048	
4-T9 030211506-0009	1530.00	0.0625	0	None Detected			0.0040	<16.00	<0.0040	
4-T10 030211506-0010	1620.00	0.0500	0	None Detected			0.0048	<20.00	<0.0048	

Analyst(s)
Jose Arriaga (10)

Jose Arriaga
Laboratory Manager
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request
Accredited for NVLAP PLM/TEM #101048-0, NY State ELAP #11508

TEMAHERA-1

NYC-WTC_000106455

NYC-WTC_000106456

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE ____ OF ____

TECHNICIAN: Carlos Tufat	CLIENT: NYCSCA.	SITE ADDRESS: Stuyvesant H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: 8-20-02	CONTACT: Hamid Sawon	WORK AREA: 4th Floor	DATE LOGGED:
ROTOVETER NO: TOG L-16.	PROJECT NO: M477-1521?-298881	PROJECT MANAGER: C. McClown.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	FIBERS/CC
4-L1		IWA ☐ OWA ☐ 4th Fl Corridor @ Room 440	4/4	1031	1519	288	4	1152			<1.3	<1.3
4-L2		IWA ☐ OWA ☐ Room 450 - Robotics - Center	4/4	1033	1520	287	4	1148			<1.3	<1.3
4-L3		IWA ☐ OWA ☐ 4th Fl Corridor @ Top of Esc + West Stair	4/4	1036	1521	286	4	1144			<1.3	<1.3
4-L4		IWA ☐ OWA ☐ Room 411 - Computer Rm	4/4	1039	1522	283	4	1132			<1.3	<1.4
4-L5		IWA ☐ OWA ☐ 4th Fl Corridor @ East Stair + Rm 401/402	4/4	1042	1523	271	4	1084			<1.4	<1.5
FB-1		IWA ☐ OWA ☐ Field Blank-1								No filter		
FB-2		IWA ☐ OWA ☐ Field Blank-2										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

RELINQUISHED TO TEG DROP BOX (SIGNATURE): John Mehring	DATE: 8.20.02	TIME: 1620	RECEIVED FROM TEG DROP BOX (SIGNATURE): Alex 8/20	DATE:	TIME:
RELINQUISHED BY: (SIGNATURE)	DATE:	TIME:	RECEIVED BY (SIGNATURE): E.A.C.	DATE: 8/21/02	TIME: 16:20
ANALYST: (SIGNATURE)	DATE:	TIME:	COMMENTS: OHSCAH NIOSH 7082		

CIRCLE: PCM TEM — BORO PRE DURING POST — OSHA OTHER Comp

LOT # FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-21-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 4th Floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	08-20-02
DATE RECEIVED:	08-20-02
DATE ANALYZED:	08-20-02
SAMPLE MEDIA:	Air Samples
ANALYSIS REQUIRED:	Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
4-L1	21336	4th Floor Corridor @ Rm 440	<1.3	1.3
4-L2	21336	Rm 450 Robotics Conyer	<1.3	1.3
4-L3	21336	4th Floor Corridor @ Top of Esc. West Stair	<1.3	1.3
4-L4	21336	Rm 411 Computer Rm	<1.3	1.3
4-L5	21336	4th Floor Corridor @ East Stair Rm 401/402	<1.4	1.4
FB1	21336	Field Blank - NO FILTER	-	-
FB2	21336	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: TCH

REPORT PREPARED BY: [signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: [signature]

LABORATORY DIRECTOR: [signature]

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106459

NYC 9/11 Public Portal Document
08/20/2002 20:35 212-290-2538 EMSL ANALYTICAL INC PAGE 02/02

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN	CLIENT	SITE ADDRESS	DATE SUBMITTED
G. POTZANEK.	NYC-SCA.	STUYVESANT H.S.	8-20-02
DATE SAMPLED	**CONTACT**	**WORK AREA**	**DATE LOGGED**
8-20-02	DAVID SAVOY	3RD FLOOR	
ROTOMETER ID	**PROJECT NO.**	**PROJECT MANAGER**	**DATE APPROVED / SIGNATURE**
TEG-147	M477-15217-298881	C. McELGUN	

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
3-T1		IWA ☒ OWA ☐ ROOM 336 - CENTER	8/8	1131	1434	183	8	1464				
3-T2		IWA ☒ OWA ☐ 3RD FL. CORRIDOR @ STAIRWELL "R"	8/8	1133	1435	182	8	1456				
3-T3		IWA ☒ OWA ☐ ROOM 350 - WEST SIDE	8/8	1135	1436	181	8	1448				
3-T4		IWA ☒ OWA ☐ 3RD FL CORRIDOR @ STAIR "W"	8/8	1137	1437	180	8	1440				
3-T5		IWA ☒ OWA ☐ 3RD FL CORRIDOR O/S RM 315	8/9	1139	1438	179	8.5	1521.5		0302	115	05
3-T6		IWA ☒ OWA ☐ 3RD FL CORRIDOR O/S GYM	8/8	1141	1439	178	8	1424				
3-T7		IWA ☒ OWA ☐ GYMNASIUM - SOUTH	8/8	1143	1440	177	8	1416				
3-T8		IWA ☒ OWA ☐ GYMNASIUM - NORTH	8/8	1145	1441	176	8	1408				
3-T9		IWA ☒ OWA ☐ ROOM 307 - EAST SIDE	8/8	1146	1442	176	8	1408				
3-T10		IWA ☒ OWA ☐ 3RD FL CORRIDOR O/S RM 302	8/9	1148	1443	175	8.5	1487.5				
FB-1		IWA ☐ OWA ☐ F/BLANK-1										
FB-2		IWA ☐ OWA ☐ F/BLANK-2										
SB-1		IWA ☐ OWA ☐ S/BLANK										

02 AUG 20 PM 5:46

EMSL MANHATTAN RECEIVED

RELINQUISHED TO TEG DROP BOX (SIGNATURE)	DATE	TIME	RECEIVED FROM TEG DROP BOX (SIGNATURE)	DATE	TIME
	8/20	1650			
RELINQUISHED BY: (SIGNATURE)	**DATE**	**TIME**	**RECEIVED BY: (SIGNATURE)**	**DATE**	**TIME**
				8/20/02	4:46 PM
ANALYST (SIGNATURE)	**DATE**	**TIME**	**COMMENTS**		
RKly	8/20/02		6 HR T/A. ANALYZE T-1 THROUGH T-10		

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER

LOT# FILTER MANUFACTURER

Noll G. Taylor for Results

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217-29881 / NYC SCA / Stuyvesant H.S. 3rd Floor

Customer ID: TAYL50
Customer PO:
Received: 08/20/02 4.45 PM
EMSL Order: 030211505
EMSL Project ID:
Analysis Date: 8/20/2002

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures ≥0.5µ < 5	# Structures ≥ 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
3-T1 030211505-0001	1464.00	0.0625	0	None Detected			0.0042	<16.00	<0.0042	
-T2 030211505-0002	1456.00	0.0625	0	None Detected			0.0042	<16.00	<0.0042	
-T3 030211505-0003	1448.00	0.0625	0	None Detected			0.0043	<16.00	<0.0043	
3-T4 030211505-0004	1440.00	0.0625	0	None Detected			0.0043	<16.00	<0.0043	
3-T5 030211505-0005	1521.50	0.0625	0	None Detected			0.0040	<16.00	<0.0040	
-T6 030211505-0006	1424.00	0.0625	0	None Detected			0.0043	<16.00	<0.0043	
-T7 030211505-0007	1416.00	0.0625	0	None Detected			0.0044	<16.00	<0.0044	
3-T8 030211505-0008	1408.00	0.0625	0	None Detected			0.0044	<16.00	<0.0044	
-T9 030211505-0009	1408.00	0.0625	0	None Detected			0.0044	<16.00	<0.0044	
-T10 030211505-0010	1487.50	0.0625	0	None Detected			0.0041	<16.00	<0.0041	

Analyst(s)
Roman Peysakhov (10)

Laboratory Manager
or other approved signatory

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request

Accredited for NVLAP PLM/TEM #101048-0, NY State ELAP #11505

TEMAHERA-1

NYC-WTC_000106460

NYC-WTC_000106461

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: Carlos Jofat	CLIENT: NYC-SCA.	SITE ADDRESS: Stuyvesant H.S.	DATE SUBMITTED: 8/20/02
DATE SAMPLED: Aug 20 2002	CONTACT: Hamid Saadi	WORK AREA: 3rd Floor	DATE LOGGED:
ROTOMETER NO.: TSI L16	PROJECT NO.: M477.15217-299561	PROJECT MANAGER: C McElwain	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
3-L1		IWA ☐ OWA ☐ 3rd Fl Corridor @ Rm C332	4/4	1104	1425	201	4	804				<1.9
3-L2		IWA ☐ OWA ☐ Rm # 351 - Carpentry Shop	4/4	1108	1426	198	4	792				<1.9
3-L3		IWA ☐ OWA ☐ 3rd Fl Corridor At Bottom of Esc + Floor P.	4/4	1110	1427	197	4	788				<1.9
3-L4		IWA ☐ OWA ☐ Ladies Gym. Center	4/4	1115	1428	193	4	772				<1.9
3-L5		IWA ☐ OWA ☐ Room 325 - ~~Carpet~~ @ Storage Cabinets	4/4	1120	1429	189	4	756				<2.0
FB-1		IWA ☐ OWA ☐ F/Blank - 1										<1.5
FB-2		IWA ☐ OWA ☐ F/Blank - 2										<1.5
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

RELINQUISHED TO TEG DROP BOX (SIGNATURE): Tony Mcwayne	DATE: 8/20/02	TIME: 1620	RECEIVED FROM TEG DROP BOX (SIGNATURE): Alc 08/20 Gyn	DATE:	TIME:
RELINQUISHED BY: (SIGNATURE)	DATE	TIME	RECEIVED BY (SIGNATURE) AT C: R. A. C L	DATE: 8/20/02	TIME: 1620
ANALYST (SIGNATURE)	DATE	TIME	COMMENTS: 6 HR T/A NIOSH 7082	LOT # / FILTER MANUFACTURER	

CIRCLE: PCM TEM — BGRD PRE DURING POST — OSHA OTHER Cont?

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-21-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 3rd Floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	08-20-02
DATE RECEIVED:	08-20-02
DATE ANALYZED:	08-20-02
SAMPLE MEDIA:	Air Samples
ANALYSIS REQUIRED:	Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
3-L1	21335	3rd Floor Corridor @ Rm C332	<1.9	1.9
3-L2	21335	Rm 351 Carpentary Shop	<1.9	1.9
3-L3	21335	3rd Floor Corridor at Bottom of Escalator P	<1.9	1.9
3-L4	21335	Large GYM Counter	<1.9	1.9
3-L5	21335	Rm 325 @ Storage Casings	<2.0	2.0
FB1	21335	Field Blank	<1.5 µg	1.5 µg
FB2	21335	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: [signature]

REPORT PREPARED BY: [signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: [signature]

LABORATORY DIRECTOR: [signature]

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.

POST GENERAL CLEANING LEAD WIPE SAMPLE RESULTS 3RD THROUGH 10TH FLOORS

PROJECT #: M477-15217
LLW#: 29881

130A JERICHO TPKE., FLORAL PARK, NY 11001 • PHONE (516) 358-2955 • FAX (516) 358-1780

NYC-WTC_000106465

NYC-WTC_000106466

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAVOJ	SAMPLER (SIGNATURE)	DATE 7.28.02	TIME 0030	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: STUYVESANT HS 345 CHAMBERS ST. NY	PROJECT # M477-15217-24981	SAMPLER NAME (PRINT): KIRK MC KENZIE			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 1010 - FLOOR 4' South of Center Wall Column	1				✓	< 9.0
	LW-02	ROOM 1010 - WORK Table Top 7' South of Center Wall Column	1				✓	
	LW-03	ROOM 1025 - FLOOR 3' of West ENT. off CORRIDOR	1				✓	
	LW-04	ROOM 1025 - STUDENT DESK Top - WINDOW ROW FRONT	1	✓				
	LW-05	ROOM 1033 - FLOOR South side of NW column	1				✓	
	LW-06	ROOM 1033 - Drafting File CABINET Top (NW CORNER CABINET)	1		✓			
	FBL-1	Field Blank	—					
	FBL-2	Field Blank	—					

FAX RESULTS TO TAYLOR 516-358-1780
212 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY 1/29/02

COMMENTS / INSTRUCTIONS: 6 HR. TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/29/02 TIME 0030	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 7.28.02. TIME	PRINTED NAME: TERESA MICHALUK	RECEIVED BY LAB (SIGNATURE)	DATE 7/29/02 TIME 5:45	PRINTED NAME

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-29-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-28-02
DATE RECEIVED: 07-29-02
DATE ANALYZED: 07-29-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20725	Rm 1010 Floor 4' South of Center Wall Column	<9.0	9.0
LW-02	20725	Rm 1010 Work Table Top 7' South of Center Wall Column	<9.0	9.0
LW-03	20725	Rm 1025 Floor 3' of West Entrance. Off Corridor	<9.0	9.0
LW-04	20725	Rm 1025 Student Desk Top Window Row Front	<9.0	9.0
LW-05	20725	Rm 1033 Floor South Side of NW Column	<9.0	9.0
LW-06	20725	Rm 1033 Drafting File Cabinet Top (NW Corner Cabinet)	<9.0	9.0
FBL-1	20725	Field Blank	<9.0 µg	9.0 µg
FBL-2	20725	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: JC

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106469

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

a0777

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA Structures

CONTACT: Hamid Sayfi

SAMPLER (SIGNATURE): [signature] DATE: 7/29/02 TIME: 4p

SAMPLER NAME (PRINT): Peter Graham

SAMPLE(S) SEALED: (YES) / NO

CORRECT CONTAINER(S): (YES) / NO

PROJECT LOCATION: 345 Chambers St

PROJECT #: M477-152017/2988

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	07	rm 1001 Floor W2-19-7	1				1	<9.0
	08	rm 1001 desk	1				1	<9.0
	09	rm 1002 floor w-2 8-1	1				1	<9.0
	10	rm 1002 Shelf	1		1			<9.0
	11	rm 1003 Floor w-4 2-1	1				1	<9.0
	12	rm 1003 Shelf	1		1			<9.0
	13	rm 1004 floor w-2-5-1	1				1	<9.0
	14	rm 1004 Teachers Desk	1				1	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☑ BY 7/29/02

COMMENTS / INSTRUCTIONS: 6 HR TA

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	7/29/02 5pm	Peter Graham	R. Drondina	7.29. 17.00	R. Drondina
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106470

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SEA Stanwyck Wall WS	CONTACT: Hamid Sano,	SAMPLER (SIGNATURE):	DATE: 7/29/02	TIME: 4:40
PROJECT LOCATION: 345 Chambers St.	PROJECT #: #477-152017-2988	SAMPLER NAME (PRINT): Petrou	SAMPLE(S) SEALED: (YES) NO	CORRECT CONTAINER(S): (YES) NO
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____				

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				LAB RESULT µg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	15	rm 1005 Floor W-2 3-1	1				1	<9.0
	16	rm 1005 Shelf	1		1			<9.0
	17	rm 1006 Floor W-8 8-8	1				1	<9.0
	18	rm 1006 table	1				1	<9.0
	19	rm 1007 Floor W4 4-2	1				1	<9.0
	20	rm 1007 desk	1				1	<9.0
	21	rm 1039 A Floor W2 3-3	1				1	<9.0
	22	rm 1039 A Shelf	1		1			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☑ BY 6/10

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE 7/29/02 TIME 4:50 pm	PRINTED NAME Petrou	RECEIVED BY (SIGNATURE) R. Drandina	DATE 7.29 TIME 17.00	PRINTED NAME R. Drandina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_00010647

20744

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA Stuyvesant
CONTACT: Howard Saroj
SAMPLER (SIGNATURE): [signature] DATE: 7/29/02 TIME: 4 W
SAMPLER NAME (PRINT): [illegible]
SAMPLE(S) SEALED: (YES) / NO
CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: 345 Chambers
PROJECT #: M427-152017-2988
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	23	rm 1039 Floor W1 1-1	1				1	<LOD
	24	rm 1039 table	1		1			<LOD
	FB-3	Bell Blank						<LOD
	FB-4	Bell Blank						<LOD

TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY / /
COMMENTS / INSTRUCTIONS: 4 hr TAT

RELINQUISHED BY (SIGNATURE): [signature]	DATE: 7/29 TIME: 1600	PRINTED NAME:	RECEIVED BY (SIGNATURE): R. Droudina	DATE: 7, 29 TIME: 17.00	PRINTED NAME: R. Droudina
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE):	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106472

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

#20715

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAWOZ		7.27.02		(YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St. NY	PROJECT # M477-15217-29981	SAMPLER NAME (PRINT): Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/FT² LAB RESULT
	FBL-1	Field Blank						<9.0
	FBL-2	Field Blank						↓

TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/28/02 0000	Kirk McKenzie	ATC Lab	07/28/02 0.00	D. Kogan
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
	7.29.02 1.00	TERESA MICHALCUK			

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-30-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-29-02
DATE RECEIVED: 07-29-02
DATE ANALYZED: 07-29-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
07	20744	Rm 1001 Floor W2 19-7	<9.0	9.0
08	20744	Rm 1001 Desk	<9.0	9.0
09	20744	Rm 1002 Floor W-2 8-1	<9.0	9.0
10	20744	Rm 1002 Shelf	<9.0	9.0
11	20744	Rm 1003 Floor W-4 2-1	<9.0	9.0
12	20744	Rm 1003 Floor Shelf	<9.0	9.0
13	20744	Rm 1004 Floor W-2 5-1	<9.0	9.0
14	20744	Rm 1004 Teachers Desk	<9.0	9.0
15	20744	Rm 1005 Floor W-2 3-1	<9.0	9.0
16	20744	Rm 1005 Shelf	<9.0	9.0
17	20744	Rm 1006 Floor W-8 8-8	<9.0	9.0
18	20744	Rm 1006 Table	<9.0	9.0
19	20744	Rm 1007 Floor W4 4-2	<9.0	9.0
20	20744	Rm 1007 Desk	<9.0	9.0
21	20744	Rm 1039A Floor W2 3-3	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

22	20744	Rm 1039A Shelf	<9.0	9.0
23	20744	Rm 1039 Floor W1 1-1	<9.0	9.0
24	20744	Rm 1039 Table	<9.0	9.0
FB-3	20744	Field Blank	<9.0 µg	9.0 µg
FB-4	20744	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft². Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RD

REPORT PREPARED BY: [signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: [signature]

LABORATORY DIRECTOR: [signature]

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106475

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA

CONTACT: Hamid Savoy

SAMPLER (SIGNATURE): AL. Kazakov

DATE: 7/29/02 TIME: 0100

SAMPLER NAME (PRINT): AL. Kazakov

SAMPLE(S) SEALED: (YES) / NO

CORRECT CONTAINER(S): (YES) / NO

PROJECT LOCATION: Stuyvesant H.S.

PROJECT #: M477-15217/29881

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT $\mu g/ft^2$
	RW-01	Room # 1017 A Work table	1	X				< 9.0
	RW-02	Room # 1017 A floor By Univent	1				X	9.0
	RW-03	Room #1017 White table By the Entrance	1	X				< 9.0
	RW-04	Room #1017 floor By TV set.	1				X	< 9.0
	RW-05	Room # 1024 A Scanner desk	1	X				< 9.0
	RW-06	Room # 1024 A floor By Entrance	1				X	< 9.0
	RW-07	Room # 1024 Teachers desk (Table)	1	X				< 9.0
	RW-08	Room # 1024 floor. By the black board	1				X	< 9.0

Fax results to Taylor at: (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/29/02 TIME 01:00	PRINTED NAME AL. Kazakov	RECEIVED BY (SIGNATURE) R. Drudina	DATE 7.29 TIME 01.00	PRINTED NAME R. Drudina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106476

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1700

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE):	DATE: 7/29/02	TIME: 0100	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): AL. Kazanov			CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: Stuyvesand H.S.	PROJECT #: M477-15217 / 29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	RW-09	Room # C1021 Electrical equipment shell	1		X			11.3
	RW-10	Room # C 1021 floor by entrance	1				X	<9.0
	RW-11	Room # C 1023 floor by the wall electrical panel	1				X	<9.0
	RW-12	Room # 1026 Top of the safety storage cabinet.	1		X			<9.0
	RW-13	Room # 1026 floor by the entrance	1				X	<9.0
	RW-14	Room # 1027 floor By the entrance	1				X	<9.0
	RW-15	Room # 1029 Bathroom floor by sink.	1				X	<9.0
	RW-16	Room # 1031 Bathroom floor by Entrance	1				X	<9.0

Fax results to Taylor at: (212)406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/29/02 TIME 01100	PRINTED NAME: AL. Kazanov	RECEIVED BY (SIGNATURE): R. Drudina	DATE 7.29 TIME 01.00	PRINTED NAME: R. Drudina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_00010647

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20151

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy		7/29/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesand H.S	M477-15217/29881	AL. Kazanov			YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				LAB RESULT µg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	RW-17	Room # 1030 Bathroom floor by the sinks	1				X	<9.0
	RW-18	Room # 1034 Bathroom floor by the entrance	1				X	<9.0
	RW-19	Room # 1038 Slop sink floor by Entrance	1				X	<9.0
	RW-20	Corridor by room # 1039 floor	1				X	<9.0
	RW-21	Corridor by room # 1017 floor	1				X	<9.0
	RW-22	Corridor by room # 1003 floor	1				X	<9.0
	RW-23	F/B "		"				<9.0
	RW-24	F/B "			"			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/29/02 01:00	AL. Kazanov.	R. Drozdina	7.29 01.00	R. Drozdina
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-30-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-29-02
DATE RECEIVED: 07-29-02
DATE ANALYZED: 07-29-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
RW-01	20757	Rm 1017A Work Table	<9.0	9.0
RW-02	20757	Rm 1017A Floor by Unitvent	<9.0	9.0
RW-03	20757	Rm 1017 White Table by the Entrance	<9.0	9.0
RW-04	20757	Rm 1017 Floor by TV Set	<9.0	9.0
RW-05	20757	Rm 1024A Scanner Desk	<9.0	9.0
RW-06	20757	Rm 1024A Floor by Entrance	<9.0	9.0
RW-07	20757	Rm 1024 Teacher Desk (Table)	<9.0	9.0
RW-08	20757	Rm 1024 Floor by the Blackboard	<9.0	9.0
RW-09	20757	Rm C1021 Electrical Euipment Shelf	11.3	9.0
RW-10	20757	Rm C1021 Floor by Entrance	<9.0	9.0
RW-11	20757	Rm C1023 Floor by the Wall Electircal Panel	<9.0	9.0
RW-12	20757	Rm 1026 Top of the Safety Storage Cabinet..	<9.0	9.0
RW-13	20757	Rm 1026 Floor by the Entrance	<9.0	9.0
RW-14	20757	Rm 1027 Floor by the Entrance	<9.0	9.0
RW-15	20757	Rm 1029 Bathroom Floor by Sink	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

RW-16	20757	Rm 1031 Bathroom Floor by Entrance	<9.0	9.0
RW-17	20757	Rm 1030 Bathroom Floor by the Sink's	<9.0	9.0
RW-18	20757	Rm 1034 Bathroom Floor by the Entrance	<9.0	9.0
RW-19	20757	Rm 1032 Slop Sink Floor by Entrance	<9.0	9.0
RW-20	20757	Corridor by Rm 1039 Floor	<9.0	9.0
RW-21	20757	Corridor by Rm 1017 Floor	<9.0	9.0
RW-22	20757	Corridor by Rm 1003 Floor	<9.0 µg	9.0 µg
RW-23	20757	Field Blank	<9.0 µg	9.0 µg
RW-24	20757	Field Blank		

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: F.D

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106480

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

#20760

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA Stuyvesant

CONTACT: Hamid Saud

SAMPLER (SIGNATURE): [signature] DATE: 7/30/02 TIME: 8:30

SAMPLER NAME (PRINT): Petrarca

SAMPLE(S) SEALED: YES / NO

CORRECT CONTAINER(S): YES / NO

PROJECT LOCATION: 345 Chambers St

PROJECT #: M477-1-50018/2988

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	01	rm 1009 Floor w 7 3-1	1				X	
	02	rm 1009 wood desk	1	X				
	03	rm 209 univent near door	1		X			
	04	rm 1010 A Floor W1 3-1	1				X	
	05	rm 1010 A Shelf	1		X			
	FB-1	Field Blank						
	FB-2	Field Blank						

Fax 516 358 2955
212-406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 48 hrs

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	7/30 8:30	Petrark	[signature]	8/2	Walter Plomb
[signature]	8/30				

RECEIVED BY LAB (SIGNATURE) | DATE / TIME | PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-30-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-30-02
DATE RECEIVED: 07-30-02
DATE ANALYZED: 07-30-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
01	20760	Rm 1009 Floor W7 3-1	23.4	9.0
02	20760	Rm 1009 Wood Desk	<9.0	9.0
03	20760	Rm 209 Unitvent Rear Panel	20.1	9.0
04	20760	Rm 1010A Floor W1 3-1	<9.0	9.0
05	20760	Rm 1010A Shelf	<9.0	9.0
FB-1	20760	Field Blank	<9.0 µg	9.0 µg
FB-2	20760	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106482

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA

CONTACT: Hamid Savoj

SAMPLER (SIGNATURE): [signature] DATE: 7/30/02 TIME:

SAMPLER NAME (PRINT): Kirk McKenzie

SAMPLE[S] SEALED: (YES) NO

CORRECT CONTAINER[S]: (YES) / NO

PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST. N.Y.

PROJECT #: M477-15217-29881

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	ROOM 1009 - FLOOR W 7 3-1	1				✓	<9.0
	FBL-1	Field Blank	—				—	<9.0
	FBL-2	Field Blank	—				—	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☑ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE 7/30/02 TIME 1735	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) R. Rondina	DATE 7.30.02 TIME 17.40	PRINTED NAME R. Rondina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

p/u. Call CHRIS McElgunn w/L Results

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-31-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-30-02
DATE RECEIVED:	07-30-02
DATE ANALYZED:	07-30-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20786	Rm 1009 Floor W7 3-1	<9.0	9.0
FBL-1	20786	Field Blank	<9.0 µg	9.0 µg
FBL-2	20786	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RP

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_00010648

NYC 9/11 Public Portal Document
08/02/2002 21:22 212-298-2538 EMSL ANALYTICAL INC PAGE 04/05

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030210496

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE) / DATE / TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy	8/02/02	(YES) / NO
		SAMPLER NAME (PRINT): AL. Kazakov	CORRECT CONTAINER(S) (YES) / NO
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-35217/29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION			AREA (FT²)	SURFACE MATERIAL				LAB RESULT µg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	W-01	Room # 939 Teachers table Lower End.	1	A.N.			X	< 10.0
	W-02	Room # 939 floor By window Univent	1				X	< 10.0
	W-03	Room # 935 Teachers table Lower End	1				X	< 10.0
	W-04	Room # 935 floor By west side Entrance	1				X	< 10.0
	W-05	Room # 931 Teacher table	1				X	< 10.0
	W-06	Room # 951 floor S-E corner.	1				X	< 10.0
	W-07	Room # 929 Book shelf By entrance	1		X			< 10.0
	W-08	Room # 929 floor By window.	1				X	< 10.0

02 AUG -2 PM 4:24
EMSL-MANHATTAN
RECEIVED

Fax Reports to Taylor on site (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/02/02 TIME 1600	PRINTED NAME: AL. Kazakov	RECEIVED BY (SIGNATURE)	DATE 8.2.02 TIME 4:24 PM	PRINTED NAME: José Arriaga
RELINQUISHED BY (SIGNATURE)	DATE TIME 1615	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_000106485

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

0302104960

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savaf	SAMPLER (SIGNATURE): [signature] DATE: 8/02/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): Al. Karakou	CORRECT CONTAINER(S): (YES) NO
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217/29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION			AREA (FT²)	SURFACE MATERIAL				LAB RESULT µg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	W-09	Room #927 Table By S-E side window	1				X	<10.0
	W-10	Room #927 floor By Teacher table	1				X	12.0
	W-11	Room #926 Book shelf By the Black Board	1	X				<10.0
	W-12	Room #926 floor By the window	1				X	<10.0
	W-13	Room #930 Bathroom floor By the sink	1				X	<10.0
	W-14	Room #934 Girls Bathroom floor By Entrance	1				X	<10.0
	W-15	Room #936 Student desk By N-E side entrance	1				X	<10.0
	W-16	Room #936 floor By East side Teacher desk	1				X	<10.0

ENSL MANHATTAN RECEIVED 02 AUG -2 PM 4:24

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/02/02 TIME 1600	PRINTED NAME: Al. Karakou	RECEIVED BY (SIGNATURE): [signature]	DATE 8.2.02 TIME 4:24 pm	PRINTED NAME: JOSE ANRIAGA
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/02/2002 21:22 212-290-2538 EMSL ANALYTICAL INC PAGE 05/06

NYC-WTC_00010486

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021049G

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Sadat		8/02/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant HS,	M477-15217/29881	AL. Karakoc			YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-17	Room # 938 Teacher desk by the windows.	1				X	<10.0
	W-18	Room # 938 floor by the entrance	1				X	<10.0
	W-19	Room # 940 Teacher desk Lower end	1				X	<10.0
	W-20	Room # 940 floor by N-W side window	1				X	<10.0
	W-21	F/B	"				"	
	W-22	F/B	"				"	

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 8/02/02 TIME 16:00	PRINTED NAME Al. Karakoc	RECEIVED BY (SIGNATURE)	DATE 8.2.02 TIME 4:24PM	PRINTED NAME Jose Arriaga
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL MANHATTAN RECEIVED 02 AUG -2 PM 4:24

NYC 9/11 Public Portal Document
08/02/2002 21:22 212-298-2538 EMSL ANALYTICAL INC PAGE 05/05

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900052 Email: manhattanlab@emsl.com

Attn. Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477 - 15217/ 29881/ SCA / Stuyvesant H.S.

Customer ID: TAYL50
Customer PO:
Received: 08/02/02 4:24 PM
EMSL Order: 030210496
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
W-01	Room #939 Teachers Table Lower End	0001	8/2/2002	144 in²	<10.0 µg/ft²	
W-02	Room #939 Floor by Window Univent	0002	8/2/2002	144 in²	<10.0 µg/ft²	
W-03	Room #935 Teachers Table Lower End	0003	8/2/2002	144 in²	<10.0 µg/ft²	
W-04	Room #935 Floor by West Side Entrance	0004	8/2/2002	144 in²	<10.0 µg/ft²	
W-05	Room #931 Teacher Table	0005	8/2/2002	144 in²	<10.0 µg/ft²	
W-06	Room #931 Floor S-E Corner	0006	8/2/2002	144 in²	<10.0 µg/ft²	
W-07	Room #929 Book Shell By Entrance	0007	8/2/2002	144 in²	<10.0 µg/ft²	
W-08	Room #929 Floor by Window	0008	8/2/2002	144 in²	<10.0 µg/ft²	
W-09	Room #927 Table by S-E Side Window	0009	8/2/2002	144 in²	<10.0 µg/ft²	
W-10	Room #927 Floor by Teacher Table	0010	8/2/2002	144 in²	12.0 µg/ft²	
W-11	Room #926 Book Shell by the Black Cord	0011	8/2/2002	144 in²	<10.0 µg/ft²	
W-12	Room #926 Floor by the Window	0012	8/2/2002	144 in²	<10.0 µg/ft²	
W-13	Room #930 Bathroom Floor by the Sink	0013	8/2/2002	144 in²	<10.0 µg/ft²	
W-14	Room #934 Girls Bathroom Floor by Entrance	0014	8/2/2002	144 in²	<10.0 µg/ft²	
W-15	Room #936 Student Desk by N-E side Entrance	0015	8/2/2002	144 in²	<10.0 µg/ft²	
W-16	Room #936 Floor by East side Teacher Desk	0016	8/2/2002	144 in²	<10.0 µg/ft²	
W-17	Room #938 Teacher Desk by the Window	0017	8/2/2002	144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106487

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn:	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/02/02 4:24 PM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030210498
Project:	M477 - 15217/ 29881/ SCA / Stuyvesant H.S.	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
W-18	Room #938 Floor by the Entrance	0018	8/2/2002	144 in²	<10.0 µg/ft²	
W-19	Room #940 Teacher Desk Lower End	0019	8/2/2002	144 in²	<10.0 µg/ft²	
W-20	Room #940 Floor by N-W side Window	0020	8/2/2002	144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106488

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477 - 15217/ 29881/ SCA / Stuyvesant H.S.

Customer ID: TAYL50
Customer PO:
Received: 08/02/02 4:24 PM
EMSL Order: 030210496
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
W-21	F/B	0021	8/2/2002	n/a	<10.0 µg/wipe	
W-22	F/B	0022	8/2/2002	n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS AIHA Environmental Lead Laboratory Accreval Program #102581

NYC-WTC_000106489

NYC-WTC_000106490

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20872

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Sadr		8/02/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-#5217/29881	AL. KAZANOV			(YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	W-23	Room # C 932 Slop sink floor By the Entrance	1				X	<9.0
	W-24	Room # 902 Teacher desk By the sink.	1				X	<9.0
	W-25	Room # 902 floor N-E side corner	1				X	<9.0
	W-26	Room # 901 Principal table	1				X	<9.0
	W-27	Room # 901 floor By the Entrance	1				X	<9.0
	W-28	Room # 903A, Table By the Entrance	1				X	<9.0
	W-29	Room # 903A floor By the windows.	1				X	<9.0
	W-30	Room # 903 Computer table	1				X	<9.0

Fax results to Taylor : (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/02/02	AL. KAZANOV	R. Drokolina	8.2.02 / 18.00	
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
	8.02.02 / 16.00	TOBIN MICHAELS.			

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106491

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoj		8/04/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477 - 15217/29881	Al. Kazanov			YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT $\mu g/ft^2$
	W-31	Room #903 floor by the oven table.	1				X	<9.0
	W-32	Room #907 Computer table	1				X	<9.0
	W-33	Room # 907 floor by the windows	1				X	12.2
	W-34	Room # 907 A floor by the Entrance.	1				X	<9.0
	W-35	Room #907 B Top of refrigirator	1		X			<9.0
	W-36	Room #907 B floor by the windows	1				X	<9.0
	W-37	F/B					"	<9.0
	W-38	F/B					"	<9.0

Fax results to Taylor on site; (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT.

RELINQUISHED BY (SIGNATURE)	DATE 8/04/02 TIME	PRINTED NAME Al. Kazanov	RECEIVED BY (SIGNATURE) R. Dreuding	DATE 8.2.02 TIME 16.00	PRINTED NAME
RELINQUISHED BY (SIGNATURE) Tweed	DATE 8.02.02 TIME 16:00	PRINTED NAME Tweed Michaels	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-05-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 08-02-02
DATE RECEIVED: 08-02-02
DATE ANALYZED: 08-02-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-23	20872	Rm 923 Slop Sink Floor by the Entrance	<9.0	9.0
W-24	20872	Rm 902 Teacher Desk by the Sink	<9.0	9.0
W-25	20872	Rm 902 Floor NE Side Corner	<9.0	9.0
W-26	20872	Rm 901 Principal Table	<9.0	9.0
W-27	20872	Rm 901 Floor by the Entrance	<9.0	9.0
W-28	20872	Rm 903A Table by the Entrance	<9.0	9.0
W-29	20872	Rm 903A Floor by the Window	<9.0	9.0
W-30	20872	Rm 903 Computer Table	<9.0	9.0
W-31	20872	Rm 903 Floor by the Oven Table	<9.0	9.0
W-32	20872	Rm 907 Computer Table	12.2	9.0
W-33	20872	Rm 907 Floor by the Windows	<9.0	9.0
W-34	20872	Rm 907A Floor by the Entrance	<9.0	9.0
W-35	20872	Rm 907B Top of Refrigerator	<9.0	9.0
W-34	20872	Rm 907B Floor by the Window	<9.0 µg	9.0 µg
W-37	20872	Field Blank	<9.0 µg	9.0 µg
W-38	20872	Field Blank		

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RD

REPORT PREPARED BY: [signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: [signature]

LABORATORY DIRECTOR: [signature]

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106494

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

J0892

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savar	SAMPLER (SIGNATURE)	DATE 8/08/02 TIME
		SAMPLER NAME (PRINT): Al. Kazakov	SAMPLE(S) SEALED (YES / NO)
PROJECT LOCATION: Stuyvesant H.S	PROJECT #: M477-15217/29881		CORRECT CONTAINER(S) (YES / NO)
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/ft² LAB RESULT
	W-01	Room #911 Teachen table Cowan end	1				X	< 9.0
	W-02	Room # 911 floor By the TV set	1				X	
	W-03	Room # 913 Table By Emergency shower	1				X	
	W-04	Room # 913 floor S-E corner	1				X	
	W-05	Room # 925 Teacher desk	1				X	
	W-06	Room # 925 floor By S-W side window	1				X	
	W-07	Room # 925 B Table By the Entrance	1				X	
	W-08	Room # 925 B floor By the Entrance	1				X	

Fax Results to Taylor (212) 406-2575

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/8/02 TIME	PRINTED NAME Al. Kazakov	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/8/02 TIME 4:20 PM	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 8/8/2 TIME 6:20	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106495

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20892

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE):	DATE 8/03/02 TIME
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217 / 29881	SAMPLER NAME (PRINT): AL. KAZAKOV	SAMPLE(S) SEALED (YES) / NO; CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION.

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/ft² LAB RESULT
	W-09	Room # C923 floor By the Entrance.	1				X	<9.0
	W-10	Room # C921 floor By the Entrance	1				X	
	W-11	Room #909 Table. Computer table	1				X	
	W-12	Room # 905 floor By the Entrance	1				X	
	W-13	Corridor floor By room # 939	1				X	
	W-14	Corridor floor By room # C921	1				X	
	W-15	Corridor floor By room # 905	1				X	
	W-16	F/B						

Fax results to Taylor (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 8/02/02 TIME 4	PRINTED NAME: AL. KAZAKOV	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/3/02 TIME 4:20pm	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 8/3/02 TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106496

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

W892

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoj		8/3/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217 / 29881	AL Karacow			(YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-17	P/B 4				4		<9.0

Fax results to Taylor (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 8/3/02 TIME	PRINTED NAME AL Karacow	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/3/02 TIME 4:20PM	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 8/3/2 TIME 16:20	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-05-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	08-03-02
DATE RECEIVED:	08-03-02
DATE ANALYZED:	08-03-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20892	Rm 911 Teacher Table Lower End	<9.0	9.0
W-02	20892	Rm 911 Floor by the TV Set	<9.0	9.0
W-03	20892	Rm 913 Table by Emergency Shower	<9.0	9.0
W-04	20892	Rm 913 Floor SE Corner	<9.0	9.0
W-05	20892	Rm 925 Teacher Desk	<9.0	9.0
W-06	20892	Rm 925 Floor by SW Side Window	<9.0	9.0
W-07	20892	Rm 925B Table by the Entrance	<9.0	9.0
W-08	20892	Rm 925B Floor by the Entrance	<9.0	9.0
W-09	20892	Rm C923 Floor by the Entrance	<9.0	9.0
W-10	20892	Rm C932 Floor by the Entrance	<9.0	9.0
W-11	20892	Rm 909 Table Computer Table	<9.0	9.0
W-12	20892	Rm 909 Floor by the Entrance	<9.0	9.0
W-13	20892	Corridor Floor by Rm 939	<9.0	9.0
W-14	20892	Corridor Floor by Rm C921	<9.0	9.0
W-15	20892	Corridor Floor by Rm 905	<9.0	9.0
W-16	20892	Field Blank	<9.0 µg	9.0 µg
W-17	20892	Field Blank	<9.0 µg	9.0 µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106499

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

030210967

1 of 1

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA

CONTACT: Hamid Sayoj

SAMPLER (SIGNATURE): [signature] DATE: 8/9/02 TIME:

SAMPLER NAME (PRINT): Kirk McKenzie

SAMPLE(S) SEALED: (YES) / NO

CORRECT CONTAINER(S): (YES) / NO

PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.

PROJECT #: M477-15217-2988 1

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	Room 907A (Chem. Storage) Floor. East of entrance	1				X	11.0
	LW-02	Room 907A (Chem. Storage) SE Shelf. Top.	1				X	<10.0.
	FBL-1	Field Blank						
	FBL-2	Field Blank						

EMSL RECEIVED 02 AUG 10 AM 5:06

Fax to 212-406-2535 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/10/02 TIME 0115	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/10/02 TIME 0500	PRINTED NAME Gary McKen	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

NYC 9/11 Public Portal Document
08/10/2002 09:48 212-290-2538 EMSL ANALYTICAL INC PAGE 17

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 28th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn:	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/10/02 8:04 AM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030210967
Project:	NYC SCA/Stuyvesant H.S. 345 Chambers St., New York, N.Y./M477-15217-29881.	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		*Lab ID*	*Analyzed*	*Area Sampled*	*Lead Concentration*	*Notes*
LW-01	Room 907A (Chem. Storage) Floor. East of Entrance.	*0001*		144 in²	11.0 µg/ft²	
LW-02	Room 907A (Chem. Storage) SE Shelf Top	*0002*		144 in²	<10.0 µg/ft²	
FBL-1	Field blank	*0003*		n/a	<10.0 µg/wipe	
FBL-2	Field blank	*0004*		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106500

NYC-WTC_000106501

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

21040

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoj		8/9/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesand H.S.	M477-15217/29881	AL. Kazakov			YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	Room # 925 A shelf Right side of the entrance	1				X	<9.0
	LW-02	Room # 925 A floor by the sink	1				X	<9.0
	LW-03	1²/13 "				"		<9.0
	LW-04	F/13 "				"		<9.0

Fax results to Taylor, on site (212) 406-2535 office (516) 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr. T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
Fax ltr	8/9/02 1330		ATC Lab / Rklopf	08/08/02 1730	D. Hogan
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-12-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-09-02
DATE RECEIVED:	08-09-02
DATE ANALYZED:	08-09-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	21040	Rm 925A Shelf Right Side of the Entrance	<9.0	9.0
LW-02	21040	Rm 925A Floor by the Sink	<9.0	9.0
FB-1	21040	Field Blank	<9.0 µg	9.0 µg
FB-2	21040	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RD

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_00010503 PAGE 05/07
EMSL ANALYTICAL INC 212-290-2538
08/05/2002 07:25
NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

Q50210610 1 of 1

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Savoj		8/4/02		(YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	ROOM 829 - FLOOR 3' of WEST entrance & 2' of West wall	1				X	11.0
	LW-02	ROOM 829 - Table North END OF Lab Table	1				X	<10.0
	LW-03	ROOM 833 - FLOOR CENTER ISLE - 1st TIER.	1				X	<10.0
	LW-04	ROOM 833 - Desk FRONT Desk - South SIDE	1				X	<10.0
	LW-05	ROOM 835 - FLOOR 3' of EAST ENTRANCE	1				X	~~13.0~~ <10.0
	LW-06	ROOM 835 - Desk REAR Desk - center	1				X	~~<10.0~~ 13.0
	LW-07	ROOM 837 - FLOOR between Lab Table & EAST wall	1				X	<10.0
	LW-08	ROOM 837 - Table Lab Table center	1				X	~~15.0~~ <10.0

Fax Results To 212-406-2535 & 516-358-~~2~~1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/5/02 TIME	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE) Terry	DATE 8.5.02 TIME 1.00	PRINTED NAME TERRY MCHALZUK	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

EMSL MANHATTAN RECEIVED 02 AUG -5 AM 12:29

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_00010504 PAGE 06/07 EMSL ANALYTICAL INC 212-290-2538 08/05/2002 07:25

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021610 23

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC & CA	Hamid Shoj		8/4/02		(YES) NO
PROJECT LOCATION: Stuyvesant HS. 345 Chambers ST. NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT µg/ft2
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-09	Room 839 - Floor 3' of West entrance	1				X	15.0
	LW-10	Room 839 - Desk Front South side.	1				X	12.0
	LW-11	Room 840 - Floor below East cabinet	1		X			<10.0
	LW-12	Room 840 - Desk Teacher's center	1				X	10.0
	LW-13	Room 838 - Floor East side of East vestibule	1				X	<10.0
	LW-14	Room 838 - File cabinet Top at (East File cabinet)	1		X			<10.0
	LW-15	Room 836 - Floor 2' south of center wall column	1				X	<10.0
	LW-16	Room 836 - Teacher's Desk center	1				X	13.0

EMSL MANHATTAN RECEIVED 02 AUG -5 AM 12:29

TURNAROUND REQUIRED:	COMMENTS / INSTRUCTIONS
NORMAL ☐ STAT ☐ BY / /	6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/5/02 TIME	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8.5.02 TIME 0100	PRINTED NAME TOTOS AM	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106505

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030210610

383

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA

CONTACT: HAROLD DAVIS

PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.

PROJECT #: A# 477-15217-2988

SAMPLER (SIGNATURE): [signature] DATE: 8/4/02 TIME:

SAMPLER NAME (PRINT): Kirk McKenzie

SAMPLE(S) SEALED: (YES) / NO

CORRECT CONTAINER(S): (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-17	ROOM 826 - FLOOR 3' @ ENTRANCE	1				X	12.0
	LW-18	ROOM 826 - TOP OF File Cabinet - WEST SIDE	1		X			16.0
	LW-19	ROOM 833 - BATHROOM FLOOR - [illegible]	1				X	11.0
	LW-20	ROOM 834 - [illegible] FLOOR 5' @ ENTRANCE	1				X	<10.0
	LW-21	CONFERENCE ROOM - [illegible] - Between ROOMS [illegible] & 835	1				X	<10.0
	FBL-1	Field Blank						
	FBL-2	Field Blank						
	FBL-3	Field Blank						

RELINQUISHED BY (SIGNATURE): [signature] DATE 8/5/02 TIME PRINTED NAME: Kirk McKenzie

RELINQUISHED BY (SIGNATURE): [signature] DATE 8-5-02 TIME 0900 PRINTED NAME

TURNAROUND TIME REQUIRED: NORMAL ☐ STAT ☐ 1 / 1

COMMENTS / INSTRUCTIONS: 6 HR TAT

RECEIVED BY (SIGNATURE) DATE TIME PRINTED NAME

RECEIVED BY LAB (SIGNATURE) DATE TIME PRINTED NAME

EMSL ANALYTICAL INC RECEIVED AUG 5 10 25 AM

EMSL ANALYTICAL INC 08/05/2002 07:25 212-290-2535

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
207 West 38th Street, New York, NY 10013
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group. Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone. 516-358-2955
Project: NYC SCA/M477-15217-27881/Stuyvesant H.S./345 Chambers St., New York. N.Y.

Customer ID: TAYL50
Customer PO:
Received: 08/05/02 7:08 AM
EMSL Order: 030210610
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	Room 829-Floor 3' of West Unit Vent & 2' West Wall	0001		144 in²	11.0 µg/ft²	
LW-02	Room 829-Table North End of Lab Table	0002		144 in²	<10.0 µg/ft²	
LW-03	Room 833-Floor Center Isle-1st Tier	0003		144 in²	<10.0 µg/ft²	
LW-04	Room 833-Desk Front Desk-North Side	0004		144 in²	<10.0 µg/ft²	
LW-05	Room 835-Floor 3' of East Entrance	0005		144 in²	<10.0 µg/ft²	
LW-06	Room 835-Desk Rear Desk-Center	0006		144 in²	13.0 µg/ft²	
LW-07	Room 837-Floor Between Lab Table & East Wall	0007		144 in²	<10.0 µg/ft²	
LW-08	Room 837-Table Lab Table Center	0008		144 in²	<10.0 µg/ft²	
LW-09	Room 839-Floor 3' of West Entrance	0009		144 in²	15.0 µg/ft²	
LW-10	Room 839-Desk Front South Side	0010		144 in²	12.0 µg/ft²	
LW-11	Room 840-Floor Below East Cabinet	0011		144 in²	<10.0 µg/ft²	
LW-12	Room 840-Desk Teacher's Center	0012		144 in²	10.0 µg/ft²	
LW-13	Room 838-Floor East Side of East Unit Vent	0013		144 in²	<10.0 µg/ft²	
LW-14	Room 838-File Cabinet Top at (E. File Cab.)	0014		144 in²	<10.0 µg/ft²	
LW-15	Room 836-Floor-2' South of Center Wall Column	0015		144 in²	<10.0 µg/ft²	
LW-16	Room 836-Teacher's Desk Center	0016		144 in²	13.0 µg/ft²	
LW-17	Room 826-Floor 3' of	0017		144 in²	12.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102521

NYC-WTC_000106506

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10013
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: NYC SCA/M477-15217-27881/Stuyvesant H.S./345 Chambers St., New York, N.Y.

Customer ID: TAYL50
Customer PO:
Received: 08/05/02 7:08 AM
EMSL Order: 030210610
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
	Entrance					
LW-18	Room 826-Top OF File Cabinet-West Side	0018		144 in²	18.0 µg/ft²	
LW-19	Room 830-Bathroom Floor-Center Room	0019		144 in²	11.0 µg/ft²	
LW-20	Room 834-Bathroom Floor, 3' of Entrance	0020		144 in²	<10.0 µg/ft²	
LW-21	Corridor Floor-Between Rooms 836 & 835	0021		144 in²	<10.0 µg/ft²	
FBL-1	Field blank	0022		n/a	<10.0 µg/wipe	
FBL-2	Field blank	0023		n/a	<10.0 µg/wipe	
FBL-3	Field blank	0024		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106507

NYC-WTC_000106508

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20949

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoj		8/5/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217/29881	AL. Kazakov			(YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT, µg/ft²
	W-01	Room # 813 floor By Entrance	1				X	<9.0
	W-02	Room # 813 A floor By the sink	1				X	<9.0
	W-03	Room # 813 B floor By Entrance.	1				X	<9.0
	W-04	Room # 817 Table By the Entrance	1				X	<9.0
	W-05	Room # 817 Floor S-W corner.	1				X	<9.0
	W-06	Room # 817A TV stand, Middle of the room	1		X			<9.0
	W-07	Room # 817 A floor By the Entrance	1				X	<9.0
	W-08	Room # 827 A TV stand Middle of the room	1		X			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 8/5/02 TIME	PRINTED NAME Al. Kazakov	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/6/02 TIME	PRINTED NAME G. McKenzie	RECEIVED BY LAB (SIGNATURE) R. Droudina	DATE 8.6.02 TIME	PRINTED NAME R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106509

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20949

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savos		8/5/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S) (YES) / NO
Stuyvesant H.S.	M477-15217/29881	AL. Kazanow			

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				LAB RESULT, µg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	W-09	Room #827A floor by the Entrance	1				X	<9.0
	W-10	Room # 827 Teacher table Lower End	1				X	<9.0
	W-11	Room # 827 floor by middle window	1				X	<9.0
	W-12	Room # 815 Teacher table Lower End	1				X	<9.0
	W-13	Room # 815 floor by S-E side window	1				X	<9.0
	W-14	F/B	"		"			<9.0
	W-15	F/B	"		"			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/5/02 TIME	PRINTED NAME AL. Kazanow	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/6/02 TIME	PRINTED NAME G. McKee	RECEIVED BY LAB (SIGNATURE) R. Droudina	DATE 8.6.02 TIME	PRINTED NAME R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-07-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	08-05-02
DATE RECEIVED:	08-06-02
DATE ANALYZED:	08-06-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20949	Room #813 Floor by Entrance	<9.0	9.0
W-02	20949	Room #813A Floor by Sink	<9.0	9.0
W-03	20949	Room #813B Floor by Entrance	<9.0	9.0
W-04	20949	Room #817 Table by Entrance	<9.0	9.0
W-05	20949	Room #817 Floor SW Corner	<9.0	9.0
W-06	20949	Room #817A TV Stand Middle of Room	<9.0	9.0
W-07	20949	Room #817A Floor by Entrance	<9.0	9.0
W-08	20949	Room #827A TV Stand Middle of Room	<9.0	9.0
W-09	20949	Room #827A Floor by Entrance	<9.0	9.0
W-10	20949	Room #827 Teacher Table Lower End	<9.0	9.0
W-11	20949	Room #827 Floor by Middle Window	<9.0	9.0
W-12	20949	Room #815 Teacher Table Lower End	<9.0	9.0
W-13	20949	Room #815 Floor by SE Side Window	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

W-14	20949	Field Blank	<9.0 µg	9.0 µg
W-15	20949	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft². Exterior surfaces 800 µg/ft²
NOTE 3
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106512

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

030210730

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA.	HAMID SAVOJ.	Carlos Fofat	8-6-02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT): CARLOS FOFAT			CORRECT CONTAINER(S) YES / NO
STUYVESANT H.S.	M477-15217/29881	MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT $\mu g/FT^2$
	LW-01	ROOM # 801 Floor by window.	1 FT				FL TILE	12.0
	LW-02	ROOM # 801 DESK by ENTRANCE	1 FT	X				<10.0
	LW-03	ROOM # 802. Floor by Entrance.	1 FT				tile	<10.0
	LW-04	ROOM # 802 TABLE by ENTRANCE	1 FT	X				<10.0
	LW-05	ROOM # 802A FLOOR AT CENTER	1 FT				tile	<10.0
	LW-06	ROOM # 802A TABLE by windows.	1 FT	X				<10.0
	LW-07	ROOM # 802 B FLOOR AT CENTER	1 FT				TILE	<10.0
	LW-08	ROOM # 802 B. TABLE by window	1 FT	X				11.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE 8-6-02 TIME 1752	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE 8/6/02 TIME 5:56p	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

EMSL MANHATTAN RECEIVED 02 AUG -9 PM 5:55

NYC 9/11 Public Portal Document
09/07/2002 08:45 212-290-2538 EMSL ANALYTICAL INC PAGE 04/05

NYC-WTC_000106513

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021073O

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAVOJ.	~~Carlos Gutierrez~~	8-6-02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
STUYVESANT H.S.	H477-15217 / 29881	CARLOS JOFAN			YES / NO

MATRIX (CIRCLE ONE) WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				LAB RESULT Mg/Ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-09	ROOM # 802C Floor by ENTRANCE	1				✓	13.0
	LW-10	ROOM # 802C by Book Shelf	1		✓			<10.0
	LW-11	ROOM # 803 Floor. AT CENTER.	1				TILE	<10.0
	LW-12	ROOM # 803 TABLE CENTER by window.	1	✓				<10.0
	LW-13	ROOM # 807 Floor AT CENTER	1				TILE	<10.0
	LW-14.	ROOM # 807. TABLE AT CENTER OF ROOM.	1	✓				<10.0
	LW-15	ROOM # 807A Floor AT CENTER.	1				TILE	<10.0
	LW-16	ROOM # 807A → BOOK SHELF AT LEFT SIDE	1		✓			<10.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE 8-6-02 TIME 1752	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE 8/6/02 TIME 5:36 pm	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL ANALYTICAL INC RECEIVED 02 AUG -6 PM 5:56

NYC 9/11 Public Portal Document
08/07/2002 08:46 212-290-2538 EMSL ANALYTICAL INC PAGE 05/05

NYC-WTC_000106514

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030210730

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAVOS.		8-6-02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217/29851	CARLOS O TOFAT			YES / NO

MATRIX (CIRCLE ONE) (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/FC
	LW-17	ROOM # 811 Floor by Entrance	1				TILE	<10.0
	LW-18	ROOM # 811 TABLE AT CENTER OF ROOM	1	✓				<10.0
	LW-19	ROOM # 804 Floor AT CENTER.	1				TILE	<10.0
	LW-20	ROOM # 804 DESK AT Center	1	✓				13.0
	LW-21	ROOM # 809 Floor AT CENTER.	1				TILE	10.0
	LW-22	ROOM # 809. TABLE by ENTRANCE	1	✓				<10.0
	LW-23	ROOM # 823 Floor AT CENTER	1				✓	<10.0
	LW-24	ROOM # 823 ELECTRIC PANEL AT LEFT SIDE TOP	COMPOSITE 1		✓			<10.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE 8-6-02 TIME 1752	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE 8/6/02 TIME 5:56 P	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL MANHATTAN RECEIVED 02 AUG -6 PM 5:56

NYC 9/11 Public Portal Document
08/07/2002 08:46 212-298-2538 EMSL ANALYTICAL INC PAGE 06/08

NYC-WTC_000106515

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030210730

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAROLD SAVOY	Carlos Tafet	8-6-02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
STUYVESANT H.S.	M477-15217/29881	CARLOS TAFET			YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/FT^2
	LW-25	ROOM # 821 FLOOR AT CENTER	1 FT^2				✓	< 10.0
	LW-26	ROOM # 821. AT STAND AT CENTER OF ROOM.	1 FT^2		✓			< 10.0
	FB - 01	FIELD BLANK	—					-
	FB - 02	↓	—					-
	FB - 03	↓	—					-
	LW-27	8 FL CORRIDOR IN FRONT OF STAIRWELL E	1 FT^2					< 10.0
	LW-28	8 FL CORRIDOR by ROOM # 815	1 FT^2					< 10.0

EMSL ANALYTICAL INC
02 AUG -6 PM 5:56
RECEIVED

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
Carlos Tafet	8-6-02 1752			8/6/02 1752	
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/07/2002 08:46 212-290-2538 EMSL ANALYTICAL INC PAGE 07/08

NYC-WTC_000106516

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021073O

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYCSCA	CONTACT: HALIDSAWAT	SAMPLER (SIGNATURE): Carlos Ch. Jofat	DATE: 8-6-02	TIME:	SAMPLE(S) SEALED: YES / NO
		SAMPLER NAME (PRINT): CARLOS CHOFAT			CORRECT CONTAINER(S): YES / NO
PROJECT LOCATION: STUYVESANT H.S. CHAMBERS ST, NY, NY	PROJECT #: 14477-15317 / 79881	MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT: µg/Ft²
	LW-29	ROOM C821 - FLOOR center	1				✓	<10.0
	LW-30	ROOM C823 - FLOOR - center	1				✓	<10.0
	LW-31	ROOM C828 (Service Elev. Lobby) FLOOR - center	1				✓	<10.0
	LW-32	ROOM C832 - Big Pink FLOOR - center,	1				✓	<10.0
	FB-4	Field Blank	—	—	—	—	—	—

EMSL RECEIVED 02 AUG -6 PM 5:56

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE): Carlos Ch. Jofat	DATE: 8-6-02 TIME: 1752	PRINTED NAME:	RECEIVED BY (SIGNATURE):	DATE: 8/6/02 TIME: 5:56	PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE):	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/07/2002 08:46 212-230-2538 EMSL ANALYTICAL INC PAGE 08/08

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M-477-15217/ 29881/ NYC SCA/ STUYVESANT H.S.

Customer ID: TAYL50
Customer PO:
Received: 08/06/02 5:56 PM
EMSL Order: 030210730
EMSL Project ID.

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	ROOM #801 FLOOR BY WINDOW	0001		144 in²	12.0 µg/ft²	
LW-02	ROOM #801 DESK BY ENTRANCE	0002		144 in²	<10.0 µg/ft²	
LW-03	ROOM #802 FLOOR BY ENTRANCE	0003		144 in²	<10.0 µg/ft²	
LW-04	ROOM #802 TABLE BY ENTRANCE	0004		144 in²	<10.0 µg/ft²	
LW-05	ROOM #802A FLOOR AT CENTER	0005		144 in²	<10.0 µg/ft²	
LW-06	ROOM #802A TABLE BY WINDOWS	0006		144 in²	<10.0 µg/ft²	
LW-07	ROOM #802B FLOOR AT CENTER	0007		144 in²	<10.0 µg/ft²	
LW-08	ROOM #802B TABLE BY WINDOW	0008		144 in²	11.0 µg/ft²	
LW-09	ROOM #802C FLOOR BY ENTRANCE	0009		144 in²	13.0 µg/ft²	
LW-10	ROOM #802C BY BOOK SHELF	0010		144 in²	<10.0 µg/ft²	
LW-11	ROOM #803 FLOOR AT CENTER	0011		144 in²	<10.0 µg/ft²	
LW-12	ROOM #803 TABLE CENTER BY WINDOW	0012		144 in²	<10.0 µg/ft²	
LW-13	ROOM #807 FLOOR AT CENTER	0013		144 in²	<10.0 µg/ft²	
LW-14	ROOM #807 TABLE AT CENTER OF ROOM	0014		144 in²	<10.0 µg/ft²	
LW-15	ROOM #807A FLOOR AT CENTER	0015		144 in²	<10.0 µg/ft²	
LW-16	ROOM #807A BOOK SHELF AT LEFT SIDE	0016		144 in²	<10.0 µg/ft²	
LW-17	ROOM #811 FLOOR BY ENTRANCE	0017		144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit = 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106517

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900052 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M-477-15217/ 29881/ NYC SCA/ STUYVESANT H.S.

Customer ID: TAYL50
Customer PO:
Received: 08/06/02 5:56 PM
EMSL Order: 030210730
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-18	ROOM #811 TABLE AT CENTER OF ROOM	0018		144 in²	<10.0 µg/ft²	
LW-19	ROOM #804 FLOOR AT CENTER	0019		144 in²	<10.0 µg/ft²	
LW-20	ROOM #804 DESK AT CENTER	0020		144 in²	13.0 µg/ft²	
LW-21	ROOM #809 FLOOR AT CENTER	0021		144 in²	10.0 µg/ft²	
LW-22	ROOM #809 TABLE BY ENTRANCE	0022		144 in²	<10.0 µg/ft²	
LW-23	ROOM #823 FLOOR AT CENTER	0023		144 in²	<10.0 µg/ft²	
LW-24	ROOM 3#823 ELECTRIC PANEL COMP. AT LEFT SIDE TOP	0024		144 in²	<10.0 µg/ft²	
LW-25	ROOM #821 FLOOR AT CENTER	0025		144 in²	<10.0 µg/ft²	
LW-26	ROOM #821 AT STAND AT CENTER OF ROOM	0026		144 in²	<10.0 µg/ft²	
FB-01	Field blank	0027		n/a	<10.0 µg/wipe	
FB-02	Field blank	0028		n/a	<10.0 µg/wipe	
FB-03	Field blank	0029		n/a	<10.0 µg/wipe	
LW-27	8 FL CORRIDOR IN FRONT OF STAIRWELL E	0030		144 in²	<10.0 µg/ft²	
LW-28	8 FL CORRIDOR BY ROOM #815	0031		144 in²	<10.0 µg/ft²	
LW-29	ROOM C821-FLOOR CENTER	0032		144 in²	<10.0 µg/ft²	
LW-30	ROOM C823-FLOOR CENTER	0033		144 in²	<10.0 µg/ft²	
LW-31	ROOM C828 (SERVICE ELEV. LOBBY) FLOOR-CENTER	0034		144 in²	<10.0 µg/ft²	
LW-32	ROOM C832 SLOP SINK	0035		144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106518

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn.	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/06/02 5:56 PM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030210730
Project:	M-477-15217/ 29881/ NYC SCA/ STUYVESANT H.S.	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		*Lab ID*	*Analyzed*	*Area Sampled*	*Lead Concentration*	*Notes*
	FLOOR-CENTER					
FB-4	Field blank	0036		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102981

NYC-WTC_000106519

NYC-WTC_000106520

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21001 RJ 1 87

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Sanoj	SAMPLER (SIGNATURE)	DATE 8/7/02 TIME
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St N.Y.	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie	SAMPLE(S) SEALED (YES) NO; CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT, µg/ft²
	LW-01	ROOM 704 - FLOOR Center of Room	1				X	<9.0
	LW-02	ROOM 704 - Table Top Center of EAST Lab Table	1				X	<9.0
	LW-03	ROOM 702 - FLOOR 3' S of entrance	1				X	<9.0
	LW-04	ROOM 702 - Table Top Computer Table	1				X	<9.0
	LW-05	ROOM 702 A - FLOOR Center of Room	1				X	<9.0
	LW-06	ROOM 702 A - Metal Shelf EAST side of Room	1		X			<9.0
	LW-07	ROOM 701 - FLOOR 3' S of ENTRANCE	1				X	<9.0
	LW-08	ROOM 701 A - Table Top Center Table	1				X	<9.0

FAX TO 212-406-2535 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/8/02 TIME 0045	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE) R. Droudina	DATE 8.8.2 TIME 00.45	PRINTED NAME R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_000106521

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SANOJ	SAMPLER (SIGNATURE): [signature] DATE: 8/7/02 TIME:	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.	PROJECT #: M477-1521?-2988/	SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT, µg/ft²
	LW-09	ROOM 703 - FLOOR 2' west of NE unitvent	1				X	<9.0
	LW-10	ROOM 703 - Table Top FRONT (Teacher) Lab Table	1				X	<9.0
	LW-11	ROOM 707 - FLOOR 3' of ENTRANCE	1				X	<9.0
	LW-12	ROOM 707 - Table Top Center Lab Table	1				X	<9.0
	LW-13	ROOM 709 - FLOOR 2' west of EAST CABINET	1				X	<9.0
	LW-14	ROOM 709 - Sink Top of NE Lab Sink	1				X	<9.0
	LW-15	ROOM 701A - FLOOR Center of ROOM	1				X	<9.0
	LW-16	ROOM 701A - Top of EAST center File Cabinet	1		X			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/8/02 TIME 00:45	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE): R. Broudina	DATE 8.8.02 TIME 00.45	PRINTED NAME: R. Broudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106522

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER [SIGNATURE]	DATE	TIME	SAMPLE[S] SEALED
NYC EDC A	Hamid Sanoj		8/7/02		(YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.	PROJECT # M477-15217-29881	SAMPLER[NAME PRINT] Kirk McKenzie			CORRECT CONTAINER[S] (YES) NO
		MATRIX [CIRCLE ONE]: (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:				SURFACE MATERIAL				
LABORATORY #	SAMPLE #	LOCATION	AREA [FT²]	WOOD	METAL	BRICK	OTHER	LAB RESULT
	FBL-1	Field Blank						<9.0
	FBL-2	Field Blank						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY [SIGNATURE]	DATE 8/8/02 TIME 0045	PRINTED NAME Kirk McKenzie	RECEIVED BY [SIGNATURE]	DATE TIME	PRINTED NAME
RELINQUISHED BY [SIGNATURE]	DATE TIME	PRINTED NAME	RECEIVED BY LAB [SIGNATURE] R. Drozdina	DATE 8.8.02 TIME 0045	PRINTED NAME R. Drozdina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-08-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-07-02
DATE RECEIVED:	08-08-02
DATE ANALYZED:	08-08-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	21001	Room 704 - Floor, Center of Room	<9.0	9.0
LW-02	21001	Room 704 - Table Top, Center of E Lab Table	<9.0	9.0
LW-03	21001	Room 702 - Floor, 3' of Unit Vent	<9.0	9.0
LW-04	21001	Room 702 - Table Top, Computer Table	<9.0	9.0
LW-05	21001	Room 702A - Floor, Center of Room	<9.0	9.0
LW-06	21001	Room 702A - Metal Shaft, E side of Room	<9.0	9.0
LW-07	21001	Room 701 - Floor, 3' of Entrance	<9.0	9.0
LW-08	21001	Room 701 - Table Top, Center Table	<9.0	9.0
LW-09	21001	Room 703 - Floor, 2' W of NE Unit Vent	<9.0	9.0
LW-10	21001	Room 703 - Table Top, Front (Teachers) Lab Table	<9.0	9.0
LW-11	21001	Room 707 - Floor, 3' of Entrance	<9.0	9.0
LW-12	21001	Room 707 - Table Top, Center Lab Table	<9.0	9.0
LW-13	21001	Room 709 - Floor, 2' W of E Cabinet	<9.0	9.0
LW-14	21001	Room 709 - Sink Top, NE Lab Sink	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-15	21001	Room 701A - Floor, Center of Room	<9.0	9.0
LW-16	21001	Room 701A - Top of E Center File Cabinet	<9.0	9.0
FB-1	21001	Field Blank	<9.0 µg	9.0 µg
FB-2	21001	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106525

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21023

1 of 3

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE)	DATE 8/8/02 TIME	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST. N.Y.	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie		CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT mg/ft²
	LW-01	ROOM 711 - FLOOR Center of Bathroom	1				X	<9.0
	LW-02	ROOM 713 - FLOOR Center of Bathroom	1				X	<9.0
	LW-03	ROOM 705 - FLOOR 3' north of South wall cabinet	1				X	<9.0
	LW-04	ROOM 705 - Table Top North side Lab Table	1				X	<9.0
	LW-05	ROOM 715 - FLOOR	1				X	<9.0
	LW-06	ROOM 715 - Desk Top SE Desk	1				X	<9.0
	LW-07	ROOM 717 - FLOOR 3' of MAIN ENTRANCE	1				X	<9.0
	LW-08	ROOM 717 - Table Top Teachers Table	1				X	<9.0

Fax to 212-406-2535 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/9/02 TIME 0430	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE 8.9.02 TIME 4:52	PRINTED NAME W. Plaw
RELINQUISHED BY (SIGNATURE)	DATE 8.9.02 TIME 5:00	PRINTED NAME W Plaw	RECEIVED BY LAB (SIGNATURE) ATC by A. Elbert	DATE 08.09.02 TIME 5:15 pm	PRINTED NAME A. Elbert

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106526

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21023 2 of 3

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): [signature] DATE: 8/8/02 TIME:	SAMPLE(S) SEALED (YES) / NO
		SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S) (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST. NY	PROJECT #: M477-1527-29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-09	Room 719 - Floor 6' of Entrance					X	<9.0
	LW-10	Room 719 - Book Shelf East side			X			<9.0
	LW-11	Room C-721 - Floor west side center					X	<9.0
	LW-12	Room 727 - Floor 2' of west univent					X	<9.0
	LW-13	Room 727 - Table Top West sink table					X	<9.0
	LW-14	Room 727A - Floor Center of Room					X	<9.0
	LW-15	Room 727A - Shelf north side shelf.			X			<9.0
	LW-16	Room 728 - Floor Center of Room					X	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 8 HR TAT

RELINQUISHED BY (SIGNATURE): [signature]	DATE: 8/9/02 TIME: 0430	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE): [signature]	DATE: 8.9.02 TIME: 4:27	PRINTED NAME: W Phu
RELINQUISHED BY (SIGNATURE): W Phu	DATE: 8.9.02 TIME: 5:15	PRINTED NAME: W. Phu	RECEIVED BY LAB (SIGNATURE): ATC by A. Elbert	DATE: 08.09.02 TIME: 5:45 pm	PRINTED NAME: A. Elbert

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106527

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21023 383

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Sanoj	SAMPLER (SIGNATURE): [signature] DATE: 8/8/02 TIME:	SAMPLE(S) SEALED: (YES) NO
		SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S): (YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST NY	PROJECT #: M477-15217-2988	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-17	ROOM 726 - FLOOR	1				X	<9.0
	LW-18	ROOM 726 Table Top SW side of ROOM	1				X	<9.0
	LW-19	ROOM C728 - FLOOR Service Elev. Lobby	1				X	<9.0
	LW-20	ROOM 730 - FLOOR Center of Bath Room	1				X	<9.0
	FBL-1	Field Blank						
	FBL-2	Field Blank						

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	8/9/02 1430	Kirk McKenzie	W. Ohl	8.9.02	W. Ohl
W. Ohl	8.9.02 1515		[signature] for A. Ebert	08.09.02 1515	A. Ebert

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-09-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217-29881

SAMPLED BY: Client

SAMPLE DATE: 08-08-02
DATE RECEIVED: 08-09-02
DATE ANALYZED: 08-09-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	21023	Rm 711 Floor Center of Bathroom	<9.0	9.0
LW-02	21023	Rm 713 Floor Center of Bathroom	<9.0	9.0
LW-03	21023	Rm 705 Floor 3' North of South Wall Cabinet	<9.0	9.0
LW-04	21023	Rm 705 Table Top North Side Lab Table	<9.0	9.0
LW-05	21023	Rm 715 Floor	<9.0	9.0
LW-06	21023	Rm 715 Desk Top SE Desk	<9.0	9.0
LW-07	21023	Rm 717 Floor 3' of Main Entrance	<9.0	9.0
LW-08	21023	Rm 717 Table Top Teachers Table	<9.0	9.0
LW-09	21023	Rm 719 Floor 6' of Entrance	<9.0	9.0
LW-10	21023	Rm 719 Book Shelf East Side	<9.0	9.0
LW-11	21023	Rm C721 Floor West Side Center	<9.0	9.0
LW-12	21023	Rm 727 Floor 2' of West Unitvent	<9.0	9.0
LW-13	21023	Rm 727 Table Top West Sink Table	<9.0	9.0
LW-14	21023	Rm 727A Floor Center of Room	<9.0	9.0
LW-15	21023	Rm 727A Shelf North Side Shelf	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-16	21023	Rm 728 Floor Center of Room	<9.0	9.0
LW-17	21023	Rm 726 Floor	<9.0	9.0
LW-18	21023	Rm 726 Floor Table Top SW Side of Room	<9.0	9.0
LW-19	21023	Rm C728 Floor Service Elev. Lobby	<9.0	9.0
LW-20	21023	Rm 730 Floor Center of Bathroom	<9.0	9.0
FB-1	21023	Field Blank	<9.0 µg	9.0 µg
FB-2	21023	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106530

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

0302/0902

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAVOJ	SAMPLER(S) SIGNATURE: [signature] DATE: 8/8/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST NY	PROJECT #: M477-15217-2988	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT (µg/ft²)
	LW-21	ROOM C732 - FLOOR Center of Room	1				X	<10.0
	LW-22	Room 734 - FLOOR Center of Room	1				X	<10.0
	LW-23	ROOM 736 - FLOOR 2' EAST of EAST wall	1				X	<10.0
	LW-24	ROOM 736 - Table Top Teacher Table	1				X	<10.0
	LW-25	ROOM 738 - FLOOR 3' of EAST ENTRANCE	1				X	(a) ~~<10.0~~ <10.0
	LW-26	ROOM 738 - Desk Top SW Desk	1				X	11.0
	LW-27	Room 740 - FLOOR South of Teacher Table	1				X	<10.0
	LW-28	ROOM 740 - Table Top Teacher Table	1				X	10.0

EMSL HARTFORD RECEIVED 02 AUG -9 AM 5:34

FAX TO 212-406-2535 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

	DATE	PRINTED NAME		DATE	PRINTED NAME
RELINQUISHED BY (SIGNATURE): [signature]	DATE 8/8/02 TIME 0500	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE):	TIME	
RELINQUISHED BY (SIGNATURE): [signature]	DATE 8.9.02 TIME 5:45	PRINTED NAME: TERESA MICHELSON	RECEIVED BY LAB (SIGNATURE):	TIME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/09/2002 11:25 212-290-2538 EMSL ANALYTICAL INC PAGE 04/07

NYC-WTC_000106531

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021090Z

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA
CONTACT: HAMID SAND
SAMPLER SIGNATURE: [signature] DATE: 8/8/02 TIME:
SAMPLER NAME (PRINT): Kirk McKenzie
SAMPLE(S) SEALED: (YES) / NO
CORRECT CONTAINER(S): (YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St NY
PROJECT #: M477-15217-Z9881
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/FR
	LW-29	ROOM 739 - FLOOR 2'S WEST univent	1				X	<10.0
	LW-30	ROOM 739 - Desk Top Rear Desk - North end	1				X	<10.0
	LW-31	ROOM 737 - FLOOR 6'S EAST ENTRANCE	1				X	<10.0
	LW-32	ROOM 732 - Table Top Center of Tarchum Table.	1				X	10.0
	LW-33	ROOM 735 - FLOOR North of EAST univent	1				X	12.0
	LW-34	ROOM 735 - Desk Top North Front Desk - South END	1				X	<10.0
	LW-35	ROOM 731 - FLOOR 2'S of WEST univent	1				X	<10.0
	LW-36	ROOM 731 - Table Top Center of Lab Table (WEST LAB TABLE)	1				Y	<10.0

EMSL MANHATTAN RECEIVED 02 AUG -9 AM 5:34

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /
COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	DATE 8/9/02 TIME 0500	Kirk McKenzie			
RELINQUISHED BY (SIGNATURE) [signature]	DATE 8.9.02 TIME 8:45	PRINTED NAME TERRY MCMAHON	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/09/2002 11:25 212-298-2538 EMSL ANALYTICAL INC PAGE 05/07

NYC-WTC_000106532

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021D902

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SANJ	SAMPLER (SIGNATURE):	DATE: 8/8/02 TIME:
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST NY	PROJECT #: M477-15217-2988	SAMPLER NAME (PRINT): Kirk McKenzie	SAMPLE(S) SEALED: (YES) / NO; CORRECT CONTAINER(S): (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/FT²
	LW-37	ROOM 729 - Floor Center of Room	1				X	<10.0
	LW-38	ROOM 729 -- Lab Table Top by sink	1				X	<10.0
	LW-39	Locker # 7-93 Floor of locker	1		X			<10.0
	LW-40	CORRIDOR - O/S RM 740 EAST ENTRANCE. (FLOOR)	1				X	<10.0
	LW-41	CORRIDOR - FLOOR 14' (EAST) Room 719	1				X	<10.0
	LW-42	CORRIDOR - FLOOR O/S ROOM 707	1				X	<10.0
	FBL-3	Field Blank						
	FBL-4	Field Blank						

EMSL MANHATTAN - RECEIVED 02 AUG-9 PM 5:34

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/9/02 TIME 0500	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8.9.02 TIME 5:45	PRINTED NAME TERRY MCMILLAN	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/09/2002 11:25 212-290-2538 EMSL ANALYTICAL INC PAGE 05/07

NYC-WTC_000106533

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

0602109O7 494

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Savoj		8/8/02		YES / NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St NY	PROJECT # M477-15 217-2988	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	FBL-B	Field Blank						

EMSL MANHATTAN
RECEIVED
02 AUG -9 AM 5:34

TURNAROUND REQUIRED:
NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS
6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/8/02 TIME 0500	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/09/2002 11:25 212-298-2538 EMSL ANALYTICAL INC PAGE 07/07

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217-29881 / NYC SCA / STUYVESANT H.S. / 345 CHAMBERS ST. NY.

Customer ID: TAYL50
Customer PO:
Received: 08/09/02 5:34 AM
EMSL Order: 030210902
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-21	ROOM C732 / FLOOR / CENTER ROOM	0001		144 in²	<10.0 µg/ft²	
LW-22	ROOM 734 / FLOOR / CENTER ROOM	0002		144 in²	<10.0 µg/ft²	
LW-23	ROOM 736 / FLOOR / 2 IN.EAST OF EAST UNIT VENT	0003		144 in²	<10.0 µg/ft²	
LW-24	ROOM 736 / TABLE TOP / TEACHEN TABLE	0004		144 in²	<10.0 µg/ft²	
LW-25	ROOM 738 / FLOOR / 3 INCHES OF EAST ENTRANCE	0005		144 in²	<10.0 µg/ft²	
LW-26	ROOM 738 / DESK TOP / SW DESK	0006		144 in²	11.0 µg/ft²	
LW-27	ROOM 740 / FLOOR / SOUTH OF TEACHER TABLE	0007		144 in²	<10.0 µg/ft²	
LW-28	ROOM 740 / TABLE TOP / TEACHEN TABLE	0008		144 in²	10.0 µg/ft²	
LW-29	ROOM 739 / FLOOR / 2 INCH OF WEST UNIT VENT	0009		144 in²	<10.0 µg/ft²	
LW-30	ROOM 739 / DESK TOP / REAR DECK / N. END	0010		144 in²	<10.0 µg/ft²	
LW-31	ROOM 737 / FLOOR / 6 INCH. OF E. ENTRANCE	0011		144 in²	<10.0 µg/ft²	
LW-32	ROOM 732 / TABLE TOP / CENTER OF TEACH TABL	0012		144 in²	10.0 µg/ft²	
LW-33	ROOM 735 / NORTH OF EAST UNIT VENT	0013		144 in²	12.0 µg/ft²	
LW-34	ROOM 735 / DESK TOP / N. FRONT DESK / S. END	0014		144 in²	<10.0 µg/ft²	
LW-35	ROOM 731 / FLOOR / 2 INCH. OF WEST UNIT	0015		144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106534

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900068 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group. Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217-29881 / NYC SCA / STUYVESANT H.S. / 345 CHAMBERS ST. NY.

Customer ID: TAYL50
Customer PO:
Received: 08/09/02 5:34 AM
EMSL Order: 030210902
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
	VENT					
LW-36	ROOM 731 / TABLE TOP / CENTER OF LAB TABLE	0016		144 in²	<10.0 µg/ft²	
LW-37	ROOM 729 / FLOOR / CENTER OF ROOM	0017		144 in²	<10.0 µg/ft²	
LW-38	ROOM 729 / LAB TABLE / TOP BY SINK	0018		144 in²	<10.0 µg/ft²	
LW-39	LOCKER #7-93 / FLOOR OF LOCKER	0019		144 in²	<10.0 µg/ft²	
LW-40	CORRIDOR / O/S RM 740 E. ENTRANCE / FLOOR	0020		144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106535

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Take.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217-29881 / NYC SCA / STUYVESANT H.S. / 345 CHAMBERS ST. NY.

Customer ID: TAYL50
Customer PO:
Received: 08/09/02 5:34 AM
EMSL Order: 030210902
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-41	CORRIDOR / FLOOR 14 INCH. EAST OF RM 719	0021		144 in²	<10.0 µg/ft²	
LW-42	CORRIDOR / FLOOR / O/S ROOM 707	0022		144 in²	<10.0 µg/ft²	
FBL-3	Field blank	0023		n/a	<10.0 µg/wipe	
FBL-4	Field blank	0024		n/a	<10.0 µg/wipe	
FBL-3	Field blank	0025		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106536

NYC-WTC_000106537

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2905 ?? 1502

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Shojaei	SAMPLER (SIGNATURE)	DATE 8/11/02 TIME	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St. NY	PROJECT # 14477-15217-2988	SAMPLER NAME (PRINT) Kirk McKenzie		CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	ROOM 601 - FLOOR Center of ROOM	1				X	<9.0
	LW-02	ROOM 601 - Table Top South side Table	1				X	<9.0
	LW-03	ROOM 601A - FLOOR 3' of ENTRANCE	1				X	<9.0
	LW-04	ROOM 601A - Top of File Cabinet	1		X			<9.0
	LW-05	ROOM 601B - FLOOR 10' of ENTRANCE	1				X	<9.0
	LW-06	ROOM 601B - Top of File Table	1				X	<9.0
	LW-07	ROOM C621 - FLOOR Right of Entrance	1				X	<9.0
	LW-08	ROOM C623 - FLOOR CENTER OF ROOM	1				X	<9.0

FAX to 212-406-2535 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/11/02 TIME 0440	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) ATC Lab /	DATE 08/11/02 TIME 04:40	PRINTED NAME D. KOGAN
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT SAMPLES TO CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106538

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2 of 2

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Sinoj	SAMPLER (SIGNATURE)	DATE 8/11/02 TIME
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St NY	PROJECT # M477-15217-2988/	SAMPLER NAME (PRINT): Kirk McKenzie	SAMPLE(S) SEALED (YES / NO); CORRECT CONTAINER(S) (YES / NO)
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09	6th Floor Corridor O/S Room 615 Main Entr.-Floor	1				Y	<9.0
	LW-10	6th Floor Corridor O/S Room 601 - Floor	1				X	<9.0
	LW-11	Locker # 6-53 Floor of Locker	1		X			<9.0
	LW-12	Room C632 (Slop sink) Floor	1				X	<9.0
	FBL-1	Field Blank						<9.0
	FBL-2	Field Blank						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/12/02 TIME 0440	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) ATC Lab / Rokosol	DATE 08/11/02 TIME 0440	PRINTED NAME D. Kogan
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

AIC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-12-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-11-02
DATE RECEIVED:	08-11-02
DATE ANALYZED:	08-11-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	21059	Rm 601 Floor Centre of Room	<9.0	9.0
LW-02	21059	Rm 601 Table Top South Side Table	<9.0	9.0
LW-03	21059	Rm 601A Floor 3' of Entrance	<9.0	9.0
LW-04	21059	Rm 601A Top of File Cabinet	<9.0	9.0
LW-05	21059	Rm 601B Floor 10' of Entrance	<9.0	9.0
LW-06	21059	Rm 601B Top of File Table	<9.0	9.0
LW-07	21059	Rm C621 Floor Right of Entrance	<9.0	9.0
LW-08	21059	Rm C623 Floor Center of Room	<9.0	9.0
LW-09	21059	6th Floor Corridor O/S Rm 615 Mqain Ent. Floor	<9.0	9.0
LW-10	21059	6th Floor Corridor O/S Rm 601 Floor	<9.0	9.0
LW-11	21059	Locker #6-53 Floor of Locker	<9.0	9.0
LW-12	21059	Rm C632 (Slop Sink) Floor	<9.0	9.0
FBL-1	21059	Field Blank	<9.0 µg	9.0 µg
FBL-2	21059	Field Blank	<9.0 µg	9.0 µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft². Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RD

REPORT PREPARED BY: [signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: [signature]

LABORATORY DIRECTOR: [signature]

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_00010541

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

184

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAWOJ		08.09.02		YES / NO
PROJECT LOCATION: STUYVESANT HS 345 CHAMBERS ST NY. NY	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) KIRK MC KENZIE			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-01	ROOM 627 - FLOOR 2' OF EAST UNIVENT	1				X	<10.0
	LW-02	ROOM 627 - TOP OF File cabinet	1		X			<10.0
	LW-03	ROOM 627A - Floor Center OF ROOM	1				X	11.0
	LW-04	ROOM 627A - Desk Top	1				X	14.0
	LW-05	ROOM 625 - FLOOR By ENTRANCE	1				X	<10.0
	LW-06	ROOM 629 - FLOOR 3' OF EAST ENTRANCE	1				X	<10.0
	LW-07	ROOM 629 - Desk Top NE Desk.	1				X	<10.0
	LW-08	ROOM 635 - FLOOR 3' OF WEST UNIVENT	1				X	<10.0

EMSL ANALYTICAL INC
RECEIVED
02 AUG 10 PM 4:33

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/10/02 TIME 0115	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 08.10 TIME 5.00	PRINTED NAME FERRER MICHELLE	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

FAX TO: 212 406-2535 & 516 358-1780

PAGE 09/14
EMSL ANALYTICAL INC
212-290-2538
08/10/2002 09:48
NYC 9/11 Public Portal Document

NYC-WTC_000106542 PAGE 10/14
EMSL ANALYTICAL INC 212-290-2538 08:48 08/10/2002
NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

294

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAWOY		08.8.02		(YES) / NO
PROJECT LOCATION: STUY NOGANT HS 345 CHAMBERS ST. NY NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) KIRK MC KENZIE			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09	Room 635 - Table Top Teachers Table	1				X	10.0
	LW-10	Room 633 - Floor Center of Room	1				X	<10.0
	LW-11	Room 639 - Floor Center of Room	1				X	<10.0
	LW-12	Room 639 - Top of File Cabinet	1		X			<10.0
	LW-13	Room C.637 - Floor Center of Room	1				X	<10.0
	LW-14	Room 631 - Floor Center of Room	1				X	<10.0
	LW-15	Room 640 - Floor 2' off SE cabinet	1				X	11.0
	LW-16	Room 640 - Desk Top SE Desk	1				X	<10.0

EMSL MANHATTAN RECEIVED 02 AUG 10 AM 4:33

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/10/02 TIME 0115	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8.10.02 TIME 0530	PRINTED NAME TERESA MICHELUCCI	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

FAX TO 212 406-2935

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_00010543 PAGE 11/14 EMSL ANALYTICAL INC 212-290-2538 08/10/2002 09:48

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAWOJ		08.08.02		(YES) / NO
PROJECT LOCATION: STUYVESANT HS 345 CHAMBERS ST. NY. NY	PROJECT # M477-15217-24881	SAMPLER NAME (PRINT) KIRK MC KENZIE			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT mg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-17	ROOM 638 - FLOOR at north center column	1				X	<10.0
	LW-18	ROOM 638 - TABLE TOP Teachers table	1				X	<10.0
	LW-19	ROOM 636 - FLOOR 3' of WEST ENTRANCE	1				X	12.0
	LW-20	ROOM 636 - Desk Top NE Desk	1				X	<10.0
	LW-21	ROOM 634 - FLOOR 3' OF ENTRANCE	1				X	<10.0
	LW-22	ROOM 630 - FLOOR CENTER OF ROOM	1				X	<10.0
	LW-23	ROOM C628 - FLOOR 3' of Service Elevator	1				X	<10.0
	LW-24	Locker # 6-127 Locker FLOOR.	1		X			10.0

EMSL MANHATTAN RECEIVED 02 AUG 10 AM 4:33

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /	COMMENTS / INSTRUCTIONS 6 HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/10/02 TIME 0115	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/10/02 TIME 5:00	PRINTED NAME TERESA MICHIMOVIL	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

FAX TO 212 406-2935 & 516 358-1780

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106544 PAGE 12/14
EMSL ANALYTICAL INC 212-290-2538
08/10/2002 09:48
NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE , FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

05021077C

T 0 T

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE 8/10/02	TIME	SAMPLE(S) SEALED (YES) NO
NYC SCA	HAMID SANDJ				
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St N.Y.	PROJECT # M477-05217-2988	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-25	6th Floor Corridor Between Rooms 636 & 629	1				X	<10.0
	FBL-1	Field Blank						
	FBL-2	Field Blank						
	FBL-3	Field Blank						

EMSL MANHATTAN RECEIVED
02 AUG 10 PM 4:33

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/10/02 TIME 0115	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE) Tim Zak	DATE 08.10.02 TIME 5:00	PRINTED NAME TERESA MICHALSKI	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn.	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/10/02 8:45 AM
Fax:	(516) 358-1780 Phone: 516-358-2955		
Project:	NYC SCA/Stuyvesant H.S. 345 Chambers St., New York, N.Y./M477-15217-29881.	EMSL Order:	030210972
		EMSL Project ID.	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		*Lab ID*	*Analyzed*	*Area Sampled*	*Lead Concentration*	*Notes*
LW-01	Room 627-Floor 2' of East Unit Vent	*0001*		144 in²	<10.0 µg/ft²	
LW-02	Room 627-Top of File Cabinet	*0002*		144 in²	<10.0 µg/ft²	
LW-03	Room 627A-Floor Center of Room	*0003*		144 in²	11.0 µg/ft²	
LW-04	Room 627A-Desk Top	*0004*		144 in²	14.0 µg/ft²	
LW-05	Room 625-Floor by Entrance	*0005*		144 in²	<10.0 µg/ft²	
LW-06	Room 629- Floor 3' of East Entrance	*0006*		144 in²	<10.0 µg/ft²	
LW-07	Room 629-Desk Top NE Desk	*0007*		144 in²	<10.0 µg/ft²	
LW-08	Room 635-Floor 3" of West Unit Vent	*0008*		144 in²	<10.0 µg/ft²	
LW-09	Room 635-Table Top Teachers Table	*0009*		144 in²	10.0 µg/ft²	
LW-10	Room 633- Floor Center of Room	*0010*		144 in²	<10.0 µg/ft²	
LW-11	Room 639-Floor Center of Room	*0011*		144 in²	<10.0 µg/ft²	
LW-12	Room 639-Top of Filing Cabinet	*0012*		144 in²	<10.0 µg/ft²	
LW-13	Room C637-Floor Center of Room	*0013*		144 in²	<10.0 µg/ft²	
LW-14	Room 631-Floor Center of Room	*0014*		144 in²	<10.0 µg/ft²	
LW-15	Room 640-Floor 2' of SE Cabinet	*0015*		144 in²	11.0 µg/ft²	
LW-16	Room 640-Desk Top SE Desk	*0016*		144 in²	<10.0 µg/ft²	
LW-17	Room 638-Floor at North Center Column	*0017*		144 in²	<10.0 µg/ft²	
LW-18	Room 638-Table Top	*0018*		144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106545

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900052 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: NYC SCA/Stuyvesant H.S. 345 Chambers St., New York, N.Y./M477-15217-29881.

Customer ID: TAYL50
Customer PO:
Received: 08/10/02 8:45 AM
EMSL Order: 030210972
EMSL Project ID.

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
	Teachers Table					
LW-19	Room 636-Floor 3' of West Entrance	0019		144 in²	12.0 µg/ft²	
LW-20	Room 636-Desk Top NE Desk	0020		144 in²	<10.0 µg/ft²	
LW-21	Room 634-Floor 3' of Entrance	0021		144 in²	<10.0 µg/ft²	
LW-22	Room 630-Floor Center of Room	0022		144 in²	<10.0 µg/ft²	
LW-23	Room C628-Floor 3' of Service Elevator	0023		144 in²	<10.0 µg/ft²	
LW-24	Locker #6-127 Locker Floor	0024		144 in²	10.0 µg/ft²	
LW-25	6th Floor Corridor Between Rms 636&629.	0025		144 in²	<10.0 µg/ft²	
LW-26	Filed Blank	0026		n/a	<10.0 µg/wipe	
LW-27	Field Blank	0027		n/a	<10.0 µg/wipe	
LW-28	Field blank	0028		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106546

NYC-WTC_00010947

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021087

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Sadj		8/11/02		YES / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. NY.	PROJECT # M477-1521?-2988/	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-13	Gym (G-680) - Floor 6' of entrance	1				X	<10.0
	LW-14	Gym (G-680) - East side Ledge.	1				X	<10.0
	LW-15	G-680A - Floor Center of Room	1				X	<10.0
	LW-16	G-680A - Shelf Top SE side	1		X			<10.0
	LW-17	G-680B - Floor Center of Room	1				X	<10.0
	LW-18	G-680B - ~~Shelf~~ Top Cabinet East side	1		X			<10.0
	LW-19	G-680C - Floor by entrance	1				X	<10.0
	LW-20	G-680D - Floor by entrance	1				X	<10.0

02 AUG 11 AM 4:55
EMSL-MANHATTAN
RECEIVED

Fax To: 212-406-2535 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/11/02 TIME 0500	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

PAGE 02/03
EMSL ANALYTICAL INC
212-290-2538
08/11/2002 15:29
NYC 9/11 Public Portal Document

NYC-WTC_00010948

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

08021103?

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SANOJ		8/11/02		(YES) / NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St. N.Y	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT µg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-21	G 680 E - Floor Center	1				X	<10.0
	~~FBL-1~~ LW-22	Field Blank	—					
	FBL-2	Field Blank	—					
	LW-22	G-680 D - Shelf Top	1		X			<10.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 8 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/11/02 TIME 0500	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

02 AUG 11 AM 4:53
CHSL MANHATTAN
RECEIVED

EMSL ANALYTICAL INC 212-290-2538 08/11/2002 15:29 PAGE 03/03

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke
Floral Park, NY 11001

Fax: (516) 358-1780 Phone: 516-358-2955

Project: M477-15217-29881 / Stuyvesant H.S. 345 Chambers St. NY. / NYC SCA

Customer ID: TAYL50
Customer PO:
Received: 08/11/02 5:53 AM
EMSL Order: 030211037
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-13	GYM (G680) FLOOR 6 OF ENTRANCE	0001	8/11/02	144 in²	<10.0 µg/ft²	
LW-14	GYM (G680) EAST SIDE LEDGE	0002	8/11/02	144 in²	<10.0 µg/ft²	
LW-15	G680 A FLOOR CENTER OF ROOM	0003	8/11/02	144 in²	<10.0 µg/ft²	
LW-16	G680 A SHELF TOP SE SIDE	0004	8/11/02	144 in²	<10.0 µg/ft²	
LW-17	G680 B FLOOR CENTER OF ROOM	0005	8/11/02	144 in²	<10.0 µg/ft²	
LW-18	G680 B TOP CABINET EAST SIDE	0006	8/11/02	144 in²	<10.0 µg/ft²	
LW-19	G680 C FLOOR BY ENTRANCE	0007	8/11/02	144 in²	<10.0 µg/ft²	
LW-20	G680 D FLOOR BY ENTRANCE	0008	8/11/02	144 in²	<10.0 µg/ft²	
LW-21	G680 E FLOOR CENTER	0009	8/11/02	144 in²	<10.0 µg/ft²	
FBL1	Field blank	0010	8/11/02	n/a	<10.0 µg/wipe	
FBL2	Field blank	0011	8/11/02	n/a	<10.0 µg/wipe	
LW-22	G680 D SHELF TOP	0012	8/11/02	144 in²	<10.0 µg/ft²	

M. Apfelbaum
Laboratory Manager or other approved signatory / ANALYST

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106549

NYC-WTC_000106550

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2104L

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYCSCA STUYVESANT H.S.	CONTACT: HAMID SAWAT	SAMPLER (SIGNATURE): Carlos Tofet	DATE: 8/9/02	TIME: 1140
		SAMPLER NAME (PRINT): CARLOS TOFET		SAMPLE(S) SEALED: YES / NO
PROJECT LOCATION: CHAMBERS ST, NY, NY	PROJECT #: M477-1521/29881			CORRECT CONTAINER(S): YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	6TH FL DANCE STUDIO FLOOR ADJ. LEFT WINDOW	1.0	X				<9.0
	LW-02	6TH FL DANCE STUDIO TABLE TOP - R.H.S.	1.0	X				<9.0
	FB-1	F/BLANK	—					<9.0
	FB-2	F/BLANK	—					<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE): Carlos Tofet	DATE: 8-9-02 TIME:	PRINTED NAME:	RECEIVED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: TIME: 530	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE): ATC Lab / [illegible]	DATE: 08/09/02 TIME: 17.30	PRINTED NAME: D. KOGAN

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-12-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-09-02
DATE RECEIVED:	08-09-02
DATE ANALYZED:	08-09-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	21042	6th Floor Dance Studio Floor Adj.Left Window	<9.0	9.0
LW-02	21042	6th Floor Dance Studio Table Top R.H.S.	<9.0	9.0
FB-1	21042	Field Blank	<9.0 µg	9.0 µg
FB-2	21042	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879). (AIHA #100229).

NYC-WTC_000106552

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030210969

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYCSCA	Hamid Savaj		8/9/02		YES / NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St N.Y.	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE) WIPE PAINT SOIL OTHER			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-01	ROOM 660 (DANCE STUDIO) FLOOR - 6' @ ENTRANCE	1	X				<10.0
	~~FBL-1~~	Field Blank						
	FBL-2	Field Blank						

µg/FT²

RECEIVED
02 AUG 10 AM 4:33
EMSL ANALYTICAL INC
NEW HAMPTON

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE	PRINTED NAME
	8/9/02	Kirk McKenzie			
	TIME 0115			TIME	
RELINQUISHED BY (SIGNATURE)	DATE 8.10.02	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE	PRINTED NAME
	TIME 0500	TERESA MCMENAMIN		TIME	

FAX RESULTS TO: QTI INC

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

PAGE 01/14
EMSL ANALYTICAL INC 212-290-2538
08/10/2002 08:48
NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: NYC SCA/Stuyvesant H.S. 345 Chambers St., New York, N.Y./M477-15217-29881.

Customer ID: TAYL50
Customer PO:
Received: 08/10/02 8:18 AM
EMSL Order: 030210969
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	Room 660	0001		144 in²	<10.0 µg/ft²	
FBL-1	Field blank	0002		n/a	<10.0 µg/wipe	
FBL-2	Field blank	0003		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106553

NYC-WTC_000106554

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030211095

1 of 4

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Saeed		8/12/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217/29881	AL. KAZAKOV			(YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	Rm 507 TEACHER'S DESK	1				X	<10.0
	LW-02	Rm 507 FLOOR SW NEAR WINDOW	1				X	<10.0
	L-W-03	Rm 505 TEACHER'S DESK	1				X	<10.0
	LW-04	Rm 505 FLOOR NEAR EAST DOOR	1				X	<10.0
	LW-05	Rm 503 TEACHER'S DESK	1				X	<10.0
	LW-06	Rm 503 FLOOR SE NEAR WINDOW	1				X	<10.0
	LW-07	Rm 001B REFRIGERATOR TOP	1		X		X	<10.0
	LW-08	Rm 501B FLOOR SE NEAR WINDOW	1				X	<10.0

EMSL-MANHATTAN RECEIVED 02 AUG 12 PM 4:50

Fax results to Taylor on site (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr. TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8-12-02 1600			8/12/2	
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/12/02 1650				

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/12/2002 21:14 212-290-2538 EMSL ANALYTICAL INC PAGE 03/06

NYC-WTC_000106555

NYC 9/11 Public Portal Document
08/12/2002 21:14 212-298-2538 EMSL ANALYTICAL INC PAGE 04/05

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE , FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021095

1 of 4

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA.	CONTACT: HAMID SAADJ.	SAMPLER (SIGNATURE): Carlos Cayford DATE: 8-12-02. TIME:	SAMPLE(S) SEALED: YES / NO
PROJECT LOCATION: STUYVESANT H S.	PROJECT #: M477-15217 / 24881	SAMPLER NAME (PRINT): CARLOS JOYCE	CORRECT CONTAINER(S): YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-09	Rm 501 F FLOOR UNDER SINK	1				X	<10.0
	LW-10	Rm 501 C TOP of LOCKER # 94	1		X			<10.0
	LW-11	Rm 501 C FLOOR NEAR LOCKER # 91	1				X	<10.0
	LW-12	Rm 501 E FLOOR SHOWER AREA	1				X	<10.0
	LW-13	Rm 501 A BOOK CABINET	1	X				<10.0
	LW-14	Rm 501 A FLOOR NEAR MIDDLE WINDOW	1				X	<10.0
	LW-15	Rm 502 B SHELF AT ENTRANCE	1		X			<10.0
	LW-16	Rm 502 B FLOOR BELOW CABINETS	1					<10.0

FAX Results to (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE): Carlos Cayford	DATE: 8-12-02 TIME: 1600	PRINTED NAME: C. JOYCE	RECEIVED BY (SIGNATURE): Elsa Quispe	DATE: 8/12/02 TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: 8/12/02 TIME: 1650	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE):	DATE: TIME:	PRINTED NAME:

EMSL ANALYTICAL, INC
RECEIVED
02 AUG 12 PM 4:50

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_000106556

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021095

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAADAT	SAMPLER (SIGNATURE): Carlos Tofat	DATE: 8-12-02	TIME:
PROJECT LOCATION: STUYVESANT H.S.	PROJECT #: M477-15217/24881	SAMPLER NAME (PRINT): CARLOS TOFAT	SAMPLE(S) SEALED: YES / NO	CORRECT CONTAINER(S): YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-17.	Rm 502 A TOP of FILING CABINET	1		X			<10.0
	LW-18	Rm 502 A FLOOR BENEATH COMPUTER DESK	1				X	<10.0
	LW-19.	Rm 502 TOP of CABINET	1		X			<10.0
	LW-20.	Rm 502 FLOOR NEAR ENTRANCE	1				X	<10.0
	LW-21	Rm 504 COMPUTER DESK	1				X	<10.0
	LW-22	Rm 504 FLOOR SE CORNER	1				X	<10.0
	LW-23	Rm 6582 BENCH TOP	1	X				<10.0
	LW-24	Rm 6582 FLOOR BENEATH SINK.	1				X	<10.0

FAX results to (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6HRS TAT

	DATE	PRINTED NAME
RELINQUISHED BY (SIGNATURE): Carlos Tofat	8-12-02 TIME 1600	C. J. [illegible]
RELINQUISHED BY (SIGNATURE): Tanser M	DATE TIME 1650	PRINTED NAME
RECEIVED BY (SIGNATURE): Ubi Quispe	DATE 8/12 TIME	PRINTED NAME
RECEIVED BY LAB (SIGNATURE):	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL ANALYTICAL INC
RECEIVED
02 AUG 12 PM 4:50

NYC 9/11 Public Portal Document
08/12/2002 21:14 212-290-2538

NYC-WTC_000106557

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

0302110 95

4 of 4

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAADAT.	SAMPLER (SIGNATURE): Carlos Tolat	DATE: 8-12-02 TIME:
PROJECT LOCATION: STUYVESANT H-S.	PROJECT #: 7477-15217/29881	SAMPLER NAME (PRINT): CARLOS TOLAT	SAMPLE(S) SEALED: YES / NO; CORRECT CONTAINER(S): YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-25	fm G581 TOP OF LOCKER # V53	1		X			<10.0
	LW-26	fm G581 FLOOR BENEATH MIRROR (NEAR BENCH)	1				X	<10.0
	LW-27	fm G580 TOP OF WEIGHT BENCH NEAR ENTRANCE	1				X	32.0
	LW-28	fm G580 FLOOR NEAR SE WINDOW	1				X	<10.0
	LW-29	fm G580A TOP OF LOCKER	1		X			<10.0
	LW-30	fm 580A FLOOR BY ENTRANCE	1				X	<10.0
	LW-31	FIELD BLANK						—
	LW-32	FIELD BLANK						—

EMSL MANHATTAN RECEIVED 02 AUG 12 PM 4:50

FAX RESULTS TO (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE): Carlos Tolat	DATE: 8-12-02 TIME:	PRINTED NAME:	RECEIVED BY (SIGNATURE): Edgar Quispe	DATE: 8/12/2 TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE): TAYLOR	DATE: 8.12.02 TIME: 16.50	PRINTED NAME: TERRY MICHIGAN	RECEIVED BY LAB (SIGNATURE):	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document
08/12/2002 21:14 212-298-2538 EMSL ANALYTICAL INC PAGE 05/05

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
207 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217/29881 / NYC SCA / Stuyvesant HS

Customer ID: TAYL50
Customer PO:
Received: 08/12/02 4:50 PM

EMSL Order: 030211095
EMSL Project ID.

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	Rm 507 teachers desk	0001	8/12/02	144 in²	<10.0 µg/ft²	
LW-02	Rm 507 floor SW near window	0002	8/12/02	144 in²	<10.0 µg/ft²	
LW-03	Rm 505 teachers desk	0003	8/12/02	144 in²	<10.0 µg/ft²	
LW-04	Rm 505 floor near east door	0004	8/12/02	144 in²	<10.0 µg/ft²	
LW-05	Rm 503 teachers desk	0005	8/12/02	144 in²	<10.0 µg/ft²	
LW-06	Rm 503 SE floor near window	0006	8/12/02	144 in²	<10.0 µg/ft²	
LW-07	Rm 501B Refrigerator	0007	8/12/02	144 in²	<10.0 µg/ft²	
LW-08	Rm 501B SE floor near window	0008	8/12/02	144 in²	<10.0 µg/ft²	
LW-09	Rm 501F floor under sink	0009	8/12/02	144 in²	<10.0 µg/ft²	
LW-10	Rm 501C floor near locker #94	0010	8/12/02	144 in²	<10.0 µg/ft²	
LW-11	Rm 501C floor near locker #91	0011	8/12/02	144 in²	<10.0 µg/ft²	
LW-12	Rm 501E floor shower area	0012	8/12/02	144 in²	<10.0 µg/ft²	
LW-13	Rm 501A book cabinet	0013	8/12/02	144 in²	<10.0 µg/ft²	
LW-14	Rm 501A near floor middle window	0014	8/12/02	144 in²	<10.0 µg/ft²	
LW-15	Rm 502B shelf at entrance	0015	8/12/02	144 in²	<10.0 µg/ft²	
LW-16	Rm 502B floor below cabinet	0016	8/12/02	144 in²	<10.0 µg/ft²	
LW-17	RM 502A top of filing cabinet	0017	8/12/02	144 in²	<10.0 µg/ft²	
LW-18	RM 502A floor beneath computer desk	0018	8/12/02	144 in²	<10.0 µg/ft²	
LW-19	RM 502 top of cabinet	0019	8/12/02	144 in²	<10.0 µg/ft²	
LW-20	RM 502 floor near entrance	0020	8/12/02	144 in²	<10.0 µg/ft²	

M. Apfelbaum
Laboratory Manager
or other approved signatory /ANALYST

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106558

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: **M477-15217/29881 / NYC SCA / Stuyvesant HS**

Customer ID: TAYL50
Customer PO:
Received 08/12/02 4:50 PM
EMSL Order 030211095
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		*Lab ID*	*Analyzed*	*Area Sampled*	*Lead Concentration*	*Notes*
LW-21	Rm 504 computer desk	0021	8/12/02	144 in²	<10.0 µg/ft²	
LW-22	RM 504 floor SE corner	0022	8/12/02	144 in²	<10.0 µg/ft²	
LW-23	RM G582 bench top	0023	8/12/02	144 in²	<10.0 µg/ft²	
LW-24	Rm G582 floor beneath sink	0024	8/12/02	144 in²	<10.0 µg/ft²	
LW-25	RM G581 top of locker #V53	0025	8/12/02	144 in²	<10.0 µg/ft²	
LW-26	RM G581 floor beneath mirror (near bench)	0026	8/12/02	144 in²	<10.0 µg/ft²	
LW-27	Rm G580 top of weight bench near entrance	0027	8/12/02	144 in²	32.0 µg/ft²	
LW-28	Rm G580 floor near SE window	0028	8/12/02	144 in²	<10.0 µg/ft²	
LW-29	RM G580 top of locker	0029	8/12/02	144 in²	<10.0 µg/ft²	
LW-30	Rm 580 by floor entrance	0030	8/12/02	144 in²	<10.0 µg/ft²	
LW-31	Field blank	0031	8/12/02	n/a	<10.0 µg/wipe	
LW-32	Field blank	0032	8/12/02	n/a	<10.0 µg/wipe	

M. Fakhoder
Laboratory Manager
or other approved signatory / ANALYST

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106559

NYC-WTC_0001006960 PAGE 03/05 EMSL ANALYTICAL INC 212-290-2538 08/12/2002 21:40

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

1 of 5

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA.	HAROLD SAVOS.	Carlos Tofat	8-12-02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
STUYVESANT HS.	1147-15217 / 29881	CARLOS TOFAT			YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
1	LW-33	Rm 6583 Top of Bench (Near Locker #1200)	1	X				<10.0
	LW-34	Rm 6583 Floor Near Locker #104	1				X	<10.0
	LW-35	Rm 6583 Shower Area Floor - Center Area	1				X	<10.0
	LW-36	Rm 6583 Floor Middle Shower Stall	1				X	<10.0
	LW-37	Rm 6584 Top of Bench Near Locker # 2590	1	X				<10.0
	LW-38	Rm 6584 Floor Near Locker #2091	1				X	<10.0
	LW-39	Rm 6584 Rear Shower Stall Floor (SW Area)	1				X	<10.0
	LW-40	Rm 509 Floor Bench Middle Sink	1				X	<10.0

FAX Results to (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE	TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE	TIME	PRINTED NAME
Carlos Tofat	8-12-02	18:31	CARLOS TOFAT	Margaret Ole			
RELINQUISHED BY (SIGNATURE)	DATE	TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE	TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL MANHATTAN LAB RECEIVED 02 AUG 12 PM 6:29

NYC 9/11 Public Portal Document

NYC-WTC_00010691 PAGE 04/05 EMSL ANALYTICAL INC 212-290-2538 08/12/2002 21:40

PATEOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA
CONTACT: HAMID SHOJ.
PROJECT LOCATION: STUYVESANT H.S.
PROJECT #: 11477-15217 / 24881
SAMPLER (SIGNATURE): Carlos Tofat
DATE: 8-12-02.
TIME:
SAMPLER NAME (PRINT): CARLOS TOFAT
SAMPLE(S) SEALED: (YES) NO
CORRECT CONTAINER(S): (YES) / NO
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-41	Rm 511 Top of Teachers Desk	1				X	<10.0
	LW-42	Rm 511 Floor near SW window	1				X	<10.0
	LW-43	Rm 513 Top of Teachers Desk	1				X	<10.0
	LW-44	Rm 513 Floor Between ent. doors	1				X	<10.0
*	LW-45	Rm 517 Floor Beneath middle sink	1				X	<10.0
*	LW-46	Rm C521 Floor Center Aisle	1				X	<10.0
	LW-47	Rm C523 Floor Center Area	1				X	<10.0
	LW-48	Rm 525 Top of Teachers Desk	1				X	<10.0

FAX RESULTS to (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
Carlos Tofat	8-12-02 / 1831	C. Tofat	Chayati Ehs		
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL ANALYTICAL INC RECEIVED 02 AUG 12 PM 6:29

NYC 9/11 Public Portal Document

NYC-WTC_00010962 PAGE 05/05 EMSL ANALYTICAL INC 212-290-2538 08/12/2002 21:48

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

5 of 5

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAROLD SAVOY	SAMPLER (SIGNATURE): Carlos Tofat 8/12	DATE: 8-12-02	TIME:	SAMPLE(S) SEALED: (YES) NO
PROJECT LOCATION: STUYVESANT H.S.	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): CARLOS TOFAT			CORRECT CONTAINER(S): (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-49	Rm 525 Floor Beneath clock	1				1	<10.0
	LW-50	~~Empty~~ FIELD BLANK						—
	LW-51	FIELD BLANK.						—

02 AUG 12 PM 6:30 RECEIVED

Note. There were two samples marked LW-46 Talked TO C. Taylor over the phone, As per C. Taylor I remarked one of the samples to LW-45.

N.A 8/12/02

FAX results to (212) 4106-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

	DATE	TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE): Carlos Tofat	8-12-02	1831	C. Tofat
RELINQUISHED BY (SIGNATURE):	DATE	TIME	PRINTED NAME
RECEIVED BY (SIGNATURE):	DATE	TIME	PRINTED NAME
RECEIVED BY LAB (SIGNATURE):	DATE	TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900068 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217 / 29881 / SCA / Stuyvesant H.S.

Customer ID: TAYL50
Customer PO:
Received: 08/12/02 6:29 AM
EMSL Order: 030211099
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-33	Rm 6583 Top of Bench (near locker #1200)	0001	8/12/02	144 in²	<10.0 µg/ft²	
LW-34	Rm 6583 Floor near Locker #104	0002	8/12/02	144 in²	<10.0 µg/ft²	
LW-35	Rm 6583 Storage Area Floor Center Area	0003	8/12/02	144 in²	<10.0 µg/ft²	
LW-36	Rm 6583 Floor Middle Shower Stall	0004	8/12/02	144 in²	<10.0 µg/ft²	
LW-37	Rm 6584 Top of Bench near Locker #2590	0005	8/12/02	144 in²	<10.0 µg/ft²	
LW-38	Rm 6584 Floor near Locker #2091	0006	8/12/02	144 in²	<10.0 µg/ft²	
LW-39	Rm 6584 Rear Shower Stall Floor (SW Area)	0007	8/12/02	144 in²	<10.0 µg/ft²	
LW-40	Rm 509 Floor Beneath Middle Sink	0008	8/12/02	144 in²	<10.0 µg/ft²	
LW-41	Rm 511 Top of Teachers Desk	0009	8/12/02	144 in²	<10.0 µg/ft²	
LW-42	Rm 511 Floor near SW Window	0010	8/12/02	144 in²	<10.0 µg/ft²	
LW-43	Rm 513 Top of Teachers desk	0011	8/12/02	144 in²	<10.0 µg/ft²	
LW-44	Rm 513 Floor between ent. Doors	0012	8/12/02	144 in²	<10.0 µg/ft²	
LW-45	Rm 517 Floor Beneath Middle Sink	0013	8/12/02	144 in²	<10.0 µg/ft²	
LW-46	Rm C521 Floor Center Area	0014	8/12/02	144 in²	<10.0 µg/ft²	
LW-47	Rm C523 Floor Center Area	0015	8/12/02	144 in²	<10.0 µg/ft²	
LW-48	Rm 525 Top of Teachers desk	0016	8/12/02	144 in²	<10.0 µg/ft²	
LW-49	Rm 525 Floor Beneath Clock	0017	8/12/02	144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106563

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: **M477-15217 / 29881 / SCA / Stuyvesant H.S.**

Customer ID: TAYL50
Customer PO:
Received: 08/12/02 6:29 AM
EMSL Order: 030211099
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		*Lab ID*	*Analyzed*	*Area Sampled*	*Lead Concentration*	*Notes*
LW-50	Field blank	0018	8/12/02	n/a	<10.0 µg/wipe	
LW-51	Field blank	0019	8/12/02	n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106564

NYC-WTC_000106565

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21096

PP 1584

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Savoj		8/13/02		YES / NO
PROJECT LOCATION: Stuyvesant H.S.	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT): Kirk McKenzie			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT mg/Ft²
	LW-19	ROOM K550A - FLOOR 3' @ ENTRANCE	1				X	<9.0
	LW-20	ROOM K550A - Locker #6	1		X			<9.0
	LW-21	ROOM C550B - FLOOR	1 composit				X	<9.0
	LW-22	ROOM K550C - FLOOR 3' @ ENTRANCE	1				X	<9.0
	LW-23	ROOM K550C - Locker #23	1		X			<9.0
	LW-24	ROOM K550D - FLOOR ~~CARDBOARD BOX~~	1 composit				X	10.2
	LW-25	ROOM K550D. Top @ Metal Table ~~CARDBOARD BOX~~ (Left side)	1		X			12.4
	LW-26	ROOM K550E - FLOOR Center of ROOM	1 composit				X	10.9

FAX 212-406-2515 @ 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR. TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/13/02 0415	Kirk McKenzie			
	8/13 0432	G. Mckenzie	R. Droudina	8.13 4.35	R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - FIELD

NYC 9/11 Public Portal Document

NYC-WTC_000106566

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE . FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#2096

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SANDJ	SAMPLER (SIGNATURE):	DATE 8/13/02 TIME	SAMPLE(S) SEALED (YES) / NO
		SAMPLER NAME (PRINT): Kirk McKenzie		CORRECT CONTAINER(S) (YES) / NO
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M 477-15217-2988	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/Ft²
	LW-27	ROOM K550E - Top of CARDBOARD BOX	1				X	13.7
	LW-28	ROOM K550 I - FLOOR at ENTRANCE	1 Composit				X	12.1
	LW-29	ROOM K550 K - FLOOR Center of ROOM	1 Composit				X	<9.0
	LW-30	ROOM K550 K - Top of File CABINET	1		X			13.9
	LW-31	ROOM K550 L FLOOR at Center	1 composit				X	12.9
	LW-32	ROOM K550 L - Top of Refrigerator	1		X			24.2
	LW-33	Kitchen - FLOOR by South Center Column	1 Composit				X	<9.0
	LW-34	Kitchen - Top of South center sink Table	1		X			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/13/02 TIME 0415	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/13 TIME 0432	PRINTED NAME G. McKenna	RECEIVED BY LAB (SIGNATURE) R. Dracolina	DATE 8.13 TIME 4.35	PRINTED NAME R. Dracolina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106567

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21096 5/6 4

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SADJ		8/13/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217-2988	Kirk McKenzie			YES / NO

MATRIX (CIRCLE ONE): WIPE / PAINT / SOIL / OTHER _____

SAMPLE INFORMATION:				SURFACE MATERIAL				
LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-35	ROOM K540 B - FLOOR Center	1 composit				X	<9.0
	LW-36	ROOM K540 B - Table Top - North side	1				X	<9.0
	LW-37	ROOM K540 C - FLOOR Center	1 Composit				X	<9.0
	LW-38	ROOM K540 C - Table Top	1				X	<9.0
	LW-39	ROOM K540 A - FLOOR Center	1 composite				X	<9.0
	LW-40	ROOM K540A - Top of MIDDLE Service counter	1		X			<9.0
	LW-41	Cafeteria - FLOOR Center	1				X	<9.0
	LW-42	Cafeteria - Table Top NE SIDE	1				X	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/13/02 0415	Kirk McKenzie			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/13 0432		R. Diodilla	8.13 4.35	R. Diodilla

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106568

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21096

484

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC EDC	Hamid Bandj		8/13/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S) (YES) / NO
Stuyvesant H.S.	M477-15217-29881	Kirk McKenzie			

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT $\mu g/Ft^2$
	LW-43	ROOM C540D - FLOOR 3' of ENTRANCE	1				X	<9.0
	LW-44	ROOM C540E - FLOOR 3' of ENTRANCE	1				X	<9.0
	LW-45	ROOM C528 (Service Elev. Lobby) FLOOR	1				X	<9.0
	FBL-1 (46)	Field Blank	—					<9.0
	FBL-2 (47)	Field Blank	—					<9.0
	FBL-3 (48)	Field Blank	—					<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/13/02 TIME 0415	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/13 TIME 0432	PRINTED NAME G. McKenzie	RECEIVED BY LAB (SIGNATURE) R. Droudina	DATE 8.13 TIME 4.35	PRINTED NAME R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-13-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-13-02
DATE RECEIVED:	08-13-02
DATE ANALYZED:	08-13-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-19	21096	Rm K550A Floor 3' of Entrance	<9.0	9.0
LW-20	21096	Rm K550A Locker #6	<9.0	9.0
LW-21	21096	Rm C550B Floor	<9.0	9.0
LW-22	21096	Rm K550C Floor 3' of Entrance	<9.0	9.0
LW-23	21096	Rm K550C Locker #23	<9.0	9.0
LW-24	21096	Rm K550D Floor	10.2	9.0
LW-25	21096	Rm K550D Top of Metal Tabel (Left Side)	12.4	9.0
LW-26	21096	Rm K550E Floor Center of Rm	10.9	9.0
LW-27	21096	Rm K550E Top of Cardboard Box	13.7	9.0
LW-28	21096	Rm K550J Floor at Entrance	12.1	9.0
LW-29	21096	Rm K550K Floor Center of Rm	<9.0	9.0
LW-30	21096	Rm K550K Top of File Cabinet	13.9	9.0
LW-31	21096	Rm K550L Floor of Center	12.9	9.0
LW-32	21096	Rm K550L Top of Regrigeration	24.2	9.0
LW-33	21096	Kitchen Floor by South Center Column	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-34	21096	Kitchen Top of South Center Sink Table	<9.0	9.0
LW-35	21096	Rm K540B Floor Center	<9.0	9.0
LW-36	21096	Rm K54D B Table Top North Side	<9.0	9.0
LW-37	21096	Rm K540C Floor Center	<9.0	9.0
LW-38	21096	Rm K540C Table Top	<9.0	9.0
LW-39	21096	Rm K540A Floor Center	<9.0	9.0
LW-40	21096	Rm K540A Top of Middle Service Counter	<9.0	9.0
LW-41	21096	Cafeteria Floor Center	<9.0	9.0
LW-42	21096	Cafeteria Table Top NE Side	<9.0	9.0
LW-43	21096	Rm C540D Floor 3' of Entrance	<9.0	9.0
LW-44	21096	Rm C540E Floor 3' of Entrance	<9.0	9.0
LW-45	21096	Rm C528 Service Elev. Lobby Floor	<9.0	9.0
FBL-1	21096	Field Blank	<9.0 µg	9.0 µg
FBL-2	21096	Field Blank	<9.0 µg	9.0 µg
FBL-3	21096	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft². Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY:_____

REPORT PREPARED BY:_____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:_____

LABORATORY DIRECTOR:_____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106571

NYC 9/11 Public Portal Document
08/13/2002 09:36 212-290-2536

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA

CONTACT: HAMID SAVOI

PROJECT LOCATION: STUYVESANT HS

PROJECT #: M477-15217 /29881

SAMPLER (SIGNATURE): DATE 08.13.02 TIME

SAMPLER NAME (PRINT): KIRK MC KENZIE

SAMPLE(S) SEALED (YES) NO

CORRECT CONTAINER(S) (YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAIN SOIL OTHER

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	5th FLOOR CORRIDOR O/S ROOM 584 - FLOOR	1				X	12.0
	LW-02	5th FLOOR CORRIDOR O/S STAIRCASE "E" - FLOOR	1				X	14.0
	LW-03	5th FLOOR CORRIDOR ~~O/S~~ AT ESCALATOR (WEST SIDE) FLOOR	1				X	<10.0
	LW-04	ROOM 501 - FLOOR 5' OF ENTRANCE	1				X	10.0
	LW-05	ROOM 501 - TABLE TOP RIGHT SIDE OF OFFICE	1				X	<10.0
	LW-06	ROOM 501D - FLOOR 3' OF ENTRANCE	1				X	<10.0
	LW-07	ROOM 501D . TOP OF SHELF (EAST SIDE)	1		X			<10.0
	LW-08	ROOM 510 - FLOOR Center	1				X	12.0

FAX RESULTS TO 212 406-2535
516 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE): DATE 8/13/02 TIME 0415 PRINTED NAME KIRK McKenzie

RELINQUISHED BY (SIGNATURE): DATE 08.13.02 TIME 4:30 PRINTED NAME TERESA MICHALSKI

RECEIVED BY (SIGNATURE): DATE TIME PRINTED NAME JOSE ARANGO

RECEIVED BY LAB (SIGNATURE): DATE TIME PRINTED NAME

ENSR MANHATTAN RECEIVED 02 AUG 13 AM 4:13

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_000106572

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-350-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA

CONTACT: HAMID SADOZ

PROJECT LOCATION: STUYVESANT H.S

PROJECT #: 1147-15217 / 29881

SAMPLER SIGNATURE: [signature] DATE: 08.13.02 TIME:

SAMPLER NAME (PRINT): KIRK MCKENZIG

SAMPLE(S) SEALED: (YES) / NO

CORRECT CONTAINER(S): (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/FT²
	LW-09	~~Room 527~~ Locker # 5-221 O/S RM 525	1		X			< 10.0
	LW-10	ROOM 527 — Floor Center	1				X	< 10.0
	LW-11	ROOM 529 — Floor Center	1				X	10.0
	LW-12	ROOM K531 - Floor 2' of East wall	1				X	11.0
	LW-13	ROOM K531 - Table Top	1				X	< 10.0
	LW-14	Serving Area to K531 Floor -4' of window	1 composit				X	< 10.0
	LW-15	Serving Area to K531 Sink Counter Top	1		X			17.0
	LW-16	Hallway Floor O/S Room K550C	1 Composit				X	< 10.0

02 AUG 13 PM 4:13
EHAL LEAD LAB RECEIVED

FAX RESULTS TO 212 406-2535
516 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE) [signature]	DATE 8/13/02 TIME 0415	PRINTED NAME KIRK McKENZIE	
RELINQUISHED BY (SIGNATURE) [signature]	DATE 08.13.02 TIME 4:30	PRINTED NAME TERESA MICHALOWSKI	
RECEIVED BY (SIGNATURE)			DATE / TIME / PRINTED NAME
RECEIVED BY LAB (SIGNATURE) [signature]			DATE / TIME / PRINTED NAME JOSE ARROYO

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106573

NYC 9/11 Public Portal Document
08/13/2002 09:36 212-298-2538 EMSL ANALYTICAL INC PAGE 03/05

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030211110

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAHOJ	SAMPLER (SIGNATURE): ~~Kirk McKenzie~~	DATE: 08.13.02 TIME:	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): Kirk McKenzie		CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: STUYVESANT HS.	PROJECT #: 1477-15217 / 29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER:		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT mg/FT²
	LW-17	Locker # 5-26 o/s Girls Locker Rm	1		X			K10.0
	LW-18	Locker # 5-204 By Room 517	1		X			13.0
	FBL-1	Field Blank						
	FBL-2	Field Blank						

EMSL TAUNTON RECEIVED 02 AUG 13 AM 4:13

FAX RESULTS TO 212 406-2535
516 998-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/13/02 TIME 0415	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 08.13.02 TIME 430	PRINTED NAME TERESA MICHALOVE	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME JOSE ARRIAGA

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax 2122900058 Email: manhattanlab@emsl.com

Attn. Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: NYC SCA/Stuyvesant H.S./M477-15217/29881.

Customer ID: TAYL50
Customer PO:
Received: 08/13/02 7:44 AM
EMSL Order: 030211111
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	5th Floor Corridor O/S Room 548-Floor	0001		144 in²	12.0 µg/ft²	
LW-02	5th Floor Corridor O/S Staircase "E"-Floor	0002		144 in²	14.0 µg/ft²	
LW-03	5th Floor Corridor at Escalator (West Side) Floor	0003		144 in²	<10.0 µg/ft²	
LW-04	Room 501-Floor 5' of Entrance	0004		144 in²	10.0 µg/ft²	
LW-05	Room 501 Table Top Right Side of Office	0005		144 in²	<10.0 µg/ft²	
LW-06	Room 501D-Floor 3' of Entrance	0006		144 in²	<10.0 µg/ft²	
LW-07	Room 501D-Top of Shelf (East Side)	0007		144 in²	<10.0 µg/ft²	
LW-08	Room 510-Floor Center	0008		144 in²	12.0 µg/ft²	
LW-09	Locker #5-221 O/S Room 525	0009		144 in²	<10.0 µg/ft²	
LW-10	Room 527-Floor Center	0010		144 in²	<10.0 µg/ft²	
LW-11	Room 529-Floor Center	0011		144 in²	10.0 µg/ft²	
LW-12	Room K531-Floor 3' of East Unitvent	0012		144 in²	11.0 µg/ft²	
LW-13	Room K531-Table Top	0013		144 in²	<10.0 µg/ft²	
LW-14	Serving Area to K531 4' of Window	0014		144 in²	<10.0 µg/ft²	
LW-15	Serving Area to K531 Sink Counter Top	0015		144 in²	12.0 µg/ft²	
LW-16	Hallway Floor O/S Room K550C	0016		144 in²	<10.0 µg/ft²	
LW-17	Locker #5-26 O/S Girls Locker Room	0017		144 in²	<10.0 µg/ft²	
LW-18	Locker #5-204 by Room 517	0018		144 in²	13.0 µg/ft²	
LW-19	Field Blank	0019		n/a	<10.0 µg/wipe	

Eric B. Lyle
Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106574

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: NYC SCA/Stuyvesant H.S./M477-15217/29881.

Customer ID: TAYL50
Customer PO:
Received: 08/13/02 7:44 AM
EMSL Order: 030211111
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-20	Field blank	0020		n/a	<10.0 µg/wipe	

Eric B. Lyle
Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106575

NYC-WTC_000106576

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21148

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: ~~Silver~~ SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE):	DATE: 8/14/02 TIME:
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): A. Kazandow	SAMPLE(S) SEALED: YES / NO; CORRECT CONTAINER(S): YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	Room # 401 Teachers desk.	1					< 9.0
	LW-02	Room # 401 floor by N-E side window	1					< 9.0
	LW-03	Room # 402 computer desk	1					< 9.0
	LW-04	Room # 402 floor by Refrigerator.	1					< 9.0
	LW-05	Room # 402 A Desk	1					< 9.0
	LW-06	Room # 402 A floor by the window.	1					< 9.0
	LW-07	Room # 407 Teacher desk	1					< 9.0
	LW-08	Room # 407 floor by S-W side window	1					< 9.0

Fax results to Taylor (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr TAT

RELINQUISHED BY (SIGNATURE): Carlos A Vlat	DATE: 8-14-02 TIME: 1700	PRINTED NAME: C. Vlat	RECEIVED BY (SIGNATURE): A. Cla 08/14/02	DATE: TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE):	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106577

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21148

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savat		8/14/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	#1477-15217/29881	Al Kazamov			YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:				SURFACE MATERIAL				
LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09	Room #405 Teacher desk	1				X	<9.0
	LW-10	Room # 405 floor by S-W window	1				X	<9.0
	LW-11	Room #403 File cabinet center	1		X			<9.0
	LW-12	Room #403 floor by TV set,	1				X	<9.0
	LW-13	Room # 404 Student desk by Entrance	1				X	<9.0
	LW-14	Room #404 floor by North side Blackboard.	1				X	<9.0
	LW-15	Room # 406 book shelf by Entrance	1		X			<9.0
	LW-16	Room # 406 floor by the Entrance	1				X	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8-11-02 1800			08/14	
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106578

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21148

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Sayaf		8/14/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15287/29881	A.L. Kraemer			YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-17	Room # 408 Computer desk	1				X	<9.0
	LW-18	Room # 408 Floor Center of the Room	1				X	<9.0
	LW-19	Room #409 book shelf	1		X			<9.0
	LW-20	Room # 409 floor Center of the room	1				X	<9.0
	LW-21	Room #411 computer desk 1st on end row	1				X	<9.0
	LW-22	Room #411 floor by the Entrance	1				X	<9.0
	LW-23	F/B						<9.0
	LW-24	F/B						<9.0

Fax results to Taylor at (212)406-2555

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
Carlos Cofet	8-14-02 1800	Client	AC 08/14		
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-15-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-14-02
DATE RECEIVED:	08-14-02
DATE ANALYZED:	08-14-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	21148	Rm 401 Teacher Desk	<9.0	9.0
LW-02	21148	Rm 401 Floor by NE Side Window	<9.0	9.0
LW-03	21148	Rm 402 Computer Desk	<9.0	9.0
LW-04	21148	Rm 402 Floor by Regrigerator	<9.0	9.0
LW-05	21148	Rm 402A Desk	<9.0	9.0
LW-06	21148	Rm 402A Floor by the Window	<9.0	9.0
LW-07	21148	Rm 407 Teacher Desk	<9.0	9.0
LW-08	21148	Rm 407 Floor by SW Side Window	<9.0	9.0
LW-09	21148	Rm 405 Teacher Desk	<9.0	9.0
LW-10	21148	Rm 403 Floor by SW Window	<9.0	9.0
LW-11	21148	Rm 403 File Cabinet Center	<9.0	9.0
LW-12	21148	Rm 403 Floor by TV Set	<9.0	9.0
LW-13	21148	Rm 404 Student Desk by Entrance	<9.0	9.0
LW-14	21148	Rm 404 Floor by North Side Blackboard	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-15	21148	Rm 406 Book Shelf by Entrance	<9.0	9.0
LW-16	21148	Rm 406 Floor by the Entrance	<9.0	9.0
LW-17	21148	Rm 408 Computer Desk	<9.0	9.0
LW-18	21148	Rm 408 Floor Center of the Room	<9.0	9.0
LW-19	21148	Rm 409 Book Shelf	<9.0	9.0
LW-20	21148	Rm 409 Floor Center of the Room	<9.0	9.0
LW-21	21148	Rm 411 Computer Desk 1st on 2nd	<9.0	9.0
LW-22	21148	Rm 411 Floor by the Entrance	<9.0	9.0
LW-23	21148	Field Blank	<9.0 µg	9.0 µg
LW-24	21148	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft². Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106580

NYC-WTC_000106581

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2114 T

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA
CONTACT: Hamid Saros
SAMPLER (SIGNATURE): [signature] DATE: 8/14/02 TIME:
SAMPLE(S) SEALED: YES / NO
SAMPLER NAME (PRINT): AL. KAZAKOV
CORRECT CONTAINER(S): YES / NO
PROJECT LOCATION: Stuyvesant HS
PROJECT #: M477-15217/29881
MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	Room 615 F book shelf	1		X			< 9.0
	LW-02	Room #615 F floor by the entrance	1				X	< 9.0
	LW-03	Room # 635 A book shelf	1		X			< 9.0
	LW-04	Room # 635 A floor Center of the room	1				X	< 9.0
	LW-05	F/B 4						< 9.0
	LW-06	F/B 4						< 9.0

Fax results to Taylor (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	8-14-02 1700	[illegible]	[signature] 8/14 6pm		
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-15-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-14-02
DATE RECEIVED:	08-14-02
DATE ANALYZED:	08-14-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	21147	Rm 615F Book Shelf	<9.0	9.0
LW-02	21147	Rm 615F Floor by the Entrance	<9.0	9.0
LW-03	21147	Rm 655A Book Shelf	<9.0	9.0
LW-04	21147	Rm 655A Floor Center of the Room	<9.0	9.0
LW-05	21147	Field Blank	<9.0 µg	9.0 µg
LW-06	21147	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106584

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21155

P9 184

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Sanoj	SAMPLER (SIGNATURE):	DATE: 8/14/02 TIME:
PROJECT LOCATION: Stuyvesant HS 345 Chambers St NY	PROJECT #: M477-15217-27881	SAMPLER NAME (PRINT): Kirk McKenzie	SAMPLE(S) SEALED: (YES) NO
			CORRECT CONTAINER(S): (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-26	ROOM 438 - FLOOR Center of ROOM	1				X	<9.0
	LW-27	ROOM 438 - Shelf EAST SIDE of ROOM	1		X			<9.0
	LW-28	ROOM 438A - FLOOR Center of ROOM	1				X	<9.0
	LW-29	ROOM 438A - Table Top EAST SIDE OF ROOM	1				X	<9.0
	LW-30	ROOM 436 - FLOOR 3' of WEST ENTRANCE	1				X	<9.0
	LW-31	ROOM 436 - Table Top PRINTER TABLE - WEST SIDE	1				X	<9.0
	LW-32	ROOM 432 - FLOOR 2' of ENTRANCE	1				X	<9.0
	LW-33	ROOM 432 - FLOOR Center of ROOM	1				X	<9.0

Fax to 212-406-2535 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/14/02 TIME 2300	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE) Gr. Pulatov	DATE 8-15-02 TIME 4:50	PRINTED NAME Gr. Pulatov	RECEIVED BY LAB (SIGNATURE) R. Droudina	DATE 8.15 TIME 4.50	PRINTED NAME R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106585

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21155 P9 284

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: N/C SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): [signature] DATE: 8/14/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.	PROJECT #: M477-1517-2988	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-34	ROOM 430 - FLOOR 3' OF ENTRANCE	1				X	<9.0
	LW-35	ROOM C428 - FLOOR Center	1				X	<9.0
	LW-36	CORRIDOR O/S RM 438 - FLOOR	1				X	<9.0
	LW-37	ROOM 446 - FLOOR 4' OF ENTRANCE	1				X	<9.0
	LW-38	ROOM 448 - FLOOR 4' OF ENTRANCE	1				X	<9.0
	LW-39	LOCKER #4-235 O/S RM 438A	1		X			<9.0
	LW-40	ROOM 453 - FLOOR 2' OF VENT	1				X	<9.0
	LW-41	ROOM 453 - 7.1 OF SE WORK TABLE	1				X	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	8/14/02 2300	Kirk McKenzie			
Gr. Pulaski	8/15/02 4:50	GREGORY PULASKI	R. Droudina	8.15 4.50	R. Droudina

NYC 9/11 Public Portal Document

NYC-WTC_000106586

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21155

3.74

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAVOJ		8/14/02		YES / NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers ST NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-42	ROOM 452 - FLOOR center of ROOM	1				X	<9.0
	LW-43	ROOM 452 - Shelf Top Right side of ROOM	1		X			<9.0
	LW-44	ROOM 451 - FLOOR 7' of ENTRANCE	1				X	<9.0
	LW-45	ROOM 451 - Top of EAST PRINTER Table	1				X	<9.0
	LW-46	ROOM 450 - FLOOR 3' of EAST window	1				X	<9.0
	LW-47	ROOM 450 - Table Top Computer Table at center wall	1				X	<9.0
	LW-48	~~ROOM 450A~~ CORRIDOR, 10' of WEST side ESCALATOR. - FLOOR	1				X	<9.0
	LW-49	Locker #4414 at CORRIDOR N/O ESCALATOR	1		X			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/14/02 2300	Kirk McKenzie			
RELINQUISHED BY (SIGNATURE) Gregory Pulaski	DATE 8/15/02 TIME 4:50	PRINTED NAME Gregory Pulaski	RECEIVED BY LAB (SIGNATURE) R. Droudina	DATE 8.15 TIME 4.50	PRINTED NAME R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106587

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

#21155

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAVOJ		8/14/02		(YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers BST NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/FILT
	LW-50	CORRIDOR O/S RM 403 FLOOR	1				X	<9.0
	FBL-1 ~~51~~ 51	Field Blank	—					<9.0
	FBL-2 ~~52~~ 52	Field Blank	—					<9.0
	FBL-3 ~~53~~ 53	Field Blank	—					<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 8 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/14/02 2300	Kirk McKenzie			
Gr. Pulatov	8-15-02 4:50	Gregory Pulatov	R. Droudina	8.15 4.50	R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-15-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217-29881

SAMPLED BY: Client

SAMPLE DATE: 08-14-02
DATE RECEIVED: 08-15-02
DATE ANALYZED: 08-15-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-26	21155	Rm 438 Floor Center of Room	<9.0	9.0
LW-27	21155	Rm 438 Shelf East Side of Room	<9.0	9.0
LW-28	21155	Rm 438A Floor Center of Room	<9.0	9.0
LW-29	21155	Rm 438A Table Top Side of Room	<9.0	9.0
LW-30	21155	Room 436 Floor 3' of West Entrance	<9.0	9.0
LW-31	21155	Room 436 Table Top Printer Table West Side	<9.0	9.0
LW-32	21155	Room 434 Floor 3' of Entrance	<9.0	9.0
LW-33	21155	Room C432 Floor Center of Room	<9.0	9.0
LW-34	21155	Room 430 Floor 3' of Entrance	<9.0	9.0
LW-35	21155	Room C428 Floor Center	<9.0	9.0
LW-36	21155	Corridor O/S Rm 438 Floor	<9.0	9.0
LW-37	21155	Room 446 Floor 4' of Entrance	<9.0	9.0
LW-38	21155	Room 448 Floor 4' of Entrance	<9.0	9.0
LW-39	21155	Locker #4 - 235 O/S Rm 438A	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-40	21155	Room 453 Floor 2' of Unitvent	<9.0	9.0
LW-41	21155	Room 453 Top of SE Work Table	<9.0	9.0
LW-42	21155	Room 452 Floor Center of Room	<9.0	9.0
LW-43	21155	Room 452 Shelf Top Right Side of Room	<9.0	9.0
LW-44	21155	Room 451 Floor 7' of Entrance	<9.0	9.0
LW-45	21155	Room 451 Top of East Printer Table	<9.0	9.0
LW-46	21155	Room 450 Floor 3' of East Unitvent	<9.0	9.0
LW-47	21155	Room 450 Table Top Computer Table at Center Wall	<9.0	9.0
LW-48	21155	Corridor 10' of West Side Escalator Floor	<9.0	9.0
LW-49	21155	Locker #4-414 at Corridor N/O Escalator	<9.0	9.0
LW-50	21155	Corridor O/S Rm 403 Floor	<9.0	9.0
FBL-1	21155	Field Blank	<9.0 µg	9.0 µg
FBL-2	21155	Field Blank	<9.0 µg	9.0 µg
FBL-3	21155	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft².
Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_0001060
PAGE 03/06

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030211254

Pg 1 of 4

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYCSCA	Hamid Savoj		8/14/02		YES / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St NY	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER			

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				µg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 413 - FLOOR 4' SO ENTRANCE	1				X	< 10.0
	LW-02	ROOM 413 - Table Top NE Computer Desk	1				X	10.0
	LW-03	ROOM C421 - FLOOR By ENTRANCE	1				X	< 10.0
	LW-04	ROOM C423 - FLOOR Center of ROOM	1				X	< 10.0
	LW-05	ROOM C425 - FLOOR 3' SO ENTRANCE	1				X	< 10.0
	LW-06	ROOM C425 - shelf Left side of ROOM	1		X			12.0
	LW-07	~~ROOM~~ Locker #471 O/S RM 427	1		X		X	12.0
	LW-08	ROOM 427 - FLOOR 3' OF WEST Window	1				X	<10.0

EMSL HAINHAI LAB RECEIVED 02 AUG 15 AM 4:34

Fax to 212-406-2535 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR. TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/15/02 TIME 5:43	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL ANALYTICAL INC 212-290-2538
08/15/2002 09:47

NYC 9/11 Public Portal Document

NYC-WTC_0001069691 PAGE 04/06

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

0502116-1 2 of 7

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE):	DATE: 8/14/02 TIME:	SAMPLE(S) SEALED: YES / NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St NY	PROJECT #: M477-15217-29881	SAMPLER NAME (PRINT): Kirk McKenzie		CORRECT CONTAINER(S): YES / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/ft² LAB RESULT
	LW-09	ROOM 427 - Top of Teachers Desk	1				X	<10.0
	LW-10	ROOM 429 - FLOOR ~~EAST~~ SIDE of ROOM	1				X	<10.0
	LW-11	ROOM 429 - Desk Top NE STUDENT DESK	1				X	<10.0
	LW-12	ROOM 431 - FLOOR 3' OF EAST ENTRANCE	1				X	<10.0
	LW-13	ROOM 431 - Top of Teachers Desk	1				X	<10.0
	LW-14	ROOM 433 - FLOOR 2' of EAST WALL	1				X	<10.0
	LW-15	ROOM 433 - Top of CABINET	1				X	10.0
	LW-16	ROOM 435 - FLOOR Center of ROOM	1				X	<10.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/15/02 0435	Kirk McKenzie			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL ANALYTICAL INC 212-290-2538 08:47 08/15/2002

EMSL-HARTFORD RECEIVED 02 AUG 15 AM 11:34

NYC 9/11 Public Portal Document

NYC-WTC_00010692 PAGE 05/06

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Savoj		8/14/02		YES / NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St. NY.	PROJECT # M477-1527-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/ft² LAB RESULT
	LW-17	ROOM 435 - Desk Top SE Desk.	1				X	< 10.0
	LW-18	ROOM 437 - FLOOR 3' S/ EAST ENTRANCE	1				X	< 10.0
	LW-19	ROOM 437 - Desk Top Teachers Desk.	1				X	< 10.0
	LW-20	ROOM 439 - FLOOR West of Teachers Desk	1				X	< 10.0
	LW-21	ROOM 439 - Top of Cabinet	1		X			< 10.0
	LW-22	ROOM 442 - FLOOR 4' S/ ENTRANCE	1				X	< 10.0
	LW-23	ROOM 442 - Cabinet Top	1		X			< 10.0
	LW-24	ROOM 440 - FLOOR SW side of ROOM	1				X	< 10.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/14/02 0436	Kirk McKenzie			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL ANALYTICAL INC 212-290-2538 08/15/2002 09:47

EMSL ANALYTICAL INC RECEIVED 02 AUG 15 AM 4:34

NYC 9/11 Public Portal Document

NYC-WTC_00010593 PAGE 06/06 EMSL ANALYTICAL INC 212-290-2538 08/15/2002 09:47

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030211234

7 of 71

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAVOJ		8/14/02		YES / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St. NY.	PROJECT # 14477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/ft² LAB RESULT
	LW-25	Room 440 – Desk Top Front 5 Desks from South	1				X	<10.0
	FBL-1	Field Blank						<10.0 wipe
	FBL-2	Field Blank						<10.0 wipe
	FBL-3	Field Blank						<10.0 wipe

02 AUG 15 AM 4:34
EMSL MARINELLI LAB RECEIVED

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/15/02 0435	Kirk McKenzie			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: NYC SCA/Stuyvesant H.S. 345 Chambers St., N.Y., NYIM477-15217-29881

Customer ID: TAYL50
Customer PO:
Received: 08/15/02 7:44 AM
EMSL Order: 030211234
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	Room 413-Floor 4' of Entrance	0001		144 in²	<10.0 µg/ft²	
LW-02	Room 413-Table Top NE Computer Desk	0002		144 in²	10.0 µg/ft²	
LW-03	Room C421-Floor by Entrance	0003		144 in²	<10.0 µg/ft²	
LW-04	Room C423-Floor Center of Room	0004		144 in²	<10.0 µg/ft²	
LW-05	Room C425-Floor 3' of Entrance	0005		144 in²	<10.0 µg/ft²	
LW-06	Room C425-Shelf Left Side of Room	0006		144 in²	12.0 µg/ft²	
LW-07	Locker #471 O/S Rm 427	0007		144 in²	12.0 µg/ft²	
LW-08	Room 427-Floor 3' of West Unitvent	0008		144 in²	<10.0 µg/ft²	
LW-09	Room 427-Top of Teachers Desk	0009		144 in²	<10.0 µg/ft²	
LW-10	Room 429-Floor East Side of Room	0010		144 in²	<10.0 µg/ft²	
LW-11	Room 429-Desk Top NE Student Desk	0011		144 in²	<10.0 µg/ft²	
LW-12	Room 431-Floor 3' of East Entrance	0012		144 in²	<10.0 µg/ft²	
LW-13	Room 431-Top of Teachers Desk	0013		144 in²	<10.0 µg/ft²	
LW-14	Room 433-Floor 2' of East Unitvent	0014		144 in²	<10.0 µg/ft²	
LW-15	Room 433-Top of Cabinet	0015		144 in²	10.0 µg/ft²	
LW-16	Room 435-Floor Center of Room	0016		144 in²	<10.0 µg/ft²	
LW-17	Room 435-Desk Top SE Desk	0017		144 in²	<10.0 µg/ft²	
LW-18	Room 437-Floor 3' of East Entrance	0018		144 in²	<10.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102561

NYC-WTC_000106594

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn:	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/15/02 7:44 AM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030211234
Project:	NYC SCA/Stuyvesant H.S. 345 Chambers St., N.Y., NY/M477-15217-29881	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-19	Room 437-Desk Top Teachers Desk	0019		144 in²	<10.0 µg/ft²	
LW-20	Room 439-Floor West of Teachers Desk	0020		144 in²	<10.0 µg/ft²	
LW-21	Room 439-Top of Cabinet	0021		144 in²	<10.0 µg/ft²	
LW-22	Room 442-Floor 4' of Entrance	0022		144 in²	<10.0 µg/ft²	
LW-23	Room 442-Cabinet Top	0023		144 in²	<10.0 µg/ft²	
LW-24	Room 440-Floor SW side of Room	0024		144 in²	<10.0 µg/ft²	
LW-25	Room 440-Desk Top Front 5 Desks from South	0025		144 in²	<10.0 µg/ft²	
FBL-1	Field Blank	0026		n/a	<10.0 µg/wipe	
FBL-2	Field Blank	0027		n/a	<10.0 µg/wipe	
FBL-3	Field blank	0028		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106595

NYC-WTC_000106596

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2/248 1 of 3

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: Stuy Mason SCA	CONTACT: Hamid Sayed	SAMPLER (SIGNATURE): [signature] DATE: 8/16/02 TIME: 5	SAMPLE(S) SEALED: YES / NO	
		SAMPLER NAME (PRINT): Peyam C	CORRECT CONTAINER(S): YES / NO	
PROJECT LOCATION: 345 Chambers	PROJECT #: M479.15217-2981	MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	8	rm 450A Floor at entrance	1				WIPE	< 9.0
	9	rm 450A metal shelf ~~floor~~ rear entr.	1				WIPE	< 9.0

Fax 212-406-2535
cc 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1/01

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	8/16/02 1830	[signature]			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-19-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-16-02
DATE RECEIVED:	08-16-02
DATE ANALYZED:	08-16-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
8	21248	Rm 450A Floor at Entrance	<9.0	9.0
9	21248	Rm 450A Metal Shelf Near Entr.	<9.0	9.0
10	21248	Rm 307 Floor at Rear Entrance	<9.0	9.0
11	21248	Rm 307 Floor Table Top Near Entrance	<9.0	9.0
12	21248	Cellar Corr. O/S C029 Supply	<9.0	9.0
13	21248	Cellar Corr. O/S C029 Supply	15.1	9.0
14	21248	Cellar Corr. O/S C029 Supply	<9.0	9.0
16	21248	Rm 517 Floor Left Side	53.0	9.0
17	21248	Rm 317 Shelf at Entr.	49.0	9.0
18	21248	3rd Floor GYM Floor Storage Rm 380B SW	53.6	9.0
19	21248	3rd Floor GYM Shelf Storage Rm 380B	18.6	9.0
FB7	21248	Field Blank	<9.0 µg	9.0 µg
FB8	21248	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106599

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

21224

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): [signature] DATE: 8/15/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
PROJECT LOCATION: Stuyvesand H.S.	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): M. Kazakov	CORRECT CONTAINER(S): (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW01	Rm 302 Top of Computer Desk	1.0				X	< 9.0
	LW02	Rm 302 Floor Center of Room	1.0				X	11.1
	LW03	Rm 302A Top of Desk	1.0				X	< 9.0
	LW04	Rm 302A Floor near entrance	1.0				X	< 9.0
	LW05	Rm 302B Top of File Cabinet	1.0		X			< 9.0
	LW06	Rm 302B Floor between bookshelves	1.0				X	< 9.0
	LW07	Rm 301 Floor Center Area	1.0				X	< 9.0
	LW08	Rm 301B Top of Desk	1.0				X	< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

RELINQUISHED BY (SIGNATURE): [signature]	DATE: 8/16/02 TIME: 13:00	PRINTED NAME: M. Kazakov	RECEIVED BY (SIGNATURE): [signature] at ATL	DATE: 8/16/02 TIME: 1420	PRINTED NAME: MELWIN
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106600

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

2124

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoi		8/16/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	#447-15217/29881	AL. KAZAKOV			(YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT ug/ft²
	LW 09	Room 301B FLOOR EAST of DESK	1.0				X	< 9.0
	LW 10	Room 301A Top of COMPUTER DESK / BENEATH CLOCK	1.0				X	< 9.0
	LW 11	Room 301A FLOOR CENTER AREA	1.0				X	< 9.0
	LW 12	Room 301C TOP of DESK / NEAR COMPUTER	1.0				X	< 9.0
	LW 13	Room 301C FLOOR NEAR WINDOW	1.0				X	< 9.0
	LW 14	Room 303 TOP of TEACHER'S DESK	1.0				X	< 9.0
	LW 15	Room 303 FLOOR NEAR CABINETS	1.0				X	< 9.0
	LW 16	Room 305 TOP of TEACHER'S DESK	1.0				X	< 9.0

Fax results to Taylor (212)406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/16/02	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE 8/16/02	PRINTED NAME
	TIME 1300	AL. KAZAKOV		TIME 1420	[illegible]
RELINQUISHED BY (SIGNATURE)	DATE	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE	PRINTED NAME
	TIME			TIME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106601

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21224

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA [redacted]
CONTACT: Hamid Savoj
SAMPLER (SIGNATURE): [signature] DATE: 8/16/02 TIME:
SAMPLER NAME (PRINT): AL. Kazemow
SAMPLE(S) SEALED: YES / NO
CORRECT CONTAINER(S): YES / NO
PROJECT LOCATION: Stuyvesant H.S.
PROJECT #: M477-15217/29881
MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT ug/ft²
	LW 17	Room 305 Floor NEAR WEST WINDOW	1.0				X	< 9.0
	LW 18	Room 309 MIDDLE of NORTH BOOKSHELF	1.0		X			< 9.0
	LW 19	Room 309 FLOOR NEAR ENTRANCE	1.0				X	< 9.0
	LW 20	Room 313 TOP of TEACHER'S DESK	1.0				X	< 9.0
	LW 21	Room 313 FLOOR NEAR TEACHER'S DESK.	1.0				X	< 9.0
	LW 22	FIELD BLANKS						—
	LW 23	FIELD BLANKS						—

Fax results to Taylor (212)406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/16/02 TIME 1300	PRINTED NAME AL. Kazemow	RECEIVED BY (SIGNATURE)	DATE 8/16/02 TIME 1420	PRINTED NAME [illegible]
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-16-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-16-02
DATE RECEIVED:	08-16-02
DATE ANALYZED:	08-16-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	21224	Rm 302 Top of Computer Desk	<9.0	9.0
LW-02	21224	Rm 302 Floor Center of Room	11.1	9.0
LW-03	21224	Rm 302A Top of Desk	<9.0	9.0
LW-04	21224	Rm 302A Floor Near Entrance	<9.0	9.0
LW-05	21224	Rm 302B Top of File Cabinet	<9.0	9.0
LW-06	21224	Rm 302B Floor between Bookshelves	<9.0	9.0
LW-07	21224	Rm 301 Floor Center Area	<9.0	9.0
LW-08	21224	Rm 301B Top of Desk	<9.0	9.0
LW-09	21224	Rm 301B Floor East of Door	<9.0	9.0
LW-10	21224	Rm 301A Top of Computer Desk beneath Clock	<9.0	9.0
LW-11	21224	Rm 301A Floor Center Area	<9.0	9.0
LW-12	21224	Rm 301C Top of Desk/Near Computer	<9.0	9.0
LW-13	21224	Rm 301C Floor Near Window	<9.0	9.0
LW-14	21224	Rm 303 Top of Teacher's Desk	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-15	21224	Rm 303 Floor Near Cabinets	<9.0	9.0
LW-16	21224	Rm 305 Top of Teacher's Desk	<9.0	9.0
LW-17	21224	Rm 305 Floor Near West Window	<9.0	9.0
LW-18	21224	Rm 309 Middle of North Bookshelf	<9.0	9.0
LW-19	21224	Rm 309 Floor Near Entrance	<9.0	9.0
LW-20	21224	Rm 313 Top of Teacher's Desk	<9.0	9.0
LW-21	21224	Rm 313 Floor Near Teacher's Desk	<9.0	9.0
LW-22	21224	Field Blank	<9.0 µg	9.0 µg
LW-23	21224	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106604

NYC 9/11 Public Portal Document
08/16/2002 19:49 212-290-2538 EMSL ANALYTICAL INC PAGE 03/05

150 JERICHO TPKE., FLORAL PARK, NY 11001

03021363

Fax

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE):	DATE 8/16/02 TIME
		SAMPLER NAME (PRINT): AL. Kazakov	SAMPLE(S) SEALED (YES / NO)
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217/29881		CORRECT CONTAINER(S) (YES / NO)

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft2
	LW 24	Room 311 Top of computer desk.	1.0				X	<10.0
	LW 25	Room 311 Floor center area	1.0				X	<10.0
	LW 26	Room 315 Top of Teacher's desk	1.0				X	<10.0
	LW 27	Room 315 Floor near east window	1.0				X	<10.0
	LW 28	Room C321 Floor near entrance	1.0				X	<10.0
	LW 29	Room C323 Floor center of room	1.0				X	<10.0
	LW 30	Room 325 Top of Teacher's desk	1.0				X	<10.0
	LW 31	Room 325 Floor beneath thermostat	1.0				X	<10.0

Fax results to Faylan (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 8/16/02 TIME 13:00	PRINTED NAME AL. KAZAKOV	RECEIVED BY (SIGNATURE)	DATE 8/16/02 TIME 15pm	PRINTED NAME S Petrecky
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL MANHATTAN RECEIVED 02 AUG 16 PM 1:54

NYC-WTC_000106605

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

0302113G3

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): [signature] DATE: 8/16/02 TIME:	SAMPLE(S) SEALED: YES / NO
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): AL. KAZACOS	CORRECT CONTAINER(S): YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW32	Room 327 Top of Teachers Desk	1.0				X	< 10.0
	LW33	Room 327 Floor NEAR EAST WINDOW	1.0				X	< 10.0
	LW34	Room 329 Top of Teachers Desk	1.0				X	< 10.0
	LW35	Room 329 Floor NEAR CABINETS	1.0				X	< 10.0
	LW36	Room 333 Top of FILING CABINET / NEAR E. ENT.	1.0		X			< 10.0
	LW37	Room 333 FLOOR CENTER of Room	1.0				X	< 10.0
	LW38	Room 335 Top of Teachers Desk	1.0				X	< 10.0
	LW39	Room 335 FLOOR CENTER of Room	1.0				X	< 10.0

Fax results to Taylor (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr TAT

RELINQUISHED BY (SIGNATURE): [signature]	DATE: 8/16/02 TIME: 13:00	PRINTED NAME: AL. KAZACOS	RECEIVED BY (SIGNATURE): [signature]	DATE: 8/16/02 TIME: 1:54pm	PRINTED NAME: S. Petreck
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE):	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

EMSL MANHATTAN RECEIVED 02 AUG 15 PM 1:54

NYC 9/11 Public Portal Document
08/16/2002 19:49 212-290-2536 EMSL ANALYTICAL INC PAGE 04/05

130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030211363

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamlet Senay	SAMPLER (SIGNATURE) / DATE 8/16/02 / TIME	SAMPLE(S) SEALED: YES / NO
		SAMPLER NAME (PRINT): AL Kazakov	CORRECT CONTAINER(S): YES / NO
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: 11477-15217/29881	MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW 40	Room 337 Top of Filing cabinet	1.0			~~BRICK~~	X	< 10.0
	LW 41	Room 337 Floor Behind Clock	1.0				X	< 10.0
	LW 42	Room 339 Top of Teacher's Desk	1.0				X	< 10.0
	LW 43	Room 339 Floor South side / between windows	1.0				X	< 10.0
	LW 44	FIELD BLANK						—
	LW 45	FIELD BLANK						—

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

	DATE	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	8/16/02	AL. Kazakov
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
RECEIVED BY (SIGNATURE)	DATE 8/16/02	PRINTED NAME S Petrecky
RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

TIME 13:00 / TIME 1542

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

02 AUG 16 PM 1:54
EMSL ANALYTICAL INC RECEIVED

NYC-WTC_000106606
NYC 9/11 Public Portal Document
08/16/2002 19:49 212-290-2538 EMSL ANALYTICAL INC PAGE 05/05

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217 / 29881 / SCA / Stuyvesant HS

Customer ID: TAYL50
Customer PO:
Received: 08/16/02 1:54 PM
EMSL Order: 030211363
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW24	Room 311 Top oF Computer Desk	0001	8/16/02	144 in²	<10.0 µg/ft²	
LW25	Room 311 Floor Center Area	0002	8/16/02	144 in²	<10.0 µg/ft²	
LW26	Room 315 Top of Teachers Desk	0003	8/16/02	144 in²	<10.0 µg/ft²	
LW27	Room 315 Floor Near East Window	0004	8/16/02	144 in²	<10.0 µg/ft²	
LW28	Room C321 Floor Near Entrance	0005	8/16/02	144 in²	<10.0 µg/ft²	
LW29	Room C323 Floor Center of Room	0006	8/16/02	144 in²	<10.0 µg/ft²	
LW30	Room 325 Top of Teachers Desk	0007	8/16/02	144 in²	<10.0 µg/ft²	

M. Appleldorter
Laboratory Manager
or other approved signatory /ANALYST

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106607

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: **M477-15217 / 29881 / SCA / Stuyvesant HS**

Customer ID: TAYL50
Customer PO:
Received: 08/16/02 1:54 PM
EMSL Order: 030211363
EMSL Project ID

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		*Lab ID*	*Analyzed*	*Area Sampled*	*Lead Concentration*	*Notes*
LW31	Room 325 Floor Beneath Thermostat	*0008*	8/16/02	144 in²	<10.0 µg/ft²	
LW32	Room 327 Top of Teachers Desk	*0009*	8/16/02	144 in²	<10.0 µg/ft²	
LW33	Room 327 Floor Near East Window	*0010*	8/16/02	144 in²	<10.0 µg/ft²	
LW34	Room 329 Top of Teachers Desk	*0011*	8/16/02	144 in²	<10.0 µg/ft²	
LW35	Room 329 Floor Near Cabinets	*0012*	8/16/02	144 in²	<10.0 µg/ft²	
LW36	Room 333 Top of Filing Cabinet / Near E. Ent	*0013*	8/16/02	144 in²	<10.0 µg/ft²	
LW37	Room 333 Floor Center of Room	*0014*	8/16/02	144 in²	<10.0 µg/ft²	
LW38	Room 335 Top of Teachers Desk	*0015*	8/16/02	144 in²	<10.0 µg/ft²	
LW39	Room 335 Floor Center of Room	*0016*	8/16/02	144 in²	<10.0 µg/ft²	
LW40	Room 337 Top of Filing Cabinet	*0017*	8/16/02	144 in²	<10.0 µg/ft²	
LW41	Room 337 Floor Beneath Clock	*0018*	8/16/02	144 in²	<10.0 µg/ft²	
LW42	Room 339 Top of Teachers Desk	*0019*	8/16/02	144 in²	<10.0 µg/ft²	
LW43	Room 339 Floor South Side / Between Windows	*0020*	8/16/02	144 in²	<10.0 µg/ft²	
LW44	Field blank	*0021*	8/16/02	n/a	<10.0 µg/wipe	
LW45	Field blank	*0022*	8/16/02	n/a	<10.0 µg/wipe	

M. Hatfield-Lee
Laboratory Manager
or other approved signatory ANALYST

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106608

NYC-WTC_000106609

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21248 2 of 3

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SGI Stuyvesant

CONTACT: Hamid Sauci,

SAMPLER (SIGNATURE): [signature] DATE: 8/16/02 TIME: 5

SAMPLER NAME (PRINT): Petranik

SAMPLE(S) SEALED: (YES) / NO

CORRECT CONTAINER(S): (YES) / NO

PROJECT LOCATION: 345 Chambers

PROJECT #: M477-15217/29881

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	10	rm 307 Floor ab rear entrance	1				VCT X	< 9.0
	11	rm 307 Floor Table top near entra.	1				VCT X	< 9.0
	16	rm 317 Floor (Rm317) Left S.	1				cemt X	53.0
	17	rm 317 Shelf (Rm317) ~~DR~~ at entrance	1		X			49.0
	18	3'x9' Sylm. Floor Storage room w/ ~~380~~ 380-A. Sewn	1				cemt X	53.6
	19	3'x9' Sylm Shelf Storage rm 380-A	1		X			18.6

212-406-2535 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 10/11

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	8/16/02 1830	R. Petrato			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - FIELD

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-19-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE:	08-16-02
DATE RECEIVED:	08-16-02
DATE ANALYZED:	08-16-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
8	21248	Rm 450A Floor at Entrance	<9.0	9.0
9	21248	Rm 450A Metal Shelf Near Entr.	<9.0	9.0
10	21248	Rm 307 Floor at Rear Entrance	<9.0	9.0
11	21248	Rm 307 Floor Table Top Near Entrance	<9.0	9.0
12	21248	Cellar Corr. O/S C029 Supply	<9.0	9.0
13	21248	Cellar Corr. O/S C029 Supply	15.1	9.0
14	21248	Cellar Corr. O/S C029 Supply	<9.0	9.0
16	21248	Rm 517 Floor Left Side	53.0	9.0
17	21248	Rm 317 Shelf at Entr.	49.0	9.0
18	21248	3rd Floor GYM Floor Storage Rm 380B SW	53.6	9.0
19	21248	3rd Floor GYM Shelf Storage Rm 380B	18.6	9.0
FB7	21248	Field Blank	<9.0 µg	9.0 µg
FB8	21248	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106612

NYC 9/11 Public Portal Document
08/17/2002 12:40 212-290-2538 EMSL ANALYTICAL INC PAGE 01/05

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030211390

185

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAWOJ		8/14/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
STUYVESANT HS.	M477-15217/29881	KIRK MC KENZIE			(YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM C328 - FLOOR Center Elevator Lobby	1.0				X	<10 ug/ft2
	LW-02	ROOM 330 - FLOOR 3' of ENTRANCE	1.0				X	<10 "
	LW-03	ROOM 334 - FLOOR 3' of ENTRANCE	1.0				X	<10
	LW-04	ROOM 336 - FLOOR Center of ROOM	1.0				X	<10
	LW-04A	ROOM 336 - Table Top Left side work Table	1.0				X	<10
	LW-05	ROOM 336A - FLOOR Center of ROOM	1.0				X	<10
	LW-06	ROOM 336A - Table Top - North side cabinet	1.0				X	<10
	LW-07	ROOM 336C - FLOOR Center of ROOM	1.0				X	<10 S.M. 08/17/02

EMSL MANHATTAN RECEIVED
02 AUG 17 AM 4:33

FAX RESULTS TO: 212 406-2535
516 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 4:15	PRINTED NAME KIRK McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8.17.02 TIME 4.30	PRINTED NAME TERESA MICHALUK	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

Client asked for analysis to marshall

NYC-WTC_000106613

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

0302 11390. 285

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAWOJ	SAMPLER (SIGNATURE):	DATE: 8/16/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): KIRK MC KENZIE		CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: STUYVESANT HS	PROJECT #: M477-15217 /29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-08	ROOM 336 C - Shelf EAST SIDE	1.0		X			<10 ug/ft2
	LW-09	ROOM 336 R - FLOOR Center of ROOM	1.0				X	<10 "
	LW-10	ROOM 336 R - Table Top - South Table	1.0				X	<10
	LW-11	ROOM 338 - FLOOR 6' of ENTRANCE	1.0				X	<10
	LW-12	ROOM 338 - # 3 Booth Table Top - Left of Ent.	1.0				X	14.41 ug/ft2
	LW-13	Locker # 3-193 O/S RM 333	1.0		X			<10
	LW-14	CORRIDOR O/S ROOM 338 - FLOOR	1.0					<10
	LW-15	ROOM 351 - FLOOR LW SIDE BY RADIATOR	1.0				X	<10 SM. 08/17/02

EMSL ANALYTICAL INC RECEIVED 02 AUG 17 AM 6:33

FAX RESULTS TO: 212 406-2535, 516 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr. TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 0415	PRINTED NAME: KIRK McKENZIE	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8.17.02 TIME 4.30	PRINTED NAME: TEKEYA MICHAELOVE	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE YELLOW - LAB PINK - CLIENT Hold for results

NYC 9/11 Public Portal Document
08/17/2002 12:40 212-290-2538 EMSL ANALYTICAL INC PAGE 02/05

NYC-WTC_000106614

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021139O

385

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID BINOJ		8/16/02		(YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-16	ROOM 351 - Table Top SW work Table	1.0	X				<10 MG/FT2
	LW-17	ROOM 351A - FLOOR 5' of ENTRANCE	1.0				X	<10
	LW-18	ROOM 351A - Shelf Top South Shelf	1.0		X			<10
	LW-19	ROOM 351 B - FLOOR Center of ROOM	1.0				X	<10
	LW-20	ROOM 351 B - Shelf Top white Shelf - CABINET	1.0				X	<10
	LW-21	Locker # 3-283 NW CORRIDOR	1.0		X			<10
	LW-22	ROOM 350 - FLOOR 5' of EAST Center column	1.0				X	<10
	LW-23	ROOM 350 - Table Top SE work Table	1.0	X				<10 Surface Wipes 08/17/02

EMSL MANHATTAN RECEIVED 02 AUG 17 AM 4:33

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /	COMMENTS / INSTRUCTIONS 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 0415	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE) Teresa	DATE 8,17,02 TIME 04,30	PRINTED NAME TERESA MICHALUZUK	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

NYC 9/11 Public Portal Document
08/17/2002 12:40 212-290-2538 EMSL ANALYTICAL INC PAGE 03/05

NYC-WTC_000106615

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021139O

485

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC B CA	CONTACT: HAMID SAVOJ	SAMPLER (SIGNATURE)	DATE 8/16/02 TIME	SAMPLE(S) SEALED (YES) / NO
		SAMPLER NAME (PRINT) Kirk McKenzie		CORRECT CONTAINER(S) (YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St NY	PROJECT # M477-15217-2988	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-24	ROOM 360 - FLOOR 3' of ENTRANCE	1.0				X	<10 Mg/Ft²
	LW-25	ROOM 362 - FLOOR 3' of ENTRANCE	1.0				X	<10
	LW-26	ROOM 350A - FLOOR Center of ROOM	1.0				X	<10
	LW-27	ROOM 350A - Table Top - Center Table	1.0				X	<10
	LW-28	ROOM 350 B - FLOOR 3' of ENTRANCE	1.0				X	<10
	LW-29	ROOM 350 B - Top of CABINET. Left side	1.0		X			<10
	LW-30	ROOM 332 - FLOOR	1.0					<10
	~~FBL-1~~ FBL-1	Field Blank	—					<10 Mg/Wipe

EMSL-MANHATTAN RECEIVED 02 AUG 17 AM 4:34

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 04:15	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 08.17.02 TIME 4.30	PRINTED NAME TERESA MICHALSKI	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

NYC 9/11 Public Portal Document
08/17/2002 12:40 212-290-2538 EMSL ANALYTICAL INC PAGE 04/05

NYC-WTC_000106616

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021139O

5 of 5

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CUENT NAME/ADDRESS	CONTACT:	SAMPLER(SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAVOJ		8/16		(YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST NY	PROJECT # M477-15217-2	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	FBL-2	Field Blank						<10 ug/wipe
	FBL-3	Field Blank						<10 ug/wipe
	FBL-4	Field Blank						<10 ug/wipe
								Susan Morse 08/17/02

EMSL MANHATTAN RECEIVED 02 AUG 17 AM 4:34

TURNAROUND REQUIRED:	COMMENTS / INSTRUCTIONS
NORMAL ☐ STAT ☐ BY / /	6 Hr. TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 0415	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8.17.02 TIME 4.30	PRINTED NAME TERESA MICHALUSKI	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

NYC 9/11 Public Portal Document
08/17/2002 12:40 212-290-2538 EMSL ANALYTICAL INC PAGE 05/05

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217 / 29881 /NYCSCA/ STUYVESANT H.S.

Customer ID: TAYL50
Customer PO:
Received: 08/17/02 4:30 AM
EMSL Order: 030211390
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	ROOM C328 FLR CENTER ELEV LOBBY	0001	8/17/02	144 in²	<10.0 µg/ft²	
LW-02	ROOM 330 / FLOOR / 3 IN. OF ENTRANCE	0002	8/17/02	144 in²	<10.0 µg/ft²	
LW-03	ROOM 334 / FLOOR 3 IN. OF ENTRANCE	0003	8/17/02	144 in²	<10.0 µg/ft²	
LW04	ROOM 336 / FLOOR / CENTER OF ROOM	0004	8/17/02	144 in²	<10.0 µg/ft²	
LW-04A	ROOM 336 / TABLE TOP / LEFT SIDE WORK TABLE	0005	8/17/02	144 in²	<10.0 µg/ft²	
LW-05	ROOM 336A / FLOOR / CENTER OF ROOM	0006	8/17/02	144 in²	<10.0 µg/ft²	
LW-06	ROOM 336A / TABLE TOP / NORTH SIDE CABINET	0007	8/17/02	144 in²	<10.0 µg/ft²	
LW-07	ROOM 336C / FLOOR / CENTER OF ROOM	0008	8/17/02	144 in²	<10.0 µg/ft²	
LW-08	ROOM 336C / SHELF / EAST SIDE	0009	8/17/02	144 in²	<10.0 µg/ft²	
LW-09	ROOM 336B / FLOOR / CENTER OF ROOM	0010	8/17/02	144 in²	<10.0 µg/ft²	
LW-10	ROOM 336B / TABLE TOP / SOUTH TABLE	0011	8/17/02	144 in²	<10.0 µg/ft²	
LW-11	ROOM 338 / FLOOR / 6 IN. OF ENTRANCE	0012	8/17/02	144 in²	<10.0 µg/ft²	
LW-12	ROOM 338 / #3 BOOTH TABLE TOP / LEFT OF ENT.	0013	8/17/02	144 in²	14.0 µg/ft²	
LW-13	LOCKER #3-193 O/S RM 333	0014	8/17/02	144 in²	<10.0 µg/ft²	
LW-14	CORRIDOR O/S ROOM 338 / FLOOR	0015	8/17/02	144 in²	<10.0 µg/ft²	
LW-15	ROOM 351 / FLOOR / NW SIDE BY RADIATOR	0016	8/17/02	144 in²	<10.0 µg/ft²	

Laboratory Manager or other approved signatory Analyst

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106617

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217 / 29881 /NYCSCA/ STUYVESANT H.S.

Customer ID: TAYL50
Customer PO:
Received: 08/17/02 4:30 AM
EMSL Order: 030211390
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-16	ROOM 351 / TABLE TOP / SW WORK TABLE	0017	8/17/02	144 in²	<10.0 µg/ft²	
LW-17	ROOM 351A / FLOOR / 3 IN. OF ENTRANCE	0018	8/17/02	144 in²	<10.0 µg/ft²	
LW-18	ROOM 351A / SHELF TOP / SOUTH SHELF	0019	8/17/02	144 in²	<10.0 µg/ft²	
LW-19	ROOM 351B / FLOOR / CENTER OF ROOM	0020	8/17/02	144 in²	<10.0 µg/ft²	

Laboratory Manager or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106618

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217 / 29881 /NYCSCA/ STUYVESANT H.S.

Customer ID: TAYL50
Customer PO:
Received: 08/17/02 4:30 AM
EMSL Order: 030211390
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-20	ROOM 351B / SHELF TOP / WHITE SHELF CABINET	0021	8/17/02	144 in²	<10.0 µg/ft²	
LW-21	LOCKER #3-283 / NW CORRIDOR	0022	8/17/02	144 in²	<10.0 µg/ft²	
LW-22	ROOM 350 / FLOOR / 5 IN. OF EAST CENTER CLMN	0023	8/17/02	144 in²	<10.0 µg/ft²	
LW-23	ROOM 350 / TABLE TOP / SE WORK TABLE	0024	8/17/02	144 in²	<10.0 µg/ft²	
LW-24	ROOM 360 / FLOOR / 3 IN. OF ENTRANCE	0025	8/17/02	144 in²	<10.0 µg/ft²	
LW-25	ROOM 362 / FLOOR / 3 IN. OF ENTRANCE	0026	8/17/02	144 in²	<10.0 µg/ft²	
LW-26	ROOM 350A / FLOOR / CENTER OF ROOM	0027	8/17/02	144 in²	<10.0 µg/ft²	
LW-27	ROOM 350A / TABLE TOP / CENTER TABLE	0028	8/17/02	144 in²	<10.0 µg/ft²	
LW-28	ROOM 350B / FLOOR / 3 IN. OF ENTRANCE	0029	8/17/02	144 in²	<10.0 µg/ft²	
LW-29	ROOM 350B / TOP OF CABINET / LEFT SIDE	0030	8/17/02	144 in²	<10.0 µg/ft²	
LW-30	ROOM 332 / FLOOR	0031	8/17/02	144 in²	<10.0 µg/ft²	
FBL-1	Field blank	0032	8/17/02	n/a	<10.0 µg/wipe	
FBL-2	Field blank	0033	8/17/02	n/a	<10.0 µg/wipe	
FBL-3	Field blank	0034	8/17/02	n/a	<10.0 µg/wipe	
FBL-4	Field blank	0035	8/17/02	n/a	<10.0 µg/wipe	

Laboratory ~~Manager~~ or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106619

NYC-WTC_00010620

130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

U3021141D

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAVOY	SAMPLER (SIGNATURE): Carlos Moffat	DATE: 8-17-02 TIME:
PROJECT LOCATION: STUYVESANT H.S.	PROJECT #: H177-15217/29881	SAMPLER NAME (PRINT): CARLOS MOFFAT	SAMPLE(S) SEALED: YES / NO; CORRECT CONTAINER(S): YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
PB-1857	LW-01	TOP OF SHELL AT CENTER. ROOM # G 380A.	1 FT²		✓			< 10.0
PB-1857	LW-02	FLOOR BY ENTRANCE. ROOM # G 380A	1 FT²				✓	< 10.0
	LW-03	TOP OF CABINET ROOM # 336 D	1 FT²		✓			110.0
	LW-04.	FLOOR BY ENTRANCE ROOM # 336 D.	1 FT²				✓	11.0
	FB-01	FIELD BLANK	—					—
	FB-02	FIELD BLANK	—					—

RECEIVED 02 AUG 17 PM 1:07

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

	DATE	PRINTED NAME		DATE	PRINTED NAME
RELINQUISHED BY (SIGNATURE): Gary McKenzie	8/17/02 TIME 1310	GARY McKENZIE	RECEIVED BY (SIGNATURE): M. Hall	TIME	
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

PAGE 02/04
EMSL ANALYTICAL INC
212-290-2538
08:21
08/19/2002
NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217/29881 / NYC-SCA / STUYVESANT H.S.

Customer ID: TAYL50
Customer PO:
Received. 08/17/02 1:07 PM
EMSL Order: 030211410
EMSL Project ID

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	TOP OF SHELL AT CENTER / ROOM #G380A	0001	8/17/02	144 in²	<10.0 µg/ft²	
LW-02	FLOOR BY ENTRANCE / ROOM #E380A	0002	8/17/02	144 in²	<10.0 µg/ft²	
LW-03	TOP OF CABINET / ROOM #336D	0003	8/17/02	144 in²	110.0 µg/ft²	
LW-04	FLOOR BY ENTRANCE / ROOM #336D	0004	8/17/02	144 in²	11.0 µg/ft²	
FB-01	Field blank	0005	8/17/02	n/a	<10.0 µg/wipe	
FB-02	Field blank	0006	8/17/02	n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106621

NYC-WTC_00010922

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1700

0302114215

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAUDJ	SAMPLER (SIGNATURE): Carlos Tofat — DATE: 8-17-02. TIME:	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): CARLOS TOFAT	CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: STUYVESANT H.S	PROJECT #: HH77-15217/29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT (mg/cm²)
Pb-1051	LW-01	ROOM # 336 D. TOP OF CABINET			✓			<10.0
Pb-1052	LW-02	ROOM # 336 D FLOOR by ENTRANCE.					✓	<10.0
	FB 1	FIELD BLANK						
	FB 2.	FIELD BLANK						

02 AUG 17 PM 4:28

EMSL ANALYTICAL INC RECEIVED

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: A S A P.

	DATE	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	8/17/02	GARY McGENZIE			
	TIME 1629			TIME	
RELINQUISHED BY (SIGNATURE)	DATE	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE	PRINTED NAME
	TIME			TIME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

PAGE 03/04 EMSL ANALYTICAL INC 212-290-2538 08:21 08/19/2002

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn:	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/17/02 4:28 PM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030211415
Project:	M477-15217/29881 / NYC-SCA / STUYVESANT H.S	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		*Lab ID*	*Analyzed*	*Area Sampled*	*Lead Concentration*	*Notes*
LW-01	ROOM #336-D / TOP OF CABINET	*0001*	8/17/2002	144 in^2	<10.0 $\mu g/ft^2$	
LW-02	ROOM #336-D / FLOOR BY ENTRANCE	*0002*	8/17/2002	144 in^2	<10.0 $\mu g/ft^2$	
FB 1	Field blank	*0003*	8/17/2002	n/a	<10.0 µg/wipe	
FB 2	Field blank	*0004*	8/17/2002	n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102591

NYC-WTC_000106623

NYC-WTC_000106624

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2/251, 64

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAWOJ	SAMPLER (SIGNATURE)	DATE 8/17/02 TIME
PROJECT LOCATION: STUYVESANT HS.	PROJECT # M477-15217/29881	SAMPLER NAME (PRINT) Kirk McKenzie	SAMPLE(S) SEALED (YES) / NO; CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-31	Room 273 - Floor North side by Radiator	1				X	< 9.0
	LW-32	Room 373 - Table Top North side	1				X	< 9.0
	LW-33	Room 372 - Floor Center of Room	1				X	< 9.0
	LW-34	Room 372 - Desk Top South Desk	1				X	< 9.0
	LW-35	Room 371 - Floor North side by Rinck Board	1				X	< 9.0
	LW-36	Room 371 - Table Top Northeast side	1				X	< 9.0
	LW-37	Room 371A - Floor 3' of Entrance	1				X	< 9.0
	LW-38	Room 371A - Desk Top 1st Desk	1				X	< 9.0

FAX Results to 212-406-2536 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 0520	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) R. Proudlina	DATE 8.17.02 TIME 05.20	PRINTED NAME R. Proudlina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE) 08/17 10AM	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106625

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21251 2845

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAWOJ		8/17/02		(YES) / NO
PROJECT LOCATION: STUYVESANT HS	PROJECT # M477-15217 (29881)	SAMPLER NAME (PRINT) KIRK MC KENZIE			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-39	ROOM 371 B - FLOOR [redacted] 3' of ROOM ENT.	1				X	< 9.0
	LW-40	ROOM 371 B - TOP OF [redacted] 1ST DESK	1				X	< 9.0
	LW-41	ROOM 371 C - FLOOR center of ROOM	1				X	13.8
	LW-42	ROOM 371 C - TOP of Red [redacted]	1		[redacted]		X	18.7
	LW-43	ROOM 371 D - FLOOR by entrance	1				X	< 9.0
	LW-44	ROOM 371 D - TOP of Red PLATFORM	1		X			< 9.0
	LW-45	ROOM 371 E - FLOOR NW SIDE	1				X	26.8
	LW-46	ROOM 371 E - TOP of Refrigerator - South	1				X	< 9.0

FAX RESULTS TO: 212 406-2536
516 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 0520	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) A. Cu 08/17 10AM	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE) R. Droudina	DATE 8.17.02 TIME 05:20	PRINTED NAME R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106626

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21251

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAWOZ	SAMPLER (SIGNATURE):	DATE: 8/17/02 TIME:
PROJECT LOCATION: STUY WEST HS	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): KIRK MC KENZIE	SAMPLE(S) SEALED: YES / NO; CORRECT CONTAINER(S): YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-47	ROOM 371 E - FLOOR 3' @ ENTRANCE	1				X	< 9.0
	LW-48	ROOM 371 G - FLOOR 3' @ ENTRANCE	1				X	< 9.0
	LW-49	NE CORRIDOR O/S GYM FLOOR - by North ENTRANCE					X	< 9.0
	LW-50	~~Room~~ GYM (G380) - FLOOR Center of Gym		X				< 9.0
	LW-51	GYM (G380) ~~Locker~~ TOP of Bleachers South END		X				13.2
	LW-52	G380 B - FLOOR Center of ROOM					X	11.4
	LW-53	G380 B - Shelf TOP Left SIDE			X			< 9.0
	LW-54	G380 C - FLOOR West SIDE					X	15.5

FAX RESULTS TO: 212 406-2536
516 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 05:20	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE): R. Droudilla	DATE 8.17.02 TIME 05.20	PRINTED NAME: R. Droudilla

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106627

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21251

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CUENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAWOZ	SAMPLER (SIGNATURE):	DATE: 8/17/02 TIME:
PROJECT LOCATION: STUYVESANT HS	PROJECT #: M477-15217 / 29881	SAMPLER NAME (PRINT): KIRK MC KENZIE	SAMPLE(S) SEALED (YES) NO; CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-55	G380 C - Shelf Center	1		X			< 9.0
	LW-56	G382 (Aux Gym) - Floor By G382 B	1				X	< 9.0
	LW-57	G382 - Top of Tumbling Pads	1				X	23.4
	LW-58	G382/A - Floor by entrance	1					26.0
	LW-59	G382 B - Floor Center of Room	1				X	27.9
	LW-60	G382 B - Shelf Left side	1		X			30.8
Re-Test	LW-61	Room 317 - Floor 3' of Entrance	1				X	19.2
Re-Test	LW-62	Room 317 - Shelf Right side	1		X			< 9.0

FAX RESULTS TO: 212 406-2536
516 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 05:20	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE): K.C 08/17 10 AM	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE): R. Droudina	DATE 8.17.02 TIME 05.20	PRINTED NAME: R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106628

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

21251 5 of 5

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Bavoj		8/17/02		(YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St N.Y.	PROJECT # M477-D217-2881	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S) (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-63	Corridor - East side by Elevators - Floor	1				X	< 9.0
	LW-64	Locker # 3-98 O/S Gym	1		X			< 9.0
	~~FBL-1~~	~~Locker~~ Field Blank	—					< 9.0
	FBL-2	Field Blank	—					< 9.0
	FBL-3	Field Blank	—					< 9.0
	FBL-4	Field Blank	—					< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 8 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/17/02 TIME 0520	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-19-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217-29881

SAMPLED BY: Client

SAMPLE DATE: 08-17-02
DATE RECEIVED: 08-17-02
DATE ANALYZED: 08-17-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-31	21251	Rm 373 Floor North Side by Radiator	<9.0	9.0
LW-32	21251	Rm 373 Tabel Top North Side	<9.0	9.0
LW-33	21251	Rm 372 Floor Center of Room	<9.0	9.0
LW-34	21251	Rm 372 Desk Top South Desk	<9.0	9.0
LW-35	21251	Rm 371 Floor North Side by Blackboard	<9.0	9.0
LW-36	21251	Rm 371 Table Top North East Side	<9.0	9.0
LW-37	21251	Rm 371A Floor 3' of Entrance	<9.0	9.0
LW-38	21251	Rm 371A Desk Top 1st Desk	<9.0	9.0
LW-39	21251	Rm 371B Floor of Room Ent.	<9.0	9.0
LW-40	21251	Rm 371B Top of 1st Desk	<9.0	9.0
LW-41	21251	Rm 371C Floor Center of Room	13.8	9.0
LW-42	21251	Rm 371C Top of Bed	18.7	9.0
LW-43	21251	Bedroom 371D Floor by Entrance	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-44	21251	Rm 371D Top of Bedroom Platform	<9.0	9.0
LW-45	21251	Rm 371E Floor NW Side	26.8	9.0
LW-46	21251	Rm 371E Top of Refrigerator South	<9.0	9.0
LW-47	21251	Rm 371F Floor 3' of Entrance	<9.0	9.0
LW-48	21251	Rm 371G Floor 3' of Entrance	<9.0	9.0
LW-49	21251	NE Corridor O/S GYM Floor by North Entrance	<9.0	9.0
LW-50	21251	GYM (G380) Floor Center of GYM	<9.0	9.0
LW-51	21251	GYM (G380) Top of Bleechers South End	13.2	9.0
LW-52	21251	G380B Floor Center of Room	11.4	9.0
LW-53	21251	G380 Shelf Top Left Side	<9.0	9.0
LW-54	21251	G380C Floor West Side	15.5	9.0
LW-55	21251	G380C Shelf Center	<9.0	9.0
LW-56	21251	G382 (Aux. GYM) Floor by G382B	<9.0	9.0
LW-57	21251	G382 Top of Tumbling Pads	23.4	9.0
LW-58	21251	G382A Floor by Entrance	26.0	9.0
LW-59	21251	G382B Floor Center of Room	27.9	9.0
LW-60	21251	G382B Shelf Left Side	30.8	9.0
LW-61	21251	Rm 317 Floor 3' of Entrance	19.2	9.0
LW-62	21251	Rm 317 Shelf Right Side	<9.0	9.0
LW-63	21251	Corridor East Side by Elevator Floor	<9.0	9.0
LW-64	21251	Locker #3-98 O/S GYM	<9.0	9.0
FBL-1	21251	Field Blank	<9.0 µg	9.0 µg
FBL-2	21251	Field Blank	<9.0 µg	9.0 µg
FBL-3	21251	Field Blank	<9.0 µg	9.0 µg
FBL-4	21251	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: ITCM

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_00010632 PAGE 02/02 EMSL ANALYTICAL INC 212-290-2538 08/19/2002 14:04

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYCSCA Stuyvesant H.S.
CONTACT: H. Sadoi
SAMPLER (SIGNATURE): [signature] DATE: 8/19/02 TIME: 4C
SAMPLER NAME (PRINT): [illegible]
SAMPLE(S) SEALED: YES / NO
CORRECT CONTAINER(S): YES / NO
PROJECT LOCATION: Chambers St, NY, NY
PROJECT #: M477-15217-29881
MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
RJ Test	LW-01	Rm 371-E Floor next to Desk	1.0				X	<10.0
RJ Test	LW-02	Rm 371-E Desk-Top	1.0				X	<10.0
RJ Test	LW-03	Aux Gym G-382-A Floor	1.0				X	<10.0
RJ Test	LW-04	Rm G-382-B Floor	1.0				X	12.0
RJ Test	LW-05	Rm G-382-B Shelf. L.H.S.	1.0		X			<10.0
RJ Test	LW-06	Rm G-382 - Aux Gym Floor @ Center Window	1.0	X				<10.0
RJ Test	LW-07	Rm G-382 - Aux Gym. Tumbling Mat.	1.0				X	<10.0
	FB-1 / FB-2	F/Blank-1 / F/Blank-2	—					—

02 AUG 19 AM 11:59 EMSL TAMPA FLA RECEIVED

TURNAROUND REQUIRED: NORMAL ☐ STAT ☒ BY / /
COMMENTS / INSTRUCTIONS: ASAP (Stat)

RELINQUISHED BY (SIGNATURE)	DATE	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE	PRINTED NAME
[signature]	8/19	Cathy McKenzie		TIME	
RELINQUISHED BY (SIGNATURE)	DATE	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE	PRINTED NAME
	TIME			TIME	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001

Fax: (516) 358-1780 Phone: 516-358-2955

Project: M477-15217-29881/ NYC SCA STUYVESANT H.S./ CHAMBERS ST. NY, NY

Customer ID: TAYL50
Customer PO:
Received: 08/19/02 11:59 AM

EMSL Order: 030211452
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	RM. 371-E FLOOR ADJ. TO DESK	0001	8/19/2002	144 in²	<10.0 µg/ft²	
LW-02	RM. 371-E DESK-TOP	0002	8/19/2002	144 in²	<10.0 µg/ft²	
LW-03	AUX GYM G-382-A FLOOR	0003	8/19/2002	144 in²	<10.0 µg/ft²	
LW-04	RM. G-382-B FLOOR	0004	8/19/2002	144 in²	12.0 µg/ft²	
LW-05	RM. G-382-B SHELF L.H.S.	0005	8/19/2002	144 in²	<10.0 µg/ft²	
LW-06	RM. G-382 FLOOR @ CONTOR WINDOW	0006	8/19/2002	144 in²	<10.0 µg/ft²	
LW-07	RM. G-382 TUMBLING MAT.	0007	8/19/2002	144 in²	<10.0 µg/ft²	
FB-1	F/BLANK-1	0008	8/19/2002	n/a	<10.0 µg/wipe	
FB-2	F/BLANK-2	0009	8/19/2002	n/a	<10.0 µg/wipe	

M. Applebaum
Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106633

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.

UNIT VENTILATOR LEAD WIPE SAMPLE RESULTS 3RD THROUGH 10TH FLOORS

PROJECT #: M477-15217
LLW#: 29881

130A JERICHO TPKE., FLORAL PARK, NY 11001 ▪ PHONE (516) 358-2955 ▪ FAX (516) 358-1780

NYC-WTC_000106635

NYC-WTC_000106636

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20362

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savov		7/14/02		YES / NO
PROJECT LOCATION: Stuyvesant HS	PROJECT # M477-15217/29881	SAMPLER NAME (PRINT) Al. Kazamov			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-01	Room # 1001, East side Univent (back wall)	1		X			<9.0
	W-02	Room # 1001, South side Left Univent (back wall)	1		X			<9.0
	W-03	Room # 1001, South side Right Univent (back wall)	1		X			<9.0
	W-04	Room # 1007, South side Left Univent (back wall)	1		X			<9.0
	W-05	Room # 1007, South side Middle Univent (back wall)	1		X			<9.0
	W-06	Room # 1007, South side Right Univent (back wall)	1		X			<9.0
	W-07	F/B						<9.0
	W-08	F/B						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☑ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/14/02 2100	Al. Kazamov			
RELINQUISHED BY (SIGNATURE) Georgiek	DATE 7.14.02 TIME 21.00	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-15-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS

SAMPLED BY: Client

SAMPLE DATE 07-14-02
DATE RECEIVED: 07-14-02
DATE ANALYZED: 07-14-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20362	Room 1001 East Side Univent Back Wall	<9.0	9.0
W-02	20362	Room 1001 South Side Left Univent Back Wall	<9.0	9.0
W-03	20362	Room 1001 South Side Right Univent Back Wall	<9.0	9.0
W-04	20362	Room 1007 South Side Left Univent Back Wall	<9.0	9.0
W-05	20362	Room 1007 South Side Middle Univent Back Wall	<9.0	9.0
W-06	20362	Room 1007 South Side Right Univent Back Wall	<9.0	9.0
W-07	20362	Field Blank	<9.0	9.0
W-08	20362	Field Blank	<9.0	9.0

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106638

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20386

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Sotvoj
PROJECT LOCATION: Stuyvesant HS 345 Chambers St NY	PROJECT #: M477-15217/2988
SAMPLER SIGNATURE:	DATE: 7/15/02 TIME:
SAMPLER NAME (PRINT): Kirk McKenzie	SAMPLE(S) SEALED (YES) / NO; CORRECT CONTAINER(S) (YES) / NO
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 1009, South side Left unitvent - REAR	1		✓			< 9.0 µg/ft²
	LW-02	ROOM 1009, South side Right unitvent - Rear	1		✓			< 9.0
	LW-03	ROOM 1017, South side Left unitvent - REAR	1		✓			< 9.0
	LW-04	ROOM 1017, South side Right unitvent - REAR	1		✓			< 9.0
	LW-05	ROOM 1025, South side Left unitvent - REAR	1		✓			< 9.0
	LW-06	ROOM 1025, South side Middle unitvent - REAR	1		✓			< 9.0
	LW-07	ROOM 1025, South side Right side - Rear	1		✓			< 9.0
	LW-08	ROOM 1024, North side Left unitvent - Rear	1		✓			< 9.0

6:00pm

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/15/02 TIME 1700	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

[redacted] ENVIRONMENTAL [redacted] GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20386

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): [signature] DATE: 7/15/02 TIME:	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St, NY	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 1009, South side Left unitvent - REAR	1		✓			< 9.0 µg/ft²
	LW-02	ROOM 1009, South side Right unitvent - REAR	1		✓			< 9.0
	LW-03	ROOM 1017, South side Left unitvent - REAR	1		✓			< 9.0
	LW-04	ROOM 1017, South side Right unitvent - REAR	1		✓			< 9.0
	LW-05	ROOM 1025, South side Left unitvent - REAR	1		✓			< 9.0
	LW-06	ROOM 1025, South side Middle unitvent - REAR	1		✓			< 9.0
	LW-07	ROOM 1025, South side Right side - REAR	1		✓			< 9.0
	LW-08	ROOM 1024, North side Left unitvent - REAR	1		✓			< 9.0

[signature] 6:00pm			TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /	COMMENTS / INSTRUCTIONS: 6 HR TAT
RELINQUISHED BY (SIGNATURE): [signature]	DATE: 7/15/02 TIME: 1700	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE): [signature]	DATE: TIME: PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE): [signature]	DATE: TIME: PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_000106639
NYC 9/11 Public Portal Document

NYC-WTC_000106640

[redacted] ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20386

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Bavoj	SAMPLER (SIGNATURE)	DATE 7/15/02 TIME	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST, NY	PROJECT # M477-15217/2988	SAMPLER NAME (PRINT)		CORRECT CONTAINER(S) (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09	ROOM 1024, North side Right unit vent - REAR	1		✓			< 9.0
	LW-10	ROOM 1033, South side Left unit vent - REAR	1		✓			< 9.0
	LW-11	ROOM 1033, South side Right unit vent - REAR	1		✓			< 9.0
	LW-12	ROOM 1039, South side - REAR	1		✓			< 9.0
	LW-13	ROOM 1039, North side Left unit vent, - REAR	1		✓			11.3
	LW-14	ROOM 1039, North side Middle unit vent - REAR	1		✓			< 9.0
	LW-15	ROOM 1039, North side Right unit vent - REAR	1		✓			< 9.0
	FBL-1	Field Blank -						< 9.0
	FBL-2	Field Blank -						< 9.0

TURNAROUND REQUIRED. NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/15/02 TIME 1700	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106641

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

2039/

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy		7/15/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M447-15217/29881	AL. Kazakov			(YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	W-01	Room # 1004 North side Left Univent (Back wall)	1		X			
	W-02	Room # 1004 North side Right Univent (Back wall)	1		X			
	W-03	Room # 1006 North side Left Univent (Back wall)	1		X			
	W-04	Room # 1006 North side Right Univent (Back wall)	1		X			
	W-05	Room # 1006 North side Middle Univent (Back wall)	1		X			
	W-06	F/B "						"
	W-07	F/B "						"
	W-08							

TURNAROUND REQUIRED.
NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS
06 hr

RELINQUISHED BY (SIGNATURE)	DATE 7/15/02 TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE 7/16/02 TIME 4pm	PRINTED NAME
		AL. Kazakov			
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-16-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers St., NY

SAMPLED BY: Client

SAMPLE DATE 07-16-02
DATE RECEIVED: 07-16-02
DATE ANALYZED: 07-16-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20391	Rm 1004 North Side Left Univent Back Wall	<9.0	9.0
W-02	20391	Rm 1004 North Side Right Univent Back Wall	<9.0	9.0
W-03	20391	Rm 1006 North Side Left Univent Back Wall	<9.0	9.0
W-04	20391	Rm 1006 North Side Right Univent Back Wall	<9.0	9.0
W-05	20391	Rm 1006 North Side Middle Univent Back Wall	<9.0	9.0
W-06	20391	Field Blank	<9.0 µg	9.0 µg
W-07	20391	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106643

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20410

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): [signature] DATE: 7/16/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers ST. NY NY	PROJECT #	SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S): (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 1010, North side Left unitvent - REAR	1		✓			23.2
	LW-02	ROOM 1010, North side Middle unitvent - REAR	1		✓			22.3
	LW-03	ROOM 1010, North side Right unitvent - REAR.	1		✓			26.2
	FBL-1	Field Blank	—	—	—	—	—	<9.0
	FBL-2	Field Blank	—	—	—	—	—	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/16/02 TIME 1100	PRINTED NAME	RECEIVED BY (SIGNATURE) [signature] 07/16	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE) [signature]	DATE 7/16/02 TIME 1450	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106644

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20409

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): [signature] DATE: 7/16/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. NY NY	PROJECT #: M477-15217/2988	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 901, EAST SIDE unitVent - REAR	1		✓			14.3
	LW-02	ROOM 903 - South side Left unitVent - REAR	1		✓			16.1
	LW-03	ROOM 903 - South side middle unitVent - REAR	1		✓			9.5
	LW-04	ROOM 903 - South side Right unitVent - REAR	1		✓			12.0
	LW-05	ROOM 907 - South side unitVent - REAR	1		✓			12.7
	LW-06	ROOM 911 - South side Left unitVent - REAR	1		✓			15.8
	LW-07	ROOM 911 - South side Right unitVent - REAR	1		✓			30.3
	FBL-1	Field Blank						< 9.0
	FBL-2	Field Blank						< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6HR TAT

RELINQUISHED BY (SIGNATURE): [signature]	DATE: 7/16/02 TIME: 1600	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE): [signature]	DATE: TIME: 5:00pm	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE): [signature] 7/16 6pm	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-17-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers St., NY

SAMPLED BY: Client

SAMPLE DATE 07-16-02
DATE RECEIVED: 07-16-02
DATE ANALYZED: 07-16-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20409	Rm 901 East Side Unitvent Rear	14.3	9.0
LW-02	20409	Rm 903 South Side Left Unitvent Rear	16.1	9.0
LW-03	20409	Rm 903 South Side Middle Unitvent Rear	9.5	9.0
LW-04	20409	Rm 903 South Side Right Unitvent Rear	12.0	9.0
LW-05	20409	Rm 907 South Side Unitvent Rear	12.7	9.0
LW-06	20409	Rm 911 South Side Left Unitvent Rear	15.8	9.0
LW-07	20409	Rm 911 South Side Right Unitvent Rear	30.3	9.0
FBL-1	20409	Field Blank	<9.0 µg	9.0 µg
FBL-2	20409	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$.
Window wells 400 $\mu g/ft^2$. Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106646

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE):	DATE: 7/17/02 TIME:
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): Al. Kazakov	SAMPLE(S) SEALED: YES / NO; CORRECT CONTAINER(S): YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	W-01	Room # 925 South side Left Univent (back wall)	1		X			<9.0
	W-02	Room # 925 South side Right Univent (back wall)	1		X			<9.0
	W-03	Room #913 South side Right Univent (back wall)	1		X			10.1
	W-04	Room # 913 South side Middle Univent (back wall)	1		X			11.4
	W-05	Room # 913 South side Left Univent (back wall)	1		X			<9.0
	W-06	F/B						<9.0
	W-07	F/B						<9.0
	~~W-08~~							

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: Fax Results to Taylor (212)406-25 & (516) 358-1780

RELINQUISHED BY (SIGNATURE)	DATE 7/17/02 TIME 01:00	PRINTED NAME Al. Kazakov	RECEIVED BY (SIGNATURE) R. Droudina	DATE 7.17.02 TIME 01.00	PRINTED NAME R. Droudina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

Glen T.A.T.

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-17-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers St., NY

SAMPLED BY: Client

SAMPLE DATE 07-16-02
DATE RECEIVED: 07-16-02
DATE ANALYZED: 07-16-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20410	Rm 925 South Side Left Univent (Back Wall)	23.2	9.0
LW-02	20410	Rm 925 South Side Right Univent (Back Wall)	22.3	9.0
LW-03	20410	Rm 913 South Side Right Univent (Back Wall)	26.2	9.0
FBL-1	20410	Field Blank	<9.0 µg	9.0 µg
FBL-2	20410	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106648

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

6hr T.A.T. 20452

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Saadi	SAMPLER (SIGNATURE):	DATE: 7/17/02 TIME:
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): AL. Kazakov	SAMPLE(S) SEALED: (YES) / NO; CORRECT CONTAINER(S): (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-01	Room #911 South side Right Univent (Back wall)	1		X			18.0
	W-02	Room #927 South side Right Univent (Back wall)	1		X			<9.0
	W-03	Room #927 South side Middle Univent (Back wall)	1		X			<9.0
	W-04	Room #927 South side Left Univent (Back wall)	1		X			<9.0
	W-05	Room #931 South side Left Univent (Back wall)	1		X			<9.0
	W-06	Room #931 South side Right Univent (Back wall)	1		X			<9.0
	W-07	Room #938 North side Univent (Back wall)	1		X			<9.0
	W-08	Room #939 South side Left Univent (Back wall)	1		X			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☑ BY / /

COMMENTS / INSTRUCTIONS: Fax results to Taylor (212) 406-2535

RELINQUISHED BY (SIGNATURE)	DATE 7/17/02 TIME 21:30	PRINTED NAME AL. Kazakov	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106649

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

6hr T.A.T. 2045 C

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217/29881
SAMPLER (SIGNATURE)	DATE: 7/17/02 TIME:
SAMPLER NAME (PRINT): AL. Karamov.	SAMPLE(S) SEALED: (YES) / NO; CORRECT CONTAINER(S): (YES) / NO
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-09	Room # 939 South side Right Univent (Back wall)	1		X			< 9.0
	W-10	Room # 935 South side Right Univent (Back wall)	1		X			17.2
	W-11	Room # 935, South side Left univent (Back wall)	1		X			15.5
	W-12	Room # 940 North side Left Univent (Back wall)	1		X			90.3
	W-13	Room # 940 North side Right Univent (Back wall)	1		X			9.1
	W-14	Room # 936 North side Left Univent (Back wall)	1		X			13.9
	W-15	Room # 936 North side Right Univent (Back wall)	1		X			16.1
	W-16	Room # 926 north side Univent	1		X			11.6

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: Fax Results to Taylor at Stuyvesant (212) 406-2535

RELINQUISHED BY (SIGNATURE)	DATE 7/17/02 TIME 21:30	PRINTED NAME AL. Karamov	RECEIVED BY (SIGNATURE)	DATE / TIME / PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME / PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106650

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA

CONTACT: Hamid Savoy

PROJECT LOCATION: Stuyvesant H.S.

PROJECT #: M477-15217/29881

SAMPLER (SIGNATURE):

DATE: 7/17/02 TIME:

SAMPLER NAME (PRINT): AL. Kaeaman

SAMPLE(S) SEALED: YES / NO

CORRECT CONTAINER(S): YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-17	F/13 4						4 < 9.0
	W-18	F/13 4						4 < 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE): DATE 7/17/02 TIME 21:30 PRINTED NAME: AL. Kaeaman

RELINQUISHED BY (SIGNATURE): DATE TIME PRINTED NAME

RECEIVED BY (SIGNATURE): DATE 07/17/02 TIME 10pm PRINTED NAME

RECEIVED BY LAB (SIGNATURE): DATE TIME PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-18-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers St., NY

SAMPLED BY: Client

SAMPLE DATE 07-17-02
DATE RECEIVED: 07-17-02
DATE ANALYZED: 07-17-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20452	Rm 911 South Side Right Univent (Back Wall)	18.0	9.0
W-02	20452	Rm 927 South Side Left Univent (Back Wall)	<9.0	9.0
W-03	20452	Rm 927 South Side Middle Univent (Back Wall)	<9.0	9.0
W-04	20452	Rm 927 South Side Left Univent (Back Wall)	<9.0	9.0
W-05	20452	Rm 931 South Side Left Univent (Back Wall)	<9.0	9.0
W-06	20452	Rm 931South Side Right Univent (Back Wall)	<9.0	9.0
W-07	20452	Rm 938 North Side Univent (Back Wall)	<9.0	9.0
W-08	20452	Rm 939 South Side Left Univent (Back Wall)	<9.0	9.0
W-09	20452	Rm 939 South Side Right Univent (Back Wall)	17.2	9.0
W-10	20452	Rm 935 South Side Right Univent (Back Wall)	15.5	9.0
W-11	20452	Rm 935 South Side Left Univent (Back Wall)	90.3	9.0
W-12	20452	Rm 940 North Side Left Univent (Back Wall)	9.1	9.0
W-13	20452	Rm 940 North Side Right Univent (Back Wall)	13.9	9.0
W-14	20452	Rm 936 North Side Left Univent (Back Wall)	11.1	9.0
W-15	20452	Rm 936 North Side Right Univent (Back Wall)		

NYC-WTC_000106652

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

6 HRS TAT

00479

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA.	CONTACT: HAMID SAVOJ.	SAMPLER (SIGNATURE): Carlos Jofat	DATE: 7-17-02.	TIME:	SAMPLE(S) SEALED: (YES) NO
		SAMPLER NAME (PRINT): CARLOS JOFAT			CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: STUYVESANT H.S.	PROJECT #: M477-15217/29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT ug/ft^2
	LW-01	ROOM # 1010 LEFT side. UNIVENT BACKWALL	1		/			11.1
	LW-02	ROOM # 1010 CENTER UNIVENT back wall.	1		/			19.1
	LW-03	ROOM # 1010 Right side. UNIVENT back wall.	1		/			11.7
	FB 1	FIELD BLANK	—	—	—	—	—	<9.0
	FB 2.	FIELD BLANK	—	—	—	—	—	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HRS TAT FAX TO TETS AT (212) 406-2535

RELINQUISHED BY (SIGNATURE): Carlos Jofat	DATE: 7-17-02 TIME: 1650	PRINTED NAME: CARLOS JOFAT	RECEIVED BY (SIGNATURE): A Cc 07/17 6p	DATE: TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE):	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106653

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20467 1 of 2

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYCSCA	Hamid Saadj		7/18/02		(YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. NY. NY.	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 940, North side Left unitvent - REAR	1		✓			<9.0 µg/ft²
	LW-02	ROOM 940, North side Right ~~side~~ unitvent, REAR	1		✓			<9.0
	LW-03	ROOM 839, South side Left unitvent, REAR	1		✓			<9.0
	LW-04	ROOM 839, South side Right unitvent - REAR	1		✓			<9.0
	LW-05	ROOM 837, South side Left unitvent, REAR	1		✓			<9.0
	LW-06	ROOM 837, South side Right unitvent - REAR	1		✓			<9.0
	LW-07	ROOM 835, South side Left unitvent - REAR	1		✓			<9.0
	LW-08	ROOM 835, South side Right unitvent - REAR	1		✓			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/18/02 TIME 1624	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
			AC 07/18 6		
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

1780

NYC 9/11 Public Portal Document

NYC-WTC_000106654

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20467 2 of 2

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamida Sanoj	SAMPLER (SIGNATURE): [signature] DATE: 7/18/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
		SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S): (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.C.	PROJECT #: M477-15217-29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-09	ROOM 833, South side Left unitvent - Rear	1		✓			< 9.0
	LW-10	ROOM 833, South side Right unitvent - Rear	1		✓			< 9.0
	LW-11	ROOM 829, South side Left unitvent - Rear	1		✓			< 9.0
	LW-12	ROOM 829, South side Right unitvent - Rear	1		✓			< 9.0
	FBL-1	Field Blank	—	—	—	—	—	< 9.0
	FBL-2	Field Blank	—	—	—	—	—	< 9.0

			TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /	COMMENTS / INSTRUCTIONS: 6 HR TAT	
RELINQUISHED BY (SIGNATURE): [signature]	DATE: 7/18/02 TIME: 1624	PRINTED NAME:	RECEIVED BY (SIGNATURE): [signature] 07/18	DATE: TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE):	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

AIC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-19-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers St., NY

SAMPLED BY: Client

SAMPLE DATE 07-18-02
DATE RECEIVED: 07-18-02
DATE ANALYZED: 07-18-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION (µg/ft²)	DETECTION LIMIT (µg/ft²)
LW-01	20467	Rm 940 North Side Left Univent Rear	<9.0	9.0
LW-02	20467	Rm 940 North Side Right Univent Rear	<9.0	9.0
LW-03	20467	Rm 839 SouthSide Left Univent Rear	<9.0	9.0
LW-04	20467	Rm 839 South Side Right Univent Rear	<9.0	9.0
LW-05	20467	Rm 837 South Side Left Univent Rear	<9.0	9.0
LW-06	20467	Rm 837 South Side Right Unitvent Rear	<9.0	9.0
LW-07	20467	Rm 835 South Side Left Unitvent Rear	<9.0	9.0
LW-08	20467	Rm 835 South Side Right Unitvent Rear	<9.0	9.0
LW-09	20467	Rm 833 South Side Left Unitvent Rear	<9.0	9.0
LW-10	20467	Rm 833 South Sdie Right Unitvent Rear	<9.0	9.0
LW-11	20467	Rm 829 South Side Left Unitvent Rear	<9.0	9.0
LW-12	20467	Rm 829 South Side Right Unitvent Rear	<9.0	9.0
FBL-13	20467	Field Blank	<9.0 µg	9.0 µg
FBL-14	20467	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

NYC-WTC_000106656

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20479

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): AL. Kazakov	DATE: 7/18/02 TIME:
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-15217/29881	SAMPLER NAME (PRINT): AL. Kazakov	SAMPLE(S) SEALED: (YES) / NO; CORRECT CONTAINER(S): (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/ft² LAB RESULT
	W-01	Room # 836 North side Univent Right (back wall)	1		X			< 9.0
	W-02	Room # 836 North side Left Univent (back wall)	1		X			< 9.0
	W-03	Room # 838 North side Left Univent (back wall)	1		X			< 9.0
	W-04	Room # 838 North side Right Univent (back wall)	1		X			10.5
	W-05	Room # 840 North side Left Univent (back wall)	1		X			11.7
	W-06	Room # 840 North side Right Univent (back wall)	1		X			< 9.0
	W-07	F/B	"					< 9.0
	W-08	F/B	"					< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/18/02 TIME 21:30	PRINTED NAME AL. Kazakov	RECEIVED BY (SIGNATURE) AL 07/18 22	DATE 30 TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

[illegible] ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-19-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers St., NY
SAMPLED BY:	Client
SAMPLE DATE	07-18-02
DATE RECEIVED:	07-18-02
DATE ANALYZED:	07-18-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20479	Rm 836 North Side Univent Right Back Wall	<9.0	9.0
W-02	20479	Rm 836 North Side Univent Left Back Wall	<9.0	9.0
W-03	20479	Rm 838 North Side Univent Left Back Wall	<9.0	9.0
W-04	20479	Rm 838 North Side Univent Right Back Wall	10.5	9.0
W-05	20479	Rm 840 North Side Left Univent Back Wall	11.7	9.0
W-06	20479	Rm 840 North Side Right Univent Back Wall	<9.0	9.0
W-07	20479	Field Blank	<9.0 µg	9.0 µg
W-08	20479	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2.
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106658

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20511

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy	AL. Kazanov	7/19/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S) (YES) / NO
Stuyvesant H.S. .M.	M477-15217/29881	AL. Kazanov			

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-01	Room # 1017 A, Top Univent Composid sample (Air Daoffen)	1		X			<9.0
	W-02	Room # 1017 A, Bottom Univent. South side (Back wall)	1		X			<9.0
	W-03	Room # 801 South side Univent, back wall	1		X			<9.0
	W-04	Room # 807 South side Univent (Back wall)	1		X			<9.0
	W-05	Room # 809 South side Univent (Back wall)	1		X			<9.0
	W-06	Room # 811 South side Right Univent (Back wall)	1		X			<9.0
	W-07	Room # 811 South side Middle Univent (Back wall)	1		X			<9.0
	W-08	Room # 811 South side Left Univent (Back wall)	1		X			<9.0

Fax results to Taylor (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 8hr TAT

RELINQUISHED BY (SIGNATURE)	DATE	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE	PRINTED NAME
[signature]	7/19/02 TIME 01:00	AL. Kazanov.	R. Droudma	7.20.01 TIME	R. Droudma
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106659

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20511

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savos		7/19/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesand H.S.	M477-15217/29881	AL. Kacanow			YES / NO

MATRIX (CIRCLE ONE): WIPE / PAINT / SOIL / OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-09	Room # 826 North side Univent (back wall)	1		X			9.8
	W-10	Room # 803 South side Right side Univent (back wall)	1		X			12.2
	W-11	Room # 803 South side Middle Univent (back wall)	1		X			<9.0
	W-12	Room # 803 South side Left Univent (back wall)	1		X			<9.0
	W-13	Room # 803 East side Univent (back wall)	1		X			<9.0
	W-14	F/B "				"		<9.0
	W-15	F/B "				"		<9.0

Fax results to Taylor: (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT.

RELINQUISHED BY (SIGNATURE)	DATE 7/19/02 TIME 01:00	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE 7.20.01 TIME	PRINTED NAME
		Al. Kacanow	R. Droudina		R. Droudina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-22-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY 8th, 10th Floors
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE	07-19-02
DATE RECEIVED:	07-20-02
DATE ANALYZED:	07-20-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20511	Rm #1017A Top Unit Vent (Composit Sample)	<9.0	9.0
W-02	20511	Rm #1017A Bottom Unit Vent South Side Back Wall	<9.0	9.0
W-03	20511	Rm #801 East Side Unit Vent Back Wall	<9.0	9.0
W-04	20511	Rm #807 South Side Unit Vent Back Wall	<9.0	9.0
W-05	20511	Rm #809 South Side Unit Vent Back Wall	<9.0	9.0
W-06	20511	Rm #811 South Side Right Unit Vent Back Wall	<9.0	9.0
W-07	20511	Rm #811 South Side Middle Unit Vent Back Wall	<9.0	9.0
W-08	20511	Rm #811 South Side Left Unit Vent Back Wall	<9.0	9.0
W-09	20511	Rm #826 North Side Unit Vent Back Wall	9.8	9.0
W-10	20511	Rm #803 South Side Right Unit Vent Back Wall	12.2	9.0
W-11	20511	Rm #803 South Side Middle Unit Vent Back Wall	<9.0	9.0
W-12	20511	Rm #803 South Side Left Unit Vent Back Wall	<9.0	9.0
W-13	20511	Rm #803 East Side Unit Vent Back Wall	<9.0	9.0
W-14	20511	Field Blank	<9.0 µg	9.0 µg

NYC-WTC_000106661

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

6 HRS TAT

20506

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC BCA	HAMID SAVOJ.	Carlos Tofat	7-19-02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
STUYVESANT H.S	H477-15217 / 29881	CARLOS TOFAT			(YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-01	ROOM # 902. LEFT UNIVENT - REAR	1		✓			<9.0 ug/ft2
	LW-02.	ROOM # 902 RIGHT UNIT VENT → REAR.	1		✓			<9.0
	LW-03	ROOM # 804 LEFT UNIT VENT → REAR	1		✓			<9.0
	LW-04	ROOM # 804 RIGHT UNIT VENT → REAR.	1		✓			<9.0
	LW-05	ROOM # 815 LEFT UNIT VENT → REAR	1		✓			<9.0
	LW-06	ROOM # 815 RIGHT UNIT VENT → REAR.	1		✓			<9.0
	LW-07	ROOM # 827 LEFT UNIT VENT → REAR	1		✓			<9.0
	LW-08	ROOM # 827 CENTER UNIT VENT → REAR	1		✓			<9.0.

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: NIOSH Method 7082.

RELINQUISHED BY (SIGNATURE)	DATE	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE	PRINTED NAME
Carlos Tofat	7-19-02 TIME 1600	CARLOS TOFAT	7/19	TIME	
RELINQUISHED BY (SIGNATURE)	DATE 7-19-02 TIME 5:00pm	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

Fax results to (917) [illegible] office

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106662

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

6 HRS TAT

20506

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA.	HAMID SAVOJ.	Carlos Tofat	7-19-02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	H477-15217 / 29881	carlos TOFAT			(YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09.	ROOM. # 829. Right Unit Vent → REAR	1		✓			11.3
	FB - 1	FIELD BLANK	—	—	—	—	—	< 9.0
	FB - 2.	FIELD BLANK	—	—	—	—	—	< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: NIOSH Method 7082

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
Carlos Tofat	7-19-02 / 1600	CARLOS TOFAT			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-22-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY 9th, 8th Floors
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE	07-19-02
DATE RECEIVED:	07-19-02
DATE ANALYZED:	07-19-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20506	Room #902, Left Unit Vent - Rear	<9.0	9.0
LW-02	20506	Room #902, Right Unit Vent - Rear	<9.0	9.0
LW-03	20506	Room #804, Left Unit Vent - Rear	<9.0	9.0
LW-04	20506	Room #804, Right Unit Vent - Rear	<9.0	9.0
LW-05	20506	Room #815, Left Unit Vent - Rear	<9.0	9.0
LW-06	20506	Room #815, Right Unit Vent - Rear	<9.0	9.0
LW-07	20506	Room #827, Left Unit Vent - Rear	<9.0	9.0
LW-08	20506	Room #827, Center Unit Vent - Rear	<9.0	9.0
LW-09	20506	Room #827, Right Unit Vent - Rear	11.3	9.0
FB-1	20506	Field Blank	<9.0 µg	9.0 µg
FB-2	20506	Field Blank	<9.0 µg	9.0 µg

NOTE 1
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106664

LOR ENVIRONMENTAL GROUP, INC.
30 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20516

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA.	HAMID SAUDJ.	Carlos A. Jofat	7-20-02.		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
STUYVESANT H.S.	H477-15217/29881	CARLOS JOFAT			YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM # 903 A. South side LEFT UNIT VENT REAR	1		✓			<9.0
	LW-02	ROOM # 903 A. South side RIGHT UNIT VENT REAR.	1		✓			<9.0
	LW-03	ROOM # 817 South side UNIT VENT REAR.	1		✓			<9.0
	FB 1	FIELD BLANK						<9.0
	FB 2	FIELD BLANK						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7-20-02 TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
Carlos A. Jofat					
RELINQUISHED BY (SIGNATURE)	DATE TIME 4:30Pm	PRINTED NAME	RECEIVED BY LAB (SIGNATURE) R. Droudina	DATE 7.20.02 TIME 16.30	PRINTED NAME R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-22-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY 8th-9th Floors
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	07-20-02
DATE RECEIVED:	07-20-02
DATE ANALYZED:	07-20-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20516	Room #903A South Side Left Unit Vent Rear	<9.0	9.0
LW-02	20516	Room #903A South Side Right Unit Vent Rear	<9.0	9.0
LW-03	20516	Room #817 South Side Unit Vent Rear	<9.0	9.0
FB-1	20516	Field Blank	<9.0 µg	9.0 µg
FB-2	20516	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$. Window sills 250 $\mu g/ft^2$. Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106666

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

205/5

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC BCA	Hamid Saroj		7/20/02		(YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St. NYC	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT : µg/ft²
	LW-01	Room 703, East Side window - Rear	1		✓			<9.0
	LW-02	Room 703 - South side Left window - Rear	1		✓			<9.0
	LW-03	Room 703 - South side Right window - Rear	1		✓			<9.0
	FBL-1	Field Blank						<9.0
	FBL-2	Field Blank						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/20/02 TIME 1800	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE) R. Drudina	DATE 7.20.02 TIME 16.30	PRINTED NAME R. Drudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-22-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY 7th Floor
PROJECT NUMBER:	M477-15217-29881
SAMPLED BY:	Client
SAMPLE DATE	07-20-02
DATE RECEIVED:	07-20-02
DATE ANALYZED:	07-20-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20515	Room #703 East Side Unit Vent Rear	<9.0	9.0
LW-02	20515	Room #703 South Side Left Unit Vent Rear	<9.0	9.0
LW-03	20515	Room #703 South Side Right Unit Vent Rear	<9.0	9.0
FBL-1	20515	Field Blank	<9.0 µg	9.0 µg
FBL-2	20515	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106668

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LW 523

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoy	SAMPLER [SIGNATURE]	DATE 7/21/02 TIME	SAMPLE(S) SEALED (YES) / NO
		SAMPLER NAME [PRINT] Al. Kazanow		CORRECT CONTAINER(S) (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. "M"	PROJECT # 10477-15217 / 29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA [FT²]	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	W-01	Room # 701 East side Univent (Back wall)	1		X			<9.0
	W-02	Room # 701A, East side Univent (Back wall)	1		X			<9.0
	W-03	Room # 705 South side Right Univent (Back wall)	1		X			<9.0
	W-04	Room # 705 South side Left Univent (Back wall)	1		X			<9.0
	W-05	Room # 707 South side Univent (Back wall)	1		X			<9.0
	W-06	Room # 709 South side Left univent (Back wall)	1		X			<9.0
	W-07	Room # 709 South side Right Univent (Back wall)	1		X			<9.0
	W-08	FIELD BLANK						<9.0

Fax results to Taylor: (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY [SIGNATURE]	DATE 7/21/02 TIME 17:30	PRINTED NAME Al. Kazanow	RECEIVED BY [SIGNATURE]	DATE TIME	PRINTED NAME
RELINQUISHED BY [SIGNATURE]	DATE TIME	PRINTED NAME	RECEIVED BY LAB [SIGNATURE]	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_000106669

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20520

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE / TIME	SAMPLE(S) SEALED
SCA	Hamid Savage		7/21/02	(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)		CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217 / 29881	AL. Kazamov		(YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				LAB RESULT µg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	W-09	F/13						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/21/02 17:30	AL. Kazamov			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-22-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY 7th Floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	07-21-02
DATE RECEIVED:	07-21-02
DATE ANALYZED:	07-21-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20523	Room #701 East Side Univent Back Wall	<9.0	9.0
W-02	20523	Room #701A East Side Univent Back Wall	<9.0	9.0
W-03	20523	Room #705 South Side Right Univent Back Wall	<9.0	9.0
W-04	20523	Room #705 South Side Left Univent Back Wall	<9.0	9.0
W-05	20523	Room #707 South Side Univent Back Wall	<9.0	9.0
W-06	20523	Room #709 South Side Left Univent Back Wall	<9.0	9.0
W-07	20523	Room #709 South Side Right Univent Back Wall	<9.0	9.0
W-08	20523	Field Blank	<9.0 µg	9.0 µg
W-09	20523	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106670

NYC-WTC_00010667

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

#20526

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy	AL. Karakow	7/21/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M4[illegible]-15217/29881	AL. Karakow			(YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/Ft²
	2W-01	Room # 702 North side Univent (back wall)	1		X			<9.0
	2W-02	Room # 704 North side Univent (back wall)	1		X			<9.0
	2W-03	Room # 715 (south side) Right Univent (back wall)	1		X			<9.0
	2W-04	Room # 715 South side) Left Univent (back wall)	1		X			13.2
	2W-05	Room # 717 South side Left Univent (back wall)	1		X			<9.0
	2W-06	Room # 717 South side Right Univent (back wall)	1		X			<9.0
	2W-07	Room # 727 South side Right Univent (back wall)	1		X			<9.0
	2W-08	Room # 727 South side Left Univent (back wall)	1		X			<9.0

2nd set for today.

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	7/21/02 01:00	AL. Karakow	[signature]	7/22/	
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106672

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savage		7/21/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S) (YES) NO
Stuyvesant H.S.	M277-15217/29881	Al. Kazanow			

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	2W-09	F/13 "		4				
	2W-10	F/13 "			4			

Fax results to Taylor at: (212)406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/21/02 01:00	Al. Kazanow.		7/21/ 8:00	
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-22-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY
7th Floor

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE 07-21-02
DATE RECEIVED: 07-21-02
DATE ANALYZED: 07-22-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
2 W-01	20526	Room #702 North Side Univent Back Wall	<9.0	9.0
2 W-02	20526	Room #704 North Side Univent Back Wall	<9.0	9.0
2 W-03	20526	Room #715 South Side Right Univent Back Wall	<9.0	9.0
2 W-04	20526	Room #715 South Side Left Univent Back Wall	13.2	9.0
2 W-05	20526	Room #717 South Side Left Univent Back Wall	<9.0	9.0
2 W-06	20526	Room #717 South Side Right Univent Back Wall	<9.0	9.0
2 W-07	20526	Room #727 South Side Right Univent Back Wall	<9.0	9.0
2 W-08	20526	Room #727 South Side Left Univent Back Wall	<9.0	9.0
2 W-09	20526	Field Blank	<9.0 µg	9.0 µg
2 W-10	20526	Field Blank	<9.0 µg	9.0 µg

NOTE 1
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3.
Blank units are in µg

NYC-WTC_000106674

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20538

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA. Stuyvesant

CONTACT: Hamid Sawoj

SAMPLER (SIGNATURE):

DATE: 7/22/02

TIME: 12 00

SAMPLER NAME (PRINT): Petrarca

SAMPLE(S) SEALED: YES / NO

CORRECT CONTAINER(S): YES / NO

PROJECT LOCATION: 345 Chambers St

PROJECT #: N 477-1527

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/Ft²
	1	Univents rm 739 right	1		X			16.0
	2	↓ left	1		X			<9.0
	3	rm 737 right	1		X			<9.0
	4	↓ left	1		X			<9.0
	5	rm 735 right	1		X			<9.0
	6	↓ Left	1		X			<9.0
	7	rm 731 right 4	1		X			<9.0
	8	↓ right 3	1		X			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY (9/5)

COMMENTS / INSTRUCTIONS: Wipes Univent from left to right

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/22/02 12:30	Petrarca			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
				7/22/02 16:10	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106675

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20538

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA Stuyvesant
CONTACT: Hani Sow
PROJECT LOCATION: 325 Chambers rm 477
PROJECT #: m477-15217
SAMPLER (SIGNATURE): [signature] DATE: 7/22/02 TIME: 12
SAMPLER NAME (PRINT): Petland
SAMPLE(S) SEALED: YES / NO
CORRECT CONTAINER(S): YES / NO
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	9	UNIVON rm 731 right 2	1		X			<9.0
	10	↓ left 1	1		X			<9.0
	11	rm 723 1	1		X			12.2
	12	rm 726 1	1		X			<9.0
	13	rm 736 right	1		X			<9.0
	14	rm 736 Left	1		X			11.7
	15	rm 738 right	1		X			<9.0
	16	rm 738 Left	1		X			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 48 HRS
COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE 7/22/02 TIME 1235	PRINTED NAME Petland	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 7/22/02 TIME 14:20	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106676

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20538

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
Sara Studios	Hana Sou!		7/22/02	12:46	YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
345 Chambers	sm.477 1528	Retrank			YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/FT²
	17	UNIVONIS Yr 740 Right	1		X			<9.0
	18	" Left	1		X			<9.0
	FB-1	Field Blank						
	FB-2	Field Blak						

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 48 hr

COMMENTS / INSTRUCTIONS: FAX TO Taylor @ 212 406 2555 + 516 358 7790

RELINQUISHED BY (SIGNATURE)	DATE 7/22/02 TIME 12:35	PRINTED NAME Retrank	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 7/22/02 TIME 1400	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-22-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY
7th Floor

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE 07-22-02
DATE RECEIVED: 07-22-02
DATE ANALYZED: 07-22-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
01	20538	Room 739 Right	16.0	9.0
02	20538	Room 739 Left	<9.0	9.0
03	20538	Room 737 Right	<9.0	9.0
04	20538	Room 737 Left	<9.0	9.0
05	20538	Room 735 Right	<9.0	9.0
06	20538	Room 735 Left	<9.0	9.0
07	20538	Room 731 Right 4	<9.0	9.0
08	20538	Room 731 Right 3	<9.0	9.0
09	20538	Room 731 Right 2	<9.0	9.0
10	20538	Room 731 Left 1	<9.0	9.0
11	20538	Room 729	12.2	9.0
12	20538	Room 726	<9.0	9.0
13	20538	Room 736 Right	<9.0	9.0
14	20538	Room 736 Left	11.7	9.0
15	20538	Room 738 Right	<9.0	9.0
16	20538	Room 738 Left	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

17	20538	Room 740 Right	<9.0	9.0
18	20538	Room 740 Left	<9.0	9.0
FB-1	20538	Field Blank	<9.0 µg	9.0 µg
FB-2	20538	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106679

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20543

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA Stuyvesant
CONTACT: Hamid Saror
SAMPLER (SIGNATURE): [signature] DATE: 7/22/02 TIME: 10
SAMPLER NAME (PRINT): Peter K
SAMPLE(S) SEALED: YES / NO
CORRECT CONTAINER(S): YES / NO
PROJECT LOCATION: 345 Chambers
PROJECT #: 47-15217
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	19	rm 639 left	1		1			14.4
	20	" right	1		1			25.8
	21	Rm 640 Left	1		1			16.8
	22	" right	1		1			15.3
	FB-3	Field Blank						< 9.0
	FB-4	Field Blank						< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /
COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE): [signature] DATE: 7/22 TIME: 4:30p PRINTED NAME:
RECEIVED BY (SIGNATURE): [signature] 07/22 6p DATE: TIME: PRINTED NAME:
RELINQUISHED BY (SIGNATURE): DATE: TIME: PRINTED NAME:
RECEIVED BY LAB (SIGNATURE): DATE: TIME: PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-23-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217

SAMPLED BY: Client

SAMPLE DATE 07-22-02
DATE RECEIVED: 07-22-02
DATE ANALYZED: 07-22-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
19	20543	Rm 639 Left	14.4	9.0
20	20543	Rm 639 Right	25.8	9.0
21	20543	Rm 640 Left	16.8	9.0
22	20543	Rm 640 Right	15.3	9.0
FB-3	20543	Field Blank	<9.0 µg	9.0 µg
FB-4	20543	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106681

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20557

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy		7/22/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S) (YES) / NO
Stuyvesant H.S.	M277-15217/29881	AL. Kazanov			

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT mg/ft²
	W-01	Room # 638 North side Left Univent (back wall)	1		X			9.7
	W-02	Room # 638 North side Right Univent (back wall)	1		X			<9.0
	W-03	Room # 615 B South side Left Univent (back wall)	1		X			<9.0
	W-04	Room # 615 B South side Right Univent (back wall)	1		X			<9.0
	W-05	Room # 636 North side Right Univent (back wall)	1		X			<9.0
	W-06	Room # 636 North side Right Univent (back wall)	1		X			<9.0
	W-07	Room # 627 South side Right Univent (back wall)	1		X			<9.0
	W-08	Room # 627 South side Left Univent (back wall)	1		X			<9.0

Please fax results to Taylor: (212)406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/22/02 TIME 0100	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE 7.23.02 TIME	PRINTED NAME
		AL. Kazanov	R. Drozdina		R. Drozdina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106682

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2059

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savaj		7/22/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S) (YES) / NO
Stuyvesant H.S.	M477-15217/29881	AL Karakow			

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:			AREA (FT²)	SURFACE MATERIAL				LAB RESULT mg/ft²
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	W-09	F/B "		"				<9.0
	W-10	F/B "			"			<9.0

Please fax results to TayCon: (212)406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/23/02 TIME 01:00	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE 7.23.02 TIME	PRINTED NAME
		AL Karakow	R. Drouding		R. Drouding
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-23-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE 07-22-02
DATE RECEIVED: 07-22-02
DATE ANALYZED: 07-22-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20559	Rm 638 North Sdie Left Univent (Back Wall)	9.7	9.0
W-02	20559	Rm 639 North Side Right Univent (Back Wall)	<9.0	9.0
W-03	20559	Rm 615B South Side Left Univent (Back Wall)	<9.0	9.0
W-04	20559	Rm 615B South Side Right Univent (Back Wall)	<9.0	9.0
W-05	20559	Rm 636 North Side Right Univent (Back Wall)	<9.0	9.0
W-06	20559	Rm 636 North Side Right Univent (Back Wall)	<9.0	9.0
W-07	20559	Rm 627 South Side Right Univent (Back Wall)	<9.0	9.0
W-08	20559	Rm 627 South Side Left Univent (Back Wall)	<9.0	9.0
W-09	20559	Field Blank	<9.0 µg	9.0 µg
W-10	20559	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$. Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106684

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20599 1/3

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Savoy	SAMPLER (SIGNATURE):	DATE: 7/23/02 TIME:
		SAMPLER NAME (PRINT): Kirk McKenzie	SAMPLE(S) SEALED: (YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers ST. NY	PROJECT #: M477-15217-29881		CORRECT CONTAINER(S): (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 601 - EAST SIDE unitvent - REAR	1		✓			18.3
	LW-02	ROOM 615 - EAST SIDE unitvent - REAR	1		✓			24.4
	LW-03	ROOM 615 - South SIDE unitvent "A" - REAR	1		✓			30.1
	LW-04	ROOM 615 - South SIDE unitvent "B" - REAR	1		✓			<9.0
	LW-05	ROOM 615 - South SIDE unitvent "C" - REAR	1		✓			<9.0
	LW-06	ROOM 615 - South SIDE unitvent "D" - REAR	1		✓			15.5
	LW-07	ROOM 615 - South SIDE unitvent "E" - REAR	1		✓			11.7
	LW-08	ROOM 615 - South SIDE unitvent "F" - REAR	1		✓			13.3

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/24/02 TIME 0005	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE): ACC 07/23	DATE TIME 1 PM.	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 7.24.02 TIME 1.00	PRINTED NAME: Tere Murray	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106685

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

292

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID CAVOJ		7/23/02		YES / NO
PROJECT LOCATION: Stuyvesant HS. 345 Chambers St. NY.	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) KIRK McKenzie			CORRECT CONTAINER(S) YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09	ROOM 615 - South side unitvent "G" - REAR	1		✓			<9.0
	LW-10	ROOM 615 - South side unitvent "H" - REAR	1		✓			<9.0
	LW-11	ROOM 615 - South side unitvent "I" - REAR	1		✓			<9.0
	LW-12	ROOM 615 - South side unitvent "J" - REAR	1		✓			<9.0
	LW-13	ROOM 615 - South side unitvent "K" - REAR	1		✓			<9.0
	LW-14	ROOM 629/635 - South side Left unitvent - REAR	1		✓			<9.0
	LW-15	ROOM 629/635 - South side Left Center unitvent - REAR	1		✓			<9.0
	LW-16	ROOM 629/635 - South side Right center unitvent - REAR	1		✓			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/23/02 0005	KIRK McKenzie		7/23/02	
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106686

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

3 of 3

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE) / DATE / TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Savoj	7/23/02	(YES) / NO
PROJECT LOCATION: Stuyvesant H-S 345 Chambers St. NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie	CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-17	Room 629/635 - South side Right unitvent - Rear	1		✓			< 9.0
	LW-18	Room 639 - South side ~~Left~~ unitvent - Rear	1		✓			< 9.0
	LW-19	Room 639 - South side Right unitvent - Rear	1		✓			< 9.0
	FBL-1	Field Blank	—					< 9.0
	FBL-2	Field Blank	—					< 9.0

TURNAROUND REQUIRED:	COMMENTS / INSTRUCTIONS
NORMAL ☐ STAT ☐ BY / /	6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	7/24/02 0005	Kirk McKenzie	[signature]	07/23 / [illegible]	
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

AIC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-24-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-23-02
DATE RECEIVED: 07-23-02
DATE ANALYZED: 07-23-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20599	Rm 601 East Side Unitvent Rear	18.3	9.0
LW-02	20599	Rm 615 East Side Unitvent Rear	24.4	9.0
LW-03	20599	Rm 615 South Side Unitvent A Rear	30.1	9.0
LW-04	20599	Rm 615 South Side Unitvent B Rear	<9.0	9.0
LW-05	20599	Rm 615 South Side Unitvent C Rear	<9.0	9.0
LW-06	20599	Rm 615 South Side Unitvent D Rear	15.5	9.0
LW-07	20599	Rm 615 South Side Unitvent E Rear	11.7	9.0
LW-08	20599	Rm 615 Souht Side Unitvent F Rear	13.3	9.0
LW-09	20599	Rm 615 South Side Unitvent G Rear	<9.0	9.0
LW-10	20599	Rm 615 South Side Unitvent H Rear	<9.0	9.0
LW-11	20599	Rm 615 South Side Unitvnet I Rear	<9.0	9.0
LW-12	20599	Rm 615 South Side Unitvent J Rear	<9.0	9.0
LW-13	20599	Rm 615 South Side Unitvent K Rear	<9.0	9.0
LW-14	20599	Rm 629/635 South Side Left Center Unitvent Rear	<9.0	9.0
LW-15	20599	Rm 629/635 South Side Left Center Unitvent Rear	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-16	20599	Rm 829/635 South Side Right Center Unitvent Rear	<9.0	9.0
LW-17	20599	Rm 629/635 South Side Right Unitvent Rear	<9.0	9.0
LW-18	20599	Rm 639 South Side Left Unitvent Rear	<9.0	9.0
LW-19	20599	Rm 639 South Side Right Unitvent Rear	<9.0	9.0
FBL-1	20599	Field Blank	<9.0 µg	9.0 µg
FBL-2	20599	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: #04

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106689

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

1 of 3 20617

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA Stuyvesant
CONTACT: Hany Sawi
PROJECT LOCATION: 345 Chambers St.
PROJECT #: m477-15217-29881
SAMPLER (SIGNATURE): [signature] DATE: 7/24/00 TIME: 10a
SAMPLER NAME (PRINT): Peter
SAMPLE(S) SEALED: YES / NO
CORRECT CONTAINER(S): YES / NO
MATRIX (CIRCLE ONE): (WIPE) [illegible] OTHER

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	1	1: brary/B15 (Rm 615) east s.d. rear - univ	1		X			< 9.0
	2	Library/B15 (Rm 615) "A" rear - univ	1		X			24.4
	3	Rm 525 left - univ	1		X			22.3
	4	Rm 525 right univ	1		X			21.2
	5	Rm 513 left	1		X			32.5
	6	" right	1		X			< 9.0
	7	Rm 513 left	1		X			15.1
	8	" right	1		X			< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 10/11
COMMENTS / INSTRUCTIONS: Fax 212-406-2538

RELINQUISHED BY (SIGNATURE): [signature] DATE: 7/24/00 TIME: 5:28pm PRINTED NAME:
RECEIVED BY (SIGNATURE): [signature] DATE: 07/24 TIME: 6p PRINTED NAME:
RELINQUISHED BY (SIGNATURE): DATE: TIME: PRINTED NAME:
RECEIVED BY LAB (SIGNATURE): [signature] DATE: TIME: PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106690

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2 of 3 20674

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA
Stuyvesant HS

CONTACT: Hamid Sanai

SAMPLER (SIGNATURE): [signature] DATE: 7/24/02 TIME: 1500

SAMPLER NAME (PRINT): Petrone

SAMPLE(S) SEALED: YES / NO

CORRECT CONTAINER(S): YES / NO

PROJECT LOCATION: 345 Chambers St

PROJECT #: M477-15215-29881

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	9	rm 501 C. Universal	1		X			< 9.0
	10	rm 501 B universal	1		X			13.9
	11	507 universal left	1		X			13.3
	12	507 universal right	1		X			20.3
	13	rm 531 universal right	1		X			< 9.0
	14	universal center	1		X			< 9.0
	15	universal left	1		X			< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 6 hrs

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE): [signature] DATE: 7/24/02 TIME: 5:28 pm PRINTED NAME

RECEIVED BY (SIGNATURE): [signature] 7/24 DATE TIME PRINTED NAME

RELINQUISHED BY (SIGNATURE) DATE TIME PRINTED NAME

RECEIVED BY LAB (SIGNATURE) DATE TIME PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-25-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-24-02
DATE RECEIVED: 07-24-02
DATE ANALYZED: 07-24-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
01	20614	Library/615 East Side Rear Unitvent	<9.0	9.0
02	20614	Library/315 A Rear Unitvent	24.4	9.0
03	20614	Rm 525 Left Unitvent	22.3	9.0
04	20614	Rm 525 Right Unitvent	21.2	9.0
05	20614	Rm 513 Left	32.5	9.0
06	20614	Rm 513 Right	<9.0	9.0
07	20614	Rm 513 Left	15.1	9.0
08	20614	Rm 513 Right	<9.0	9.0
09	20614	Rm 501C Unitvent	<9.0	9.0
10	20614	Rm 501B Unitvent	13.9	9.0
11	20614	Rm 508 Unitvent Left	13.3	9.0
12	20614	Rn 508 Unitvent Right	20.3	9.0
13	20614	Rm 531 Unitvent Right	<9.0	9.0
14	20614	Rm 531 Unitvent Center	<9.0	9.0
15	20614	Rm 531 Unitvent Left	<9.0	9.0

NYC-WTC_000106692

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20598

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA

CONTACT: HAMID SAWOJ

PROJECT LOCATION: STUYVESANT H.S 345 CHAMBERS ST NY. NY

PROJECT #: M477-15217-29881

SAMPLER (SIGNATURE): [signature]

DATE: 7.24.02 TIME:

SAMPLER NAME (PRINT): KIRK MC KENZIE

SAMPLE(S) SEALED: (YES) / NO

CORRECT CONTAINER(S): (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 501 C UNIT VENT - REAR	1		✓			21.9
	LW-02	ROOM 503 - LEFT SIDE UNIT VENT - REAR	1		✓			13.4
	LW-03	ROOM 503 - RIGHT SIDE UNIT VENT - REAR	1		✓			< 9.0
	LW-04	ROOM 505 - LEFT SIDE UNIT VENT - REAR	1		✓			12.9
	LW-05	ROOM 505 - RIGHT SIDE UNIT VENT - REAR	1		✓			< 9.0
	LW-06	ROOM 1024 A UNIT VENT - REAR	1 composit		✓			< 9.0
	FBL-1	Field Blank						< 9.0
	FBL-2	Field Blank						< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR - TAT

	DATE	PRINTED NAME		DATE	PRINTED NAME
RELINQUISHED BY (SIGNATURE): [signature]	DATE 7/24/02 TIME 0005	KIRK McKENZIE	RECEIVED BY (SIGNATURE): ACW 07/23	DATE TIME 1A.M.	
RELINQUISHED BY (SIGNATURE): [signature]	DATE 7.24.02 TIME 1.00	TOM MICHELS	RECEIVED BY LAB (SIGNATURE):	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-24-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
DATE RECEIVED:	07-23-02
DATE ANALYZED:	07-23-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20598	Rm 501C Univent Rear	21.9	9.0
LW-02	20598	Rm 503 Left Side Univent Rear	13.4	9.0
LW-03	20598	Rm 503 Right Side Univent Rear	<9.0	9.0
LW-04	20598	Rm 505 Left Side Univent Rear	12.9	9.0
LW-05	20598	Rm 505 Right Side Univent Rear	<9.0	9.0
LW-06	20598	Rm 1024A Univent Rear	<9.0	9.0
LW-07	20598	Field Blank	<9.0 µg	9.0 µg
LW-08	20598	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106694

20633 / 82

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA
CONTACT: HAMID SAVOI
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST. N.Y
PROJECT #: M477-15217-29881
SAMPLER (SIGNATURE):
DATE: 7/24/02
TIME:
SAMPLER NAME (PRINT): Kirk McKenzie
SAMPLE(S) SEALED: (YES) NO
CORRECT CONTAINER(S): (YES) NO
MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	ROOM 911 South side Left ceiling unitvent - Damper	1 COMPOSIT		✓			<9.0
	LW-02	ROOM 511, South side Left unitvent - REAR	1		✓			<9.0
	LW-03	ROOM 511, South side Right unitvent - REAR	1		✓			13.3
	LW-04	ROOM 403, South side Left unitvent - REAR	1		✓			<9.0
	LW-05	ROOM 403, South side Right unitvent - REAR	1		✓			<9.0
	LW-06	ROOM 405, South side Left unitvent - REAR	1		✓			<9.0
	LW-07	ROOM 405, South side Right unitvent - REAR	1		✓			<9.0
	LW-08	ROOM 407, South side Left unitvent - REAR	1		✓			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /
COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE):
DATE 7/24/02 TIME 0015 PRINTED NAME Kirk McKenzie

RELINQUISHED BY (SIGNATURE):
DATE 7/24/02 TIME 400 PRINTED NAME GARY McKenzie

RECEIVED BY (SIGNATURE): R. Brondina
DATE 7.25.02 TIME 00.30 PRINTED NAME R. Brondina

RECEIVED BY LAB (SIGNATURE):
DATE TIME PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106695

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20633 282

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE) / DATE / TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAND	7/24/02	(YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers H.S. N.Y.	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie	CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09	ROOM 407, South side Right unitvent - Rear	1		✓			<9.0
	FBL-1	Field Blank	—					<9.0
	FBL-2	Field Blank	—					<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/24/02 0015	Kirk McKenzie	R. Stoudina	7.25.02 00.30	R. Stoudina
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
Gary McKenzie	7/24/02 0100	GARY McKENZIE			

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-25-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-24-02
DATE RECEIVED:	07-25-02
DATE ANALYZED:	07-25-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20633	Rm 911 South Side Left Ceiling Unitvent Damper Composit	<9.0	9.0
LW-02	20633	Rm 511 South Side Left Unitvent Rear	<9.0	9.0
LW-03	20633	Rm 511 South Side Right Unitvent Rear	13.3	9.0
LW-04	20633	Rm 403 South Side Left Unitvent Rear	<9.0	9.0
LW-05	20633	Rm 403 South Side Right Unitvent Rear	<9.0	9.0
LW-06	20633	Rm 405 South Side Left Unitvent Rear	<9.0	9.0
LW-07	20633	Rm 405 South Side Right Unitvent Rear	<9.0	9.0
LW-08	20633	Rm 407 South Side Left Unitvent Rear	<9.0	9.0
LW-09	20633	Rm 407 South Side Right Unitvent Rear	<9.0	9.0
FBL-1	20633	Field Blank	<9.0 µg	9.0 µg
FBL-2	20633	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$.
Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106696

NYC-WTC_000106697

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20669

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: 3x1 Stuyvesant	CONTACT: Hanif Sevi	SAMPLER (SIGNATURE):	DATE: 7/25/07 TIME: 3p
		SAMPLER NAME (PRINT): Richard	SAMPLE(S) SEALED: YES / NO
PROJECT LOCATION: 345 Chambers St	PROJECT #: M477-1527-29881	MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____	CORRECT CONTAINER(S): YES / NO

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	1	fm 431 left	1		X			14.3
	2	↓ right	1		X			11.9
	3	fm 429 right	1		X			11.0
	4	↓ left	1		X			14.2
	5	fm 427 right	1		X			26.5
	6	↓ Left	1		X			23.4
	7	fm 413 right	1		X			<9.0
	8	↓ Left	1		X			<9.0

all sample from rear of cmi.-vent

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 10/

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/25/07 5pm	Richard	07/25 6		
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106698

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA / Structural

CONTACT: Frank Sovo,

SAMPLER (SIGNATURE): [signature] DATE: 7/25/07 TIME: 3:40

SAMPLER NAME (PRINT): Peter Favata

SAMPLE(S) SEALED: YES / NO

CORRECT CONTAINER(S): YES / NO

PROJECT LOCATION: 345 Chambers St

PROJECT #: M477-15217-29881

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	9	SW 4th floor	1		X			<9.0
	10	↓ 4th	1		X			<9.0
	FB1	Field Blank						<9.0
	FB2	Field Blank						<9.0

Fax 516-558-1780
212-406-2555

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 10/1

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	7/25/07 5:00	Peter Favata	[signature] 07/25 6		
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-26-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-26-02
DATE RECEIVED:	07-26-02
DATE ANALYZED:	07-26-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
1	20669	Rm 431 Left	14.3	9.0
2	20669	Rm 431 Right	11.9	9.0
3	20669	Rm 429 Right	11.0	9.0
4	20669	Rm 429 Left	14.2	9.0
5	20669	Rm 427 Right	26.5	
6	20669	Rm 427 Left	23.4	9.0
7	20669	Rm 413 Right	<9.0	9.0
8	20669	Rm 413 Left	<9.0	9.0
9	20669	Rm 411 Right	<9.0	9.0
10	20669	Rm 411 Left	<9.0	9.0
11	20669	Field Blank	<9.0 µg	9.0 µg
12	20669	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106700

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoj		7/25/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217/29881	Al. Kazanov	# 20658		YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM # 525 RIGHT UNIT VENT → REAR.	1 FT^2		✓			
	LW-02	ROOM # 525 LEFT UNIT VENT → REAR.	1 FT^2		✓			
	LW-03	ROOM # 513 LEFT UNIT VENT → REAR	1 FT^2		✓			
	LW-04	ROOM # 507 RIGHT UNIT VENT → REAR	1 FT^2		✓			
	LW-05	ROOM # 615 UNIT VENT # A. REAR.	1 FT^2		✓			
	LW-06	ROOM # 404 UNIT VENT REAR	1 FT^2		✓			
	LW-07	ROOM # 401 East UNIT VENT REAR	1 FT^2		✓			
	LW-08	ROOM # 401 LEFT UNIT VENT REAR	1 FT^2		✓			

Fax results to Taylor (212) 406-2555

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr tat.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/25/02 14:40	Al. Kazanov			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
				7/26/2 15:50	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106701

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Saraf		7/25/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M4777-15217/29881	AL. Kazakov	# 20658		(YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09.	ROOM # 401 RIGHT UNIT VENT REAR	1 FT².		✓			
	FB 1	FIELD BLANK	—					
	FB 2.	FIELD BLANK	—					

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/25/02 TIME 14:40	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
		AL. Kazakov			
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 7/26/02 TIME 15:00	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-25-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-25-02
DATE RECEIVED:	07-25-02
DATE ANALYZED:	07-25-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20658	Rm 525 Right Unitvent Rear	<9.0	9.0
LW-02	20658	Rm 525 Left Unitvent Rear	<9.0	9.0
LW-03	20658	Rm 513 Left Unitvent Rear	<9.0	9.0
LW-04	20658	Rm 507 Right Unitvent Rear	<9.0	9.0
LW-05	20658	Rm 615 Unitvent #1 Rear	<9.0	9.0
LW-06	20658	Rm 404 Unitvent Rear	<9.0	9.0
LW-07	20658	Rm 401 East Unitvent Rear	<9.0	9.0
LW-08	20658	Rm 401 Left Unitvent Rear	<9.0	9.0
LW-09	20658	Rm 401 Right Unitvent Rear	<9.0	9.0
FBL-1	20658	Field Blank	<9.0 µg	9.0 µg
FBL-2	20658	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106703

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCH

CONTACT: HAMID SADJ

PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST. N.Y

PROJECT #: M477-15217-29881

SAMPLER (SIGNATURE): [signature] DATE: 7/26/02 TIME: 0015

SAMPLER NAME (PRINT): Kirk McKenzie

SAMPLE(S) SEALED: (YES) NO

CORRECT CONTAINER(S): (YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 427, South side. Left unit vent - Rear	1		✓			< 9.0
	LW-02	ROOM 427, South side Right unit vent - Rear	1		✓			
	LW-03	ROOM 433, South side Left unit vent - Rear	1		✓			
	LW-04	ROOM 433, South side Right unit vent - Rear	1		✓			
	LW-05	ROOM 437 - South side Left unit vent - Rear	1		✓			
	LW-06	ROOM 437 - South side Right unit vent - Rear	1		✓			
	LW-07	ROOM 439 - South side Left unit vent - Rear	1		✓			
	LW-08	ROOM 439 - South side Right unit vent - Rear.	1		✓			

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE): [signature]	DATE: 7/26/02 TIME: 0015	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE): [signature] 7/26/02	DATE: TIME:	PRINTED NAME:

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106704

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Shvoj		7/26/02	0015	(YES) / NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St NY	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:				SURFACE MATERIAL				
LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	WOOD	METAL	BRICK	OTHER	LAB RESULT
	LU-09	Room 445 - North side Left Unit vent - Rear	1		✓			<9.0
	FBL-1	Field Blank	—					↓
	FBL-2	Field Blank	—					

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/26/02 0015	Kirk McKenzie			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
			7	7/26/01	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-26-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-26-02
DATE RECEIVED:	07-26-02
DATE ANALYZED:	07-26-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20671	Rm 427 South Side Left Unitvent Rear	<9.0	9.0
LW-02	20671	Rm 427 South Side Right Unitvent Rear	<9.0	9.0
LW-03	20671	Rm 433 South Side Left Unitvent Rear	<9.0	9.0
LW-04	20671	Rm 433 South Side Right Unitvent Rear	<9.0	9.0
LW-05	20671	Rm 437 South Side Left Unitvent Rear	<9.0	9.0
LW-06	20671	Rm 437 South Side Right Univent Rear	<9.0	9.0
LW-07	20671	Rm 439 South Side Left Unitvent Rear	<9.0	9.0
LW-08	20671	Rm 439 South Side Right Unitvent Rear	<9.0	9.0
LW-09	20671	Rm 451 North Side Left Unitvent Rear	<9.0	9.0
FBL-1	20671	Field Blank	<9.0 µg	9.0 µg
FBL-2	20671	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106706

NYC 9/11 Public Portal Document

20694

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA

CONTACT: Hamid Savoj

SAMPLER (SIGNATURE): [signature]

DATE: 7/26/02

TIME:

SAMPLE(S) SEALED: (YES) NO

SAMPLER NAME (PRINT): Kirk McKenzie

CORRECT CONTAINER(S): (YES) NO

PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.

PROJECT #: M477-1521-29881

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LWED-01	Room 1017A - Ceiling unitvent exhaust Duct	1		✓			< 9.0
	LWED-02	Room 907. Ceiling unitvent	1		✓			< 9.0
	FBL-1	Field Blank	—					< 9.0
	FBL-2	Field Blank	—					< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE): [signature]	DATE 7/26/02 TIME 1855	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE):	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE): [signature]	DATE 7/26/02 TIME	PRINTED NAME: Igor Levit	RECEIVED BY LAB (SIGNATURE):	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-29-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-26-02
DATE RECEIVED:	07-26-02
DATE ANALYZED:	07-26-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LWED-01	20694	Rm 1017A Ceiling Unitvent Exhaust Duct	<9.0	9.0
LWED-02	20694	Rm 907 Ceiling Unitvent	<9.0	9.0
FBL-1	20694	Field Blank	<9.0 µg	9.0 µg
FBL-2	20694	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106708

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20702

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy		7/27/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-75217/29881	AL. Karaxcov			YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LDW-01	Room # 802 A Ceiling unit Exhaust duct.	1		X			<9.0
	LDW-02	Room # 807 Ceiling unit Exhaust duct	1		X			<9.0
	LDW-03	Room # 817 Ceiling unit Exhaust duct.	1		X			<9.0
	LDW-04	F/B	"					<9.0
	LDW-05	F/B	"					<9.0

Fax Results to Taylor at: (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/27/02 TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 7/27 TIME 16:00	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106709

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

Batch #2073

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAVOJ	SAMPLER (SIGNATURE)	DATE 7/27/02 TIME	SAMPLE(S) SEALED (YES) NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St N.Y.	PROJECT # M477-15217-29881	SAMPLER (NAME PRINT) KIRK McKENZIE		CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION: LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/Ft² LAB RESULT
	LW-01	ROOM 925 - Ceiling unitvent - Damper	1 composit		✓			< 9.0
	FBL-1	Field Blank						< 9.0
	FBL-2	Field Blank						< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/28/02 TIME 2400	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) ATC Lab	DATE 07/28/02 TIME 0.00	PRINTED NAME D. KOGAN
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-29-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-27-02
DATE RECEIVED:	07-28-02
DATE ANALYZED:	07-28-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20713	Rm 925 Ceiling Unitvent Damper	<9.0	9.0
FBL-1	20713	Field Blank	<9.0 µg	9.0 µg
FBL-2	20713	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$. Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106711

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

#20714

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAVOJ	SAMPLER (SIGNATURE)	DATE 7/27/02 TIME	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant HS. 345 Chambers ST. N.Y.	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT): Kirk McKenzie		CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/Ft² LAB RESULT
	LWD-01	ROOM 925 - Ceiling Univent Exhaust Duct	1		✓			<9.0
	FBL-1	Field Blank						<9.0
	FBL-2	Field Blank						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/28/02 TIME 2400	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) ATC Lab	DATE 07/28/02 TIME 0.00	PRINTED NAME D. Kosan
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-29-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-27-02
DATE RECEIVED:	07-28-02
DATE ANALYZED:	07-28-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LWD-01	20714	Rm 925 Ceiling Unitvent Exhaust Duct	<9.0	9.0
FBL-1	20714	Field Blank	<9.0 µg	9.0 µg
FBL-2	20714	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106712

NYC-WTC_000106713

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

Batch #20712

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamida Savoj	SAMPLER (SIGNATURE)	DATE: 7/27/02 TIME: SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. NY	PROJECT #: M477-15217-29881	SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	$\mu g/Ft^2$ LAB RESULT
	LWD-01	Room 911 - Ceiling Univent Exhaust Duct	1		✓			<9.0
	FBL-1	Field Blank	—					<9.0
	FBL-2	Field Blank	—					<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/28/02 TIME 2400	PRINTED NAME: Kirk McKenzie	RECEIVED BY (SIGNATURE): ATC Lab	DATE 07/28/02 TIME 0.00	PRINTED NAME: D. Kocan
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-29-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-27-02
DATE RECEIVED:	07-28-02
DATE ANALYZED:	07-28-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LWD-01	20712	Rm 911 Ceiling Unitvent Exhaust Duct	<9.0	9.0
FBL-1	20712	Field Blank	<9.0 µg	9.0 µg
FBL-2	20712	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples, (ELAP #10879), (AIHA #100229).

NYC-WTC_000106715

NYC 9/11 Public Portal Document

20698

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAVOJ	SAMPLER (SIGNATURE)	DATE 7/27/02 TIME	SAMPLE(S) SEALED (YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) Kirk McKenzie		CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:				SURFACE MATERIAL				
LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	ROOM 907 - Ceiling unitvent - DAMPER	1 composit		✓			<9.0
	FBL-1	Field Blank						<9.0
	FBL-2	Field Blank						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/27/02 TIME 2400	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) R. Droudina	DATE 7.27.02 TIME 00.30	PRINTED NAME R. Droudina
RELINQUISHED BY (SIGNATURE)	DATE TIME 1230 hrs	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-29-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-27-02
DATE RECEIVED:	07-27-02
DATE ANALYZED:	07-27-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20698	Rm 907 Ceiling Unitvent Damper	<9.0	9.0
FBL-1	20698	Field Blank	<9.0 µg	9.0 µg
FBL-2	20698	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RD

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106717

T. YLC'S ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

158 ✓

20724

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAVOJ		7/28/02		(YES) NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-01	ROOM 301A EAST SIDE unitvent - REAR	1		✓			<9.0
	LW-02	ROOM 301A South SIDE unitvent - REAR	1		✓			
	LW-03	ROOM 303 - South SIDE Left unitvent - REAR.	1		✓			
	LW-04	ROOM 303 - South SIDE Right unitvent - REAR	1		✓			
	LW-05	ROOM 305 - South side Left unitvent - REAR	1		✓			
	LW-06	ROOM 305 - South side Right unitvent - REAR	1		✓			
	LW-07	Room 325 - South side Left unitvent - REAR	1		✓			
	LW-08	ROOM 325 - South side Right unitvent - REAR	1		✓			

FAX results to TAYLOR 212 406-2635 & 516 358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/29/02 0030	Kirk McKenzie			
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME
Tom Lutz	7.29.02 1.00	JEREMY MICHALUZOK	7/29	5:00	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106718

AYLOR ENVIRONMENTAL GROUP, INC.
.0 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2592

20724

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAWOJ		7.28.02		(YES) / NO
PROJECT LOCATION: STUYVESANT HS 345 CHAMBERS ST. NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) KIRK MC KENZIE			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-09	ROOM 313 - South side Left univent - REAR	1		✓			<9.0
	LW-10	ROOM 313 - South side Right univent - REAR	1		✓			
	FBL-1	Field Blank	—					
	FBL-2	Field Blank	—					

FAX RESULTS to TAYLOR 212 406-2535 #516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT.

RELINQUISHED BY (SIGNATURE)	DATE 7/29/02 TIME 0030	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 7.28.02 TIME 1.00	PRINTED NAME TOMASZ MICHALCZUK	RECEIVED BY LAB (SIGNATURE)	DATE 7/29/02 TIME 5:00	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-29-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-28-02
DATE RECEIVED: 07-29-02
DATE ANALYZED: 07-29-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20724	Rm 301A East Side Unitvent Rear	<9.0	9.0
LW-02	20724	Rm 301A South Side Unitvent Rear	<9.0	9.0
LW-03	20724	Rm 303 Souht Side Left Unitvent Rear	<9.0	9.0
LW-04	20724	Rm 303 South Side Right Unitvent Rear	<9.0	9.0
LW-05	20724	Rm 305 South Side Left Unitvent Rear	<9.0	9.0
LW-06	20724	Rm 305 South Side Right Unitvent Rear	<9.0	9.0
LW-07	20724	Rm 325 South Side Left Unitvent Rear	<9.0	9.0
LW-08	20724	Rm 325 South Side Right Unitvent Rear	<9.0	9.0
LW-09	20724	Rm 313 South Side Left Unitvent Rear	<9.0	9.0
LW-10	20724	Rm 313 South Side Right Unitvent Rear	<9.0	9.0
FBL-1	20724	Field Blank	<9.0 µg	9.0 µg
FBL-2	20724	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-29-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-28-02
DATE RECEIVED: 07-29-02
DATE ANALYZED: 07-29-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20724	Rm 301A East Side Unitvent Rear	<9.0	9.0
LW-02	20724	Rm 301A South Side Unitvent Rear	<9.0	9.0
LW-03	20724	Rm 303 Souht Side Left Unitvent Rear	<9.0	9.0
LW-04	20724	Rm 303 South Side Right Unitvent Rear	<9.0	9.0
LW-05	20724	Rm 305 South Side Left Unitvent Rear	<9.0	9.0
LW-06	20724	Rm 305 South Side Right Unitvent Rear	<9.0	9.0
LW-07	20724	Rm 325 South Side Left Unitvent Rear	<9.0	9.0
LW-08	20724	Rm 325 South Side Right Unitvent Rear	<9.0	9.0
LW-09	20724	Rm 313 South Side Left Unitvent Rear	<9.0	9.0
LW-10	20724	Rm 313 South Side Right Unitvent Rear	<9.0	9.0
FBL-1	20724	Field Blank	<9.0 µg	9.0 µg
FBL-2	20724	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106722

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

#20715

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SAVOJ		7/27/02		(YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St. N.Y.	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) KIRK McKENZIE			CORRECT CONTAINER(S) (YES) / NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/Ft² LAB RESULT
	LW-01	ROOM 327 - South side Left unitvent - REAR	1		✓			69.0
	LW-02	ROOM 327 - South side Right unitvent - REAR	1		✓			
	LW-03	ROOM 335 - South side Left unitvent - REAR	1		✓			
	LW-04	ROOM 335 - South side Right unitvent - REAR	1		✓			
	LW-05	ROOM 337 - South side Left unitvent - REAR	1		✓			
	LW-06	ROOM 337 - South side Right unitvent - REAR	1		✓			
	LW-07	ROOM 339 - South side Left unitvent - REAR	1		✓			
	LW-08	ROOM 339 - South side Right unitvent - REAR	1		✓			

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE 7/28/02 TIME 2400	PRINTED NAME KIRK McKENZIE	RECEIVED BY (SIGNATURE)	DATE 07/28/02 TIME 0.000	PRINTED NAME D. KOENIG
RELINQUISHED BY (SIGNATURE)	DATE 7.29.02 TIME 728PM	PRINTED NAME TERESA MICHALOVE	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

FAX TO (212) 406-8545 ATT: TEA WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106723

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE . FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

#20715

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAWOZ	SAMPLER (SIGNATURE)	DATE 7.27.02 TIME	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St. NY	PROJECT # M477-15217-29991	SAMPLER NAME (PRINT): Kirk McKenzie		CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	µg/ft² LAB RESULT
	FBL-1	Field Blank						<9.0
	FBL-2	Field Blank						↓

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/28/02 TIME	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) AFC Lab	DATE 07/28/02 TIME 0930	PRINTED NAME D. Kogan
RELINQUISHED BY (SIGNATURE)	DATE 7.29.02 TIME 1.00	PRINTED NAME TERRELL MICHALOUK	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-29-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-27-02
DATE RECEIVED: 07-28-02
DATE ANALYZED: 07-28-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20715	Rm 327 South Side Left Unitvent Rear	<9.0	9.0
LW-02	20715	Rm 327 South Side Right Unitvent Rear	<9.0	9.0
LW-03	20715	Rm 335 South Side Left Unitvent Rear	<9.0	9.0
LW-04	20715	Rm 335 South Side Right Unitvent Rear	<9.0	9.0
LW-05	20715	Rm 337 South Side Left Unitvent Rear	<9.0	9.0
LW-06	20715	Rm 337 South Side Right Unitvent Rear	<9.0	9.0
LW-07	20715	Rm 339 South Side Left Unitvent Rear	<9.0	9.0
LW-08	20715	Rm 339 South Side Right Unitvent Rear	<9.0	9.0
FBL-1	20715	Field Blank	<9.0 µg	9.0 µg
FBL-2	20715	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106724

NYC-WTC_000106725

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20677

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Humid Savoy	SAMPLER (SIGNATURE): [signature] DATE: 7/25/02 TIME:	SAMPLE(S) SEALED: (YES) NO
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M477-25217/29881	SAMPLER NAME (PRINT): AL. Karasov	CORRECT CONTAINER(S): (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/FT²
	W-01	Room # 435 South side Left Univent (Back wall)	1		X			9.4
	W-02	Room # 435 South side Right Univent (Back wall)	1		X			14.6
	W-03	Room # 450 Univent (Back wall)	1		X			<9.0
	W-04	Room # 315 South side ~~Left~~ Univent (Back wall)	1		X			<9.0
	W-05	Room # 315 South side Right Univent (Back wall)	1		X			<9.0
	W-06	Room # 307 South side Left Univent (Back wall)	1		X			<9.0
	W-07	Room # 307 South side Middle Univent (Back wall)	1		X			<9.0
	W-08	Room # 307 South side Right Univent (Back wall)	1		X			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY (SIGNATURE): [signature]	DATE: 7/26/02 TIME: 2:30 PM	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE): [signature]	DATE: 7/26/1 TIME: 2:10	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC-WTC_000106726

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20672

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE):	DATE: 7/26/02 TIME:
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: 11479-#5217/29881	SAMPLER NAME (PRINT): AL. KAZAMOV	SAMPLE(S) SEALED: (YES) NO; CORRECT CONTAINER(S): (YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-09	F/B						
	W-10	F/B						

Fax results to TayCom (212)406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr TAT.

RELINQUISHED BY (SIGNATURE)	DATE: 7/26/02 TIME: 2:30 pm	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-26-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-26-02
DATE RECEIVED: 07-26-02
DATE ANALYZED: 07-26-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20677	Rm 435 South Side Left Unitvent (Back Wall)	9.4	9.0
W-02	20677	Rm 435 South Side Right Unitvent (Back Wall)	14.6	9.0
W-03	20677	Rm 450 Unitvent (Back Wall)	<9.0	9.0
W-04	20677	Rm 315 South Side Left Unitvent (Back Wall)	<9.0	9.0
W-05	20677	Rm 315 South Side Right Unitvent (Back Wall)	<9.0	9.0
W-06	20677	Rm 307 South Side Left Unitvent (Back Wall)	<9.0	9.0
W-07	20677	Rm 307 South Side Middle Unitvent (Back Wall)	<9.0	9.0
W-08	20677	Rm 307 South Side Right Unitvent (Back Wall)	<9.0	9.0
W-09	20677	Field Blank	<9.0 µg	9.0 µg
W-10	20677	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$.
Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106728

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

#2070/

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy		7/27/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217/29881	AL. Kazakov			YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-01	Room # 802A Ceiling Unit (Univent)	Composit 1 sq'		X			31.7
	W-02	Room # 807 Ceiling Unit (Univent)	Composit 1 sq'		X			30.5
	W-03	Room # 817 Ceiling Unit (Univent)	Composit 1 sq'		X			35.5
	W-04	Room # 333 South side Left Univent	1		X			38.8
	W-05	Room # 333 South side Right Univent	1		X			<9.0
	W-06	Room # 329 South side Left Univent (Back wall)	1		X			13.8
	W-07	Room # 329 South side Right Univent (Back wall)	1		X			<9.0
	W-08	F/B						<9.0

Fax Results to Fay Cox at (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/27/02 TIME	PRINTED NAME A. Kazakov	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	~~7/27~~ 7/28 TIME 18:00	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106729

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

T 20701

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savaj		7/27/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217/29881	A. Kazakov			(YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-09	F/13						<9.0

TURNAROUND REQUIRED.
NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS
6 hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/27/02 TIME	PRINTED NAME A. Kazakov	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 7/27/2 TIME 16:00	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-29-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-27-02
DATE RECEIVED: 07-27-02
DATE ANALYZED: 07-27-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20701	Rm 802A Ceiling Unit (Unitvent)	31.7	9.0
W-02	20701	Rm 807 Ceiling Unit (Unitvent)	30.5	9.0
W-03	20701	Rm 817 Ceiling Unit (Unitvent)	35.5	9.0
W-04	20701	Rm 333 South Side Left Unitvent	38.8	9.0
W-05	20701	Rm 333 South Side Right Unitvent	<9.0	9.0
W-06	20701	Rm 329 South Side Left Unitvent (Back Wall)	13.8	9.0
W-07	20701	Rm 329 South Side Right Unitvent (Back Wall)	<9.0	9.0
W-08	20701	Field Blank	<9.0 µg	9.0 µg
W-09	20701	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106731

I A. .. ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

2071

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE)	DATE 7/28/02 TIME
PROJECT LOCATION: Stuyvesant H.S.	PROJECT # M477-15217/29881	SAMPLER NAME (PRINT) AL. Kazanow	SAMPLE(S) SEALED (YES) NO; CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/Ft²
	W-01	Room # 802A Ceiling Unit (Univent)	Composite 1 sq'		X			<9.0
	W-02	Room # 807 Ceiling Unit (Univent)	Composit 1 sq'		X			<9.0
	W-03	Room # 817 Ceiling Unit (Univent)	composit 1 sq'		X			<9.0
	W-04	Room # 533 South side Left Univent	1 sq'		X			<9.0
	W-05	F/B				4		<9.0 (µg)
	W-06	F/B				4		<9.0 (µg)

Fax results to Taylor at (202) 406-2535.

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 7/28/02 TIME 10:00	PRINTED NAME AL. Kazanow	RECEIVED BY (SIGNATURE)	DATE 7/29/02 TIME 1500	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-29-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-28-02
DATE RECEIVED:	07-28-02
DATE ANALYZED:	07-28-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20719	Rm 802A Ceiling Unit (Unitvent)	<9.0	9.0
W-02	20719	Rm 807 Ceiling Unit (Unitvent)	<9.0	9.0
W-03	20719	Rm 817 Ceiling Unit (Unitvent)	<9.0	9.0
W-04	20719	Rm 333 South Side Left Unitvent	<9.0	9.0
W-05	20719	Field Blank	<9.0 µg	9.0 µg
W-06	20719	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$.
Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg.

NYC-WTC_000106733 PAGE 02/07
EMSL ANALYTICAL INC 212-290-2538 08/05/2002 07:25
NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030210609

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid & Javoj	SAMPLER (SIGNATURE)	DATE 8/4/02 TIME
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St NY	PROJECT # 14477-15217-29881	SAMPLER NAME (PRINT): Kirk McKenzie	SAMPLE(S) SEALED (YES) NO; CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	LW-01	Room 301 C - Ceiling unitvent - Damper	1 composit		✓			<10.0
	LW-02	Room 371 E - Ceiling unitvent - Damper	1 composit		✓			<10.0
	LW-03	Room 350 - Floor/wall unitvent - Rear	1		✓			11.0
	LW-04	Room 350 - Ceiling unitvent (Left) - Damper	1 composit		✓			<10.0
	LW-05	Room 350 - Ceiling unitvent (Right) - Damper	1 composit		✓			<10.0
	FBL-1	Field Blank						
	FBL-2	Field Blank						

EMSL-MANHATTAN RECEIVED 02 AUG -5 AM 12:28

Fax Results To. 212-406-2525 & 516-358-1780

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 8 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 8/5/02 TIME 24:00	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 08.05.02 TIME 01:	PRINTED NAME TEKEYA MICHAELS	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn:	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/05/02 6:52 AM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030210609
Project:	NYC SCA/M477-15217-27881/345 Chambers St. New York, N.Y.	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	Room 301C-Ceiling Unit Vent-Damper	0001		144 in²	<10.0 µg/ft²	
LW-02	371E-Ceiling Unit Vent-Damper	0002		144 in²	<10.0 µg/ft²	
LW-03	350-Floor/Wall Unit Vent-Rear	0003		144 in²	11.0 µg/ft²	
LW-04	350-Floor Wall Unit Vent (Left)-Damper	0004		144 in²	<10.0 µg/ft²	
LW-05	Room 350-Ceiling Unit Vent (Right)-Damper	0005		144 in²	<10.0 µg/ft²	
FBL-1	Field blank	0006		n/a	<10.0 µg/wipe	
FBL-2	Field blank	0007		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106734

NYC-WTC_00010735 PAGE 02/05 EMSL ANALYTICAL INC 212-290-2538 08:58 08/07/2002

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030210734

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAROLD SOUDJ.	Carlos Gonzalez	8-6-02	0913	YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
STUYVESANT H.S.	M477-15217/29881	CARLOS JOFAT			YES / NO

MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	ROOM # 373 CEILING UNITVENT AIR DAMPER	composite. 1 FT²		X			10.0
	FB 1	FIELD BLANK						—
	FB 2	FIELD BLANK						—
	LW-02	ROOM # 351 CEILING UNITVENT AIR DAMPER. RIGHT UNIT	1 FT²		X			<10.0
	LW-03	ROOM # 351 CEILING UNITVENT AIR DAMPER. LEFT UNIT	1 FT²		X			11.0

EMSL MARTINSBURG RECEIVED 02 AUG -6 PM 5:55

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: NIOSH Method 7082.

RELINQUISHED BY (SIGNATURE)	DATE	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE	PRINTED NAME
Carlos Gonzalez	8-6-02 TIME 1752	CARLOS JOFAT		8/6/02 TIME 555	
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 36th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900059 Email: manhattanlab@emsl.com

Attn:	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/06/02 5:55 PM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030210734
Project:	M477-15217/29881/ NYC SCA/ STUYVESANT H.S.	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	ROOM #373 CEILING UNITUENT AIR DAMPER	0001		144 in²	10.0 µg/ft²	
FB 1	Field blank	0002		n/a	<10.0 µg/wipe	
FB 2	Field blank	0003		n/a	<10.0 µg/wipe	
LW-02	ROOM #351 CEILING UNITUENT AIR DAMPER RIGHT UNIT	0004		144 in²	<10.0 µg/ft²	
LW-03	ROOM #351 CEILING UNITUENT AIR DAMPER LEFT UNIT	0005		144 in²	11.0 µg/ft²	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106736

NYC-WTC_000106737

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20133

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAVOJ	SAMPLER (SIGNATURE)	DATE 7/30/02 TIME	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST. NY	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT) Kirk McKenzie		CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT $\mu g/ft^2$
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-01	ROOM 209 - South side unitvent - REAR	1		✓			9.6
	LW-02	ROOM 229 - South side Left unitvent - REAR	1		✓			<9.0
	LW-03	ROOM 229 - South side Right unitvent - REAR	1		✓			<9.0
	LW-04	ROOM 235 - South side Left unitvent - REAR	1		✓			<9.0
	LW-05	ROOM 235 - South side Right unitvent - REAR	1		✓			<9.0
	LW-06	ROOM 237 - South side Left unitvent - REAR	1		✓			<9.0
	LW-07	ROOM 237 - South side Right unitvent - REAR	1		✓			<9.0
	LW-08	ROOM 250 - North side unitvent - REAR	1		✓			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/30/02 TIME 0130	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) L. Droudina	DATE 7.31.02 TIME 01.30	PRINTED NAME R. Droudina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

F. & 212-442-1775 & 516-358-1780

NYC 9/11 Public Portal Document

NYC-WTC_000106738

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LW193

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER SIGNATURE	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	Hamid Savoj		7/30/02		(YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.	PROJECT # M47715217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-09	Room 251 - North side Left unitvent - Rear	1		✓			<9.0
	LW-10	Room 251 - North side Right unitvent north side	1		✓			<9.0
	FBL-1	Field Blank	—					<9.0
	FBL-2	Field Blank	—					<9.0
	LW-11	Room 233 - South side Left unitvent - Rear	1		✓			<9.0
	LW-12	Room 233 - South side Right unitvent - Rear	1		✓			<9.0

TURNAROUND REQUIRED. NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/30/02 TIME 0130	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) R. Droudina	DATE 7.31.02 TIME 01.30	PRINTED NAME R. Droudina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106739

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE) / DATE / TIME	SAMPLE(S) SEALED
NYCSCA	HAMID SAVOJ	7/21/02	(YES) / NO
PROJECT LOCATION: Stuyvesant HS 345 Chambers St NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie	CORRECT CONTAINER(S) (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	ROOM 601 A Ceiling unitvent - Damper	1 composit		✓			<9.0
	LW-02	ROOM 615 FLOOR unitvent "L" - REAR	1		✓			<9.0
	LW-03	ROOM 615 - Ceiling unitvent "O" - Damper	1 composit		✓			<9.0
	4	Blank						<9.0
	5	Blank						<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	7/21/02 2356	Kirk McKenzie			
	8/1/02 901	G. McKenna	R. Droudina	8.1.02 01.00	R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

Fax Results to 212-442-2525 & 516-358-1780

NYC 9/11 Public Portal Document

NYC-WTC_000106740

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20822

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC DCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE): [signature] DATE: 7/31/02 TIME:	SAMPLE(S) SEALED: (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST. N.Y.	PROJECT #: M477-15217-29881	SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S): (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LWD-01	Room 601A - Ceiling unitvent - Duct	1		✓			11.8
	LWD-02	Room 615 - Ceiling unitvent "O" - Duct	1		✓			<9.0
	FBL-1	Field Blank	—	—	—	—	—	<9.0
	FBL-2	Field Blank	—	—	—	—	—	<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
[signature]	7/31/02 2350	Kirk McKenzie			
[signature]	8/1/02 0100	G. McKenzie	R. Droudina	8.1.02 01.00	R. Droudina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-01-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	07-31-02
DATE RECEIVED:	08-01-02
DATE ANALYZED:	08-01-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LWD-01	20822	Rm 601A Ceiling Unitvent Duct	11.8	9.0
LWD-02	20822	Rm 615 Ceiling Unitvent O - Duct	<9.0	9.0
FBL-1	20822	Field Blank	<9.0 µg	9.0 µg
FBL-2	20822	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RD

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106742

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

20793

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: HAMID SAVOJ	SAMPLER (SIGNATURE)	DATE 7/30/02 TIME	SAMPLE(S) SEALED (YES) / NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST. NY	PROJECT # M477-15217-2988	SAMPLER NAME (PRINT): Kirk McKenzie		CORRECT CONTAINER(S) (YES) / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:				SURFACE MATERIAL				
LABORATORY #	SAMPLE #	LOCATION	AREA (FT^2)	WOOD	METAL	BRICK	OTHER	LAB RESULT $\mu g/ft^2$
	LW-01	ROOM 209 - South side unitvent - REAR	1		✓			9.6
	LW-02	ROOM 229 - South side Left unitvent - REAR	1		✓			<9.0
	LW-03	ROOM 229 - South side Right unitvent - REAR	1		✓			<9.0
	LW-04	ROOM 235 - South side Left unitvent - REAR	1		✓			<9.0
	LW-05	ROOM 235 - South side Right unitvent - REAR	1		✓			<9.0
	LW-06	ROOM 237 - South side Left unitvent - REAR	1		✓			<9.0
	LW-07	ROOM 237 - South side Right unitvent - REAR	1		✓			<9.0
	LW-08	ROOM 250 - North side unitvent - REAR	1		✓			<9.0

TURNAROUND REQUIRED.
NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS
6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/30/02 TIME 0130	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) R. Droudina	DATE 7.31.02 TIME 01.30	PRINTED NAME R. Droudina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC-WTC_000106743

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20793

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE)	DATE 7/30/02 TIME
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. N.Y.	PROJECT # M477/5217-29881	SAMPLER NAME (PRINT) Kirk McKenzie	SAMPLE(S) SEALED (YES) NO; CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-09	ROOM 251 - North side Left unitvent - REAR	1		✓			<9.0
	LW-10	ROOM 251 - North side Right unitvent north side	1		✓			<9.0
	FBL-1	Field Blank	—					<9.0
	FBL-2	Field Blank	—					<9.0
	LW-11	ROOM 233 - South side Left unitvent - REAR	1		✓			<9.0
	LW-12	ROOM 233 - South side Right unitvent - REAR	1		✓			<9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE 7/30/02 TIME 0130	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) R. Droudina	DATE 7/31/02 TIME 01:30	PRINTED NAME R. Droudina
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-31-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-30-02
DATE RECEIVED: 07-31-02
DATE ANALYZED: 07-31-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20793	Rm 209 South Side Unitvent Rear	9.6	9.0
LW-02	20793	Rm 229 South Side Left Unitvent Rear	<9.0	9.0
LW-03	20793	Rm 229 South Side Right Unitvent Rear	<9.0	9.0
LW-04	20793	Rm 235 South Side Left Unitvent Rear	<9.0	9.0
LW-05	20793	Rm 235 South Side Right Unitvent Rear	<9.0	9.0
LW-06	20793	Rm 237 South Side Left Unitvent Rear	<9.0	9.0
LW-07	20793	Rm 237 South Side Right Unitvent Rear	<9.0	9.0
LW-08	20793	Rm 250 North Side Unitvent Rear	<9.0	9.0
LW-09	20793	Rm 251 North Side Left Unitvent Rear	<9.0	9.0
LW-10	20793	Rm 251 North Side Right Unitvent North Side	<9.0	9.0
FBL-1	20793	Field Blank	<9.0 µg	9.0 µg
FBL-2	20793	Field Blank	<9.0 µg	9.0 µg
LW-11	20793	Rm 233 South Side Left Unitvent Rear	<9.0	9.0
LW-12	20793	Rm 233 South Side Right Unitvent Rear	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RD

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106746

NYC 9/11 Public Portal Document
07/31/2002 18:49 212-290-2538 EMSL ANALYTICAL INC PAGE 02/02

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

030210370

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA Stuyvesant
CONTACT: Hamid Saucy
SAMPLER (SIGNATURE): DATE 7/31/02 TIME 11:36
SAMPLER NAME (PRINT):
SAMPLE(S) SEALED: YES / NO
CORRECT CONTAINER(S): YES / NO
PROJECT LOCATION: 345 Chambers St
PROJECT #: (M477-15217-2985)
MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	5	in gill ceiling unionb outside gill side	1		X			61.0 µg/FT²
	FB-3	field Blank						
	FB 4	field Blank						

EMSL MANHATTAN RECEIVED
02 JUL 31 PM 4:16

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE): DATE 7/31/02 TIME 4:10 PRINTED NAME: Peterlonis
RECEIVED BY (SIGNATURE): DATE 7/31 TIME 4 PRINTED NAME: Copa
RELINQUISHED BY (SIGNATURE): DATE 7/31 TIME 4:10 PRINTED NAME:
RECEIVED BY LAB (SIGNATURE): DATE TIME PRINTED NAME:

WHITE - YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: M477-15217-29881/ SCA/ STUYVESANT/ 345 CHAMBERS ST

Customer ID: TAYL50
Customer PO:
Received: 07/31/02 4:16 PM
EMSL Order: 030210370
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
5	IN 911 CEILING UNI. OUTSIDE GRILL SIDE	0001	7/31/02	144 in²	61.0 µg/ft²	
FB-3	Field blank	0002	7/31/02	n/a	<10.0 µg/wipe	
FB-4	Field blank	0003	7/31/02	n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 µg/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102981

NYC-WTC_000106747

NYC-WTC_00010674B PAGE 02/02 EMSL ANALYTICAL INC 212-290-2538 08/01/2002 13:25

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

03021042 3

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Sevgi		8/01/02		(YES) / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S) (YES) / NO
Stuyvesant H.S.	M477-15217/29881	AL. Kraemer			

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-08	Room #615E Ceiling Univent Air dumper	Composit 1 sq'		X			<10 µg/ft²
	W-09	Room #615E Wall univent back wall	1 sq'		X			<10 µg/ft²
	W-10	F/B						
	W-11	F/B						

EMSL MANHATTAN RECEIVED 02 AUG -1 PM 3:36

For results to Taylor on site: (212) 406-2585

TURNAROUND REQUIRED. NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8.01.02 15:35				
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn:	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO.	
		Received:	08/01/02 3:36 PM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030210423
Project:	M477-15217/ 29881 / SCA / Stuyvesant H.S.	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		*Lab ID*	*Analyzed*	*Area Sampled*	*Lead Concentration*	*Notes*
W-08	Room #615 E Ceiling Univent Air Dumper	*0001*	8/1/02	144 in^2	<10.0 $\mu g/ft^2$	
W-09	Room #615 E Wall Univent Back Wall	*0002*	8/1/02	144 in^2	<10.0 $\mu g/ft^2$	
W-10	F/B	*0003*	8/1/02	n/a	<10.0 µg/wipe	
W-11	F/B	*0004*	8/1/02	n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106749

NYC-WTC_000106750

NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savos	SAMPLER (SIGNATURE): [signature] DATE: 8/01/02 TIME:	SAMPLE(S) SEALED: (YES) NO
PROJECT LOCATION: Stuyvesant H.S.	PROJECT #: M744-15217/29881	SAMPLER NAME (PRINT): A. Kazakov	CORRECT CONTAINER(S): (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER 20833	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	W-01	Room #911 Ceiling Unit Air dumper	Composit 1 SF		X			29.0
	F/B-01	F/B	"					"
	F/B-02	F/B	"					"

Please fax results to Taylor at (212)406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: S.T.A.T. (A.S.A.P.)

RELINQUISHED BY (SIGNATURE): [signature]	DATE: 8/1/02 TIME: 11:30	PRINTED NAME: A. KAZAKOV	RECEIVED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:
RELINQUISHED BY (SIGNATURE):	DATE: TIME:	PRINTED NAME:	RECEIVED BY LAB (SIGNATURE): [signature]	DATE: 8/1/2 TIME: 11:30	PRINTED NAME:

WHITE - OFFICE / YELLOW - [illegible]

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-01-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 08-01-02
DATE RECEIVED: 08-01-02
DATE ANALYZED: 08-01-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20833	Rm 911 Ceiling Unitvent Air Dumper	<9.0	9.0
F/B-01	20833	Field Blank	<9.0 µg	9.0 µg
F/B-02	20833	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_00010752 PAGE 02/02 EMSL ANALYTICAL INC 212-290-2538 08/02/2002 07:10

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

0302104446

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
NYC SCA	HAMID SANJ		8/1/02		(YES) NO
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers St. NY	PROJECT # M477-15217-29881	SAMPLER NAME (PRINT) Kirk McKenzie			CORRECT CONTAINER(S) (YES) NO
		MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____			

SAMPLE INFORMATION:			AREA (FT^2)	SURFACE MATERIAL				LAB RESULT
LABORATORY #	SAMPLE #	LOCATION		WOOD	METAL	BRICK	OTHER	
	LW-01	ROOM 501 - Ceiling ambient - Damper	1 composit		✓			<10.0 µg/ft²
	FBL-1	Field Blank						
	FBL-2	Field Blank						

EMSL MANHATTAN RECEIVED
02 AUG -2 AM 12:35

			TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /	COMMENTS / INSTRUCTIONS 6 HR TAT	
RELINQUISHED BY (SIGNATURE)	DATE 8/2/02 TIME 0030	PRINTED NAME Kirk McKenzie	RECEIVED BY (SIGNATURE) Javier Quispe@emsl.	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn:	Taylor Environmental Group, Inc. Floral Park Corporate Center 130 Jericho Tpke. Floral Park, NY 11001	Customer ID:	TAYL50
		Customer PO:	
		Received:	08/02/02 12:35 AM
Fax:	(516) 358-1780 Phone: 516-358-2955	EMSL Order:	030210446
Project:	M477-15217-29881 / Stuyvesant H.S. 345 Chambers St. NY / NYC SCA	EMSL Project ID:	

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area Sampled	Lead Concentration	Notes
LW-01	Room 501 ceiling	0001		144 in²	<10.0 µg/ft²	
FBL-1	Field blank	0002		n/a	<10.0 µg/wipe	
FBL-2	Field blank	0003		n/a	<10.0 µg/wipe	

Laboratory Manager
or other approved signatory

Reporting limit is 10 ug/wipe
ACCREDITATIONS: AIHA Environmental Lead Laboratory Approval Program #102581

NYC-WTC_000106753

NYC-WTC_000106754

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Himiel Savoj		8/01/02		YES / NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesant H.S.	M477-15217/24881	AL. Kaganov			YES / NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER 20834

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT
	W-02	Room # 615, Ceiling Univent "P" air dumper	Composit 1 sq'		X			
	W-03	Room # 615 Univent "M" back wall	1 sq'		X			
	W-04	Room # 615 Ceiling Unit "Q" air dumper	Composit 1 sq'		X			
	W-05	Room # 615 Univent "N" back wall	1 sq'		X			
	W-06	F/13					4	
	W-07	F/13					4	

Fax results to Taylor on site (212) 406-2535

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 8/01/02 TIME 11:10	PRINTED NAME AL. Kaganov	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 8/1/11 TIME	PRINTED NAME JO

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-01-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 08-01-02
DATE RECEIVED: 08-01-02
DATE ANALYZED: 08-01-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-02	20834	Rm 615 Ceiling Unitvent P Air Dumper	<9.0	9.0
W-03	20834	Rm 615 Unitvent M Back Wall	<9.0	9.0
W-04	20834	Rm 615 Ceiling Unitvent Q Air Dumper	<9.0	9.0
W-05	20834	Rm 615 Unitvent N Back Wall	<9.0	9.0
W-06	20834	Field Blank	<9.0 µg	9.0 µg
W-07	20834	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106755

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106757

NYC 9/11 Public Portal Document

20871

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: SCA	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE)	DATE 8/02/02 TIME	SAMPLE(S) SEALED (YES) NO
		SAMPLER NAME (PRINT) AL. KAZAKOV		CORRECT CONTAINER(S) (YES) NO
PROJECT LOCATION: Stuyvesant HS.	PROJECT # M477-15217/29881	MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____		

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	DW-01	Room # 501 A, Ceiling univent c/n damper.	Composit 1		X			< 9.0
	DW-02	Room # 231 Left Univent Back wall	1		X			< 9.0
	DW-03	Room # 231 Right Univent Back wall	1		X			< 9.0
	DW-04	F/B					4	< 9.0
	D-W-05	F/B					4	< 9.0

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS

RELINQUISHED BY (SIGNATURE)	DATE 8/02/02 TIME	PRINTED NAME AL. KAZAKOV	RECEIVED BY (SIGNATURE) R. DiMolina	DATE 8.2.02 TIME 16.00	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8.2.02 TIME 16	PRINTED NAME T. Mikolajczyk	RECEIVED BY LAB (SIGNATURE)	DATE TIME	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel 212-353-8280
Fax 212-353-8306

REPORT DATE: .08-05-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 08-02-02
DATE RECEIVED: 08-02-02
DATE ANALYZED: 08-02-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
DW-01	20871	Rm 501A Ceiling Unitvent Air Damper	<9.0	9.0
DW-02	20871	Rm 231 Left Unitvent Back Wall	<9.0	9.0
DW-03	20871	Rm 231 Right Unitvent Back Wall	<9.0	9.0
DW-04	20871	Field Blank	<9.0 µg	9.0 µg
DW-05	20871	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: BD

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000106759

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001
516-358-2955
Fax 516-358-1780

20898

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS: NYC EDC	CONTACT: Hamid Savoj	SAMPLER (SIGNATURE) / DATE: 8/3/02 / TIME	SAMPLE(S) SEALED: YES / NO
PROJECT LOCATION: Stuyvesant H.S 345 Chambers St. NY	PROJECT #: M477-15217-2881	SAMPLER NAME (PRINT): Kirk McKenzie	CORRECT CONTAINER(S): YES / NO
		MATRIX (CIRCLE ONE): WIPE PAINT SOIL OTHER _____	

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT µg/ft²
	LW-01	ROOM 451 - North side Wall univent - Rear	1		✓			<9.0
	LW-02	ROOM 451 - North side Ceiling univent - Damper	1 composit		✓			<9.0
	LW-03	ROOM 453 - North side Wall univent - Rear	1		✓			<9.0
	LW-04	ROOM 453 - North side Ceiling univent - Damper	1 composit		✓			<9.0
	FBL-1 ~~FBL-05~~	Field Blank						<9.0
	FBL-2	Field Blank						<9.0

Fax To 212-406-2535 # 516-358-2955

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6 HR TAT

RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY (SIGNATURE)	DATE / TIME	PRINTED NAME
	8/4/02 0020	Kirk McKenzie	ATC Lab / [illegible]	08/04/02 00.20	D. Kogan
RELINQUISHED BY (SIGNATURE)	DATE / TIME	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE / TIME	PRINTED NAME

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-05-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 345 Chambers Street, NY
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE:	08-03-02
DATE RECEIVED:	08-04-02
DATE ANALYZED:	08-04-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20898	Rm 451 North Side Wall Unitvent Rear	<9.0	9.0
LW-02	20898	Rm 451 North Side Ceiling Unitvent Damper	<9.0	9.0
LW-03	20898	Rm 453 North Side Wall Unitvent Rear	<9.0	9.0
LW-04	20898	Rm 453 North Side Ceiling Unitvent Damper	<9.0	9.0
FBL-1	20898	Field Blank	<9.0 µg	9.0 µg
FBL-2	20898	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

NYC-WTC_000106761

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

516-358-2955
Fax 516-358-1780

70893

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS	CONTACT:	SAMPLER (SIGNATURE)	DATE	TIME	SAMPLE(S) SEALED
SCA	Hamid Savoy		8/03/02		(YES) NO
PROJECT LOCATION:	PROJECT #	SAMPLER NAME (PRINT)			CORRECT CONTAINER(S)
Stuyvesand H.S.	M477-15217/29881	AL. Kazanov			(YES) NO

MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____

SAMPLE INFORMATION:

LABORATORY #	SAMPLE #	LOCATION	AREA (FT²)	SURFACE MATERIAL: WOOD	METAL	BRICK	OTHER	LAB RESULT mg/m²
	DW-01	Room #450 Ceiling Univent Air dumper	1		X			<9.0
	DW-02	Room #450 Wall Univent Back wall.	1		X			
	DW-03	Room #402 ceiling Univent Air dumper	1		X			
	DW-04	F/B						
	DW-05	F/B						

TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /

COMMENTS / INSTRUCTIONS: 6hr T.A.T.

RELINQUISHED BY (SIGNATURE)	DATE 8/03/02 TIME	PRINTED NAME AL. Kazanov	RECEIVED BY (SIGNATURE)	DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE)	DATE 8/3/02 TIME 420	PRINTED NAME	RECEIVED BY LAB (SIGNATURE)	DATE 8/3/2 TIME 16:00	PRINTED NAME

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-05-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 08-03-02
DATE RECEIVED: 08-03-02
DATE ANALYZED: 08-03-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
DW-01	20893	Rm 450 Ceiling Unitvent Air Damper	<9.0	9.0
DW-02	20893	Rm 450 Wall Unitvent Back Wall	<9.0	9.0
DW-03	20893	Rm 402 Ceiling Unitvent Air Damper	<9.0	9.0
DW-04	20893	Field Blank	<9.0 µg	9.0 µg
DW-05	20893	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).