

WTC Visual Survey Form

1001040

Premise Address: 120 LIBERTY STREET		
Block: 52 Lot: 21	Residential ☐ Commercial ☐ Mix Use ☒ Other ☐	Name of Building: 125 CEDAR STREET
# of Stories: 13 AKA's: 125 CEDAR ST.		
Building Owner/Management: Name: SAMSON . JOE MASINO		Telephone Number: (718) 830-0131 x25 FAX: (718) 897-4387
Address:		
On Site Contact: Name: Telephone Number: ()		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks ☐ N/A					
Floor:	3 rd	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:	2 nd	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:	_____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:	_____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:	_____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					
2 nd Fl. - breakthrough from apt 25 for clean-up of lower sky light.					
DEP Contractors performed exterior clean-up activities					
TRIO & FIBER CONTROL					

Date: 10/15/2002

Inspection Team: Name: Penny Theodorelly Agency: NYC DEP
Name: _____ Agency: _____