

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 40805 0

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST. / 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #:

PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL HUTCHMEDIAN SQUAD #: 1 BADGE #: A058

DATE OF INSPECTION: 6/23/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐

Contact at site: JAN WOLKOWICZ #84919 To: 1:30 AM ☐ PM ☒

Inspection disclosed that the following sections were complied with: (Check all that apply)

☒ 1-51 - Notifications, Reports, Pla	☒ 1-71 - Air Sampling and Monitorin	☒ 1-91 - Worker Protection
☒ 1-101 - Materials and Equipment	☒ 1-116 - Work Place Preparation	☒ 1-117 - Worker Decontamination System
☒ 1-118 - Waste Decontamination System	☒ 1-126 - Engineering Controls	☒ 1-127 - Entry/Exit Procedures
☒ 1-129 - Maintenance of Barriers	☒ 1-138 - Encapsulation	☒ 1-139 - Enclosure
☒ 1-140 - Glovebag	☒ 1-141 - Tent	☒ 1-137 - ACM Disturbance, RemoveL, Handling
☒ 1-146 - Preliminary Clean-up	☒ 1-147 - Final Clean-up	

Project not started

Inspection

revealed all ACM to be intact. New start date: / /

Project ongoing, expected completion date: / /

Project completed on or about / / All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on / /

Samples taken: No Yes 1 2 3

4 5 6 Photos taken: No Yes No

Additional comments: Early in the vent over with Jan all areas that needed more cleaning. this was done. At about 1:45 pm Roof was inspected and all WIC had been removed. Roof

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

ASBESTOS INSPECTION REPORT (con't)

Page _____ of _____

28. Methods of ACM Abatement (Check all appropriate boxes)

- ☐ Full Containment ☐ Repair ☐ Enclose ☐ Clean up
☐ Glovebag ☐ Encapsulation ☐ Tent
☐ Other, Specify: _____

29. This asbestos abatement is part of a

- ☐ Demolition ☐ Boiler Replacement ☐ Sprinkler Replacement
☐ Renovation/Alteration ☐ Fire proofing Replacement
☐ Other, (Describe): _____

FL	AREA	METHOD	SF	LF
ROOFS	ITEM NO.3		11565	0
WALLS	ITEM NO.8		3635	0
	AIR SHAFT		0	0
ROOF	ITEM NO. 3		1500	0
WALLS	ITEM NO. 8		24105	0

**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
ASBESTOS INSPECTION REPORT**

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

**NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)**

TOTAL FEET: 40805 0

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST./ 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #:

PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL HUTCHMEDIAN

SQUAD #: 1

BADGE #: A058

DATE OF INSPECTION: 6/23/02

TIME OF INSPECTION: From: 8

AM ☒ PM ☐

Contact at site:

JAN WOLKOWICZ #84919

To: 1:30

AM ☐ PM ☒

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--|---|--|
| ☒ 1-51 - Notifications, Reports, Pla | ☒ 1-71 - Air Sampling and Monitorin | ☒ 1-91 - Worker Protection |
| ☒ 1-101 - Materials and Equipment | ☒ 1-116 - Work Place Preparation | ☒ 1-117 - Worker Decontamination System |
| ☒ 1-118 - Waste Decontamination System | ☒ 1-126 - Engineering Controls | ☒ 1-127 - Entry/Exit Procedures |
| ☒ 1-129 - Maintenance of Barriers | ☒ 1-138 - Encapsulation | ☒ 1-139 - Enclosure |
| ☒ 1-140 - Glovebag | ☒ 1-141 - Tent | ☒ 1-137 - ACM Disturbance, Removal, Handling |
| ☒ 1-146 - Preliminary Clean-up | ☒ 1-147 - Final Clean-up | |

Project not started

Inspection

revealed all ACM to be intact. New start date: / /

Project ongoing, expected completion date: / /

Project completed on or about / /

All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on / /

Samples taken:

No

Yes

1

2

3

4

5

6

Photos taken:

Yes

No

Additional comments:

Early in the vent over with Jan all areas that needed more cleaning. This was done. At about 1:45 pm Roof was inspected and all WIC had been removed. Roof

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

ASBESTOS INSPECTION REPORT (con't)

Page _____ of _____

28. Methods of ACM Abatement (Check all appropriate boxes)

- ☐ Full Containment ☐ Repair ☐ Enclose ☐ Clean up
☐ Glovebag ☐ Encapsulation ☐ Tent
☐ Other, Specify: _____

29. This asbestos abatement is part of a

- ☐ Demolition ☐ Boiler Replacement ☐ Sprinkler Replacement
☐ Renovation/Alteration ☐ Fire proofing Replacement
☐ Other, (Describe): _____

FL	AREA	METHOD	SF	LF
ROOFS	ITEM NO.3		11565	0
WALLS	ITEM NO.8		3635	0
	AIR SHAFT		0	0
ROOF	ITEM NO. 3		1500	0
WALLS	ITEM NO. 8		24105	0