

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 40805 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST. / 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #:

PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY

ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL LUTCHMEYER SQUAD #: 1 BADGE #: 8058

DATE OF INSPECTION: 6/20/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐

To: 6 AM ☐ PM ☒

Contact at site: Steve Parmigiani - Pj Mn

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--|---|--|
| ☒ 1-51 - Notifications, Reports, Pla | ☒ 1-71 - Air Sampling and Monitorin | ☒ 1-91 - Worker Protection |
| ☒ 1-101 - Materials and Equipment | ☒ 1-116 - Work Place Preparation | ☒ 1-117 - Worker Decontamination System |
| ☒ 1-118 - Waste Decontamination System | ☒ 1-126 - Engineering Controls | ☒ 1-127 - Entry/Exit Procedures |
| ☒ 1-129 - Maintenance of Barriers | ☒ 1-138 - Encapsulation | ☒ 1-139 - Enclosure |
| ☒ 1-140 - Glovebag | ☒ 1-141 - Tent | ☒ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☒ 1-146 - Preliminary Clean-up | ☒ 1-147 - Final Clean-up | |

☐ Project not started . Inspection

revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /

☐ Project completed on or about / / . All surfaces, including abated surfaces are free of visible ACM and encapsulat

☐ Follow up necessary on / /

Samples taken: ☒ No ☐ Yes 1 2 3

4 5 6 Photos taken: ☐ Yes ☒ No

Additional comments: Work started after 114 Liberty St was underway. Access was gained from roof of 114 Liberty St. The same "decon" from 114 Liberty was also utilized for this project. Cleaning was conducted around the construction material on the roof. A scaffold set up was also on the roof for Cedar St side.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

ASBESTOS INSPECTION REPORT (con't)

Page _____ of _____

28. Methods of ACM Abatement (Check all appropriate boxes)

- ☐ Full Containment
 ☐ Repair
 ☐ Enclose
 ☐ Clean up
☐ Glovebag
 ☐ Encapsulation
 ☐ Tent
☐ Other, Specify: _____

29. This asbestos abatement is part of a

- ☐ Demolition
 ☐ Boiler Replacement
 ☐ Sprinkler Replacement
☐ Renovation/Alteration
 ☐ Fire proofing Replacement
☐ Other, (Describe): _____

FL	AREA	METHOD	SF	LF
ROOFS	ITEM NO.3		11565	0
WALLS	ITEM NO.8		3635	0
	AIR SHAFT		0	0
ROOF	ITEM NO. 3		1500	0
WALLS	ITEM NO. 8		24105	0

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 40805 0

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST. / 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY

ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL LUTCHMANN SQUAD #: 1 BADGE #: A058

DATE OF INSPECTION: 6/21/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐

Contact at site: JAN WOLKOWICZ # 84919 To: 7:00 AM ☐ PM ☒

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--|---|--|
| ☒ 1-51 - Notifications, Reports, Pla | ☒ 1-71 - Air Sampling and Monitorin | ☒ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☒ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☒ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☒ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |
| ☐ Project not started | | Inspection |

revealed all ACM to be intact. New start date: / /

Project ongoing, expected completion date: / /

Project completed on or about / / . All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on / /

Samples taken: No ☐ Yes ☐ 1 ☐ 2 ☐ 3 ☐ 4 ☐ 5 ☐ 6 Photos taken: ☐ Yes ☐ No

Additional comments: Project ongoing, four workers on roof. No problems encountered.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

ASBESTOS INSPECTION REPORT (con't)

Page _____ of _____

28. Methods of ACM Abatement (Check all appropriate boxes)

- ☐ Full Containment
 ☐ Repair
 ☐ Enclose
 ☐ Clean up
☐ Glovebag
 ☐ Encapsulation
 ☐ Tent
☐ Other, Specify: _____

29. This asbestos abatement is part of a

- ☐ Demolition
 ☐ Boiler Replacement
 ☐ Sprinkler Replacement
☐ Renovation/Alteration
 ☐ Fire proofing Replacement
☐ Other, (Describe): _____

FL	AREA	METHOD	SF	LF
ROOFS	ITEM NO.3		11565	0
WALLS	ITEM NO.8		3635	0
	AIR SHAFT		0	0
ROOF	ITEM NO. 3		1500	0
WALLS	ITEM NO. 8		24105	0

TOTAL FEET: 40805 0

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

Basis of Inspection:

TRU0929MN02

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

FEE EXEMPT: Yes

1. \$0.00

Variance

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST./ 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #

PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL HUTCHMEDIAN

SQUAD #: 1

BADGE #: A058

DATE OF INSPECTION: 6/23/02

TIME OF INSPECTION: From: 8

AM ☒ PM ☐

Contact at site:

JAN WOLKOWICZ #84919

To: 1:30

AM ☐ PM ☒

Inspection disclosed that the following sections were complied with: (Check all that apply)

1-51 - Notifications, Reports, Pla

1-71 - Air Sampling and Monitorin

1-91 - Worker Protection

1-101 - Materials and Equipment

1-116 - Work Place Preparation

1-117 - Worker Decontamination System

1-118 - Waste Decontamination System

1-126 - Engineering Controls

1-127 - Entry/Exit Procedures

1-129 - Maintenance of Barriers

1-138 - Encapsulation

1-139 - Enclosure

1-140 - Glovebag

1-141 - Tent

1-137 - ACM Disturbance, RemoveL, Handling

1-146 - Preliminary Clean-up

1-147 - Final Clean-up

Project not started

Inspection

revealed all ACM to be intact. New start date:

Project ongoing, expected completion date:

Project completed on or about

All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on

Samples taken:

No

Yes

1

2

3

4

5

6

Photos taken:

Yes

No

Additional comments:

Earlier in the vent over with Jan all areas
that needed more cleaning. This was done.
At about 1:45 pm Roof was inspected and all
WIC had been removed.
Roof

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 40805 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST./ 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #:

PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY

ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL LUTCHMEYER SQUAD #: 1 BADGE #: A058

DATE OF INSPECTION: 6/22/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐

Contact at site: JAN WOLKOWSKI # 84919 To: 5 AM ☐ PM ☒

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--|---|--|
| ☒ 1-51 - Notifications, Reports, Pla | ☒ 1-71 - Air Sampling and Monitorin | ☒ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☒ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☒ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☒ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |
| ☐ Project not started | | Inspection |

revealed all ACM to be intact. New start date: / /

Project ongoing, expected completion date: / /

Project completed on or about / / All surfaces, including abated surfaces are free of visible ACM and encapsulat

Follow up necessary on / /

Samples taken: ☐ No ☐ Yes 1 2 3

4 5 6 Photos taken: ☐ Yes ☐ No

Additional comments: Most of the Debris was removed today
Expected final cleaning early tomorrow, then
final inspection.
no problems

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

