

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 40805 0

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST./ 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #:

PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY

ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL LUTCHMEYER

SQUAD #: 1

BADGE #: 2058

DATE OF INSPECTION: 6/20/02

TIME OF INSPECTION: From: 8

AM ☒ PM ☐

To: 6

AM ☐ PM ☒

Contact at site: Steve Parnagian - Pj Mn

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--|---|--|
| ☒ 1-51 - Notifications, Reports, Pla | ☒ 1-71 - Air Sampling and Monitorin | ☒ 1-91 - Worker Protection |
| ☒ 1-101 - Materials and Equipment | ☒ 1-116 - Work Place Preparation | ☒ 1-117 - Worker Decontamination System |
| ☒ 1-118 - Waste Decontamination System | ☒ 1-126 - Engineering Controls | ☒ 1-127 - Entry/Exit Procedures |
| ☒ 1-129 - Maintenance of Barriers | ☒ 1-138 - Encapsulation | ☒ 1-139 - Enclosure |
| ☒ 1-140 - Glovebag | ☒ 1-141 - Tent | ☒ 1-137 - ACM Disturbance, Removal, Handling |
| ☒ 1-146 - Preliminary Clean-up | ☒ 1-147 - Final Clean-up | |
| ☐ Project not started | | |

revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /

☐ Project completed on or about / / . All surfaces, including abated surfaces are free of visible ACM and encapsulat

☐ Follow up necessary on / /

Samples taken: ☒ No ☐ Yes 1 2 3

4 5 6 Photos taken: ☐ Yes ☒ No

Additional comments: Work started after 114 Liberty St was underway. Access was gained from roof of 114 Liberty St. The same "decon" from 114 Liberty St was also utilized for this project. Cleaning was conducted around the construction material on the roof. A scaffold set up was also on the roof for Cedar St side.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 40805 0

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST./ 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006
TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC Contact:
TEL #: ADDRESS: N/A CITY: STATE: ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error
TEL #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII
ADDRESS: 14-20 129 STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E
NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL HUTCHINGS SQUAD #: 1 BADGE #: A058

DATE OF INSPECTION: 6/21/02 TIME OF INSPECTION: From: 8 AM ☒ PM ☐

Contact at site: JAN WOLKOWICZ #84919 To: 7.00 AM ☐ PM ☒

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--|---|--|
| ☒ 1-51 - Notifications, Reports, Pla | ☒ 1-71 - Air Sampling and Monitorin | ☒ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☐ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☒ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☒ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |
| ☐ Project not started | | Inspection |

revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /

☐ Project completed on or about / / . All surfaces, including abated surfaces are free of visible ACM and encapsulat

☐ Follow up necessary on / /

Samples taken: ☐ No ☐ Yes 1 2 3
4 5 6 Photos taken: ☐ Yes ☐ No

Additional comments: Project ongoing, four workers on roof. No problems encountered.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS
4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 40805 0

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST. / 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY

ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL LUTCHMEYER

SQUAD #: 1

BADGE #: A058

DATE OF INSPECTION: 6/22/02

TIME OF INSPECTION: From: 8

AM ☒ PM ☐

Contact at site: JAN Wolkowicz # 84919

To: 5

AM ☐ PM ☒

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--|---|--|
| ☒ 1-51 - Notifications, Reports, Pla | ☒ 1-71 - Air Sampling and Monitorin | ☒ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☒ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☒ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☒ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |

☐ Project not started . Inspection

revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /

☐ Project completed on or about / / . All surfaces, including abated surfaces are free of visible ACM and encapsulat

☐ Follow up necessary on / /

Samples taken: ☐ No ☐ Yes 1 2 3

4 5 6 Photos taken: ☐ Yes ☐ No

Additional comments: Most of the Debris was removed today
Expected final cleaning early tomorrow, then I
final inspection.
no problems

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

SUPERVISOR INITIALS

TOTAL FEET: 40805 0

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

Basis of Inspection:

TRU0929MN02

FEE EXEMPT: Yes

1. \$0.00

☐ Variance

START DATE: 6/20/02

PROJ. COMPLETION DATE: 6/30/02

I. FACILITY

ADDRESS: 120 LIBERTY ST./ 125 CEDAR ST. BORO: MANHATTAN ZIP: 10006

TYPE OFFACILITY: BLOCK: 52 LOT: 21

II. BUILDING OWNER

NAME: 120 LIBERTY STREET, LLC

Contact

TEL. #:

ADDRESS: N/A

CITY:

STATE:

ZIP:

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: #Error

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #:

PII

ADDRESS: 14-20 129 STREET

CITY: COLLEGE POINT STATE: NY

ZIP: 11356

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER E

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☒ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: CARL HUTCHINSON

SQUAD #: 1

BADGE #: A058

DATE OF INSPECTION: 6/23/02

TIME OF INSPECTION: From: 8

AM ☒ PM ☐

Contact at site: JAN WOLKOWICZ #84919

To: 1:30

AM ☐ PM ☒

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|--|---|--|
| ☒ 1-51 - Notifications, Reports, Pla | ☒ 1-71 - Air Sampling and Monitorin | ☒ 1-91 - Worker Protection |
| ☒ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☐ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☒ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☒ 1-137 - ACM Disturbance, RemoveL, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |
| ☐ Project not started | | Inspection |

revealed all ACM to be intact. New start date: / /

☐ Project ongoing, expected completion date: / /

☐ Project completed on or about / / . All surfaces, including abated surfaces are free of visible ACM and encapsulat

☐ Follow up necessary on / /

Samples taken: ☐ No ☐ Yes 1 2 3

4 5 6 Photos taken: ☐ Yes ☐ No

Additional comments: Earlier in the week over with Jan all areas that needed more cleaning. This was done. At about 1:45 pm Roof was inspected and all WTC had been removed. Roof

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

5

SUPERVISOR INITIALS