

120 Liberty

WTC Visual Survey Form

Bldg # 1001040

Premise Address: <u>125 Cedar St</u> <u>120 Liberty</u>		
Block: <u>52</u>	Residential ☒ Commercial ☐	Name of Building:
Lot: <u>21</u>	Mix Use ☐ Other ☐	
# of Stories: <u>6</u>	AKA's: <u>123-125 CEDAR ST / 120-122 Liberty.</u>	
Building Owner/Management:		Telephone Number: ()
Name: <u>None</u>		FAX: () <u>on file</u>
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: <u>Samples were negative</u>		
ACM Clean Up ☐ Yes ☒ No Locations:		
Air Monitoring ☐ Yes ☒ No Locations:		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
North	☒ N/A	Inspected	Debris
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East	☒ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: <u>env</u>			
Roof			
Debris: ☐ No Visible /Fine Layer ☐ 1/2 to 1" ☒ > 1"			
Description: <u>Clean up taking place today by Gateway Cleaning</u>			
Setbacks ☐ N/A			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Comments			

Date: 1/25/2002Inspection Team: Name: CAEAgency: DER

FEB-25-2002 11:49

BANHM LABORATORY UNIT

P.03/07

BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

DUPLICATE

JOEL A. MIELKE, SR., P.E.
 COMMISSIONER

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____ Date Sampled: 2-23-02
 Premise: 125 CEDAR STREET Time: 1:00 AM/PM
 Boro: MANHATTAN
 Inspector: SAM NEBEDUM Samuel Nebedum
 Print Sign

TURNAROUND TIME: 24HRS [✓] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A038001	Fibrous	Roof (-)	059
2. 20223/A038002			060
3. 20223/A038003			061
4. 20223/A038004			062
5. 20223/A038005			063
6. 20223/A038006			064
7. 20223/A038007		(CHRY 17-1)	065
8. 20223/A038008		(-)	066
9. 20223/A038009			067
10. 20223/A038010			068

ANALYSES REQUESTED: Asbestos PLM [✓] Asbestos TEM [] Lead []

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	4:00 PM	PRINT <u>Greg Frygman</u> SIGN <u>[Signature]</u>	SYFE Cyst 91 BEC 696
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

BEP REV 9/94