

Clean-up
Activity

Mar 07 02 01:24p

joe monani fish co

212 267 2898

p.1

TELEPHONE: (212)233-3916
FAX: (212)267-2898



112 JOHN ST LLC

10 FULTON FISH MARKET

NEW YORK, N.Y. 10038

Dear Mrs. Wyatt.

I had two maintenance men go up onto my roof and sweep it clean. They then hosed it down. Everything was removed. I did not get any dust or material tested for any asbestos because, I did not know I was supposed to.

Respectfully

Edward Monani

Call ask what
happened to
assessment

3/4/02 - hit message

3/5/02 - will fax assessment

TELEPHONE: (212)233-3916
FAX: (212)267-2898



112 JOHN ST LLC

10 FULTON FISH MAKET

NEW YORK, N.Y. 10038

Dear Mr. Radhakrishnan

I have sent my workers to
clean the Roof. as per your
letter.

Respect fully

Edward Monani

Feb 19 02 01:56p

joe monani fish co

212 267 2898

p.2



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

February 16, 2002

Building Owner Name: Edward Monnani

Address: 112 John street
New York, NY 10038

Subject: 112 John street

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☐ building facade(s)
- ☐ setback(s)
- ☒ roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by February 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan (RAMMOHAN)
R. Radhakrishnan, P.E.
Director
Asbestos Control Program



Other

Address: 112 JOHN

Bulk Samples PLM Yes No

Number of Negative ($\leq 1\%$) Samples _____

Number of Positive ($> 1\%$) Samples _____

Air Samples Yes No

PCM

Number of Samples Collected (≤ 0.012 cc) _____

Number of Samples Collected (>0.01 f/cc) _____

TEM

Number of Samples Collected (≤ 70 s/mm²) _____

Number of Samples Collected (>70 s/mm²) _____

HIS WORKERS TO
ONLY STATED THAT HE SEND A "CLEAN ROOF"
SAMPLE - M