

WTC Visual Survey Form

Premise Address: 267 - 269 Waver St		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: <u>Cleaned</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 9/1/2002Inspection Team: Name: AL
Name: _____Agency: _____
Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 26, 2002

Building Owner Name: _____

Address: _____

267-269 Wale St
NYC

Subject: _____

Dear Sir/ Madam:


In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,


**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



(718) DEP-HELP

```

04/29/02          N.Y.C. DEPARTMENT OF BUILDINGS          BISPIQ31
          MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
269..... WATER STREET..... 1 MANHATTAN          10038 BIN# 1001383
DCP GEOGRAPHICAL INFORMATION:
WATER STREET          269 - 269          HEALTH AREA : 77          TAX BLK: 107..
          CENSUS TRACT: 11001          TAX LOT: 46...
          COMMUNITY BD: 101          CONDO :
          MULTI STRUCT: 1          CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : VJHC PROPERTIES INC          VJHC PROPERTIES INC
CORP. NAME :          LPC LANDMARK STATUS: LANDMARK
ADDRESS : 6          BOWERY          DOB LOCAL LAW STATUS: NO
          NEW YORK NY 10013-5101
DOF BUILDING INFORMATION:          TRANS LAND VALUE: 100,000
BLDG SIZE: 0024.00 X 0082.00          TAX EXEMPT FLAG : NO
LOT SIZE: 0024.00 X 0082.17          TAX EXEMPT CLASS:
BLDG CLASS : G2 GARAGE/GAS STAT'N          CITY OWNERSHIP : NO
STORIES : 1          UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE:          MGMT CODE:          MGMT CODE NAME:
OWNERSHIP }          MGMT HOLDER CODE:          MGMT HOLDER CODE NAME:
-----
PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

```

NYC DEP 59-17 Junction Blvd Corona, NY 11368 (718)DEP-HELP Fax (718)595-4096		Service Request Inspection Detail									
Report Date	04/24/2002 12:51 PM	Submitted By	Page 2								
Linked Requests <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">Service #</th> <th style="text-align: left;">Problem Location</th> <th style="text-align: left;">Problem Date</th> <th style="text-align: left;">Address</th> </tr> </thead> <tbody> <tr> <td colspan="4" style="padding: 5px;">No Linked Requests for this Service Request Inspection</td> </tr> </tbody> </table>				Service #	Problem Location	Problem Date	Address	No Linked Requests for this Service Request Inspection			
Service #	Problem Location	Problem Date	Address								
No Linked Requests for this Service Request Inspection											
NYC DEP <table border="1" style="width: 100%; border-collapse: collapse;"> <tbody> <tr> <td style="padding: 5px;">Method</td> </tr> <tr> <td style="padding: 5px;">Source</td> </tr> <tr> <td style="padding: 5px;">Critical Service</td> </tr> </tbody> </table>				Method	Source	Critical Service					
Method											
Source											
Critical Service											
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">Log Log Type Entered By</th> <th style="text-align: left;">Description Comments</th> <th style="text-align: left;">Log Started</th> <th style="text-align: left;">Log Ended</th> </tr> </thead> <tbody> <tr> <td colspan="4" style="padding: 5px;">There are no log entries for this service number</td> </tr> </tbody> </table>				Log Log Type Entered By	Description Comments	Log Started	Log Ended	There are no log entries for this service number			
Log Log Type Entered By	Description Comments	Log Started	Log Ended								
There are no log entries for this service number											
End of Report											