

WTC Visual Survey Form

Premise Address: 75 PARK PL		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: 3	AKA's: 44 West Bway	
Building Owner/Management:		Telephone Number: (212) 608-5857
Name: Jack Kesnick & Sons		FAX: ()
Address:		
On Site Contact:		Telephone Number: (212) 608-5857
Name: Mike Martin		
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No		Locations: entire BLDG
ACM Clean Up ☐ Yes ☐ No		Locations: none
Air Monitoring ☒ Yes ☐ No		Locations: ALL
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: broken windows etc. All windows < facade have been cleaned					
Roof					
Debris: ☒ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust					
Description:					
Setbacks N/A ☐					
Floor:	14	Debris:	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	10	Debris:	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments All roofs and setbacks are cleaned					

Date: 1/28/2002

Inspection Team: Name: AL
Name: REBJSAgency: NYCEP
Agency: NYCEP