

WTC Visual Survey Form

1001965

Premise Address: 177 W. Broadway		
Block: 176	Residential ☐ Commercial ☒	Name of Building:
Lot: 16	Mix Use ☒ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management Name:		Telephone Number: ()
Address:		FAX: ()
On Site Contact Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: Cleaned					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☒					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					

Date: 5/17/2002

Inspection Team: Name: _____

Name: _____

Agency: _____

Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422**

May
~~April~~ 17, 2002

Building Owner Name: _____

Address: _____

*177 W. Broadway
NYC*

Subject: _____

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



www.nyc.gov/dep

(718) DEP-HELP

```

05/21/02          N.Y.C. DEPARTMENT OF BUILDINGS          BISPI031
          MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
177..... WEST BROADWAY..... 1 MANHATTAN          10013 BIN# 1001965
DCP GEOGRAPHICAL INFORMATION:
WEST BROADWAY          177 - 177          HEALTH AREA : 77          TAX BLK: 176..
          CENSUS TRACT: 2008          TAX LOT: 16...
          COMMUNITY BD: 101          CONDO :
          MULTI STRUCT: 1          CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : SHILOH COMPANY          SHILOH COMPANY
CORP. NAME :          LPC LANDMARK STATUS: CALENDARED
ADDRESS : 170          CHANGEBRIDGE RD          DOB LOCAL LAW STATUS: NO
          MONTVILLE NJ 07045-9115
DOF BUILDING INFORMATION:          TRANS LAND VALUE: 300.000
BLDG SIZE: 0022.00 X 0059.00          TAX EXEMPT FLAG : NO
LOT SIZE: 0022.17 X 0059.33          TAX EXEMPT CLASS:
BLDG CLASS : K9 STORE BUILDING          CITY OWNERSHIP : NO
STORIES : 3          UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE:          MGMT CODE:          MGMT CODE NAME:
OWNERSHIP }          MGMT HOLDER CODE:          MGMT HOLDER CODE NAME:
-----
PF1 =PREV  PF2 =MAIN  PF7 = NEW ADDRESS  PF8 = NEW BLK/LOT  PF9 = NEW BIN

```

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN: