

Aug 02 02 12:48p

ACTION/FIBER

5167813085

p. 1

NEWYORK CITY

DEPARTMENT OF
BUILDINGS

Notification of Staging And Outrigger Beam Use By Special Riggers

Please file 2 copies for Cranes and
Derricks, plus copies for your own use

Application Must Be Typewritten

1. Location of Job	
Borough: Manhattan	
House No(s): 30	Street Name: West Broadway
Special Place Name: Fitterman Hall	No. of Stories: 15

NOTE: The following items are to be submitted with this application.

1. Site plan / roof plan showing:
 - A) Building outline; setbacks; building heights; adjacent buildings; sidewalk bridge/other protection; and the entrances and driveways to the building
 - B) Label the streets and traffic direction.
 - C) Location of the equipment.
 - D) Tie-backs, safety lines and how they are secured
2. Side view and front view of equipment showing:
 - A) Max. load picked.
 - B) Material, size and dimension of the equipment, including the outrigger beam, the staging, overhang, etc.
 - C) Size and details on all rigging hardware and connections (i.e. tie-downs, blocks, shackles, hooks, clamps, bolts and pulleys, etc.)
 - D) The make-up and weight of the counterweight
 - E) Planking / support under legs.
 - F) If wheels or rollers are used, show blocking to prevent lateral movement.
 - G) All relevant information and notes.

2. Job Information	
Job Description	Describe & Sketch Equipment Such As Pipe Staging and Outriggers Beams To Be Used (Attach Sketch To This Form)
Expected Start Date:	Approximate Duration of Job:

3. Special Rigger Information		
Last Name: Farnsworth	First Name: Edward	M.I.:
License No.: 5549		
Business Name: Fiber Control, Inc.		
Address: 42-14 21st Street		
City: Long Island City	State: NY	ZIP: 11101
Phone: 516-781-3000	Fax: 516-781-3085	

4. Owner or Managing Agent Information		
Last Name:	First Name:	M.I.:
Business Name: Borough of Manhattan Community College		
Address: 30 West Broadway		
City: New York	State: NY	ZIP: 10007-2192
Phone: 212-220-8025	Fax:	

5. Statement and Signatures	
- I certify that the subject work and setup of equipment will be done under my supervision or under the supervision of _____ (Supervisor, Foreman or Special Rigger) The work will be done in a safe and workman like manner - Falsification of any statement is a misdemeanor under Section 26-124 of the Administrative Code and is punishable by a fine or imprisonment, or both. - It is unlawful to give to a city employee, or for a city employee to accept, any benefit, monetary or otherwise, either as a gratuity for properly performing the job or in exchange for special consideration. Violation is punishable by imprisonment or fine or both.	
Signature of Licensed Rigger	Date

CD-5 (Rev. 5/02)

WTC Visual Survey Form

30 West Broadway

Premise Address: <u>30 West Broadway / Park Place</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	<u>FITZGERALD Hall (BMLC)</u>
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ ½ to 1" ☐ > 1"
Facade Description: <u>Broken windows etc</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>light dust</u>					
Setbacks ☐ N/A					
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Comments					
<u>DAMAGE CLOSED NO ACCESS</u>					

Date: 01/27/2002Inspection Team: Name: ALName: HENRIK

Agency: _____

Agency: _____

WTC Visual Survey Form (2)

Premise Address: <u>30 West Broadway (Bmcc Extension)</u>	
Block:	Residential ☐ Commercial ☐ Name of Building:
Lot:	Mix Use ☐ Other ☒ <u>SCHOOL</u>
# of Stories:	AKA's:
Building Owner/Management:	
Name: <u>MCU</u>	Telephone Number: ()
FAX: ()	
Address:	
On Site Contact:	
Name:	Telephone Number: ()
Building Owner Management Activities	
Interior Survey Performed ☐ Yes ☐ No	
Exterior Survey Performed ☐ Yes ☐ No	
General Clean Up ☐ Yes ☐ No	Locations: _____
ACM Clean Up ☐ Yes ☐ No	Locations: _____
Air Monitoring ☐ Yes ☐ No	Locations: _____
Copies of All Reports and Data Requested ☐ Yes	

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Broken windows etc. Still dirty</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>NO ACCESS into bldg, back is partially gone.</u>					

Date: 3 12 2002Inspection Team: Name: ALAgency: _____
Agency: _____