

1001414

WTC Visual Survey Form

2012 Burdette

Premise Address: <u>SPRINGMICH / PARK PLACE</u>		
Block: Lot:	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building: <u>FITZGERALD HALL (BMCC)</u>
# of Stories:	AKA's:	
Building Owner/Management: Name:		Telephone Number: () FAX: ()
Address:		
On Site Contact: Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____ Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Architectural windows etc</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>DAMAGED CLOSED NO ACCESS</u>					

Date: 21 / 27 / 2002Inspection Team: Name: AL

Agency: _____

Name: HENRIK

Agency: _____

Reinspected
3/2/02

WTC Visual Survey Form

Premise Address: <u>30 West Broadway</u>	
Block:	Residential ☒ Commercial ☒ Name of Building:
Lot:	Mix Use ☐ Other ☐
# of Stories:	AKA's:
Building Owner/Management:	Telephone Number: ()
Name:	FAX: ()
Address:	
On Site Contact:	at <u>P11</u>
Name: <u>Jerry Cohen</u>	Telephone Number: <u>(212) 301-0200</u>
Building Owner Management Activities	
Interior Survey Performed ☒ Yes ☐ No	<u>Project MN for BARNEY SKANSKA USA</u>
Exterior Survey Performed ☒ Yes ☐ No	
General Clean Up ☐ Yes ☒ No Locations:	
ACM Clean Up ☐ Yes ☐ No Locations:	
Air Monitoring ☐ Yes ☐ No Locations:	
Copies of All Reports and Data Requested ☐ Yes	

Visual Inspection Results:

Facade:			
	Inspected	Debris	
North ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"	
South ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"	
East ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"	
West ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"	
Facade Description:			
Roof			
Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" ☐ > 1"			
Description: <u>WTC debris mixed with gravel on roof</u>			
Setbacks ☐ N/A			
Floor: <u>3</u>	Debris: ☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"		
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Comments			

Date: 3/24/2002

ENTERED

Inspection Team: Name: CARLName: Agency: Agency: