






























**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>Alfonso Plungetre</u>	BADGE # <u>A010</u>	DATE <u>2/27/01</u>
LOCATION <u>47 WEST ST (80 WASHINGTON ST)</u>		

(2) 1-5

X

X

X

X

X

POSITIVE TEST

17' 10" x 10' 0"

plus windows.

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>Alfonso Plungetre</u>	BADGE # <u>A010</u>	DATE <u>2/27/02</u>
LOCATION <u>47 WEST ST (80 WASHINGTON ST)</u>		

(2) 1-5

X

X

X

X

X

plus windows.