

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>Alfonso Plungetre</u>	BADGE # <u>A010</u>	DATE <u>2/27/01</u>
LOCATION <u>47 WEST ST (80 WASHINGTON ST)</u>		

(2) 1-5

ROOF

☐ No Visible Debris

☐ Entire Roof Covered with Debris

☒ Partial Roof Covered

☐ Local/Isolated Areas
☐ Gutters
☒ 25% of the roof
☐ 50% of the roof
☐ 75% of the roof

FACADE

☐ Clean

☒ Entire Facade req. Clean-up *plus windows.*

☐ _____ Req. Clean-up