

WTC Visual Survey Form

1078995

Premise Address: <u>One William Street</u>		
Block: <u>29</u>	Residential ☐ Commercial ☒	Name of Building:
Lot: <u>36</u>	Mix Use ☐ Other ☐	
# of Stories: <u>12</u>	AKA's:	
Building Owner/Management: <u>Intesa BCI</u>		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact: <u>blg mgr.</u>		Telephone Number: (212) 607-3680.
Name: <u>Tony Cardinale</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes <u>data received.</u>		

Visual Inspection Results:

Facade:			
North	☐ N/A	Inspected	Debris
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Facade Description:			
Roof <u>Penthouse Roof</u> KT B92 1504			
Debris: ☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"			
Description:			
Setbacks <u>N/A</u> ☒			
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Comments			

Date: 3/4/2002Inspection by: Name: R. RAMMOHAN Agency: NYC DEP.

Name: _____ Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

March

February 4, 2002

Building Owner Name: Intesa BCI

Address: One William Street
NY NY 10004

Subject: One William Street

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☐ building facade(s)
- ☐ setback(s)
- ☐ roof
- ☒ other, Penthouse Roof

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by ~~February 27~~ ^{March 11}, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
R. Radhakrishnan, P.E.
Director
Asbestos Control Program





The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
 Corona, New York
 11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner
 Bureau of
 Environmental Compliance
 Tel (718) 595-4418
 Fax (718) 595-4422

March
 February 4, 2002

Building Owner Name: Intesa BCI

Address: One William St
NY NY 10004

Subject: One William Street, NYC

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

P. R. Radhakrishnan
P. R. Radhakrishnan, P.E.
 Director
 Asbestos Control Program



www.nyc.gov/dep
 (718) DEP-HELP

Page: 1 Document Name: Extra

03/05/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
1..... WILLIAM STREET..... 1 MANHATTAN 10004 BIN# 1078995
DCP GEOGRAPHICAL INFORMATION:
WILLIAM STREET 1 - 9 HEALTH AREA : 77 TAX BLK: 29...
SOUTH WILLIAM STREET 1 - 3 CENSUS TRACT: 1002 TAX LOT: 36...
STONE STREET 63 - 67 COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : BANCA COMM ITALIANA BANCA COMM ITALIANA
CORP. NAME : LPC LANDMARK STATUS: LANDMARK
ADDRESS : 1 WILLIAM ST DOB LOCAL LAW STATUS: NO
NEW YORK NY 10004-2502
DOF BUILDING INFORMATION: TRANS LAND VALUE: 9,700,000
BLDG SIZE; 0092.00 X 0088.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0092.08 X 0094.75 TAX EXEMPT CLASS:
BLDG CLASS : 03 OFFICE BUILDING CITY OWNERSHIP : NO
STORIES : 4 UPDATE DATE : 02/28/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 3/5/ 2 Time: 08:52:45 AM