

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION **ASBESTOS INSPECTION REPORT**

TOTAL FEET: 3940 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

**NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)**

Basis of Inspection: **TRU1455MN02**

FEE EXEMPT: Yes
1. \$0.00

FL	SF	LF
roof	1,940	0
roof	2,000	0

START DATE: 9/10/2002 COMPLETION DATE: 9/17/2002

I. FACILITY

ADDRESS: 52 WILLIAM STREET BORO: MANHATTAN ZIP: _____
 TYPE OFFACILITY: _____ BLOCK: _____ LOT: _____

II. BUILDING OWNER

NAME: FINANCIAL DISTRICT ASSOCIATES LLC

TEL. #: _____

ADDRESS: n/a n/a CITY: _____ STATE: _____ ZIP: _____

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORP

TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: **P11**

ADDRESS: 14-20 129TH STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER ENGINEERS, P.C.

TEL. #: (212) 922-0077

ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☐ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Rammohan SQUAD #: 1 BADGE #: A078DATE OF INSPECTION: 11/21/02 - 11/22/02 TIME OF INSPECTION: From: 8 am AM ☒ PM ☐To: 5 pm AM ☐ PM ☒Contact at site: Jan Wolkowicz & 5 Handlers, Trio / Dipo Slemey, w & p.

Inspection disclosed that the following sections were complied with: (Check all that apply)

☐ 1-51 - Notifications, Reports, Plan	☐ 1-71 - Air Sampling and Monitoring	☐ 1-91 - Worker Protection
☐ 1-101 - Materials and Equipment	☐ 1-116 - Work Place Preparation	☐ 1-117 - Worker Decontamination System
☐ 1-118 - Waste Decontamination System	☐ 1-126 - Engineering Controls	☐ 1-127 - Entry/Exit Procedures
☐ 1-129 - Maintenance of Barriers	☐ 1-138 - Encapsulation	☐ 1-139 - Enclosure
☐ 1-140 - Glovebag	☐ 1-141 - Tent	☐ 1-137 - ACM Disturbance, Removal, Handling
☐ 1-146 - Preliminary Clean-up	☐ 1-147 - Final Clean-up	
☐ Project not started		
revealed all ACM to be intact. New start date: _____		
☐ Project ongoing, expected completion date: _____		
☐ Project completed on or about: _____ All surfaces, including abated surfaces are free of visible ACM and encapsulate		
☐ Follow up necessary on _____		

Samples taken: ☐ No ☐ Yes 1 _____ 2 _____ 3 _____
 4 _____ 5 _____ 6 _____ Photos taken: ☐ Yes ☐ No

Additional comments: 11/21/02: Crew began bagging debris on 5th floor setback and air sampling was performed by Dipo Slemey. Due to overwhelming amount of concrete and sand from sandblasting more than 50 waste bags were generated. All the brick was removed.
11/22/02: Final cleaning and washing began by two handlers. The foreman and two handlers went to the roof of stair case and kitchen exhaust and began cleaning. The cleaning was completed at the end of the day and all the waste bags were removed from the premises.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

5

SUPERVISOR INITIALS

RR