

## WTC Visual Survey Form

1001013

|                                                                                                                                                  |                                                                                     |                                                |
|--------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------------|
| <b>Premise Address:</b> <u>62 WILLIAM ST.</u>                                                                                                    |                                                                                     |                                                |
| <b>Block:</b> <u>41</u>                                                                                                                          | Residential <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> | <b>Name of Building:</b>                       |
| <b>Lot:</b> <u>24</u>                                                                                                                            | Mix Use <input type="checkbox"/> Other <input type="checkbox"/>                     |                                                |
| <b># of Stories:</b> <u>9+PH</u> <b>AKA's:</b>                                                                                                   |                                                                                     |                                                |
| <b>Building Owner/Management:</b> <u>BMS REALTY</u>                                                                                              |                                                                                     | <b>Telephone Number:</b> <u>(212) 809-2371</u> |
| <b>Name:</b> <u>Morris Frankel</u>                                                                                                               |                                                                                     | <b>FAX:</b> ( )                                |
| <b>Address:</b> <u>62 William St, NYC, NY</u>                                                                                                    |                                                                                     |                                                |
| <b>On Site Contact:</b>                                                                                                                          |                                                                                     |                                                |
| <b>Name:</b> <u>Kurt Barlas</u>                                                                                                                  |                                                                                     | <b>Telephone Number:</b> ( )                   |
| <b>Building Owner Management Activities</b>                                                                                                      |                                                                                     |                                                |
| Interior Survey Performed <input type="checkbox"/> Yes <input type="checkbox"/> No                                                               |                                                                                     |                                                |
| Exterior Survey Performed <input type="checkbox"/> Yes <input type="checkbox"/> No                                                               |                                                                                     |                                                |
| General Clean Up <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <b>Locations:</b> <u>facade washed by quality cleaning.</u> |                                                                                     |                                                |
| ACM Clean Up <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <b>Locations:</b>                                               |                                                                                     |                                                |
| Air Monitoring <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <b>Locations:</b>                                             |                                                                                     |                                                |
| <b>Copies of All Reports and Data Requested</b> <input type="checkbox"/> Yes                                                                     |                                                                                     |                                                |

**Visual Inspection Results:****Facade:**

|       |                                         | <b>Inspected</b>                                                    | <b>Debris</b>                                  |                                  |                               |
|-------|-----------------------------------------|---------------------------------------------------------------------|------------------------------------------------|----------------------------------|-------------------------------|
| North | <input type="checkbox"/> N/A            | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| South | <input checked="" type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No            | <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| East  | <input checked="" type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No            | <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| West  | <input type="checkbox"/> N/A            | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |

Facade Description:

**Roof**Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"

Description:

Pent house roof also contains paper & debris observed.**Setbacks** N/A ☒

|              |                                                        |                                  |                               |
|--------------|--------------------------------------------------------|----------------------------------|-------------------------------|
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |

**Comments**Date: 2/19/2002Inspection Team: Name: MohamAgency: DEP

Name: \_\_\_\_\_

Agency: \_\_\_\_\_

February 19, 2002



**Department of  
Environmental  
Protection**

59-17 Junction Boulevard  
Corona, New York  
11368-5107

**Joel A. Miele Sr., P.E.  
Commissioner**

**Robert C. Avaltroni  
Deputy Commissioner**

**Bureau of  
Environmental Compliance**  
Tel (718) 595-4418  
Fax (718) 595-4422

**Building Owner Name:** BMS REALTY / ATTN: MORRIS FRANKEL

**Address:** 62 William Street  
NY, NY 10038

**Subject:** 62 WILLIAMS STREET

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☐ building facade(s)
- ☐ setback(s)
- ☒ roof & PENT HOUSE ROOF
- ☐ other, \_\_\_\_\_

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by February 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8<sup>th</sup> floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

*R. Radhakrishnan* (RADHAKRISHNAN)  
R. Radhakrishnan, P.E.  
Director  
Asbestos Control Program





**Department of  
Environmental  
Protection**

59-17 Junction Boulevard  
Corona, New York  
11368-5107

**Joel A. Miele Sr., P.E.  
Commissioner**

**Robert C. Avaltroni  
Deputy Commissioner**

**Bureau of  
Environmental Compliance**  
Tel (718) 595-4418  
Fax (718) 595-4422

February 19, 2002

**Building Owner Name:**

BMS REALTY  
62 WILLIAM STREET / ATTN: MORRIS FRANKEL

**Address:**

62 William Street

NY NY 10038

**Subject:**

62 WILLIAM STREET

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8<sup>th</sup> floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan  
R. Radhakrishnan, P.E.  
Director  
Asbestos Control Program



(718) DEP-HELP

Page: 1 Document Name: Extra

02/23/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31  
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY  
62..... WILLIAM STREET..... 1 MANHATTAN 10005 BIN# 1001013

## DCP GEOGRAPHICAL INFORMATION:

WILLIAM STREET 62 - 64 HEALTH AREA : 77 TAX BLK: 41...  
CEDAR STREET 30 - 38 CENSUS TRACT: 2002 TAX LOT: 24...  
COMMUNITY BD: 101 CONDO :  
MULTI STRUCT: 1 CUI NO :

## DOF OWNER NAME &amp; ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE

OWNER NAME : B M S REALTY ASSOCIATES INC B M S REALTY ASSOCIAT  
CORP. NAME : LPC LANDMARK STATUS: NO  
ADDRESS : PO BOX 110158 DOB LOCAL LAW STATUS: YES  
BROOKLYN NY 11211-0158

## DOF BUILDING INFORMATION:

BLDG SIZE; 0024.00 X 0124.00 TRANS LAND VALUE: 2,570,000  
LOT SIZE: 0032.17 X 0123.75 TAX EXEMPT FLAG : NO  
BLDG CLASS : 01 OFFICE BUILDING TAX EXEMPT CLASS:  
STORIES : 8 CITY OWNERSHIP : NO  
UPDATE DATE : 02/22/02  
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:  
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

-----  
PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 2/23/ 2 Time: 12:32:20 PM