

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 7600 0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

TRU: MN02

FEE EXEMPT: Yes

1. \$0.00

FL	SF	LF
RO	7,600	0

START DATE: 10/02/2002 COMPLETION DATE: 10/23/2002

I. FACILITY

ADDRESS: 62 William Street. BORO: MANHATTAN ZIP: _____
TYPE OFFACILITY: _____ BLOCK: _____ LOT: _____

II. BUILDING OWNER

NAME: N/A
TEL. #: _____
ADDRESS: N/A N/A N/A N/A CITY: N/A STATE: N/A ZIP: 11368

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORP
TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION # PII
ADDRESS: 14-20 129TH STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER GROUP
TEL. #: _____
ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER

NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Rammohan SQUAD #: 1 BADGE #: A078.

DATE OF INSPECTION: 10/02/02 & 10/12/02 TIME OF INSPECTION: From: 8 am AM ☐ PM ☐
10/13/02, 10/21, 10/23. To: 5 pm AM ☐ PM ☐

Contact at site: _____

Inspection disclosed that the following sections were complied with: (Check all that apply)		
☐ 1-51 - Notifications, Reports, Plan	☐ 1-71 - Air Sampling and Monitoring	☐ 1-91 - Worker Protection
☐ 1-101 - Materials and Equipment	☐ 1-116 - Work Place Preparation	☐ 1-117 - Worker Decontamination System
☐ 1-118 - Waste Decontamination System	☐ 1-126 - Engineering Controls	☐ 1-127 - Entry/Exit Procedures
☐ 1-129 - Maintenance of Barriers	☐ 1-138 - Encapsulation	☐ 1-139 - Enclosure
☐ 1-140 - Glovebag	☐ 1-141 - Tent	☐ 1-137 - ACM Disturbance, Removal, Handling
☐ 1-146 - Preliminary Clean-up	☐ 1-147 - Final Clean-up	
☐ Project not started _____ . Inspection		
revealed all ACM to be intact. New start date: _____		
☐ Project ongoing, expected completion date: _____		
☐ Project completed on or about: _____ . All surfaces, including abated surfaces are free of visible ACM and encapsulate		
☐ Follow up necessary on _____		
Samples taken: ☒ No ☒ Yes 1 _____ 2 _____ 3 _____		
4 _____ 5 _____ 6 _____ Photos taken: ☐ Yes ☒ No		
Additional comments: 10/02/02: Jan Wolkowicz and crew mobilized and began cleaning the roof. Dipo Slemmez performed air-monitoring. Main roof completed.		
10/12/02: Facade washing began using boom truck. Ireneusz & crew on site. Oghogha Eshaber performed air-sampling.		
10/13/02: Facade washing continues and completed at the end of the day.		
10/21/02: Facade washing of rear ^{using scaffolding} performed by Jan Wolkowicz and crew. Dipo Slemmez performed air-sampling.		
10/23/02: Facade washing on scaffolding performed by Jan Wolkowicz and crew. Dipo Slemmez performed air sampling.		
The project was completed.		

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

5

SUPERVISOR INITIALS

Pl: