



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Flushing, New York
11373-5108

**Christopher O. Ward
Commissioner**

September 3, 2002

**TO: BMS Realty Associates Inc.
P.O. Box 110158
Brooklyn, NY 11211-0158**

**RE: 62 WILLIAM STREET
30-38 Cedar Street
FINAL NOTICE**

Dear BMS Realty Associates Inc.:

I am writing with regard to 62 WILLIAM STREET which was inspected by DEP on 08/30/02. During this inspection, debris from the collapse of the World Trade Center towers was observed on the exterior surfaces of the building.

You have been previously contacted with regard to participating in DEP's Lower Manhattan Building Cleaning Program. Under this program, contractors retained by DEP will clean all exterior building surfaces affected by World Trade Center debris at no cost to the building owner.

The Building Cleaning Program is now drawing to a close, and we have yet to receive a response from you regarding your participation. If you do not participate in the Program, the building will be scheduled for another DEP inspection in the near future. If that inspection shows that there is still visible debris from the World Trade Center on the exterior of the building, samples will be collected. If laboratory analysis of these samples shows that the debris is asbestos-containing material, you will then be issued a Commissioner's Order directing you to retain a contractor to clean the exterior of the building. Such cleaning would be at your expense, and failure to comply with the Commissioner's Order could result in the issuance of notices of violation carrying penalties of up to \$10,000 per day.

You are strongly urged to take advantage of the Building Cleaning Program. A blank License Agreement has been attached for your convenience. Please fill in the appropriate information and sign and return the form as soon as possible.

If you have any questions, please call 718-595-3682 during office hours, or the 24-hour Help Center at 718-DEP-HELP. Your cooperation is greatly appreciated.

Sincerely,

**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



www.nyc.gov/dep

(718) DLP-HELP

WTC Visual Survey Form

Premise Address: <u>62 William St</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>7</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
Facade Description: _____					

Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>No Access</u>					

Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>?</u>					

Date: 8/30/2002Inspection Team: Name: CARL

Agency: _____

Name: _____

Agency: _____

ENTERED