

ASBESTOS INSPECTION REPORT

PAGE 1 OF

PERMISE NO.		STREET				INSPECTION DATE	
123, WILLIAM STREET				10/2/02			
DOOR	ZIP	BORC CODE	BLOCK	LOT	SQUAD #	BADGE #	
entire facade	10038	1	78	4	1	AD10	
INSPECTOR		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES / NO	
Plumpton		A	TRU 145 Jan 02				
CONTRACTORS NAME				SAMPLE NO.			
FIBER CONTROL							
ADDRESS				CITY			
3010 BURNS AVE				WANTACH			
STATE		ZIP	PHONE	SAMPLE NO.			
N.Y		11793	(516) 781-3000				
LABORATORY NAME				OWNERS NAME			
WARREN & PAUZE ENGINEERS PC				William St. Asso 46 Glenwood			
ADDRESS		CITY	ADDRESS		CITY		
238 E. 45TH ST		N.Y	123 William St		NY		
STATE		ZIP	PHONE	STATE		ZIP	PHONE
N.Y		10017	(212) 922-0077	NYC			
CONTACT PERSON:				TIME OF INSPECTION FROM: 10:30 am TO: 6:00 am			
INSPECTION DISCLOSED:							

The Construction of the Scaffold started on 10/02/02 till 10/05/02 when the actual Cleanup of the eastside facade. The south and west facade commenced at the same time was 10/7/02. The entire facade were completed on 10/18/02 and visual inspections was done including inspector Nebedius and there were no visible debris observed after the Cleanup.

NOV #	INFRACTIONS					RESULT CODE
						5
NOV #						SUPERVISORS INITIALS
						PPP

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ASP 308

FILE