

Asbestos Inspection Report

Premise No. 136 WILLIAM STREET					Inspection Date: As NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 77	Lot 18	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken Yes ☒ No ☐
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900		Sample Number N/A				
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York		Address City				
State Zip Phone NY 10017 (212) 922-0077		State Zip Phone				
Contact Person				Time of Inspection from: N/A		

MONDAY NOVEMBER 18 2002
 THE CLEAN UP OF THE ROOF OF THE PREMISE WAS CONDUCTED TODAY. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY DIPO ELEMO (CERTIFICATE # AH01-14694 EXP 03/03) OF WARREN & PANZER ENGINEERS. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, DIPO ELEMO CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND HE OBSERVED NO VISIBLE WTC DEBRIS.

TUESDAY NOVEMBER 19 2002
 THE CLEAN UP OF THE EAST (REAR) FACADE OF THE PREMISE WAS CONDUCTED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY DIPO ELEMO. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, DIPO ELEMO CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND HE OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.

WEDNESDAY NOVEMBER 20 2002
 THE CONTRACTOR REMOVED EQUIPMENT AND MATERIALS FROM THE WORK SITE.