WTC Visual Survey Form

CLEAN

Premise Address: 140 WILLIAM STREET

Block: 77 **Lot:** 20	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐ _____	**Name of Building:**
# of Stories:	**AKA's:**	

Building Owner/Management: Telephone Number: (212) 924-9690
Name: AMERICAN NUMISMATIC SOCIETY FAX: ( )
Address:

On Site Contact:
Name: Telephone Number: ( )

Building Owner Management Activities
Interior Survey Performed ☐ Yes ☐ No
Exterior Survey Performed ☐ Yes ☐ No
General Clean Up ☐ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☐ No Locations: _____
Air Monitoring ☐ Yes ☐ No Locations: _____
Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
Description: LIGHT DUSTING (SAND TYPE DEBRIS)

Setbacks N/A ☒

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 07 / 16 /2002 Inspection Team: Name: DA / A020 Agency: NYC DEP
Name: _____ Agency: _____

WTC Visual Survey Form

CLEAN

Premise Address: 140 WILLIAM STREET

Block: 77 **Lot:** 20

Residential ☐ Commercial ☒ Mix Use ☐ Other ☐ _____

Name of Building:

# of Stories:

AKA's:

Building Owner/Management:

Name: AMERICAN NUMISMATIC SOCIETY

Telephone Number: (212) 924-9690

FAX: ( )

Address:

On Site Contact:

Name:

Telephone Number: ( )

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No Locations: _____

ACM Clean Up ☐ Yes ☐ No Locations: _____

Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

_____

_____

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: LIGHT DUSTING (SAND TYPE DEBRIS)

_____

_____

Setbacks N/A ☒

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

_____

_____

_____

_____

Date: 07 / 16 /2002

Inspection Team: Name: DA / A020 **Agency:** NYC DEP

Name: _____ **Agency:** _____

WTC Visual Survey Form

Premise Address: 140 William ST

Block: **Lot:**	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐ _____	**Name of Building:**
# of Stories: 8	**AKA's:**	

Building Owner/Management: Telephone Number: ( )
Name: FAX: ( )
Address:

On Site Contact:
Name: Telephone Number: ( )

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No
Exterior Survey Performed ☐ Yes ☐ No
General Clean Up ☐ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☐ No Locations: _____
Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
Description: _____

Setbacks N/A ☐

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments No Access to Roof

Date: 3/23/2002 Inspection Team: Name: CARL Agency: _____
ENTERED Name: _____ Agency: _____