

**BENJAMIN KURZBAN
& SON CONTROL, INC.**
1248 Ralph Ave.
BROOKLYN, N.Y. 11236

(718) 531-2900

INVOICE

1230

TO Dept of Environmental Protection
59-17 Junction Blvd
Corona, NY 11368

DATE 11/27/02	ORDER NO.
SHIP TO Contract ROF-REM2	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS	
QUANTITY	DESCRIPTION			UNIT PRICE	TOTAL
>	Registration # CT 82620020015280				
	PIN# 82602WTCROOF2				
	For work completed at 150 Williams St				
	11,362 SF @ 2/SF				
	aka 81 Fulton St.				
	Total Amount due this Invoice				\$ 22,724.00

ORIGINAL

Thank You!

R. Raab
sent to Dennis
12/10/02

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program

59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107

ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)

TRU 18684102

Building Dept. or TRU No
FOR OFFICIAL USE ONLY

1. *EX*
(See fee schedule)

ONLY
TYPEWRITTEN
FORMS WILL BE
ACCEPTED



When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 150 WILLIAM STREET Borough MAN Zip 10038
AKA _____ 3. Block _____ 4. Lot _____
5. Type of Facility _____ 6. Name of Building _____

II. BUILDING OWNER

7. Name _____ 8. Contact Person _____
9. Tel. # _____ Fax # _____
10. Address _____ City _____ State _____ Zip _____

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name BENJAMIN KURZBAN & SON CONTROL INC. 13. Contact Person LOUIE LANNICO
14. Federal Employer ID. # PII 15. Tel. # (718) 531-2900 Fax # (718) 209-1808
16. Address 1248 RALPH AVENUE City BROOKLYN State NY Zip 11236

V. THIRD PARTY AIR MONITOR

17. Name WARDEN & PANZER ENGINEERS 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # PII 20. Tel. # (212) 922-0077 Fax # (212) 922-0630
21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 11-13-02 Projected completion date 11-30-02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday


Shift from: 7⁰⁰ ☒ am ☐ pm to 7⁰⁰ ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

11362 Square Feet, and/or 0 Linear Feet



ACP 7
2/2001

DEP
BUREAU OF ENVIRONMENTAL
REMEDICATION & ENFORCEMENT
ASBESTOS CONTROL
PROGRAM
TRU 1

ASBESTOS INSPECTION REPORT (continued)

26. Asbestos Hauler IESI, NY NYS DEC Permit # NJ-462 Tel.# P11

Disposal Site(s) BLUE RIDGE LANDFILL PO BOX 399 SCOTSDALE PA 17254

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
e) ☐ Fireproofing Replacement f) ☐ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☒ Clean up



29. ABATEMENT PROCEDURE (Check all appropriate boxes)

- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application

30. LOCATIONS OF ABATEMENT ROOF MATERIAL: ROOF MEMBRANE


Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM SQUARE FEET LINEAR FEET	DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
20TH FL		ROOF SURFACE	2746	ANN STREET SIDE ONLY
17TH FL	SET BACK	SET BACK ROOF SURFACE	1596	FULTON STREET SIDE ONLY
13TH FL	SET BACK	SET BACK ROOF SURFACE	6240	ALL SIDES (ANN, GOLD, WILLIAM AND FULTON STREET)
10TH FL	SET BACK	SET BACK ROOF SURFACE	780	GOLD STREET SIDE FULTON STREET SIDE

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

WARREN & PANZER ENGINEERS Print Name of Air Monitor  Signature 11-12-02 Date	B. KURZBAN & SON CONTROL INC. Print Name of Asbestos Contractor  Signature 11-12-02 Date	Print Name of Applicant (If other than Owner) Signature Date
---	---	--

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

Print Name of Owner


Signature

11-12-02
Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

Asbestos Inspection Report

Premise No. 150 WILLIAM STREET (81 ^{AKA} FULTON ST)					Inspection Date: AS NOTED	
Floor ROOF, 17, 13, 10	Zip 10038	Borough 1	Block 93	Lot 1	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken Yes/No Yes/No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		

WEDNESDAY NOVEMBER 13 2002

THE CLEAN UP OF THE ROOF OF THE PREMISE (ANN STREET SIDE ONLY) BEGINS. WORKERS WILL UTILIZE DOUBLE TYVEK SUITS AND STEP OFF PADS IN LIEU OF A REMOTE DECONTAMINATION UNIT DUE TO SPACE LIMITATIONS. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY EDMAN DIBRA (CERTIFICATE # AH 01-12337 EXP 02/03). FOUR AIR SAMPLES WERE SET UP ON THE ROOF AND ONE SAMPLE WAS RUN INSIDE THE BUILDING AT THE ENTRANCE TO THE ROOF.

THURSDAY NOVEMBER 14 2002 - FRIDAY NOVEMBER 15 2002

THE CLEAN UP OF THE ROOF OF THE PREMISE WAS COMPLETED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMIWEGIE (CERTIFICATE # AH 01-01030 EXP 01/03) OF WARREN & PANZER ENGINEERS. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, FESTY OSEMIWEGIE CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND HE OBSERVED NO VISIBLE WTC DEBRIS.

SATURDAY NOVEMBER 16 2002

THE CLEAN UP OF THE 17TH FLOOR SET BACK WAS CONDUCTED TODAY. ACCESS TO THE SET BACK WAS ACHIEVED THROUGH AN OFFICE SPACE WINDOW. FLAPS WERE INSTALLED AT THE WINDOW USED FOR ACCESS. PLASTIC SHEETING WAS INSTALLED ON TOP OF THE CARPETING FROM THE ELEVATOR LOBBY TO THE WINDOW. DESK AND FILING CABINET IN THE IMMEDIATE VICINITY OF THE WINDOW WERE COVERED WITH PLASTIC SHEETING. DUE TO SPACE LIMITATIONS NO REMOTE DECON UNIT WAS ERECTED. STEP OFF PADS WERE UTILIZED AND WORKERS DONNED DOUBLE PROTECTIVE SUITS. THREE AIR SAMPLES WERE RUN INSIDE THE OFFICE SPACE AND TWO AIR SAMPLES WERE RUN ON THE SET BACK. AIR SAMPLING WAS PERFORMED BY FESTY OSEMIWEGIE OF WARREN & PANZER ENGINEERS. THE CLEAN UP ON THE 17TH FLOOR SET BACK WAS LIMITED TO THE FULTON STREET SIDE ONLY. NO WTC DEBRIS WAS OBSERVED ON THE ANN ST., GOLD ST. AND WILLIAM ST. SIDES

PL

Asbestos Inspection Report

Premise No. 150 WILLIAM STREET (AKA 81 FULTON STREET)	Inspection Date: AS NOTED
Inspector Dennis Antzoulatos	Page <u>2</u> of <u>2</u>

AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, FESLY OSEMWEGIE CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND HE OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP OF THE 13TH FLOOR SET BACK BEGAN. ACCESS TO THE SET BACK WAS ACHIEVED THROUGH AN OFFICE SPACE WINDOW. THE SAME PROCEDURES REGARDING WORK PLACE PREPARATION AND AIR SAMPLING WERE OBSERVED FOR THIS SET BACK AS WELL. AIR SAMPLING FOR THIS LOCATION WAS PERFORMED BY OCHOGHIO ERHABOR (CERTIFICATE #AH 00-18198 EXP 12/02). ALL FOUR SIDES OF THE SET BACK (FULTON STREET, ANN STREET, GOLD STREET AND WILLIAM STREET) UNDERWENT CLEAN UP ACTIVITIES. THE FULTON STREET AND WILLIAM STREET SIDES WERE TARGETED TODAY. THE ANN STREET AND GOLD STREET SIDES WILL BE CLEANED TOMORROW.

SUNDAY NOVEMBER 17 2002

THE CLEAN UP OF THE 13TH FLOOR SET BACK WAS COMPLETED. AIR SAMPLING WAS PERFORMED BY OCHOGHIO ERHABOR OF WARREN & PANZER ENGINEERS. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND I OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP OF THE 10TH FLOOR SET BACK WAS CONDUCTED TODAY. CLEAN UP ON THIS SET BACK WAS LIMITED THE GOLD STREET AND FULTON STREET SIDES ONLY. AIR SAMPLING FOR THIS SET BACK WAS PERFORMED BY FESLY OSEMWEGIE OF WARREN & PANZER ENGINEERS. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES FESLY OSEMWEGIE CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND HE OBSERVED NO VISIBLE WTC DEBRIS. THE PROTOCOLS USED FOR THE 11TH FLOOR AND 13TH FLOOR SETBACKS WERE USED FOR THE 10TH FLOOR SET BACK.

11/20/2002 05:36 FAX

010



ATHENICA

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7490

Fax. (718) 784-4085

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-11-073

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 150 William Street

DATE OF REPORT: 11/15/02

DATE OF ANALYSIS: 11/15/02

EFFECTIVE FILTER AREA (mm²): 385

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O. ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (struct./cm ³)	TOTAL ASBESTOS AIR CONC. (struct./cm ³)	TOTAL ASBESTOS FILTER CONC. (air-J/cm ²)	AIR CONC. FOR STRUCT. 0.55<=5µm	AIR CONC. FOR STRUCT. 5<=0.5µm	ASBEST. TYPE CHRYS.	AHERA ASBEST. TYPE SPECIFY
01	T02-11-073-4070	Entrance to roof	1590	4	0.0537	0.0045	<0.0045	<18.61	NA	NA	NA	NA
02	T02-11-073-4071	West side of roof	1590	4	0.0537	0.0045	<0.0045	<18.61	NA	NA	NA	NA
03	T02-11-073-4072	East side of roof	1590	4	0.0537	0.0045	<0.0045	<18.61	NA	NA	NA	NA
04	T02-11-073-4073	Center of roof	1590	4	0.0537	0.0045	<0.0045	<18.61	NA	NA	NA	NA
05	T02-11-073-4074	North of roof	1590	4	0.0537	0.0045	<0.0045	<18.61	NA	NA	NA	NA

ANALYST

E. Stoukri

LABORATORY DIRECTOR

Spiro Dongaris

LABORATORY CERTIFICATION STATEMENT: NOT IN SCOPE OF ANALYSIS

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling certificates will be issued for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVE AP or any other agency of the U.S. Government. Test reports may not be requested except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0030**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE _____ OF _____

	24 hr ⁺ /n	12 hr ⁺ /n	6 hr ⁺ /a	3 hr ⁺ /a	Immediate ⁺ /a
1	100	100	100	100	100
2	100	100	100	100	100
3	100	100	100	100	100
4	100	100	100	100	100
5	100	100	100	100	100
6	100	100	100	100	100
7	100	100	100	100	100
8	100	100	100	100	100
9	100	100	100	100	100
10	100	100	100	100	100
11	100	100	100	100	100
12	100	100	100	100	100
13	100	100	100	100	100
14	100	100	100	100	100
15	100	100	100	100	100
16	100	100	100	100	100
17	100	100	100	100	100
18	100	100	100	100	100
19	100	100	100	100	100
20	100	100	100	100	100
21	100	100	100	100	100
22	100	100	100	100	100
23	100	100	100	100	100
24	100	100	100	100	100
25	100	100	100	100	100
26	100	100	100	100	100
27	100	100	100	100	100
28	100	100	100	100	100
29	100	100	100	100	100
30	100	100	100	100	100
31	100	100	100	100	100
32	100	100	100	100	100
33	100	100	100	100	100
34	100	100	100	100	100
35	100	100	100	100	100
36	100	100	100	100	100
37	100	100	100	100	100
38	100	100	100	100	100
39	100	100	100	100	100
40	100	100	100	100	100
41	100	100	100	100	100
42	100	100	100	100	100
43	100	100	100	100	100
44	100	100	100	100	100
45	100	100	100	100	100
46	100	100	100	100	100
47	100	100	100	100	100
48	100	100	100	100	100
49	100	100	100	100	100
50	100	100	100	100	100
51	100	100	100	100	100
52	100	100	100	100	100
53	100	100	100	100	100
54	100	100	100	100	100
55	100	100	100	100	100
56	100	100	100	100	100
57	100	100	100	100	100
58	100	100	100	100	100
59	100	100	100	100	100
60	100	100	100	100	100
61	100	100	100	100	100
62	100	100	100	100	100
63	100	100	100	100	100
64	100	100	100	100	100
65	100	100	100	100	100
66	100	100	100	100	100
67	100	100	100	1	

P.O.

CLIENT: MYCDEP

W&P FILE #: 1079-07-01

PROJECT: 1206F

LABORATORY: ATHEMCA

LOCATION: 150 WILLIAMS ST

ANALYSIS METHOD: PCM
circle one

TECHNICIAN: Festy Ogenwelle

TECHNICIAN: FESTY OSENUWELGE

[illegible]

COMMENTS:

SAMPLE BY: FESI-055 MW ECRF DATE: 11-14-08

SIGNATURE:

SAMPLE BY: F-EST-055 MW 5/17/8

RELEASED BY: FESTY OSEMYWELP DATE: 1-14-02

SIGNATURE:

RECEIVED BY: ACATIA

DATE: 11/15/02

SIGNATURE:

105-11-013

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (Inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

TEL :

Jan 13, 01

17:36 No.001 P.02

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY



ATHENICA

ENVIRONMENTAL SERVICES INC.

Tel. (718) 794-7490
Fax. (718) 794-4065

CLIENT: Warren & Panzer Engineers, P.C.
LABORATORY ID #: T02-11-086
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: N.C.E.
AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 150 William Street
DATE OF REPORT: 11/18/02
DATE OF ANALYSIS: 11/18/02
EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB ID #	LOCATION	VOLUME (ft)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (strand/100ft ²)	TOTAL ASBESTOS AIR CONC. (strand/100ft ²)	TOTAL ASBESTOS FILTER CONC. (strand/100ft ²)	AIR CONC. FOR 0.5µm STRUCT.	AIR CONC. FOR 5-10µm STRUCT.	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-11-086-4140	West side of set back	1506	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
02	T02-11-086-4141	Entrance to set back	1506	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
03	T02-11-086-4142	Set back window	1506	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
04	T02-11-086-4143	East side of set back	1506	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
05	T02-11-086-4144	Entrance to east set back	1506	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA

E. Siakhi

ANALYST
E. Siakhi

Em. P. H.

LABORATORY DIRECTOR
Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

TEL

Jan 13.01 17:42 No.001 P.14


ATHENICA

ENVIRONMENTAL SERVICES INC.

 Tel. (718) 704-7400
 Fax. (718) 704-4085

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Paezzer Engineers, P.C.

LABORATORY ID #: T02-11-093

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

 AVERAGE G.O. AREA (mm²): 0.013433

 PROJECT: NYC DEP, 150 William Street, 13th floor

DATE OF REPORT: 11/20/02

DATE OF ANALYSIS: 11/20/02

 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT	LAB. ID #	LOCATION	VOLUME (L)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (microg/cm ³)	TOTAL ASBESTOS AIR CONC. (microg/cm ³)	TOTAL ASBESTOS FILTER CONC. (microg/cm ³)	AIR CONC. FOR STRUCT. P-55-CHIM	AIR CONC. FOR STRUCT. S-55-CHIM	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-11-093-4176	Entry in room	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA
02	T02-11-093-4177	North of hall way	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA
03	T02-11-093-4178	South of hall way	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA
04	T02-11-093-4179	Central of hall way	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA
05	T02-11-093-4180	East of hall way	1800	4	0.0537	0.0040	<0.0040	<18.61	NA	NA	NA	NA

E. Strout

 ANALYST
 E. Strout

Sam Doughty

 LABORATORY DIRECTOR
 Spiro Doughty

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling statistics will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

STYLUS & PROLOGUE Books 1400 1/2 Ave. of the Americas, New York, N.Y. 10019