

WTC Visual Survey Form

Premise Address: 150 WILLIAM STREET		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: <u>ROOF AND FACADE SURFACES</u>		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>DEBRIS LOCATED UNDER A/C UNIT AND PIPES (ANN ST SIDE OF ROOF)</u>					
Setbacks N/A ☐					
Floor: <u>17</u>	Debris: ☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"		
Floor: <u>10</u>	Debris: ☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"		
Floor: <u>13</u>	Debris: ☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"		
Floor: <u>19</u>	Debris: ☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 11 / 05 /2002Inspection Team: Name: DA / A020Agency: NYC DEP

Name: _____ Agency: _____

ENTERED