NYC 9/11 Public Portal Document

Asbestos Inspection Report

Premise No. 156 WILLIAM STREET					Inspection Date: As NOTED	
Floor ROOF AND FACADE	Zip 10038	Borough 1	Block 93	Lot 20	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos	Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken Yes (No)	
Contractor's Name Benjamin Kurzban & Son Control			Sample Number N/A			
Address City 1248 Ralph Avenue, Brooklyn			Sample Number N/A			
State Zip Phone NY 11236 (718)531-2900			Sample Number N/A			
Laboratory Name Warren & Panzer Engineers Inc.			Owner's Name			
Address City 228 East 45 Street New York			Address City			
State Zip Phone NY 10017 (212) 922-0077			State Zip Phone			
Contact Person			Time of Inspection from: As NOTED			

MONDAY JULY 8 2002 (800 AM - 800 PM)

CLEAN UP ACTIVITIES BEGIN ON THE ROOF OF THE PREMISE. A REMOTE DECONTAMINATION UNIT IS USED. AIR MONITORING FOR THIS PORTION OF THE CLEAN UP PROJECT IS PERFORMED BY LUIS SOTO (CERTIFICATE # AH 00-20894 EXP 03/03) OF WARREN & PANZER ENGINEERS.

TUESDAY JULY 9 2002 TO ~~THURSDAY~~ JULY 11 2002

THE CLEAN UP PROJECT PROGRESSES AS PER THE APPROVED SCOPE OF WORK. AIR MONITORING IS PERFORMED BY LUIS SOTO AND FESTY OSEMWEGIE (CERTIFICATE # AH 01-01030 EXP 01/03) OF WARREN & PANZER ENGINEERS

FRIDAY JULY 12 2002

THE CLEAN UP OF THE ROOF AREA IS COMPLETED. I CONDUCTED A VISUAL INSPECTION OF THE CLEANED ROOF SURFACES AND OBSERVED NO VISIBLE WTC DEBRIS.

SUNDAY AUGUST 4 2002 (700 AM TO 900 PM)

THE CLEAN UP OF THE WEST FACADE (WILLIAM STREET) WAS CONDUCTED TODAY. THE WEST FACADE CLEAN UP OF 164 WILLIAM STREET OCCURRED SIMULTANEOUSLY. FOR THE PURPOSES OF AIR MONITORING THE FACADES OF THESE TWO BUILDINGS WERE TREATED AS ONE WORK AREA. AIR MONITORING FOR THIS PORTION OF THE PROJECT WAS PERFORMED BY OCHOGHO ERHABOR (CERTIFICATE # AH 00-16198 EXP 12/02) OF WARREN & PANZER. FIVE AIR SAMPLES WERE RUN ON THE OPPOSITE SIDE WALK. THE CLEAN UP ACTIVITIES WERE LIMITED TO THE CLEANING OF THE WINDOWS AND LEDGES ON THE 2ND, 3RD AND 4TH FLOORS. A BOOM TRUCK WAS USED TO ACCESS THESE AREAS. AFTER CLEAN UP ACTIVITIES WERE COMPLETED FOR THE DAY, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES. I OBSERVED VISIBLE WTC

NYC 9/11 Public Portal Document

Asbestos Inspection Report

Premise No. 156 WILLIAM STREET	Inspection Date: AS NOTED
Inspector Dennis Antzoulatos	Page 2 of 2

SUNDAY AUGUST 4 2002 (CONTINUED)
ON THE WINDOW LEDGES AND WINDOW FRAMES. THE FACADE DID NOT PASS THE VISUAL INSPECTION AND WILL BE RE CLEANED AS SOON AS IT CAN BE SCHEDULED.

SUNDAY AUGUST 18 2002 (800 AM - 500 PM)
THE RE CLEANING OF THE WEST (WILLIAM STREET) FACADE AND THE CLEANING OF THE SOUTH (ANN STREET) FACADE WERE CONDUCTED TODAY. TWO BOOM TRUCKS WERE USED TO ACCESS THE 2ND, 3RD AND 4TH FLOOR WINDOWS AND LEDGES THAT REQUIRED THE CLEAN UP. AIR MONITORING FOR THIS PORTION OF THE PROJECT WAS PERFORMED BY CHARLES COLBERT (CERTIFICATE # AH 93-17676 EXP 10/02) OF WARREN & PANZER. FIVE AIR SAMPLES WERE RUN ON THE OPPOSITE SIDEWALK OF ANN STREET. AT THE COMPLETION OF CLEANING ACTIVITIES I CONDUCTED A VISUAL INSPECTION OF THE WILLIAM STREET (WEST) FACADE AND DEPUTY DIRECTOR (ASBESTOS CONTROL PROGRAM) PENNY THEODORELLYS CONDUCTED A VISUAL INSPECTION OF THE ANN STREET (SOUTH) FACADE. NO VISIBLE WTC DEBRIS WAS OBSERVED ON THE CLEANED FACADE SURFACES. THE CLEAN UP PROJECT AT THIS PREMISE IS NOW COMPLETE.