

Asbestos Inspection Report

Premise No. 164. WILLIAM STREET					Inspection Date: As NOTED	
Floor ROOF, FACADE SET BACKS	Zip 10038	Borough 1	Block 93	Lot 24	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken Yes ☒ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: As NOTED		
<u>MONDAY OCTOBER 28 2002</u> THE CLEAN UP OF THE ROOF OF THE PREMISE WAS CONDUCTED. AIR SAMPLING WAS PERFORMED BY EDWIN ELLIS (CERTIFICATE # AH 00-00613 EXP 10/02) OF WARREN & PANZER ENGINEERS. AIR SAMPLING EQUIPMENT WAS SET UP ON THE ROOF OF THE ADJACENT BUILDING (166 WILLIAM STREET). AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND I OBSERVED NO VISIBLE WTC DEBRIS.						
<u>TUESDAY OCTOBER 29 2002</u> THE CLEAN UP OF THE EAST (REAR) FACADE AND THE SECOND FLOOR SET BACK OF THE PREMISE WAS CONDUCTED. AIR SAMPLING WAS PERFORMED BY JESRON GARCIA (CERTIFICATE # AH 01-11633 EXP 03/03) OF WARREN & PANZER ENGINEERS. AIR SAMPLING EQUIPMENT WAS SET UP ON THE ROOF OF THE PREMISE. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, JESRON GARCIA PERFORMED A VISUAL INSPECTION OF THE CLEANED SURFACES AND HE OBSERVED NO VISIBLE WTC DEBRIS.						
<u>WEDNESDAY OCTOBER 30 2002</u> THE CLEAN UP OF THE PIT AREA OF THE SUB BASEMENT WAS PERFORMED. AIR SAMPLING WAS PERFORMED BY JESRON GARCIA OF WARREN & PANZER ENGINEERS. SAMPLES WERE VOIDED BECAUSE AIR SAMPLING WAS PERFORMED IN AN AREA WITH DAMAGED SUSPECT ACM MATERIAL (BOILER INSULATION).						
<u>THURSDAY OCTOBER 31 2002</u> FINAL CLEARANCE AIR MONITORING WAS PERFORMED BY JESRON GARCIA. AIR SAMPLING EQUIPMENT WAS LOCATED IN THE BASEMENT IN AN AREA FREE OF SUSPECT ACM. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.						

PTP

Asbestos Inspection Report

Premise No. 164 WILLIAM STREET					Inspection Date: 08-04-02	
Floor FACADE	Zip 10038	Borough 1	Block 93	Lot 24	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken (Yes) No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: 07:00AM TO 08:30 PM		
SUNDAY AUGUST 4 2002						
THE CLEAN UP OF THE WEST (FRONT) FACADE WAS CONDUCTED TODAY. THE CLEAN UP OF THE WEST FACADE OF 156 WILLIAM STREET WAS DONE SIMULTANEOUSLY. FOR THE PURPOSES OF AIR MONITORING THE WEST FACADE OF 164 WILLIAM STREET AND 156 WILLIAM STREET WERE TREATED AS ONE WORK AREA. FIVE AIR SAMPLES WERE RUN ON THE OPPOSITE SIDEWALK. AIR SAMPLING FOR THIS PROJECT WAS PERFORMED BY OCHOCHO ELHABOR (CERTIFICATE # AH 00-16198 EXP 12/02). A PLASTIC DIKE WAS CONSTRUCTED TO COLLECT RUN OFF WATER FROM THE FACADE CLEAN UP. A MOBILE DECON UNIT TRUCK WAS UTILIZED. UPON THE COMPLETION OF THE CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES. I OBSERVED NO VISIBLE WTC DEBRIS ON THE FACADE OF 164 WILLIAM STREET. THE CLEAN UP PROJECT AT THIS PREMISE IS NOW COMPLETE.						

RP