

Page: 1 Document Name: Extra

03/05/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
164..... WILLIAM STREET..... 1 MANHATTAN 10038 BIN# 1001282
DCP GEOGRAPHICAL INFORMATION:
WILLIAM STREET 164 - 164 HEALTH AREA : 77 TAX BLK: 93...
CENSUS TRACT: 12012 TAX LOT: 24...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : POLITO SALVATORE POLITO SALVATORE
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : DOB LOCAL LAW STATUS: NO
DOF BUILDING INFORMATION: TRANS LAND VALUE: 800,000
BLDG SIZE; 0025.00 X 0060.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0024.50 X 0066.83 TAX EXEMPT CLASS:
BLDG CLASS : K9 STORE BUILDING CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 02/28/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

C.L 3/5 No access
R?/ Facade

Date: 3/5/ 2 Time: 05:00:44 PM

WTC Visual Survey Form

1001282

Premise Address: 164 WILLIAM ST. - No Access		
Block: 93	Residential ☐ Commercial ☐	Name of Building:
Lot: 24	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management Name:		Telephone Number: ()
Address:		FAX: ()
On Site Contact Name:		
		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No	Locations: _____	
ACM Clean Up ☐ Yes ☐ No	Locations: _____	
Air Monitoring ☐ Yes ☐ No	Locations: _____	
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1" ☐ > 1"
Facade Description: _____					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 3/5/2002

Inspection by: Name: CARL

Agency: _____
Agency: _____