

WTC Visual Survey Form

1083364

✓

Premise Address: 7 Worth Ct

Block: 179 **Residential** ☐ **Commercial** ☐ **Name of Building:** landmark structures
Lot: 6 **Mix Use** ☒ **Other** ☐

of Stories: 2 **AKA's:** 9 Worth, 11 Worth, 13 Worth

Building Owner/Management: **Telephone Number:** ()
Name: Fine Arts Development Lab Inc. **FAX:** ()

Address: 46 Villarses 11 Worth St, NY 10013-2922

On Site Contact: **Telephone Number:** ()
Name:

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No
 Exterior Survey Performed ☐ Yes ☐ No
 General Clean Up ☐ Yes ☐ No **Locations:** unknown
 ACM Clean Up ☐ Yes ☐ No **Locations:**
 Air Monitoring ☐ Yes ☐ No **Locations:**

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: inspected from 46 Worth

Setbacks N/A ☒

Floor:	Debris:		
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 5/11/2002

Inspection Team: Name: GUN

Agency: DEP

Name: SHAN

Agency:



The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
 Corona, New York
 11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of Environmental Compliance
 Tel (718) 595-4418
 Fax (718) 595-4422

may 11 / 2002
 11
 April __, 2002

Building Owner Name: Bldg owner
Address: 7 WORTH ST.
 N.Y., N.Y.
 7 WORTH ST.
Subject:

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan

R. Radhakrishnan, P.E.
Director
Asbestos Control Program

