

WTC Visual Survey Form

1001958

Premise Address: 531 Worth St		
Block: 176	Residential ☐ Commercial ☒	Name of Building:
Lot: 4	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management Name: N.Y. Law School		Telephone Number: ()
Address:		FAX: ()
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: Cleaned					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 5/17/2002 **Inspection Team: Name:** AL **Agency:** _____

Name: _____ **Agency:** _____

WTC Visual Survey Form

1001957

Premise Address: 57 Worth St		
Block: 176	Residential ☐ Commercial ☒	Name of Building:
Lot: 1	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management Name: N.Y. Law School		Telephone Number: ()
Address:		FAX: ()
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

North ☐ N/A
 South ☐ N/A
 East ☐ N/A
 West ☐ N/A

Inspected

☐ Yes ☐ No
☐ Yes ☐ No
☐ Yes ☐ No
☐ Yes ☐ No

Debris

☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Facade Description:

Cleaned

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
Description: _____

Setbacks

N/A ☒

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 5/17/2002

Inspection Team: Name: AC

Agency: _____

Name: _____

Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

May 17, 2002

Building Owner Name:

NY Law School

Address:

59, 53, 57 W 4th St

NYC

234

Church St

Subject:

SARAH MOWR

240 Church St

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



www.nyc.gov/dep

(718) DEP-HELP

05/21/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPI031
 MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
 57..... WORTH STREET..... 1 MANHATTAN 10013 BIN# 1001957
 DCP GEOGRAPHICAL INFORMATION:
 WORTH STREET 57 - 61 HEALTH AREA : 77 TAX BLK: 176..
 CHURCH STREET 230 - 234 CENSUS TRACT: 2008 TAX LOT: 1....
 COMMUNITY BD: 101 CONDO :
 MULTI STRUCT: 1 CUI NO :
 DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
 OWNER NAME : NEW YORK LAW SCHOOL NEW YORK LAW SCHOOL
 CORP. NAME : LPC LANDMARK STATUS: NO
 ADDRESS : 57 WORTH ST DOB LOCAL LAW STATUS: YES
 NEW YORK NY 10013-2926
 DOF BUILDING INFORMATION: TRANS LAND VALUE: 2,100,000
 BLDG SIZE: 0051.00 X 0100.00 TAX EXEMPT FLAG : YES
 LOT SIZE: 0050.67 X 0100.00 TAX EXEMPT CLASS: X7
 BLDG CLASS : W6 EDUCATIONAL STRUCTURES CITY OWNERSHIP : NO
 STORIES : 9 UPDATE DATE : 03/25/02
 FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
 OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

 PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN