

WTC Visual Survey Form

1001951

Premise Address: 57 North St		
Block: 176	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
Lot: 1		
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: N.Y. Law School		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: Cleaned					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☒					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					

Date: 5/17/2002

Inspection Team: Name: AC

Agency: _____

Name: _____ Agency: _____

WTC Visual Survey Form

1001958

Premise Address: <u>531 Worth St</u>		
Block: <u>176</u>	Residential ☐ Commercial ☒	Name of Building:
Lot: <u>4</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>N.Y. Law School</u>		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Cleaned</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					

Date: 5/17 /2002Inspection Team: Name: AL

Name: _____

Agency: _____

Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

May 17, 2002

Building Owner Name: NY Law School

Address: 59, 53, 57 Worth St

NYC

Subject: SARAH MOWRT

234

Church St

240 Church St

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: Extra

05/21/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPI031
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
57..... WORTH STREET..... 1 MANHATTAN 10013 BIN# 1001957
DCP GEOGRAPHICAL INFORMATION:
WORTH STREET 57 - 61 HEALTH AREA : 77 TAX BLK: 176..
CHURCH STREET 230 - 234 CENSUS TRACT: 2008 TAX LOT: 1....
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : NEW YORK LAW SCHOOL NEW YORK LAW SCHOOL
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 57 WORTH ST DOB LOCAL LAW STATUS: YES
NEW YORK NY 10013-2926
DOF BUILDING INFORMATION: TRANS LAND VALUE: 2,100,000
BLDG SIZE: 0051.00 X 0100.00 TAX EXEMPT FLAG : YES
LOT SIZE: 0050.67 X 0100.00 TAX EXEMPT CLASS: X7
BLDG CLASS : W6 EDUCATIONAL STRUCTURES CITY OWNERSHIP : NO
STORIES : 9 UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 5/21/ 2 Time: 12:31:39 PM

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN:

Block: , Lot: , BIN: