

WTC Visual Survey Form

1079275

Premise Address: 66-77 W 4th

Block: 173 **Residential** ☐ **Commercial** ☒ **Name of Building:** LANDMARK
Lot: 10 **Mix Use** ☐ **Other** ☐ 2 STRUCTURES

of Stories: 65-67 NORTH ST, 69 NORTH ST, 229-233 Church St

Building Owner/Management: Valdina Development **Telephone Number:** ()
Name: Valdina Development **FAX:** ()

Address: Valdina North Street Partners 60 Sackett St, BK, NY 11231-1444

On Site Contact:
Name: Valdina Development **Telephone Number:** ()

Building Owner Management Activities
 Interior Survey Performed ☐ Yes ☐ No
 Exterior Survey Performed ☐ Yes ☐ No
 General Clean Up ☐ Yes ☐ No **Locations:** unknown
 ACM Clean Up ☐ Yes ☐ No **Locations:** _____
 Air Monitoring ☐ Yes ☒ No **Locations:** _____

Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Facade Description: _____

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: uninspected from 40 W 4th

Setbacks N/A ☒

Floor:	Debris:
_____	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Comments

Date: 8/14/2002Inspection Team: Name: GILAgency: DEPName: SITAN

Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

MAY
April 11, 2002

Building Owner Name: Bldg owner

Address: 65-77 WORTH ST.
N.Y., N.Y.

Subject: 65-77 WORTH ST

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
For R. Radhakrishnan, P.E.
Director
Asbestos Control Program



(718) DEP-HELP