

E066WTC
EMERGENCY
WRITTEN
FORMS WILL BE
ACCEPTED



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107
ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)

TRU 099946
Building Dept. or TRU No
FOR OFFICIAL USE ONLY
1. Nyc DEP
(See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 18 VESEY ST Borough N.Y. Zip 10007
AKA _____ 3. Block 88 4. Lot 4
5. Type of Facility _____ 6. Name of Building _____

II. BUILDING OWNER

7. Name BARCLAY VESEY LLC C/O 8. Contact Person _____
9. Tel. # (718) 343-6400 Fax # _____
10. Address 1200 Union TPKE City New Hyde Park State N.Y. Zip 11040

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name FIBER CONTROL 13. Contact Person TONY COSTA
14. Federal Employer ID. # PII 15. Tel. # 516-781-3000 Fax # 516-781-3085
16. Address 3010 BURNS AVE City WANTAGH State NY Zip 11793

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS, PC 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # _____ 20. Tel. # 212-922-0077 Fax # 212-922-0630
21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
22. Sample Analysis Laboratory SCIENTIFIC LABORATORIES, LLC 23. NYS DOH ELAP # 11480

VI. PROJECT INFORMATION

24. Starting date for this portion of work 7/18/02 Projected completion date 8/21/02

Asbestos work schedule ☐ Monday ☐ Tuesday ☐ Wednesday ☐ Thursday ☐ Friday ☐ Saturday ☐ Sunday


Shift from: _____ ☐ am ☐ pm to _____ ☐ am ☐ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

4,550 Square Feet, and/or _____ Linear Feet



NYC
BUREAU OF ENVIRONMENTAL
REMEDIATION & ENFORCEMENT
ASBESTOS CONTROL
PROGRAM
10112

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280 Fax: (212) 353-8306



Attn: Mr. Fabio Pedone
 Warren & Panzer Engineers, P.C.
 228 E. 45th Street
 New York NY 10017

Received: 7/19/02 8:30:00 AM
 ATC Group #: 8539
 Analysis Date: 7/19/02

Fax: (212) 922-0630 Phone: (212) 922-0077

Project: NYC DEP, W&P# 1079.01.02
 18 Vesey Street

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed
 by EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.3µ-5 µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²)	Notes
001A 8539 -1	1440.00	0.0562	0	None Detected	0	0.0048	<17.79	<0.0048
002A 8539 -2	1440.00	0.0562	0	None Detected	0	0.0048	<17.79	<0.0048
003A 8539 -3	1440.00	0.0562	0	None Detected	0	0.0048	<17.79	<0.0048
004A 8539 -4	1440.00	0.0562	0	CHRYSTOLE	1	0.0048	17.79	0.0048
005A 8539 -5	1440.00	0.0562	0	None Detected	0	0.0048	<17.79	<0.0048

MARK PEYSAKHOV

Analyzed by:

MICHAEL A. GORYCKI, Ph.D.

Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

Page 1 of 1

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C.

PAGE 1 OF 1

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

P.O.

12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

W&P FILE #: 1079-01-02

LABORATORY: ATC

ANALYSIS METHOD: PCM TEM
circle one 7400 AHERA EPA LEVEL II

TECHNICIAN: N. Wells

CONTACT: Nicki Nolan

CLIENT: NIK-DEP

PROJECT: Roof Cleanup

LOCATION: 18 Vesey St

8539

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	STOP	ON	OFF	TOTAL TIME	VOLUME (liters)	CONCENTRATION (lb./cc.)
001A	Entrance to roof 1st landing	3	4	08:30	08:30	08:30	14:30	360	1440	
002A	Entrance onto roof	3	4	08:31	08:31	08:31	14:31	360	1440	
003A	North end of roof	3	4	08:32	08:32	08:32	14:32	360	1440	
004A	Center area of roof	3	4	08:33	08:33	08:33	14:33	360	1440	
005A	South end of roof	3	4	08:34	08:34	08:34	14:34	360	1440	
006	Field	1								
007	Field	1								
008	Sealed	1								

COMMENTS:

SAMPLE BY: N Wells	DATE: 7/18
SIGNATURE: Nicki Nolan	
RELEASED BY: N Wells	DATE:
SIGNATURE: Nicki Nolan	
RECEIVED BY: ATC	DATE: 7/17/02
SIGNATURE: JD	8:30am

SAMPLE TYPE CODES			
1 - Blank	2 - Pre-Abatement	3 - During Abatement	4 - During Glove Bag Removal
5 - Final Clearance (inside)	6 - Final Clearance (outside)	7 - Personal	8 - Background



ATC Associates Inc.

104 East 25 Street

New York, NY 10010

TEL: (212) 353-8280 FAX: (212) 353-8306

FACSIMILE TELECOPY TRANSMISSION

To: Mr. Fabio Pedone
Warren & Panzer Engineers, P.C.

From: MARK PEYSAKHOV

Fax #: (212) 922-0630

ATC Group #: 8539

Date: Friday, July 19, 2002

Client Project: NYC DEP. W&F# 1079.01.02
18 Vesey Street

Time: 2:51:23 PM

Comments:

Number of Pages: 3
(including cover page)