

PREMISE NO. 18 VESEY STREET						INSPECTION DATE 7-18-02	
FLOOR Roof	ZIP	BORO CODE 1	BLOCK 88	LOT 4	SQUAD # 1	BADGE # AD10	
INSPECTOR ALPHONSO PLUMPTRE		BLDG TYPE	BASIS OF INSPECT. TRU0999M102			PHOTOS TAKEN YES/NO	
CONTRACTORS NAME FIBER CONTROL				SAMPLE NO.			
ADDRESS 3010 BURNS AVE				CITY WANTAGH			
STATE N.Y.				ZIP 11793		PHONE 516 781-3000	
LABORATORY NAME WARREN & PANZER ENGINEERS, PC				OWNERS NAME GLENWOOD MANAGEMENT			
ADDRESS 228 E 45TH ST				CITY N.Y.			
STATE N.Y.				ZIP 10017		PHONE 718 343-6400	
CONTACT PERSON:				TIME OF INSPECTION FROM: 2:30 am/pm TO: 3:00 am/pm			
INSPECTION DISCLOSED:							
The roof and the back alley was cleaned and during the roof cleaning, there was a flower pot filled with WTC debris that was missed. The flower was recleaned and bagged as wastes. The entire roof was cleaned and the back fire escape including the back alley. All visible debris were cleaned and no visible debris observed.							

NOV #	INFRACTIONS	RESULT CODE
		5
NOV #		SUPERVISORS INITIALS
		ca

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 = Violation Issued 2 = No Violations Issued 3 = No Access 4 = Project not Started (No NOV) 5 = Project Completed (No NOV)

ACP 30/93

FILE

ASBESTOS INSPECTION REPORT

PAGE 1 OF

PREMISE NO. 18 VESEY STREET						INSPECTION DATE 7-18-02	
FLOOR Roof	ZIP	BORO CODE 1	BLOCK 88	LOT 4	SQUAD # 1	BADGE # AD10	
INSPECTOR ALPHONSO PLUMPTRE		BLDG TYPE	BASIS OF INSPECT. TRU0999M102			PHOTOS TAKEN YES / NO	
CONTRACTORS NAME FIBER CONTROL						SAMPLE NO.	
ADDRESS 3010 BURNS AVE						CITY WANTAGH	
STATE N.Y.						ZIP 11793	
PHONE (616) 781-3000						SAMPLE NO.	
LABORATORY NAME WARREN & PANZER ENGINEERS, PC						OWNERS NAME GLENWOOD MANAGEMENT	
ADDRESS 228 E. 45TH ST						CITY N.Y.	
STATE N.Y.						ZIP 10017	
PHONE (212) 922-0077						STATE N.Y.	
CONTACT PERSON:						TIME OF INSPECTION FROM: 2:30 am/pm TO: 3:00 am/pm	
INSPECTION DISCLOSED:							
The roof and the back alley was cleaned and during the roof cleaning, there was a ^{flower} pot filled with WTC debris that was missed. The flower was recleaned and bagged as wastes. The entire roof was cleaned and the back fire escape including the back alley. All visible debris were cleaned and no visible debris observed.							

NOV #	INFRACTIONS					RESULT CODE 5
NOV #						SUPERVISORS INITIALS or

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = RICHMOND
 BLDG TYPE A > 6 Stories B < 6 Stories C Single Family
 D School E Hospital F Public Owned Property
 RESULT CODES 1 = Violation Issued 2 = No Violations Issued 3 = No Access
 4 = Project not Started (No NOV) 5 = Project Completed (No NOV)

ACP 30/93

FILE