


2/27/02
WTC ROOF SURVEY
Mohan



- ④ The above contacts were for 4 world financial center.
- ⑥ An appointment was made for this morning 9:30am for roof inspection.
- ⑤ Also an appointment was made with #3 WFC. (Annex Bldg) for 11am this morning - Engineers (212) 640-1220

File 1 copy
in
250 Vesey Pl
and another
in
200 Vesey St.

MAY-14-2002 TUE 09:35 AM RISK MANAGEMENT

FAX NO. 212 640 4883

P. 02

memorandum

M C C L I E R

605 Third Avenue
31st Floor
New York, New York 10158
212-973-2912
212-953-0399 fax
www.mcclier.com

Date: 5/14/02**To:** Krish Radhakrishnan
NYC/DEP**Project:** American Express Project**From:** Chris Sexton-McClier**Project No:** 01-957**Copies To:****Subject:** Washdown of the AMEX Bldg.
3 WFC (200 Vesey)

As per our telephone conversations, we are requesting your review of our application for FEMA funds to finance the washdown (cleaning) of our building.

Your assistance in this matter is greatly appreciated.

Sincerely,
McClier



Chris Sexton
Site Safety Manager

Inspected on April 15 2002
Bldg is clean.



ENTERED

On April 15, 2002 I met with Chris Sexton of Total Safety Consulting (212) 640-9136 and Michael Handler of Turner Construction 212.786.1480. The purpose of the meeting was to discuss the planned washdown of 1, 2, 3, 4 World Financial Centers. At this time, all the decontamination of the exterior had been completed. Samples had been collected for ACM and were negative.

Their concern was that when the washdown starts they do not violate any of DEP regulations. Water would be trucked in from outside so as to observe water restrictions. This they felt was the right thing to do, even if DEP allowed them to use the pipe borne supply. The washdown is a plain washing to give the entire clean up some finality. It was agreed that some soil sampling would be done where the run off is expected. So as to ensure that no form of contamination get into the sewer system. A review of the ACM sampling done revealed that only 4 samples were collected from each building (total of 16). Most had trace ACM. I requested that more sampling be done as 4 samples are not sufficient to represent the enormity of the buildings. However, they said that samples may be hard to find. In the end it was agreed that more samples would be taken.

If the additional samples are negative, then the cleanup can go on as planned. A look at some of the small window ledges revealed that they were free of debris.

Lutchmedial, Carlstien

From: Lutchmedial, Carlstien
Sent: Thursday, April 18, 2002 9:27 AM
To: Radhakrishnan, Krish
Subject: RE: American Express Building

I spoke to Michael Handler – the project manager and gave him Ms Rabich's number this morning.

-----Original Message-----

From: Radhakrishnan, Krish
Sent: Wednesday, April 17, 2002 3:58 PM
To: Lutchmedial, Carlstien
Subject: FW: American Express Building

Please call AE & let them know. Thanks

-----Original Message-----

From: Gilsenan, Michael
Sent: Wednesday, April 17, 2002 10:21 AM
To: Radhakrishnan, Krish
Subject: FW: American Express Building

Krish, pls. have Carl reach out to American Express with this info. before they start work.
 Thanks

-----Original Message-----

From: LaGrotta, Robert
Sent: Wednesday, April 17, 2002 7:57 AM
To: Gilsenan, Michael
Cc: Avaltroni, Robert; Heckler, Philip; Rabich, Sophia; Patel, Pravin; Collins, Betsy
Subject: RE: American Express Building

This is a separately sewered area. They will have to catch the runoff wastewater and direct it into the sanitary sewer otherwise it will go into the storm sewer and the river. They should be in contact with Sophia Rabich of my staff concerning sewer discharge approvals. She can be reached at Ext. 4707.

-----Original Message-----

From: Gilsenan, Michael
Sent: Tuesday, April 16, 2002 5:05 PM
To: Collins, Betsy 001
Cc: Avaltroni, Robert; LaGrotta, Robert
Subject: FW: American Express Building

Betsy/ Bob Fyi

-----Original Message-----

From: Radhakrishnan, Krish
Sent: Tuesday, April 16, 2002 2:59 PM
To: Gilsenan, Michael
Subject: FW: American Express Building

FYI

-----Original Message-----

From: Lutchmedial, Carlstien
Sent: Tuesday, April 16, 2002 7:32 AM
To: Radhakrishnan, Krish
Subject: American Express Building



TOTAL SAFETY CONSULTING LLC

Site Safety Management • Loss Control Consulting • Accident Investigation • Safety Training • Fire Safety

FAX COVER PAGE

DATE: 5/14/02

TO: DEP

ATTN: KRISH RADHAKRISHNA

RE: AMERICAN EXPRESS BLOC. WASHDOWN

FAX #: 718 595-3744

TOTAL PAGES (INCLUDING COVER PAGE): 2

FROM: CHRIS SEXTON

FAX #: 212-640-9223

VOICE #:

PII

NOTE

R.S.V.P. / ASAP PLEASE.

THANKS

Chris Sexton

6 Highland Avenue • Staten Island, NY 10301 • (718) 273-5113



April 17, 2002

Turner Construction Company
375 Hudson Street
New York, New York 10014-3667
phone: 212.229.6000
fax: 212.229.6329

Mr. Carlstien Lutchmedial, Director
Enforcement Asbestos Control Program
New York City Department of Environmental Protection
59-17 Junction Boulevard, 8th Floor
Corona, New York 11368-5107

Dear Mr. Lutchmedial:

Thank you for taking the time to meet with us regarding the façade cleaning at the World Financial Center.

As per our conversation, we are exempt from water restrictions when washing the building down. The results of the bulk sampling of material on the building showed less than 1% of asbestos and the D.E.P. therefore considers this a non-asbestos project. As a non-asbestos project, there is no requirement for collecting the wastewater from the wash down or any special protection.

We have attached copies of the bulk sample result for Towers 1, 2, 3, and 4. As per your suggestion, we will get 5 additional samples for each building for a total of nine (9) each. We will forward the results as they become available.

Very truly yours

TURNER CONSTRUCTION COMPANY

A handwritten signature in black ink, appearing to read "Michael Handler", written over a white background.

Michael Handler
Project Manager

:encl.

Cc: W. Murray, T. Evans, D. Collins (TCCo), G. Gutierrez (McCleir) R. Guam, C. Sexton(TSC), M. Bosso (Brookfield), B. Grant (Merrill Lynch)

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Independent Monitoring & Analysis, Inc. Date Received 03/23/2002 SciLab Job No. 202033340
 Attn: Peter Ellams Date Examined 03/23/2002 P.O. # Ellams
 511 6th Ave. ELAP Number 11480 Page 1 of 4
 Suite 353 RE: World Financial Center - Towers A,B,C, and D
 New York, NY 10012

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
WFC-01	202033340-01	Yes	<1.0% ^{1,2}

Location: Tower A, 6th Floor - East End Window Ledge

Description: Grey, Heterogeneous, Bulk Material
 Asbestos Types: Chrysotile <1.0 %
 Other Material: Animal hair Trace, Cellulose 20. %, Fibrous glass 40. %, Synthetic fibers Trace, Non-fibrous >39. %

WFC-02	202033340-02	Yes	<1.0% ^{1,2}
--------	--------------	-----	----------------------

Location: Tower A, Mezzanine Level - Northeast End Window Ledge

Description: Grey, Heterogeneous, Bulk Material
 Asbestos Types: Chrysotile Trace
 Other Material: Animal hair Trace, Cellulose 15. %, Fibrous glass 20. %, Non-fibrous 65. %

WFC-03	202033340-03	Yes	<1.0% ^{1,2}
--------	--------------	-----	----------------------

Location: Tower A, Mezzanine Level - Southeast End Window Ledge

Description: Grey, Heterogeneous, Bulk Material
 Asbestos Types: Chrysotile Trace
 Other Material: Animal hair 5. %, Cellulose 20. %, Fibrous glass 15. %, Synthetic fibers 5. %, Non-fibrous 55. %

WFC-04	202033340-04	Yes	<1.0% ^{1,2}
--------	--------------	-----	----------------------

Location: Tower A, Ground Level - Marble Ledge Structure

Description: Grey, Heterogeneous, Bulk Material
 Asbestos Types: Chrysotile <1.0 %
 Other Material: Animal hair Trace, Cellulose 30. %, Fibrous glass 15. %, Synthetic fibers Trace, Non-fibrous >54. %

**SCIENTIFIC LABORATORIES, INC.**117 EAST 30TH STREET
NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Independent Monitoring & Analysis, Inc. Date Received 03/23/2002 SciLab Job No. 202033340
 Attn: Peter Ellams Date Examined 03/23/2002 P.O. # Ellams
 511 6th Ave. ELAP Number 11480 Page 2 of 4
 Suite 353 RE: World Financial Center - Towers A,B,C, and D
 New York, NY 10012

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
WFC-05	202033340-05	Yes	<1.% ^{1,2}

Location: Tower B, 4th Floor- East Center End Window Ledge**Description:** Grey, Heterogeneous, Bulk Material**Asbestos Types:** Chrysotile Trace**Other Material:** Cellulose 20. %, Fibrous glass 15. %, Synthetic fibers Trace,
Non-fibrous 65. %

WFC-06	202033340-06	Yes	<1.% ^{1,2}
--------	--------------	-----	---------------------

Location: Tower B, 4th Floor - Southeast End Corner Structure Ledge**Description:** Grey, Heterogeneous, Bulk Material**Asbestos Types:** Chrysotile <1.0 %**Other Material:** Cellulose 20. %, Fibrous glass 35. %, Synthetic fibers Trace,
Non-fibrous >44. %

WFC-07	202033340-07	Yes	<1.% ^{1,2}
--------	--------------	-----	---------------------

Location: Tower B, 3rd Floor - Northeast End Window Ledge**Description:** Grey, Heterogeneous, Bulk Material**Asbestos Types:** Chrysotile Trace**Other Material:** Animal hair Trace, Cellulose 15. %, Fibrous glass 20. %,
Synthetic fibers Trace, Non-fibrous 65. %

WFC-08	202033340-08	Yes	<1.% ^{1,2}
--------	--------------	-----	---------------------

Location: Tower B, Mezzanine - Northeast End Window Ledge**Description:** Grey, Heterogeneous, Bulk Material**Asbestos Types:** Chrysotile Trace**Other Material:** Animal hair Trace, Cellulose 15. %, Fibrous glass 25. %,
Synthetic fibers Trace, Non-fibrous 60. %

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Independent Monitoring & Analysis, Inc. Date Received 03/23/2002 SciLab Job No. 202033340
 Attn: Peter Ellams Date Examined 03/23/2002 P.O. # Ellams
 511 6th Ave. ELAP Number 11480 Page 3 of 4
 Suite 353 RE: World Financial Center - Towers A,B,C, and D
 New York, NY 10012

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
WFC-09	202033340-09	No	NAD ²

Location: Tower C, 7th Floor - Southwest End Window Ledge

Description: Grey, Heterogeneous, Bulk Material

Asbestos Types:

Other Material: Cellulose 20. %, Fibrous glass 10. %, Non-fibrous 70. %

WFC-10	202033340-10	Yes	<1.0% ^{1, 2}
--------	--------------	-----	-----------------------

Location: Tower C, 7th Floor - Southeast End Window Ledge

Description: Grey, Heterogeneous, Bulk Material

Asbestos Types: Chrysotile Trace

Other Material: Cellulose 5. %, Fibrous glass 5. %, Synthetic fibers Trace, Non-fibrous 90. %

WFC-11	202033340-11	Yes	<1.0% ^{1, 2}
--------	--------------	-----	-----------------------

Location: Tower C, 4th Floor - Southeast End Window Ledge

Description: Grey, Heterogeneous, Bulk Material

Asbestos Types: Chrysotile Trace

Other Material: Animal hair Trace, Cellulose 15. %, Fibrous glass 25. %, Non-fibrous 60. %

WFC-12	202033340-12	Yes	<1.0% ^{1, 2}
--------	--------------	-----	-----------------------

Location: Tower C, 4th Floor - Northeast End Window Ledge

Description: Grey, Heterogeneous, Bulk Material

Asbestos Types: Chrysotile <1.0 %

Other Material: Animal hair Trace, Cellulose 15. %, Fibrous glass 30. %, Synthetic fibers Trace, Non-fibrous >54. %

**SCIENTIFIC LABORATORIES, INC.**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

PLM Bulk Asbestos Report

Independent Monitoring & Analysis, Inc. Date Received 03/23/2002 SciLab Job No. 202033340
 Attn: Peter Ellams Date Examined 03/23/2002 P.O. # Ellams
 511 6th Ave. ELAP Number 11480 Page 4 of 4
 Suite 353 RE: World Financial Center - Towers A,B,C, and D
 New York, NY 10012

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
WFC-13	202033340-13	Yes	<1.% ^{1, 2}
Location: Tower D, 4th Floor - Southwest End Window Ledge			
Description: Grey, Heterogeneous, Bulk Material			
Asbestos Types: Chrysotile Trace			
Other Material: Cellulose 15. %, Fibrous glass 35. %, Non-fibrous 50. %			
WFC-14	202033340-14	Yes	<1.% ^{1, 2}
Location: Tower D, Northeast End Balcony Below Window Ledge			
Description: Grey, Heterogeneous, Bulk Material			
Asbestos Types: Chrysotile Trace			
Other Material: Cellulose 10. %, Fibrous glass 20. %, Synthetic fibers Trace, Non-fibrous 70. %			
WFC-15	202033340-15	Yes	<1.% ^{1, 2}
Location: Tower D, 4th Floor - Southwest End Window Ledge			
Description: Grey, Heterogeneous, Bulk Material			
Asbestos Types: Chrysotile Trace			
Other Material: Animal hair Trace, Cellulose 15. %, Fibrous glass 30. %, Synthetic fibers Trace, Non-fibrous 55. %			

Reporting Notes:

- (1) PLM analysis by EPA 400 Point Count Method, where Trace = less than 1% by weight (e.g. < 1.0%)
- (2) Composite analysis results for heterogeneous debris samples may be highly variable due to inhomogenities in materials present

Analyzed by: Jonathan Teda _____

*NAD/NSD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NYLAP Lab #200546-0) and ELAP PLM Analysis Protocol 198.1 for New York samples (NYSDOH ELAP Lab # 11480); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested. AIHA# 102843; VT Cert# AL016055

Reviewed By: _____



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107

TRU 12434401
Building Dept. or TRU No
FOR OFFICIAL USE ONLY

ONLY
TYPEWRITTEN
FORMS WILL BE
ACCEPTED

**ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)**

1. \$1200
(See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

ER 11/5/01

I. FACILITY

2. Address 200 Vesey Borough Manhattan Zip 10281
AKA 3 World Financial Center 3. Block 16 4. Lot 140
5. Type of Facility Office Building 6. Name of Building American Express Tower

II. BUILDING OWNER

7. Name 3 World Financial Center American Express Tower 8. Contact Person Paul Troast
9. Tel. # (917) 416-5179 Fax # _____
10. Address 3 World Financial Center City New York State NY Zip 10281

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name Safeway Environmental Corp. 13. Contact Person Don Adler
14. Federal Employer ID. # PII 15. Tel. # (718) 794-4300 Fax # (718) 794-1411
16. Address 1379 Commerce Avenue City Bronx State NY Zip 10461

V. THIRD PARTY AIR MONITOR

17. Name EMTEQUE Corporation/JLC Environmental Consultants 18. Contact Person Eric Telemaque/Jennifer Carey
19. Federal Employer ID. # PII 20. Tel. # (212) 631-9000 Fax # _____
21. Address 505 Eighth Avenue/200 Park Avenue South City New York State NY Zip 10018
22. Sample Analysis Laboratory Final Aire/JLC Environmental Consultants, Inc. 23. NYS DOH ELAP # 11228/ 11029

VI. PROJECT INFORMATION

24. Starting date for this portion of work 9/5/01 Projected completion date 11/5/01


Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☐ Saturday ☐ Sunday

Shift from: 7 ☒ am ☐ pm to 5 ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work
115,100 Square Feet, and/or 0 Linear Feet



ACP 7
2/2001

ASBESTOS INSPECTION REPORT (continued)

26. Asbestos Hauler Asbestos Transportation Corp. NYS DEC Permit # 1A-371 Tel.# (631) 924-5050

Disposal Site(s) Meadowfill Landfill, Bridgeport, WV 26330

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
e) ☐ Fireproofing Replacement f) ☒ Other (Describe) Asbestos Abatement

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☒ Clean up

29. ABATEMENT PROCEDURE (Check all appropriate boxes)



- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application

TRU 124311101

30. LOCATIONS OF ABATEMENT

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM		DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
			SQUARE FEET	LINEAR FEET	
	**see attached				

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

EMTEQUE Print Name of Air Monitor  Signature 10/8/01 Date	Don Adler for Safeway Env Corp. Print Name of Asbestos Contractor  Signature 10/8/01 Date	Don Adler for Safeway Env Corp. Print Name of Applicant (if other than Owner)  Signature 10/8/01 Date
--	---	--

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

Paul Troast, as agent for American Express
 Print Name of Owner


 Signature

10/8/01
 Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

NYC DEP ASBESTOS CONTROL PROGRAM

EMERGENCY ASBESTOS PROJECT NOTIFICATION (15 RCNY Section 1-56)

Written notification must be received within 48 hours via

- a) Asbestos Inspection Report (ACP-7)
- b) Cover letter explaining the nature of the emergency

E 145/01

1) Caller's Name: Don Adler
 Affiliation: Safewy Environ
 Telephone #: (718) 794-4300

2) Nature of Emergency: _____

3) Actual Date and Time of Emergency: _____

4) Method of Asbestos Abatement:
 Removal _____ Sq. ft. _____ L. ft. Repair _____ Sq. ft. _____ L. Ft
 Encapsulation _____ Sq. ft. _____ L. ft. Clean-up 100,000 Sq. ft. _____ L. ft.
 Enclosure _____ Sq. ft. _____ L. ft.

5) Facility Address: 3 World Financial Center

Owner/Agent: Contact Person _____ Tel. _____

Location of Asbestos Abatement: 3rd, 4th, 5, 6, 7, 8, 9, 10, 11, 12, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 25, 26 floors and roofs on the 4th, 5th, 10th, 20th, 26th, 48th, 51st and 52nd

6) Asbestos Abatement Contractor:

Name: Safewy Environmental
 Address: _____

Telephone #: _____

7) Starting Date: 10/5/9 Projected Completion Date: _____

8) Verification by Owner/Agent: Yes.
No.

Call Taken By: L. P. J.
 Date: 10/9/01

xc: Enforcement (Urgent).


SAFEWAY ENVIRONMENTAL CORP.

1379 Commerce Avenue
Bronx, NY 10461
(718) 794-4300

October 5, 2001

Mr. R. Radhakrishnan, P.E.
Director of Asbestos Services
City of New York
Department of Environmental Protection
59-17 Junction Boulevard, 8th Floor
Corona, New York 11368-5107
FAX: (718) 595-3744

ER 145/01.



**Re: American Express Tower
3 World Financial Center
Emergency Clean Up**

Dear Mr. Radhakrishnan:

As discussed with Penny Theodorellis-Perez please find procedures for clean up work at 3 World Financial Center, as follows:

SCOPE:

Removal of approximately 10,000 square feet of contaminated debris from the building setback roofs and approximately 90,000 square feet of contaminated debris from the Interior Southeast corner of the building located at 200 Vesey Street (3 World Financial Center), New York, NY. The subject building is located immediately West of the former 1WTC site.

Setback roofs are located on the 4th, 5th, 10th, 20th, 26th, 48th, 51st and 52nd floors of the building.

Contaminated interior areas shall include the Southeast corners of the building. Work is located on the 3rd, 4th, 5th, 6th, 7th, 8th, 9th, 10th, 11th, 12th, 14th, 15th, 16th, 17th, 18th, 19th, 20th, 21st, 22nd, 23rd, 24th, 25th and 26th floors.

Contractor Safeway Environmental Corp. 1379 Commerce Avenue Bronx, NY 10461 (718) 794-4300 Asbestos License Number: 99-0955	3rd Party Air Monitor #1 JLC Environmental Consultants, Inc. 200 Park Ave South, Suite 1001 New York, NY 10003 (212) 420-8119	3rd Party Air Monitor #2 Emteque Corporation 505 Eighth Avenue, Suite 900 New York, NY 10018 (212) 631-9000
--	--	--

Work shall proceed as follows:

1. Remote showering facilities will be erected.
2. Each setback roof and contaminated Southeast corner will be its own work area. Access shall be restricted to authorized personnel. Each work area shall be cordoned off with signs and Caution barrier tape.
3. Personal protective equipment shall be worn (i.e. (2) tyvek suits, glove, ½ face negative pressure respirator, gloves, etc.).

ER 145/01.


4. All openings on the setback roof (penetrations, broken windows) shall be fully closed and sealed with two layers of 6-mil poly.
5. Clean up methods shall consist of adequately wetting the debris, placing the debris in asbestos waste bags and wet wiping / HEPA vacuuming the area. For contaminated metal debris, the metal will be thoroughly decontaminated and or and disposed of as regular construction waste.
6. Upon completion of the clean up and before final air clearance, all surfaces shall be rendered free of visible debris.
7. Air sampling shall be conducted as per Title 15 Chapter 1, Subchapter D, and Part 3.

Work shall start tonight, October 05, 2001 at approximately 6:00PM.

An ACP7 for this project shall be submitted with the DEP on Tuesday, October 09, 2001

This emergency clean up work *must* take place in order to install cranes on the setback roofs to correct the unsafe structural condition in the South East corner of the building.

Very truly yours,
Safeway Environmental Corp.



Don Adler
Vice President

McCluer Corporation (as agent for the Owner)



Paul Troast
Vice President

250 Vesey Place

Brookfield

1 Liberty Plaza (6th Floor)

N.Y. N.Y. # 10006

(212) 417-7000
