

T R U M P

STEVE LAFIOSCA
BUILDING MANAGER

40 WALL STREET, LLC.
40 WALL STREET • NEW YORK, N.Y. 10005
DIRECT: 212-809-0116 • FAX: 212-482-6875 • CELL: 917-693-1657
E-MAIL: slafiosca@trumporg.com

WTC Visual Survey Form

Premise Address: 40 WALL ST.		
Block:	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
Lot:		
# of Stories: 20	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: Trum		FAX: ()
Address:		
On Site Contact:		
Name: Steve LaFosca		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☒ Yes ☐ No	Debris	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: 25		Debris: ☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____		Debris: ☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____		Debris: ☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____		Debris: ☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Floor: _____		Debris: ☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"	
Comments					
Air Monitoring had been done by					
AGS					

Date: 4/15/2004

Inspection by: Name: CARL HUTCHINGS/A

Agency: DEP

Name: _____

Agency: _____