

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Page 1

Report Date 04/15/2002 09:23 AM

Submitted By

Service # 433402

Problem BWTC WTC RELATED (HOT LINE)

Address 60 WALL ST 1

10005

Cross Streets HANOVER ST

PEARL ST

Compass Direction

Building ID 10010

Block 00040

Lot 0003

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 04/12/2002 17:40

Taken By 3179

GREEN, JOSEPH L.

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

COMPLETED

☐ **Customer Contact Req**

Budget #

Problem Comments

Initial Caller

Last Name POLIZANO

Title MS

First Name, MI

Address 80 GOLD ST

APT 4C

City, State/Province, ZIP/PC

☐ **Foreign**

Day Phone (212)964-0310 x196

Evening Phone (212)571-0310 x

Call Date 04/12/2002 17:40

Reference #

Caller Comments

DUST ENTERING APT FROM OUTSIDE THRU A/C UNIT AFTER UNIT HAS BEEN CLEANED REQUEST INSPECTION

Inspected			Resolution		
By	Date	Time	Code	Date	Time

Building is on the list for cleanup. We have not received the lic. agreement back yet.

WTC Visual Survey Form

Premise Address: 60 WALL ST		
Block:	Residential ☐ Commercial ☒	Name of Building: Deutsche Bank
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name: Rick HARDING		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
Harding said cleaning was done					
about two weeks ago. He said he'd					
send results.					

Date: 8/30/2002

Inspection Team: Name: CARC

Agency: _____

ENTERED

Name: _____

Agency: _____