

NYDEC 1A-371

31
NYDCA 483056

Asbestos Transportation Co., Inc.

P.O. BOX 1044
HAMPTON BAYS, N.Y. 11946

TOLL FREE
1-800-755-0ATC
"EMERGENCY NUMBER"

PHONE 631-924-5050
FAX 631-924-5085

Waste Manifest # 37053	Job #	Floor or Location	Cust # 122
1. Work Site Name and Mailing Address BROWN BROTHERS HARRIMAN 63 WALL ST. NEW YORK, N.Y.		Owner's Name, Address, Phone Number BROWN BROTHERS HARRIMAN 63 WALL ST. NEW YORK, N.Y.	
Contractor's Name, Address TRIO 14-20 129TH STREET COLLEGE POINT, NY		Waste Disposal Site MEADOWFILL LANDFILL RT. #2, BOX 68 BRIDGEPORT, WV. 26330	
Name and Address of Responsible NESHAPS Agency U.S. EPA REGION II, 290 BROADWAY, NEW YORK, NY 10007			
Description of Materials ☒ RQ Waste Asbestos, Class 9, NA2212, PGIII ☐ Other _____		Bags - 19	Cubic Yds. -
☐ RQ Waste White Asbestos, Class 9, UN2590, PGIII		Drums or Tons -	OTHER -
Special Handling Instructions and Additional Information			
OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled and are in all respects in proper condition for transport by highway according to applicable international government regulations. Leo Title _____ x Leon Sauer Signature _____ Date (M/DD/YY) 7-31-02			
Transporter 1 (Acknowledgement of Receipt of Materials)			
Company Name and Address ASBESTOS TRANSPORTATION CO., INC. P.O. BOX 1044 HAMPTON BAYS, NY 11946	Signature: [Signature]	Telephone No. 631-924-5050	
	Printed Name: Richard Johnson	Date	
	Title: DRIVER	7/30/02	
Transporter 2 (Acknowledgement of Receipt of Materials)			
Company Name and Address ASBESTOS TRANSPORTATION CO., INC. P.O. BOX 1044 HAMPTON BAYS, NY 11946	Signature: [Signature]	Telephone No. 631-924-5050	
	Printed Name: David G...	Date	
	Title: DRIVER	8/7/02	
Discrepancy Indication Space:			
MEADOWFILL LANDFILL 1(304)842-2784 Company Name and Address	Waste Disposal Site Owner or Operator's Certification (Receipt of Above Waste Accepted)		Telephone No.
	Signature: [Signature]		Date
	Printed Name: John Martin		8-9-02
Title: oper.			

7000820

WTC Visual Survey Form

Premise Address:

Block: 243	Residential ☐ Commercial ☒	Name of Building:
Lot: 9	Mix Use ☐ Other ☐	
# of Stories: 35	AKA's: 83 BEAVER	
Building Owner/Management:		Telephone Number: ()
Name: JAMES LANG LASALLE AMERICAN		FAX: ()
Address: 22ND FLOOR, N.Y. N.Y. 10005		
On Site Contact:		
Name: Mike Amato - engineer		Telephone Number: (212) 493-8616
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		Roof - General clean-up Engineering staff vac. coils & filters vacuumed up dust
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		
ACM Clean Up ☐ Yes ☐ No		
Air Monitoring ☐ Yes ☐ No		
Locations: Brown Brothers		Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

	Inspected	Debris
North ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description:

Roof

Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" ☐ > 1"

Description: **pitched roof with omade center and narrow area around it. this area had visible accumulations in pockets, areas were identified to**

Setbacks N/A ☐

Floor: **20**

Floor: **15**

Floor: **4**

Floor: _____

Floor: _____

Debris: ☐ No Visible/Fine Layer	☒ 1/2 to 1"
Debris: ☐ No Visible/Fine Layer	☒ 1/2 to 1"
Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"
Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"
Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"

visible debris

in air condition unit windows still dirty only on 15 Fl.

Comments

Date: **2/14** /2002Inspection by: Name: **Penny Theodorellys** Agency: **NYC DEP**

Name: _____ Agency: _____