

WTC Visual Survey Form

1000875

Parcise Address: <u>100 Wall St</u>		
Block: <u>38</u>	Residential ☐ Commercial ☒	Name of Building:
Lot: <u>1</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>Reckson Assoc.</u>		FAX: ()
Address:		
On Site Contact:		
Name: <u>Chris Jacobson</u>		Telephone Number: <u>(212) 248-7160</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☐ Yes ☒ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☒ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A	Inspected		Debris		
	☒ Yes	☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
	☒ Yes	☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
	☒ Yes	☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments					

Date: 4/13/2002Inspection Team: Name: ObelloAgency: DEPName: Bill

Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 13, 2002
February

Building Owner Name: DECKSON ASS

Address: 100 WALL ST.
(212) 248-7160

Subject: 100 WALL ST.

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



04/16/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
100..... WALL STREET..... 1 MANHATTAN 10005 BIN# 1000875
DCP GEOGRAPHICAL INFORMATION:
WALL STREET 96 - 104 HEALTH AREA : 77 TAX BLK: 38...
WATER STREET 119 - 133 CENSUS TRACT: 1002 TAX LOT: 1....
FRONT STREET 118 - 134 COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 100 WALL CO. LLC 100 WALL CO. LLC
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 225 BROADHOLLOW RD DOB LOCAL LAW STATUS: NO
MELVILLE NY 11747-4822
DOF BUILDING INFORMATION: TRANS LAND VALUE: 42,800,000
BLDG SIZE: 0108.00 X 0174.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0117.25 X 0194.92 TAX EXEMPT CLASS:
BLDG CLASS : 04 OFFICE BUILDING CITY OWNERSHIP : NO
STORIES : 9 UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 03/13/2002 04:57 PM

Submitted By

Page 2

Linked Requests

Service #	Problem	Problem Date	Address
Location			

No Linked Requests for this Service Request Inspection

NYC DEP

Method

Source

Critical Service

Log Log Type	Description	Log Started	Log Ended	Entered By
Comments				

There are no log entries for this service number

End of Report