NYC 9/11 Public Portal Document

WTC Visual Survey Form

Premise Address: 8 Warren St

Block: **Lot:** 5	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐ ____	**Name of Building:**
# of Stories: 5	**AKA's:**	

Building Owner/Management: Telephone Number: ( )
Name: FAX: ( )
Address:

On Site Contact:
Name: 2 Construction Workers Telephone Number: ( )

Building Owner Management Activities
Interior Survey Performed ☐ Yes ☒ No
Exterior Survey Performed ☐ Yes ☒ No
General Clean Up ☐ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☐ No Locations: _____
Air Monitoring ☐ Yes ☐ No Locations: _____
Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
Description:

Setbacks N/A ☐

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments Roof accessed from 12 Warren St across to Warren into 8 Warren. Entire interior of Bldg is gutted.

Date: 6/5/2002 **Inspection Team: Name:** _____ **Agency:** _____
Name: _____ **Agency:** _____

NYC-WTC_000112655

WTC Visual Survey Form

Premise Address: 10 WARREN Street

Block: **Lot:**	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐ _____	**Name of Building:**
# of Stories: 5	**AKA's:**	

Building Owner/Management: Telephone Number: ( )
Name: FAX: ( )

Address:

On Site Contact:
Name: Telephone Number: ( )

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No
Exterior Survey Performed ☐ Yes ☐ No
General Clean Up ☐ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☐ No Locations: _____
Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ **Yes**

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Brown windows etc

Roof

Debris: ☐ No Visible /Fine Layer (Light Dust) ☐ ½ to 1" ? dust ☐ > 1" ? dust.
Description: Can't get into building.

Setbacks N/A ☒

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/27/2002 Inspection Team: Name: R. Fitzpatrick Agency: US EPA
Name: P. Theodorellis Agency: NYCDEP

RF-17

NYC 9/11 Public Portal Document

The City of New York
Department of Environmental Protection
59-17 Junction Boulevard
Corona, New York
11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner
Bureau of Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422

February 23, 2002

Building Owner
10 Warren Street
New York, NY 10007

Subject: 8 WARREN STREET
10 Warren St
Second Notice

Dear Sir/ Madam:

This is a follow-up to the NYC DEP request for copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. To date, our office has not received the requested documents and information. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.
Director
Asbestos Control Program

NEW YORK CITY DEPARTMENT OF ENVIRONMENTAL PROTECTION
DEP
www.nyc.gov/dep
(718) DEP-HELP

NYC-WTC_000112657

NYC 9/11 Public Portal Document

The City of New York

Department of Environmental Protection

59-17 Junction Boulevard
Corona, New York
11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of
Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422

February 21, 2002

Building Owner
10 Warren Street
New York, New York 10007

Subject: 10 Warren Street

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.
Director
Asbestos Control Program

NEW YORK CITY DEPARTMENT OF ENVIRONMENTAL PROTECTION
DEP
www.ny.gov/dep
(718) DEP HELP

NYC-WTC_000112658