

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368
JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 02/24/02

Premise: 16 WARREN STREET

Boro: MANHATTAN

Time: 3:50 am/pm

Inspector: R. RAMMOHAN
Print

NR Mohay
Signature

Turnaround Time: Immediate | ☒ | 24 Hours | | 48 Hours | | 1 Week | |

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20224/A078001	Fibrous Dirt	Roof	
2. 20224/A078002	Fibrous Dirt	Roof	
3. 20224/A078003	" "	Roof	
4. 20224/A078004	" "	Roof	
5. 20224/A078005	" "	Roof	
6. 20224/A078006	" "	Roof	
7. 20224/A078007	" "	Roof	
8. 20224/A078008	" "	Roof	
9. 20224/A078009	Fibrous Dirt	Roof	
10.			

ANALYSIS REQUESTED: Asbestos PLM | ☒ |


Asbestos TEM | |

Lead | |

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

MEP ACLP REV 5/00

16 Warren Street.



WTC Visual Survey Form

Premise Address: <u>16 Warren Street</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name: <u>Willy Somma</u>		Telephone Number: (212) 608- <u>5910</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

	N/A	Inspected	Debris	1/2 to 1"	> 1"
North	☐	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
South	☐	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
East	☐	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
West	☐	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"

Facade Description:

Broken windows etc.

Roof

Debris: ☒ No Visible ^{light dust} Fine Layer ☐ 1/2 to 1" of dust ☐ > 1" of dust.

Description: _____

Setbacks N/A ☒

Floor:	Debris:	No Visible/Fine Layer	1/2 to 1"	> 1"
_____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
_____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
_____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
_____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
_____	Debris:	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"

Comments

Hallway cleaned.No roof or facade cleaning.Date: 1/12/2002Inspection Team: Name: R. FitzpatrickAgency: USEPAName: P. TheodorelyAgency: NYC D&P

RF-15

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
16..... WARREN STREET..... 1 MANHATTAN 10007 BIN# 1078996
DCP GEOGRAPHICAL INFORMATION:
WARREN STREET 16 - 16 HEALTH AREA : 77 TAX BLK: 135..
CENSUS TRACT: 1011 TAX LOT: 7....
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 16 WARREN ASSOCIATES 16 WARREN ASSOCIATES
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 430 W BROADWAY DOB LOCAL LAW STATUS: NO
NEW YORK NY 10012-3784
DOF BUILDING INFORMATION: TRANS LAND VALUE: 600,000
BLDG SIZE; 0025.00 X 0100.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0025.40 X 0100.00 TAX EXEMPT CLASS:
BLDG CLASS : S4 RESIDENCE-MULTI-USE CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 12:26:57 PM