

WTC Visual Survey Form

Premise Address: <u>22 Warren Street</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Broken windows etc.</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: <u>No Access.</u>					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>RF</u>					

Date: 1 / 27 / 2002Inspection Team: Name: P. FitzpatrickAgency: USEPAName: P. ThordurAgency: NYC DEP

RF-14

Date: 1/30/ 2 Time: 12:28:15 PM

WTC Visual Survey Form

Premise Address: <u>22 Warren Street</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Broken windows etc</u>					
Roof					
<i>light dust</i>					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" <i>1 dust</i> ☐ > 1" <i>1 dust</i>					
Description: <u>NO ACCESS.</u>					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>RF</u>					

Date: 1 / 27 / 2002Inspection Team: Name: R. FitzpatrickAgency: USEPAName: P. TheodorelyAgency: NYC DEP

RF-14